




## COLORADO DIVISION OF RECLAMATION, MINING AND SAFETY COAL PROGRAM INSPECTION REPORT



### PERMIT INFORMATION

<b>Permit Number:</b> C-1981-046 <b>Mine Name:</b> Sunlight Mine <b>Operator:</b> Garfield Energy Corporation <b>Operator Address:</b>	<b>County:</b> Garfield <b>Operation Type:</b> Underground <b>Permit Status:</b> Revoked <b>Ownership:</b> Private
	<b>Operator Representative Present:</b>  None
<b>Operator Representative Signature: (Field Issuance Only)</b>  	

### INSPECTION INFORMATION

<b>Inspection Start Date:</b> September 9, 2013 <b>Inspection Start Time:</b> 09:00 <b>Inspection End Date:</b> September 9, 2013 <b>Inspection End Time:</b> 13:30	<b>Inspection Type:</b> Coal Complete Inspection <b>Inspection Reason:</b> Normal I&E Program <b>Weather:</b> Cloudy
<b>Joint Inspection Agency:</b>  None	<b>Joint Inspection Contacts:</b>  
<b>Post Inspection Agency:</b>  None	<b>Post Inspection Contacts:</b>  
<b>Inspector(s):</b>  Brock F. Bowles  Steve Renner	<b>Inspector's Signature:</b>  <b>Signature Date:</b>  September 11, 2013

**Inspection Topic Summary**

NOTE: Y=Inspected N=Not Inspected R=Comments Noted V=Violation Issued NA=Not Applicable

N - Air Resource Protection	N - Roads
N - Availability of Records	N - Reclamation Success
R - Backfill & Grading	R - Revegetation
N - Excess Spoil and Dev. Waste	R - Subsidence
N - Explosives	N - Slides and Other Damage
N - Fish & Wildlife	N - Support Facilities On-site
N - Hydrologic Balance	N - Signs and Markers
N - Gen. Compliance With Mine Plan	N - Support Facilities Not On-site
N - Other	N - Special Categories Of Mining
N - Processing Waste	N - Topsoil

**COMMENTS**

This was a complete inspection of the Sunlight Mine conducted by Brock Bowles and Steve Renner of the Colorado Division of Reclamation, Mining and Safety on September 9, 2013. Darnell Oxford of Red Dog Enterprises, was also present for the inspection. The permit for this mine was revoked and the bond was forfeited. The reclamation was completed by the Division. Weather conditions were overcast and rain started about 12:30. The purpose of this inspection was to evaluate the subsidence above the lower portal noted in previous inspection reports (June 2013, April 2013, September 2012, September 2010 and July 2013). The subsidence was located in the tall grass approximately 12 feet in by of the lower portal seal (photo 1). The subsidence hole is approximately 3 feet deep by 5 feet across.

BACKFILL and GRADING – Rule 4.14 ☐ Contemporaneous Reclamation 4.14.1; Approximate Original Contour 4.14.2; Highwall Elimination 4.14.1(2)(f); Steep Slopes 4.14.2, 4.27; Handling of Acid and Toxic Materials 4.14.3; Stabilization of Rills and Gullies 4.14.6:

The concrete block mine portal seal was backfilled and graded to approximate original contour (photo 2). The excavated subsidence area at the lower portal was backfilled and graded to approximate original contour (photo 3). The drainage ditch in front of the mine seal was backfilled. The remainder of the ditch to the east of the portal was not backfilled.

REVEGETATION – Rule 4.15 ☐ Vegetative Cover; Timing:

The surface of the excavated hillside was left in a rough condition and clumps of sod and shrubbery were placed randomly (photo 3). Flat areas disturbed and/or compacted by the machinery were roughened with the bucket of the loader (photo 4). Steve Renner will seed the entire disturbed area in October.

SUBSIDENCE – Rule 4.20:

The wood cribbing around the mine seal was collapsed and removed (photo 5). The wood debris was buried in the ditch to the east of the mine seal/portal. The portal seal was not disturbed or damaged during the cribbing removal (photo 6). Steve Renner explained that the mine seal is a double wide concrete block wall reinforced with rebar. The mine seal/portal was buried with soil. The soil came from a berm located on the mine

Number of Partial Inspection this Fiscal Year: 1

Number of Complete Inspections this Fiscal Year: 1

property approximately 40 feet in front of the mine portal.

The subsidence area was excavated. The excavated soil was very soft and sandy and had little consolidation. The mine adit was found at approximately 7.5 feet below the surface (photo 7). The mine adit was approximately 4 feet in diameter. Within the adit, there was evidence of collapsing including a large rock.

The mine adit was excavated for another 5 feet, horizontally inby. At 24 feet inby of the mine seal, the top of the mine adit was 11 feet below the surface (photo 8). At this point the adit had collapsed and only small hand-sized openings in the soil existed (photo 9). The entire length of the mine adit up to this point was collapsed.

The mine adit is approximately 4 feet in diameter and the overburden at the last excavation was 11 feet thick. The mine adit went in a northwesterly direction and appeared to be declining. The surface topography in the direction of the mine adit is inclining. It was determined that if any non-collapsed sections of the mine adit beyond this point should later collapse, it would only have a small subsidence expression on the surface and a mine adit opening is unlikely.

### **PHOTOGRAPHS**



Photo 1 – Location of Subsidence



Photo 2 – Mine Seal Backfilled with Soil

Number of Partial Inspection this Fiscal Year: 1

Number of Complete Inspections this Fiscal Year: 1





Photo 3 – Excavation Re-Contoured to AOC



Photo 4 – Compacted Areas Roughened with Loader



Photo 5 – Removing Wood Cribbing



Photo 6 – Concrete Block Mine Seal

Number of Partial Inspection this Fiscal Year: 1

Number of Complete Inspections this Fiscal Year: 1





Photo 7 – Mine Adit 7.5 Feet Below Surface



Photo 8 – Mine Adit 11 Feet Below Surface




Photo 9 – Collapsed Adit

Number of Partial Inspection this Fiscal Year: 1

Number of Complete Inspections this Fiscal Year: 1