

QUARTERLY SEDIMENTATION POND INSPECTION REPORT

CDMR Rule 4.05.9(17)

Mine: New Elk
NPDES ID. No.: Pond #1
Inspection Period: First Quarter 2017
Inspection Date: 02/21/17

General Description or Reference to Site Plan:

This Pond lies West of the Industrial Building and serves as a mine water settling and water storage pond.

EMBANKMENT

- 1). Adequacy of the vegetative cover: Excellent Moderate Few Poor
- 2). Erosion forming Gullies: Extensive Some Few None
- 3). Is wave action causing erosion:
- | | | |
|----------------------------------|-----------|-------------|
| On the Upstream embankment? | Yes _____ | No <u>✓</u> |
| At the principal spillway inlet? | Yes _____ | No <u>✓</u> |
- 4). Erosion of the downstream toe of the embankment? Yes _____ No ✓
Cause of erosion can be attributed to: _____

- 5). Is seepage occurring through the dam? Yes _____ No ✓
Could this seepage cause potential instability? _____

PRINCIPAL SPILLWAY

- 1). Is the principal spillway system in working order? Yes ✓ No _____
- 2). Is the inlet free of debris and restrictive material? Yes ✓ No _____
- 3). Is the discharge outlet free of restrictive material? Yes ✓ No _____
- 4). Is erosion occurring at the discharge outlet? Yes _____ No ✓
Evaluate the severity: Extensive Moderate Just starting None

EMERGENCY SPILLWAY

- 1). Does it appear that the emergency spillway has discharged water since the last inspection?
Yes _____ No ✓
- 2). Is erosion occurring at any section of the emergency spillway?
Yes _____ No ✓
- Describe extent: _____

SEDIMENT STORAGE CAPACITY

- 1). Has the design storage capacity of the reservoir been surpassed?
Yes _____ No ✓
- Explain: Water storage is controlled by pumping water
into/out of storage. No water storage 2016 - Q1 2017.

OTHER OBSERVATIONS

Pond is well maintained with no mine
or river water pumped into storage since
cessation of mining. Water level is declining
due to gradual evaporation.

Ronald G. Hanger
MSHA Trained Impoundment Inspector
February 21, 2017

QUARTERLY SEDIMENTATION POND INSPECTION REPORT

CDMR Rule 4.05.9(17)

Mine: New Elk
NPDES ID. No.: Pond #4
Inspection Period: First Quarter 2017
Inspection Date: 02/21/17

General Description or Reference to Site Plan:

This sediment control pond lies west of the Development Waste Pile. The majority of run-off from this waste pile flows to this pond. It has never received sufficient inflow to discharge.

EMBANKMENT

- 1). Adequacy of the vegetative cover: Excellent Moderate Few Poor
- 2). Erosion forming Gullies: Extensive Some Few None
- 3). Is wave action causing erosion:
On the Upstream embankment? Yes _____ No ✓
At the principal spillway inlet? Yes _____ No ✓
- 4). Erosion of the downstream toe of the embankment? Yes _____ No ✓
Cause of erosion can be attributed to: _____
- 5). Is seepage occurring through the dam? Yes _____ No ✓
Could this seepage cause potential instability? _____

PRINCIPAL SPILLWAY

- 1). Is the principal spillway system in working order? Yes ✓ No _____
- 2). Is the inlet free of debris and restrictive material? Yes ✓ No _____
- 3). Is the discharge outlet free of restrictive material? Yes ✓ No _____
- 4). Is erosion occurring at the discharge outlet? Yes _____ No ✓
Evaluate the severity: Extensive Moderate Just starting None

EMERGENCY SPILLWAY

- 1). Does it appear that the emergency spillway has discharged water since the last inspection?

Yes _____ No ☒

- 2). Is erosion occurring at any section of the emergency spillway?

Yes _____ No ☒Describe extent: _____
_____**SEDIMENT STORAGE CAPACITY**

- 1). Has the design storage capacity of the reservoir been surpassed?

Yes _____ No ☒Explain: Visual observation**OTHER OBSERVATIONS**

Minimal water pooled as ice in center of basin away from embankment. No maintenance required at this time.

Operator is planning a phase II & III vegetation assessment for the reclaimed area reporting to pond for final bond release and termination of the permit requirement for Pond 4



MSHA Trained Impoundment Inspector

February 21, 2017

QUARTERLY SEDIMENTATION POND INSPECTION REPORT

CDMR Rule 4.05.9(17)

Mine: New Elk
NPDES ID. No.: Pond #7
Inspection Period: First Quarter 2017
Inspection Date: 02/21/17

General Description or Reference to Site Plan:

This sediment control pond lies east of the preparation plant and pond #6. It receives run-off from the majority of the active surface facilities area lying south of State Highway 12.

EMBANKMENT

- 1). Adequacy of the vegetative cover: Excellent Moderate Few Poor
- 2). Erosion forming Gullies: Extensive Some Few None
- 3). Is wave action causing erosion:
 On the Upstream embankment? Yes _____ No ✓
 At the principal spillway inlet? Yes _____ No ✓
- 4). Erosion of the downstream toe of the embankment? Yes _____ No ✓
 Cause of erosion can be attributed to: _____

- 5). Is seepage occurring through the dam? Yes _____ No ✓
 Could this seepage cause potential instability? _____

PRINCIPAL SPILLWAY

- 1). Is the principal spillway system in working order? Yes ✓ No _____
- 2). Is the inlet free of debris and restrictive material? Yes ✓ No _____
- 3). Is the discharge outlet free of restrictive material? Yes ✓ No _____
- 4). Is erosion occurring at the discharge outlet? Yes _____ No ✓
 Evaluate the severity: Extensive Moderate Just starting None

EMERGENCY SPILLWAY

- 1). Does it appear that the emergency spillway has discharged water since the last inspection?

Yes _____ No ☒

- 2). Is erosion occurring at any section of the emergency spillway?

Yes _____ No ☒Describe extent: _____
_____**SEDIMENT STORAGE CAPACITY**

- 1). Has the design storage capacity of the reservoir been surpassed?

Yes _____ No ☒

Explain: _____

Pond clean-out has been completed**OTHER OBSERVATIONS**Pond is fully dewatered, access ramp for
clean-out removed and disturbance to
pond embankments mulched and reseeded

_____MSHA Trained Impoundment Inspector
February 21, 2017

QUARTERLY SEDIMENTATION POND INSPECTION REPORT

CDMR Rule 4.05.9(17)

Mine: New Elk
NPDES ID. No.: Pond #8
Inspection Period: First Quarter 2017
Inspection Date: 02/21/17

General Description or Reference to Site Plan:

This pond lies north of Highway 12 at the base of the refuse disposal area. The pond receives run-off from the refuse disposal area.

EMBANKMENT

- 1). Adequacy of the vegetative cover: Excellent Moderate Few Poor
- 2). Erosion forming Gullies: Extensive Some Few None
- 3). Is wave action causing erosion:
On the Upstream embankment? Yes _____ No ✓
At the principal spillway inlet? Yes _____ No ✓
- 4). Erosion of the downstream toe of the embankment? Yes _____ No ✓
Cause of erosion can be attributed to: _____

- 5). Is seepage occurring through the dam? Yes _____ No ✓
Could this seepage cause potential instability? _____

PRINCIPAL SPILLWAY

- 1). Is the principal spillway system in working order? Yes ✓ No _____
- 2). Is the inlet free of debris and restrictive material? Yes ✓ No _____
- 3). Is the discharge outlet free of restrictive material? Yes ✓ No _____
- 4). Is erosion occurring at the discharge outlet? Yes _____ No ✓
Evaluate the severity: Extensive Moderate Just starting None

EMERGENCY SPILLWAY

- 1). Does it appear that the emergency spillway has discharged water since the last inspection?

Yes _____ No ✓

- 2). Is erosion occurring at any section of the emergency spillway?

Yes _____ No ✓

Describe extent: _____

SEDIMENT STORAGE CAPACITY

- 1). Has the design storage capacity of the reservoir been surpassed?

Yes ? No _____

Explain: Visual Observation

Recommend Survey as soon as ponds dewatered

OTHER OBSERVATIONS

Dewatering and clear-out should be completed
to increase retention time.

Ronald L. Hays

MSHA Trained Impoundment Inspector
February 21, 2017

QUARTERLY SEDIMENTATION POND INSPECTION REPORT

CDMR Rule 4.05.9(17)

Mine: New Elk Pond 6
NPDES ID. No.: None
Inspection Period: First Quarter 2017
Inspection Date: 02/21/17

General Description or Reference to Site Plan:

Pond 6 is a non-discharging facility designed to contain plant processing water. The plant has been idle since 1996 and the pond is now used to dewater other ponds prior to clean-out.

EMBANKMENT

- 1). Adequacy of the vegetative cover: Excellent Moderate Few Poor
- 2). Erosion forming Gullies: Extensive Some Few None
- 3). Is wave action causing erosion:
 On the Upstream embankment? Yes _____ No ✓
- 4). Erosion of the downstream toe of the embankment? Yes _____ No ✓
 Cause of erosion can be attributed to: _____
- 5). Is seepage occurring through the dam? Yes _____ No ✓
 Could this seepage cause potential instability? _____

SEDIMENT STORAGE CAPACITY

- 1). Has the design storage capacity of the reservoir been surpassed? Yes _____ No ✓
 Explain: operator controls water flow to pond.

OTHER OBSERVATIONS:

operator is currently pumping
water from Pond 8 to Pond 6. Pond 6 water
is estimated @ 40% of Capacity.

Ronald L. Thompson
MSHA Trained Impoundment Inspector
February 21, 2017

QUARTERLY SEDIMENTATION POND INSPECTION REPORT

CDMR Rule 4.05.9(17)

Mine: New Elk WP Containment #1
NPDES ID. No.: None
Inspection Period: First Quarter 2017
Inspection Date: 02/21/17

General Description or Reference to Site Plan:

This containment basin is a non-discharging facility designed to contain run-off from the West Portal Warehouse area.

EMBANKMENT

- 1). Adequacy of the vegetative cover: Excellent Moderate Few Poor
- 2). Erosion forming Gullies: Extensive Some Few None
- 3). Is wave action causing erosion:
On the Upstream embankment? Yes _____ No ✓
- 4). Erosion of the downstream toe of the embankment? Yes _____ No ✓
Cause of erosion can be attributed to: _____
- 5). Is seepage occurring through the dam? Yes _____ No ✓
Could this seepage cause potential instability? _____

SEDIMENT STORAGE CAPACITY

- 1). Has the design storage capacity of the reservoir been surpassed? Yes _____ No ✓
Explain: Visual Observation

OTHER OBSERVATIONS:

Containment held a minor
amount of water as ice in center of basin
No maintenance required

Ronald A. Hoyer
MSHA Trained Impoundment Inspector
February 21, 2017

QUARTERLY SEDIMENTATION POND INSPECTION REPORT

CDMR Rule 4.05.9(17)

Mine: New Elk WP Containment #2
NPDES ID. No.: None
Inspection Period: First Quarter 2017
Inspection Date: 02/21/17

General Description or Reference to Site Plan:

This containment basin is a non-discharging facility designed to contain run-off from the West Portal airshaft and manway areas.

EMBANKMENT

- 1). Adequacy of the vegetative cover: Excellent Moderate Few Poor
- 2). Erosion forming Gullies: Extensive Some Few None
- 3). Is wave action causing erosion:
 On the Upstream embankment? Yes _____ No ✓
- 4). Erosion of the downstream toe of the embankment? Yes _____ No ✓
 Cause of erosion can be attributed to: _____
- 5). Is seepage occurring through the dam? Yes _____ No ✓
 Could this seepage cause potential instability? _____

SEDIMENT STORAGE CAPACITY

- 1). Has the design storage capacity of the reservoir been surpassed? Yes _____ No ✓
 Explain: Visual Observation

OTHER OBSERVATIONS:

Containment is dry. No
Maintenance required at this time.

Ronald A. Long
MSHA Trained Impoundment Inspector
February 21, 2017

QUARTERLY SEDIMENTATION POND INSPECTION REPORT

CDMR Rule 4.05.9(17)

Mine: New Elk RDA Containment North
NPDES ID. No.: None
Inspection Period: First Quarter 2017
Inspection Date: 02/21/17

General Description or Reference to Site Plan:

This incised containment basin is a non-discharging facility designed to contain run-off from the RDA belt conveyor area north of highway 12.

EMBANKMENT / *incised with no embankment*

- 1). Adequacy of the vegetative cover: Excellent Moderate Few Poor
- 2). Erosion forming Gullies: Extensive Some Few None
- 3). Is wave action causing erosion:
 On the Upstream embankment? Yes _____ No ✓
- 4). Erosion of the downstream toe of the embankment? Yes _____ No ✓
 Cause of erosion can be attributed to: _____
- 5). Is seepage occurring through the dam? Yes _____ No ✓
 Could this seepage cause potential instability? _____

SEDIMENT STORAGE CAPACITY

- 1). Has the design storage capacity of the reservoir been surpassed? Yes _____ No ✓
 Explain: Visual Observation

OTHER OBSERVATIONS:

water storage as ice is estimated at
40-60% of Capacity. Recommend dewatering and
sediment clean-out if needed when conditions
allow.

MSHA Trained Impoundment Inspector
February 21, 2017

QUARTERLY SEDIMENTATION POND INSPECTION REPORT

CDMR Rule 4.05.9(17)

Mine: New Elk RDA Containment SE
NPDES ID. No.: None
Inspection Period: First Quarter 2017
Inspection Date: 02/21/17

General Description or Reference to Site Plan:

This partially incised containment basin is a non-discharging facility designed to contain run-off from the area east of the RDA belt conveyor and south of highway 12.

EMBANKMENT

- 1). Adequacy of the vegetative cover: Excellent Moderate Few Poor
- 2). Erosion forming Gullies: Extensive Some Few None
- 3). Is wave action causing erosion:
 On the Upstream embankment? Yes _____ No ✓
- 4). Erosion of the downstream toe of the embankment? Yes _____ No ✓
 Cause of erosion can be attributed to: _____
- 5). Is seepage occurring through the dam? Yes _____ No ✓
 Could this seepage cause potential instability? _____

SEDIMENT STORAGE CAPACITY

- 1). Has the design storage capacity of the reservoir been surpassed? Yes _____ No ✓
 Explain: Visual Observation

OTHER OBSERVATIONS:

Dry ; No maintenance required at this time

Ronald G. Thompson
MSHA Trained Impoundment Inspector
February 21, 2017

QUARTERLY SEDIMENTATION POND INSPECTION REPORT

CDMR Rule 4.05.9(17)

Mine: New Elk RDA Containment SE
NPDES ID. No.: None
Inspection Period: Fourth Quarter 2016
Inspection Date: 12/05/16

General Description or Reference to Site Plan:

This partially incised containment basin is a non-discharging facility designed to contain run-off from the area east of the RDA belt conveyor and south of highway 12.

EMBANKMENT

- 1). Adequacy of the vegetative cover: Excellent Moderate Few Poor
- 2). Erosion forming Gullies: Extensive Some Few None
- 3). Is wave action causing erosion:
 On the Upstream embankment? Yes _____ No ✓
- 4). Erosion of the downstream toe of the embankment? Yes _____ No ✓
 Cause of erosion can be attributed to: _____
- 5). Is seepage occurring through the dam? Yes _____ No ✓
 Could this seepage cause potential instability? _____

SEDIMENT STORAGE CAPACITY

- 1). Has the design storage capacity of the reservoir been surpassed? Yes _____ No ✓
 Explain: Visual observation

OTHER OBSERVATIONS:

Dry; No Maintenance required at this time

Ronald H. King
MSHA Trained Impoundment Inspector
February 21, 2017