

# QUARTERLY SEDIMENTATION POND INSPECTION REPORT

CDMR Rule 4.05.9(17)

Mine: New Elk  
NPDES ID. No.: Pond #1  
Inspection Period: Second Quarter 2017  
Inspection Date: 06/15/17

## General Description or Reference to Site Plan:

This Pond lies West of the Industrial Building and serves as a mine water settling and water storage pond.

## EMBANKMENT

- 1). Adequacy of the vegetative cover:      Excellent Moderate      Few      Poor
- 2). Erosion forming Gullies:      Extensive      Some      Few      None
- 3). Is wave action causing erosion:  
    On the Upstream embankment?      Yes \_\_\_\_\_      No ✓  
    At the principal spillway inlet?      Yes \_\_\_\_\_      No ✓
- 4). Erosion of the downstream toe of the embankment?      Yes \_\_\_\_\_      No ✓  
    Cause of erosion can be attributed to: \_\_\_\_\_  
    \_\_\_\_\_
- 5). Is seepage occurring through the dam?      Yes \_\_\_\_\_      No ✓  
    Could this seepage cause potential instability?      \_\_\_\_\_  
    Pond is lined

## PRINCIPAL SPILLWAY

- 1). Is the principal spillway system in working order?      Yes ✓      No \_\_\_\_\_
- 2). Is the inlet free of debris and restrictive material?      Yes ✓      No \_\_\_\_\_
- 3). Is the discharge outlet free of restrictive material?      Yes \_\_\_\_\_      No ✓
- 4). Is erosion occurring at the discharge outlet?      Yes \_\_\_\_\_      No ✓  
    Evaluate the severity:      Extensive      Moderate      Just starting      None

### EMERGENCY SPILLWAY

- 1). Does it appear that the emergency spillway has discharged water since the last inspection?

Yes \_\_\_\_\_ No ✓

- 2). Is erosion occurring at any section of the emergency spillway?

Yes \_\_\_\_\_ No ✓

Describe extent: \_\_\_\_\_  
\_\_\_\_\_

### SEDIMENT STORAGE CAPACITY

- 1). Has the design storage capacity of the reservoir been surpassed?

Yes \_\_\_\_\_ No ✓

Explain: \_\_\_\_\_

*Water level is managed by monitoring inflow from  
pumping water from underground or river.*

### OTHER OBSERVATIONS

*No water has been pumped to pond #1  
in 2017. Water level is slowly declining  
due to evaporation.*

*Ronald G. Thompson*

MSHA Trained Impoundment Inspector  
06/15/2017

# QUARTERLY SEDIMENTATION POND INSPECTION REPORT

CDMR Rule 4.05.9(17)

Mine: New Elk  
NPDES ID. No.: Pond #4  
Inspection Period: Second Quarter 2017  
Inspection Date: 06/15/17

## General Description or Reference to Site Plan:

This sediment control pond lies west of the Development Waste Pile. The majority of run-off from this waste pile flows to this pond. It has never received sufficient inflow to discharge.

## EMBANKMENT

- 1). Adequacy of the vegetative cover: Excellent Moderate Few Poor
- 2). Erosion forming Gullies: Extensive Some Few None
- 3). Is wave action causing erosion:  
On the Upstream embankment? Yes \_\_\_\_\_ No ✓  
At the principal spillway inlet? Yes \_\_\_\_\_ No ✓
- 4). Erosion of the downstream toe of the embankment? Yes \_\_\_\_\_ No ✓  
Cause of erosion can be attributed to: \_\_\_\_\_
- 5). Is seepage occurring through the dam? Yes \_\_\_\_\_ No ✓  
Could this seepage cause potential instability? \_\_\_\_\_

## PRINCIPAL SPILLWAY

- 1). Is the principal spillway system in working order? Yes ✓ No \_\_\_\_\_
- 2). Is the inlet free of debris and restrictive material? Yes ✓ No \_\_\_\_\_
- 3). Is the discharge outlet free of restrictive material? Yes ✓ No \_\_\_\_\_
- 4). Is erosion occurring at the discharge outlet? Yes \_\_\_\_\_ No ✓  
Evaluate the severity: Extensive Moderate Just starting None

### EMERGENCY SPILLWAY

- 1). Does it appear that the emergency spillway has discharged water since the last inspection?

Yes \_\_\_\_\_ No ☒

- 2). Is erosion occurring at any section of the emergency spillway?

Yes \_\_\_\_\_ No ☒

Describe extent: \_\_\_\_\_  
\_\_\_\_\_

### SEDIMENT STORAGE CAPACITY


- 1). Has the design storage capacity of the reservoir been surpassed?

Yes \_\_\_\_\_ No ☒

Explain: \_\_\_\_\_  
By observation

### OTHER OBSERVATIONS

This pond reportedly has seen minimal inflow since construction. Drainage basin contains Development Waste Pile #1 which has been reclaimed, seeded and is now well vegetated.



MSHA Trained Impoundment Inspector  
06/15/2017

# QUARTERLY SEDIMENTATION POND INSPECTION REPORT

CDMR Rule 4.05.9(17)

Mine: New Elk  
NPDES ID. No.: Pond #7  
Inspection Period: Second Quarter 2017  
Inspection Date: 06/15/17

## General Description or Reference to Site Plan:

This sediment control pond lies east of the preparation plant and pond #6. It receives run-off from the majority of the active surface facilities area lying south of State Highway 12.

## EMBANKMENT

- 1). Adequacy of the vegetative cover:      Excellent Moderate      Few      Poor
- 2). Erosion forming Gullies:      Extensive      Some      Few      None
- 3). Is wave action causing erosion:  
    On the Upstream embankment?      Yes \_\_\_\_\_      No ✓  
    At the principal spillway inlet?      Yes \_\_\_\_\_      No ✓
- 4). Erosion of the downstream toe of the embankment?      Yes \_\_\_\_\_      No ✓  
    Cause of erosion can be attributed to: \_\_\_\_\_  
    \_\_\_\_\_
- 5). Is seepage occurring through the dam?      Yes \_\_\_\_\_      No ✓  
    Could this seepage cause potential instability? \_\_\_\_\_  
    \_\_\_\_\_  
    \_\_\_\_\_

## PRINCIPAL SPILLWAY

- 1). Is the principal spillway system in working order?      Yes ✓      No \_\_\_\_\_
- 2). Is the inlet free of debris and restrictive material?      Yes ✓      No \_\_\_\_\_
- 3). Is the discharge outlet free of restrictive material?      Yes ✓      No \_\_\_\_\_
- 4). Is erosion occurring at the discharge outlet?      Yes \_\_\_\_\_      No ✓  
    Evaluate the severity:      Extensive      Moderate      Just starting      None

**EMERGENCY SPILLWAY**

- 1). Does it appear that the emergency spillway has discharged water since the last inspection?  
Yes \_\_\_\_\_ No ✓
- 2). Is erosion occurring at any section of the emergency spillway?  
Yes \_\_\_\_\_ No ✓
- Describe extent: \_\_\_\_\_

**SEDIMENT STORAGE CAPACITY**

- 1). Has the design storage capacity of the reservoir been surpassed?  
Yes \_\_\_\_\_ No ✓
- Explain: Pond has only recently filled with water since nearly complete sediment removal in 2016.

**OTHER OBSERVATIONS**

Primary discharge has been maintained closed with water level controlled by pumping water to pond 6.

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Ronald Y. Horgan  
MSHA Trained Impoundment Inspector  
06/15/2017



# QUARTERLY SEDIMENTATION POND INSPECTION REPORT

CDMR Rule 4.05.9(17)

Mine: New Elk  
NPDES ID. No.: Pond #8  
Inspection Period: Second Quarter 2017  
Inspection Date: 06/15/17

## General Description or Reference to Site Plan:

This pond lies north of Highway 12 at the base of the refuse disposal area. The pond receives run-off from the refuse disposal area.

## EMBANKMENT

- 1). Adequacy of the vegetative cover:      Excellent Moderate      Few      Poor
- 2). Erosion forming Gullies:      Extensive Some      Few      None
- 3). Is wave action causing erosion:
- |                                  |           |             |
|----------------------------------|-----------|-------------|
| On the Upstream embankment?      | Yes _____ | No <u>✓</u> |
| At the principal spillway inlet? | Yes _____ | No <u>✓</u> |
- 4). Erosion of the downstream toe of the embankment?      Yes \_\_\_\_\_      No ✓  
Cause of erosion can be attributed to: \_\_\_\_\_  
\_\_\_\_\_
- 5). Is seepage occurring through the dam?      Yes \_\_\_\_\_      No ✓  
Could this seepage cause potential instability? \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

## PRINCIPAL SPILLWAY

- 1). Is the principal spillway system in working order?      Yes ✓      No \_\_\_\_\_
- 2). Is the inlet free of debris and restrictive material?      Yes ✓      No \_\_\_\_\_
- 3). Is the discharge outlet free of restrictive material?      Yes ✓      No \_\_\_\_\_
- 4). Is erosion occurring at the discharge outlet?      Yes \_\_\_\_\_      No ✓  
Evaluate the severity:      Extensive      Moderate      Just starting      None

**EMERGENCY SPILLWAY**

1). Does it appear that the emergency spillway has discharged water since the last inspection?

Yes \_\_\_\_\_ No ✓

2). Is erosion occurring at any section of the emergency spillway?

Yes \_\_\_\_\_ No ✓

Describe extent: \_\_\_\_\_  
\_\_\_\_\_

**SEDIMENT STORAGE CAPACITY**

1). Has the design storage capacity of the reservoir been surpassed?

Yes \_\_\_\_\_ No ✓

Explain: \_\_\_\_\_

By observation/Pond Sediment cleaned out in 2015.

**OTHER OBSERVATIONS**

Water level was high but not discharging at  
time of inspection.

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

  
MSHA Trained Impoundment Inspector  
06/15/2017



# QUARTERLY SEDIMENTATION POND INSPECTION REPORT

CDMR Rule 4.05.9(17)

Mine: New Elk Pond 6  
NPDES ID. No.: None  
Inspection Period: Second Quarter 2017  
Inspection Date: 06/15/17

## General Description or Reference to Site Plan:

Pond 6 is a non-discharging facility designed to contain plant processing water. The plant has been idle since 1996 and the pond is now used to dewater other ponds prior to clean-out.

## EMBANKMENT

- 1). Adequacy of the vegetative cover:      Excellent Moderate      Few      Poor
- 2). Erosion forming Gullies:      Extensive Some      Few      None
- 3). Is wave action causing erosion:  
    On the Upstream embankment?      Yes \_\_\_\_\_      No ✓
- 4). Erosion of the downstream toe of the embankment?      Yes \_\_\_\_\_      No ✓  
    Cause of erosion can be attributed to: \_\_\_\_\_
- 5). Is seepage occurring through the dam?      Yes \_\_\_\_\_      No ✓  
    Could this seepage cause potential instability? \_\_\_\_\_

## SEDIMENT STORAGE CAPACITY

- 1). Has the design storage capacity of the reservoir been surpassed?      Yes \_\_\_\_\_      No ✓  
    Explain: \_\_\_\_\_

## OTHER OBSERVATIONS:

Not designed as a sediment  
treatment pond as only inflow is by direct  
precipitation or controlled and monitored pumping  
of water from sediment ponds 7 & 8.

Ronald L. Thompson

MSHA Trained Impoundment Inspector

June 15, 2017

# QUARTERLY SEDIMENTATION POND INSPECTION REPORT

CDMR Rule 4.05.9(17)

Mine: New Elk WP Containment #2  
NPDES ID. No.: None  
Inspection Period: Second Quarter 2017  
Inspection Date: 06/15/17

## General Description or Reference to Site Plan:

This containment basin is a non-discharging facility designed to contain run-off from the West Portal airshaft and manway areas.

## EMBANKMENT

- 1). Adequacy of the vegetative cover:      Excellent Moderate      Few      Poor
- 2). Erosion forming Gullies:      Extensive      Some      Few      None
- 3). Is wave action causing erosion:  
    On the Upstream embankment?      Yes \_\_\_\_\_      No ✓
- 4). Erosion of the downstream toe of the embankment?      Yes \_\_\_\_\_      No ✓  
    Cause of erosion can be attributed to: \_\_\_\_\_
- 5). Is seepage occurring through the dam?      Yes \_\_\_\_\_      No ✓  
    Could this seepage cause potential instability? \_\_\_\_\_

## SEDIMENT STORAGE CAPACITY

- 1). Has the design storage capacity of the reservoir been surpassed?      Yes \_\_\_\_\_      No ✓  
    Explain: - By observation

## OTHER OBSERVATIONS:

Containment basin was dry at time of inspection

Ronald L. Thompson

MSHA Trained Impoundment Inspector

June 15, 2017

# QUARTERLY SEDIMENTATION POND INSPECTION REPORT

CDMR Rule 4.05.9(17)

Mine: New Elk WP Containment #1 East  
NPDES ID. No.: None  
Inspection Period: Second Quarter 2017  
Inspection Date: 06/15/17

## General Description or Reference to Site Plan:

This containment basin is a non-discharging facility designed to contain run-off from the West Portal Warehouse area.

## EMBANKMENT

- 1). Adequacy of the vegetative cover: Excellent Moderate Few Poor
- 2). Erosion forming Gullies: Extensive Some Few None
- 3). Is wave action causing erosion:  
On the Upstream embankment? Yes \_\_\_\_\_ No ✓
- 4). Erosion of the downstream toe of the embankment? Yes \_\_\_\_\_ No ✓  
Cause of erosion can be attributed to: \_\_\_\_\_
- 5). Is seepage occurring through the dam? Yes \_\_\_\_\_ No ✓  
Could this seepage cause potential instability?  
Partially incised with water level below lowest elevation of the embankment.

## SEDIMENT STORAGE CAPACITY

- 1). Has the design storage capacity of the reservoir been surpassed? Yes \_\_\_\_\_ No ✓  
Explain: By observation

OTHER OBSERVATIONS: Clear and Sunny @ 1230 & 68°

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_  
MSHA Trained Impoundment Inspector  
June 15, 2017

# QUARTERLY SEDIMENTATION POND INSPECTION REPORT

CDMR Rule 4.05.9(17)

Mine: New Elk RDA Containment North  
NPDES ID. No.: None  
Inspection Period: Second Quarter 2017  
Inspection Date: 02/21/17

## General Description or Reference to Site Plan:

This incised containment basin is a non-discharging facility designed to contain run-off from the RDA belt conveyor area north of highway 12.

## EMBANKMENT

- 1). Adequacy of the vegetative cover: Excellent Moderate Few Poor
- 2). Erosion forming Gullies: Extensive Some Few None
- 3). Is wave action causing erosion:  
On the Upstream embankment? Yes \_\_\_\_\_ No ✓
- 4). Erosion of the downstream toe of the embankment? Yes \_\_\_\_\_ No ✓  
Cause of erosion can be attributed to:  
Incised / No embankment
- 5). Is seepage occurring through the dam? Yes \_\_\_\_\_ No ✓  
Could this seepage cause potential instability?  
No embankment

## SEDIMENT STORAGE CAPACITY

- 1). Has the design storage capacity of the reservoir been surpassed? Yes \_\_\_\_\_ No ✓  
Explain: By observation

## OTHER OBSERVATIONS:

Basin was cleaned of sediment in 2016; Pond currently holds significant water but likely little new sediment accumulation.

Ronald M. Hoyle

MSHA Trained Impoundment Inspector

June 15, 2017

## QUARTERLY SEDIMENTATION POND INSPECTION REPORT

CDMR Rule 4.05.9(17)

Mine: New Elk RDA Containment SW  
NPDES ID. No.: None  
Inspection Period: Second Quarter 2017  
Inspection Date: 06/15/17

### General Description or Reference to Site Plan:

This partially incised containment basin is a non-discharging facility designed to contain run-off from the area west of the RDA belt conveyor and south of highway 12.

### EMBANKMENT

- 1). Adequacy of the vegetative cover:      Excellent Moderate Few      Poor
- 2). Erosion forming Gullies:      Extensive Some Few      None
- 3). Is wave action causing erosion:  
    On the Upstream embankment?      Yes \_\_\_\_\_ No ✓
- 4). Erosion of the downstream toe of the embankment?      Yes \_\_\_\_\_ No ✓  
    Cause of erosion can be attributed to: \_\_\_\_\_  
    No Embankment
- 5). Is seepage occurring through the dam?      Yes \_\_\_\_\_ No ✓  
    Could this seepage cause potential instability? \_\_\_\_\_  
    This is an incised containment basin with no constructed embankment

### SEDIMENT STORAGE CAPACITY

- 1). Has the design storage capacity of the reservoir been surpassed?      Yes \_\_\_\_\_ No ✓  
    Explain: By observation

### OTHER OBSERVATIONS:

Pond is dry; weather sunny & clear 65°e 1130AM

Ronald M. Thompson  
MSHA Trained Impoundment Inspector  
June 15, 2017



# QUARTERLY SEDIMENTATION POND INSPECTION REPORT

CDMR Rule 4.05.9(17)

Mine: New Elk RDA Containment SE  
NPDES ID. No.: None  
Inspection Period: Second Quarter 2017  
Inspection Date: 06/15/17

## General Description or Reference to Site Plan:

This partially incised containment basin is a non-discharging facility designed to contain run-off from the area east of the RDA belt conveyor and south of highway 12.

## EMBANKMENT

- 1). Adequacy of the vegetative cover:      Excellent Moderate Few      Poor
- 2). Erosion forming Gullies:      Extensive Some      Few None
- 3). Is wave action causing erosion:  
On the Upstream embankment?      Yes \_\_\_\_\_ No ✓
- 4). Erosion of the downstream toe of the embankment?      Yes \_\_\_\_\_ No ✓  
Cause of erosion can be attributed to: No embankment
- 5). Is seepage occurring through the dam?      Yes \_\_\_\_\_ No ✓  
Could this seepage cause potential instability?  
This containment basin is incised with no constructed embankment.

## SEDIMENT STORAGE CAPACITY

- 1). Has the design storage capacity of the reservoir been surpassed?      Yes \_\_\_\_\_ No ✓  
Explain: By observation

OTHER OBSERVATIONS: Sunny and clear 65° c 11:48  
Basin contains minor water accumulation at lowest elevations within the basin

Ronald E. Long

MSHA Trained Impoundment Inspector

June 15, 2017