

Permit Number: C-1996-084

Mine Name: Lorencito Canyon Mine

1313 Sherman Street, Room 215, Denver, CO 80203 P 303.866.3567 F 303.832.8106 http://mining.state.co.us

## **PERMIT INFORMATION**

County: Las Animas
Operation Type: Surface

Operator: New Elk Coal Company Operator Address: Mr. Louis Head	, LLC	Ownership: Private  Operator Representative Present:				
12250 Highway 12 Weston, CO 81091						
Weston, CO 61091		Nick Mason				
Operator Representative Signatur	re: (Field I	(ssuance Only)				
INSPECTION INFORMATION						
Inspection Start Date: April 10, 2018 Inspection Start Time: 09:30 Inspection End Date: Inspection End Time:		Inspection Type: Coal Partial Inspection Inspection Reason: Normal I&E Program Weather: Clear				
Joint Inspection Agency:		Joint Inspection Contacts:				
None						
Post Inspection Agency:		Post Inspection Contacts:				
None						
Inspector(s):	Inspector	's Signature: Signature Date:				
Robert D. Zuber, P.E.	Phot	D. ZL				
		4/16/2018				

#### **Inspection Topic Summary**

NOTE: Y=Inspected N=Not Inspected N=Comments Noted N=Violation Issued NA=Not Applicable

NA - Air Resource Protection Y - Roads

 ${f N}$  - Availability of Records  ${f R}$  - Reclamation Success

NA - Backfill & Grading Y - Revegetation

R - Excess Spoil and Dev. Waste NA - Subsidence

NA - Explosives Y - Slides and Other Damage
N - Fish & Wildlife NA - Support Facilities On-site
R - Hydrologic Balance N - Signs and Markers

Y - Gen. Compliance With Mine Plan

N - Support Facilities Not On-site

 ${f N}$  - Other  ${f N}$  - Special Categories Of Mining

NA - Processing Waste N - Topsoil

### **COMMENTS**

A partial inspection was conducted by Rob Zuber of DRMS on April 10, 2018. The weather was clear, and the ground was dry. Nick Mason of NECC was present for the inspection.

EXCESS SPOIL and DEVELOPMENT WASTE - Rule 4.09

Placement; Drainage Control; Surface Stabilization:

Fills 7, 8, and 9 were inspected. All were generally in good condition with good vegetation cover.

#### HYDROLOGIC BALANCE - Rule 4.05

Drainage Control 4.05.1, 4.05.2, 4.05.3; Siltation Structures 4.05.5, 4.05.6; Discharge Structures 4.05.7, 4.05.10; Diversions 4.05.4; Effluent Limits 4.05.2; Ground Water Monitoring 4.05.13; Surface Water Monitoring 4.05.13; Drainage – Acid and Toxic Materials 4.05.8; Impoundments 4.05.6, 4.05.9; Stream Buffer Zones 4.05.18:

Three ponds were inspected: 5, 6, and 8. Pond 5 was dry. None of them were discharging. No problems were identified with embankments or spillways. The number and sizes of holes on the riser pipes for these three ponds met the Pond Schedule (Figure Ex. 15-14 in the PAP).

The small unnumbered ditch in the Pond 5 watershed (south of ditch D16) was inspected. The banks are not armored well but tree branches appear to be limiting the erosion of this feature.

Ditch D15 was found to be in good shape with a much larger cross section at the bottom (approximately five feet deep and 10-foot top width) than at the top of the ditch, where the depth is approximately two feet and the top width is approximately four feet. Ditch D16 should be maintained as it is somewhat eroded. No problems were identified with Ditch D9.

Culverts C11 and C12 were clear with no erosion below them.

Number of <u>Partial</u> Inspection this Fiscal Year: 9 Number of <u>Complete</u> Inspections this Fiscal Year: 3

RECLAMATION	SUCCESS	- Rule 4 15	Rule 3.
-------------	---------	-------------	---------

Rills above the pond cleaning dump area could use repair but this is not urgent. Rill repair is also needed near the shrub plot, on all three uphill sides.

## **ENFORCEMENT ACTIONS/COMPLIANCE**

No enforcement actions were initiated as a result of this inspection, nor are any pending.

# **PHOTOGRAPHS**



Ditch in Pond 5 watershed



Fill 8

Number of <u>Partial</u> Inspection this Fiscal Year: 9 Number of <u>Complete</u> Inspections this Fiscal Year: 3



West side of "the knob" and top of Fill 8 (on left)



Ditch D16



Ditch D9



Fill 7



Fill 9, with Pond 9a in background