

QUARTERLY SEDIMENTATION POND INSPECTION REPORT

CDMR Rule 4.05.9(17)

Mine: New Elk
NPDES ID. No.: Pond #1
Inspection Period: First Quarter 2018
Inspection Date: 03/27/18

General Description or Reference to Site Plan:

This Pond lies West of the Industrial Building and serves as a mine water settling and water storage pond.

EMBANKMENT

- 1). Adequacy of the vegetative cover: Excellent Moderate Few Poor
- 2). Erosion forming Gullies: Extensive Some Few None
- 3). Is wave action causing erosion:
- | | | |
|----------------------------------|-----------|-------------|
| On the Upstream embankment? | Yes _____ | No <u>✓</u> |
| At the principal spillway inlet? | Yes _____ | No <u>✓</u> |
- 4). Erosion of the downstream toe of the embankment? Yes _____ No ✓
Cause of erosion can be attributed to: _____

- 5). Is seepage occurring through the dam? Yes _____ No ✓
Could this seepage cause potential instability? _____
Pond is lined.

PRINCIPAL SPILLWAY

- 1). Is the principal spillway system in working order? Yes ✓ No _____
- 2). Is the inlet free of debris and restrictive material? Yes ✓ No _____
- 3). Is the discharge outlet free of restrictive material? Yes ✓ No _____
- 4). Is erosion occurring at the discharge outlet? Yes _____ No ✓
Evaluate the severity: Extensive Moderate Just starting None

EMERGENCY SPILLWAY

- 1). Does it appear that the emergency spillway has discharged water since the last inspection?
Yes _____ No ✓
- 2). Is erosion occurring at any section of the emergency spillway?
Yes _____ No ✓
- Describe extent: No Discharge Since start of operations

SEDIMENT STORAGE CAPACITY

- 1). Has the design storage capacity of the reservoir been surpassed?
Yes _____ No ✓
- Explain: No capacity design standard

OTHER OBSERVATIONS

No inflow other than direct precipitation.
Water level is slowly decreasing due to
evaporation.

Ronald E. Hays
MSHA Trained Impoundment Inspector
03/27/18

QUARTERLY SEDIMENTATION POND INSPECTION REPORT

CDMR Rule 4.05.9(17)

Mine: New Elk
NPDES ID. No.: Pond #4
Inspection Period: First Quarter 2018
Inspection Date: 03/27/18

General Description or Reference to Site Plan:

This sediment control pond lies west of the Development Waste Pile. The majority of run-off from this waste pile flows to this pond. It has never received sufficient inflow to discharge.

EMBANKMENT

- 1). Adequacy of the vegetative cover: Excellent Moderate Few Poor
- 2). Erosion forming Gullies: Extensive Some Few None
- 3). Is wave action causing erosion:
On the Upstream embankment? Yes _____ No ✓
At the principal spillway inlet? Yes _____ No ✓
- 4). Erosion of the downstream toe of the embankment? Yes _____ No ✓
Cause of erosion can be attributed to: _____

- 5). Is seepage occurring through the dam? Yes _____ No ✓
Could this seepage cause potential instability? _____

PRINCIPAL SPILLWAY

- 1). Is the principal spillway system in working order? Yes ✓ No _____
- 2). Is the inlet free of debris and restrictive material? Yes ✓ No _____
- 3). Is the discharge outlet free of restrictive material? Yes ✓ No _____
- 4). Is erosion occurring at the discharge outlet? Yes _____ No ✓
Evaluate the severity: Extensive Moderate Just starting None

EMERGENCY SPILLWAY

1). Does it appear that the emergency spillway has discharged water since the last inspection?

Yes _____ No ✓

2). Is erosion occurring at any section of the emergency spillway?

Yes _____ No ✓

Describe extent: _____

SEDIMENT STORAGE CAPACITY

1). Has the design storage capacity of the reservoir been surpassed?

Yes _____ No ✓

Explain: Visual observation

OTHER OBSERVATIONS

Only recent inflow has been pumping water
from Pond 8 to Pond 6 and/or Pond 4. Thus
pond contains a minor amount of water

Ronald S. Jones

MSHA Trained Impoundment Inspector
03/27/18

QUARTERLY SEDIMENTATION POND INSPECTION REPORT

CDMR Rule 4.05.9(17)

Mine: New Elk
NPDES ID. No.: Pond #7
Inspection Period: First Quarter 2018
Inspection Date: 03/27/18

General Description or Reference to Site Plan:

This sediment control pond lies east of the preparation plant and pond #6. It receives run-off from the majority of the active surface facilities area lying south of State Highway 12.

EMBANKMENT

- 1). Adequacy of the vegetative cover: Excellent Moderate Few Poor
- 2). Erosion forming Gullies: Extensive Some Few None
- 3). Is wave action causing erosion:
 On the Upstream embankment? Yes _____ No ✓
 At the principal spillway inlet? Yes _____ No ✓
- 4). Erosion of the downstream toe of the embankment? Yes _____ No ✓
 Cause of erosion can be attributed to: _____

- 5). Is seepage occurring through the dam? Yes _____ No ✓
 Could this seepage cause potential instability? _____

PRINCIPAL SPILLWAY

- 1). Is the principal spillway system in working order? Yes ✓ No _____
- 2). Is the inlet free of debris and restrictive material? Yes ✓ No _____
- 3). Is the discharge outlet free of restrictive material? Yes ✓ No _____
- 4). Is erosion occurring at the discharge outlet? Yes _____ No ✓
 Evaluate the severity: Extensive Moderate Just starting None

EMERGENCY SPILLWAY

- 1). Does it appear that the emergency spillway has discharged water since the last inspection?

Yes _____ No ☒

- 2). Is erosion occurring at any section of the emergency spillway?

Yes _____ No ☒

Describe extent: _____

SEDIMENT STORAGE CAPACITY

- 1). Has the design storage capacity of the reservoir been surpassed?

Yes _____ No ☒

Explain: _____

Pond was cleaned of sediment in 2017.

OTHER OBSERVATIONS

Water level is about a foot below base of
staff gage and lowest hole of the primary
discharge riser.



MSHA Trained Impoundment Inspector
03/27/18

QUARTERLY SEDIMENTATION POND INSPECTION REPORT

CDMR Rule 4.05.9(17)

Mine: New Elk
NPDES ID. No.: Pond #8
Inspection Period: First Quarter 2018
Inspection Date: 03/27/18

General Description or Reference to Site Plan:

This pond lies north of Highway 12 at the base of the refuse disposal area. The pond receives run-off from the refuse disposal area.

EMBANKMENT

- 1). Adequacy of the vegetative cover: Excellent Moderate Few Poor
- 2). Erosion forming Gullies: Extensive Some Few None
- 3). Is wave action causing erosion:
On the Upstream embankment? Yes _____ No ✓
At the principal spillway inlet? Yes _____ No ✓
- 4). Erosion of the downstream toe of the embankment? Yes _____ No ✓
Cause of erosion can be attributed to: _____

- 5). Is seepage occurring through the dam? Yes _____ No ✓
Could this seepage cause potential instability? _____

PRINCIPAL SPILLWAY

- 1). Is the principal spillway system in working order? Yes ✓ No _____
- 2). Is the inlet free of debris and restrictive material? Yes ✓ No _____
- 3). Is the discharge outlet free of restrictive material? Yes ✓ No _____
- 4). Is erosion occurring at the discharge outlet? Yes _____ No ✓
Evaluate the severity: Extensive Moderate Just starting None

EMERGENCY SPILLWAY

- 1). Does it appear that the emergency spillway has discharged water since the last inspection?

Yes _____ No ✓

- 2). Is erosion occurring at any section of the emergency spillway?

Yes _____ No ✓Describe extent: _____
_____**SEDIMENT STORAGE CAPACITY**


- 1). Has the design storage capacity of the reservoir been surpassed?

Yes 2 No _____

Explain: _____

Visual observation - pond water is being
pumped to pond 6/Pond 4 for scheduled April Cleanout**OTHER OBSERVATIONS**Minor snow cover. Pond water level is
several feet below staff gage based.

_____Ronald H. HaysMSHA Trained Impoundment Inspector
03/27/18



New Elk Pond 7 - March 27, 2018



New Elk Pond 8 – March 27, 2018

QUARTERLY SEDIMENTATION POND INSPECTION REPORT

CDMR Rule 4.05.9(17)

Mine: New Elk Pond 6
NPDES ID. No.: None
Inspection Period: First Quarter 2018
Inspection Date: 03/27/18

General Description or Reference to Site Plan:

Pond 6 is a non-discharging facility designed to contain plant processing water. The plant has been idle since 1996 and the pond is now used to dewater other ponds prior to clean-out.

EMBANKMENT

- 1). Adequacy of the vegetative cover: Excellent Moderate Few Poor
- 2). Erosion forming Gullies: Extensive Some Few None
- 3). Is wave action causing erosion:
 On the Upstream embankment? Yes _____ No _____
- 4). Erosion of the downstream toe of the embankment? Yes _____ No ✓
 Cause of erosion can be attributed to: _____
- 5). Is seepage occurring through the dam? Yes _____ No ✓
 Could this seepage cause potential instability? _____

SEDIMENT STORAGE CAPACITY

- 1). Has the design storage capacity of the reservoir been surpassed?
 Yes _____ No ✓
 Explain: No design standard; operator controls water

OTHER OBSERVATIONS: level by pump in to Pond 4 as needed.

Ronald L. Thompson
MSHA Trained Impoundment Inspector
3/27/2018

QUARTERLY SEDIMENTATION POND INSPECTION REPORT

CDMR Rule 4.05.9(17)

Mine: New Elk WP Containment #1
NPDES ID. No.: None
Inspection Period: First Quarter 2018
Inspection Date: 03/27/18

General Description or Reference to Site Plan:

This containment basin is a non-discharging facility designed to contain run-off from the West Portal Warehouse area.

EMBANKMENT

- 1). Adequacy of the vegetative cover: Excellent Moderate Few Poor
- 2). Erosion forming Gullies: Extensive Some Few None
- 3). Is wave action causing erosion:
On the Upstream embankment? Yes _____ No ✓
- 4). Erosion of the downstream toe of the embankment? Yes _____ No ✓
Cause of erosion can be attributed to: _____
- 5). Is seepage occurring through the dam? Yes _____ No ✓
Could this seepage cause potential instability? _____

SEDIMENT STORAGE CAPACITY

- 1). Has the design storage capacity of the reservoir been surpassed? Yes _____ No ✓
Explain: Visual observation

OTHER OBSERVATIONS: Minor amount of water as ice and a light snow cover.

Ronald M. Thompson
MSHA Trained Impoundment Inspector

3/27/18

QUARTERLY SEDIMENTATION POND INSPECTION REPORT

CDMR Rule 4.05.9(17)

Mine: New Elk WP Containment #2
NPDES ID. No.: None
Inspection Period: First Quarter 2018
Inspection Date: 03/27/18

General Description or Reference to Site Plan:

This containment basin is a non-discharging facility designed to contain run-off from the West Portal airshaft and manway areas.

EMBANKMENT

- 1). Adequacy of the vegetative cover: Excellent Moderate Few Poor
- 2). Erosion forming Gullies: Extensive Some Few None
- 3). Is wave action causing erosion:
On the Upstream embankment? Yes _____ No ✓
- 4). Erosion of the downstream toe of the embankment? Yes _____ No ✓
Cause of erosion can be attributed to: _____
- 5). Is seepage occurring through the dam? Yes _____ No ✓
Could this seepage cause potential instability? _____

SEDIMENT STORAGE CAPACITY

- 1). Has the design storage capacity of the reservoir been surpassed? Yes _____ No ✓
Explain: visual observation

OTHER OBSERVATIONS:

containment basin is dry.

Ronald L. Thayer
MSHA Trained Impoundment Inspector

3/27/2018

QUARTERLY SEDIMENTATION POND INSPECTION REPORT

CDMR Rule 4.05.9(17)

Mine: New Elk RDA Containment North
NPDES ID. No.: None
Inspection Period: First Quarter 2018
Inspection Date: 02/21/17

General Description or Reference to Site Plan:

This incised containment basin is a non-discharging facility designed to contain run-off from the RDA belt conveyor area north of highway 12.

EMBANKMENT / *incised with no embankment*

- 1). Adequacy of the vegetative cover: Excellent Moderate Few Poor
- 2). Erosion forming Gullies: Extensive Some Few None
- 3). Is wave action causing erosion:
 On the Upstream embankment? Yes _____ No ✓
- 4). Erosion of the downstream toe of the embankment?
 Cause of erosion can be attributed to: _____

- 5). Is seepage occurring through the dam?
 Could this seepage cause potential instability? Yes _____ No ✓

SEDIMENT STORAGE CAPACITY

- 1). Has the design storage capacity of the reservoir been surpassed?
 Explain: _____ Yes _____ No ?

OTHER OBSERVATIONS:

significant remaining capacity.
water held in pond is frozen with light snow cover.

Ronald L. Tonger
MSHA Trained Impoundment Inspector

3/27/2018

QUARTERLY SEDIMENTATION POND INSPECTION REPORT

CDMR Rule 4.05.9(17)

Mine: New Elk RDA Containment SE
NPDES ID. No.: None
Inspection Period: First Quarter 2018
Inspection Date: 03/27/18

General Description or Reference to Site Plan:

This partially incised containment basin is a non-discharging facility designed to contain run-off from the area east of the RDA belt conveyor and south of highway 12.

EMBANKMENT

- 1). Adequacy of the vegetative cover: Excellent Moderate Few Poor
- 2). Erosion forming Gullies: Extensive Some Few None
- 3). Is wave action causing erosion:
 On the Upstream embankment? Yes _____ No ✓
- 4). Erosion of the downstream toe of the embankment?
 Cause of erosion can be attributed to: _____

- 5). Is seepage occurring through the dam?
 Could this seepage cause potential instability? Yes _____ No ✓

SEDIMENT STORAGE CAPACITY

- 1). Has the design storage capacity of the reservoir been surpassed?
 Explain: Visual Observation Yes _____ No ✓

OTHER OBSERVATIONS:

Containment dry with no maintenance required
at this time

Ronald G. Tonger
MSHA Trained Impoundment Inspector

3/27/2018

QUARTERLY SEDIMENTATION POND INSPECTION REPORT

CDMR Rule 4.05.9(17)

Mine: New Elk RDA Containment SW
NPDES ID. No.: None
Inspection Period: First Quarter 2018
Inspection Date: 03/27/18

General Description or Reference to Site Plan:

This partially incised containment basin is a non-discharging facility designed to contain run-off from the area west of the RDA belt conveyor and south of highway 12.

EMBANKMENT

- 1). Adequacy of the vegetative cover: Excellent Moderate Few Poor
- 2). Erosion forming Gullies: Extensive Some Few None
- 3). Is wave action causing erosion:
 On the Upstream embankment? Yes _____ No ✓
- 4). Erosion of the downstream toe of the embankment?
 Cause of erosion can be attributed to: _____

- 5). Is seepage occurring through the dam?
 Could this seepage cause potential instability? Yes _____ No ✓

SEDIMENT STORAGE CAPACITY

- 1). Has the design storage capacity of the reservoir been surpassed?
 Explain: Visual Observation Yes _____ No ✓

OTHER OBSERVATIONS:

Containment is dry; No Maintenance
needed at this time

Ronald G. Thayer
MSHA Trained Impoundment Inspector

3/27/2018