

QUARTERLY POND INSPECTION REPORT

Operator:	Bowie Resources LLC	Quarter:	Second 2018
Mine:	Bowie No. 2 Mine - C-1996-083	Inspection Date:	13-Jun-18

Pond Identification	B	C	D - Gob Pile	F - New Gob	J UTL East	K UTL West
Type of Pond	Sediment	Sediment	Sediment	Sediment	Sediment	Sediment

Status During Inspection:

Approximate Water Level	Dry	Puddle	Dry	Dry	Dry	Dry
Sediment (% remaining)	95%	95%	90%	80%	95%	80%
Outflow (cfs)	0	0	0	0	0	0

Features	Problem	Problem	Problem	Problem	Problem	Problem
	Yes/No	Yes/No	Yes/No	Yes/No	Yes/No	Yes/No

Erosional

Rills & Gulleys	No	No	No	No	No	No
Inadequate Vegetation	No	No	No	No	No	No
Outlet Channel Erosion	No	No	No	No	No	No
Burrows	No	No	No	No	No	No
Other	No	No	No	No	No	No

Structural

Differential Settling	No	No	No	No	No	No
Cracks or Slides	No	No	No	No	No	No
Seepage	No	No	No	No	No	No
Other	No	No	No	No	No	No

Appurtenant Structures

Defective Spillways	No	No	No	No	No	No
Dewatering Devices Clogged	No	No	No	No	No	No
Faulty Gates, Etc.	No	No	No	No	No	No
Other	No	No	No	No	No	No

Additional Comments

Design depth measured from pond bottom to invert of emergency spillway:
 Pond B=10, C=10, D=10, J=10, K=3, F=10' TD
 Pond Bottom Elevations B=5942, C=5990, D=5970, J=5846, F=5944, K=5819
 Pond B was dry.
 Pond C held very little water and was below the primary spillway.
 Pond D was dry.
 Pond J was dry.
 Pond K was dry.
 Pond F was dry.
 There were no mud pits open at the end of the quarter.

SWMP components evaluated as part of this inspection. No corrections necessary at this time.

Name of Inspector: Tamme Bishop



Tamme Bishop
 Colorado P.E. 43402 Date