

Minerals Exploration/Sampling/Testing Inspection

U.S. Department of the Interior Bureau of Land Management Royal Gorge Field Office



The BLM has conducted an inspection of your operations, which concludes whether the documented operations on file with BLM are compliant or non-compliant. Any non-compliance issues are reported in the Additional Actions Necessary section of this inspection.

Operation Type: □ 3600 □ 3809 w/ occupa	ancy	⊠ 3809 w/o oo	ccupancy	
Date: 09/14/18 Time: 10:18 am Weather: Sunny	Operation Name: Dawson Mountain Operator: Zephyr Case Number: COC077472 CDRMS #: P2013002			
Operator(s): Mark Gravec, Will Felderhof & Loren Operation(General (s) are in compliance with documentation on file □ Yes □ No □ N/A (s) and disturbance on-site coincide with the sand access on file		
Other(s): Angela Belentoni		⊠ Yes	□ No	□ N/A
Inspection Purpose: ☐ Pre-Operations ☒ C	General	☐ Final	☐ Trespass	☐ Complaint
Inspection Items		Compliant	Non- Compliant	N/A
1. Method of Operations	_		•	
Drilling, Trenching/Surface Excavation & Underground Exc	cavation			
a. Drilling				
Pad ConstructionMud Pits				
 Borehole Abandonment/Monitoring Well Co 				
☐ Complete ☐ Incomplete				
Pad Reclamation	П	П		
b. Trenching/Surface ExcavationTrench/Excavation Construction				
Trench/Excavation Constitution Trench/Excavation Stability				
Trench/Excavation Stability Trench/Excavation Reclamation				
c. Underground Excavation				
Portal Construction				
Blasting Operations				
Portal Reclamation/Conversion of Entry				
2. Site Conditions				
a. Material/Waste Rock Management		\boxtimes		
b. Erosion & Stormwater Control		\boxtimes		
c. Man-made Structures		\boxtimes		
d. Weed Management		\boxtimes		
e. Safety Conditions		\boxtimes		
f Interim Reclamation		M		

Inspection Items	Compliant	Non- Compliant	N/A			
3. Housekeeping						
a. Container Management						
b. Spills/Leaks Observed						
c. Hazardous Substances/POL Management						
d. General Housekeeping						
4. Access						
a. Road Management						
b. Berms						
c. Security						
d. Signage						
e. Surface Water Controls			⊠			
5. Quality Assurance/Quality Control						
a. Routine Site Conditions Monitoring						
b. Air, Water, Noise, Other Monitoring			⊠			
c. Monitoring Reporting			\boxtimes			
d. Regulatory Submittals			\boxtimes			
e. Other Agency/Entity Permits	\boxtimes					
6. Final Reclamation			\boxtimes			
a. Exploration/Sampling Location						
b. Access Roads/Trails						
c. Grading						
d. Revegetation						
e. Removal of Structures						
f. Free of Trash						

Additional	Actions	Necessary
Auuluviiai	ACHUIIS	11CCCSSal V

Non-Compliance Issues to be addressed by Operator

None

Final Notes

General Comments:

- No drilling on BLM lands as of Notice Mod 3. Exploration on BLM lands is via trenching followed by collecting samples along the excavated western face of the trench (trench 1-3; ref. images below).
- Sluffing along trench 1 (middle trench) where loose material has collected along on the western face and trench center.
- Operator plans to complete interim reclamation of trench 1 & 2 within the next month. Depending upon the fire assay and petrographic results, trench 3 (highest elevated trench) may remain open as an access road for future exploration and hauling.
- 4 additional holes remain to be drilled. The operator plans to drill the remaining holes within the next couple of weeks.
 - o 2 holes are located NE of BLM lands & the other 2 holes along the access road/switch back to the BLM lands and trench excavation (ref. images below).
- The 2016 Mod 3 road design was constructed differently on both the private and BLM lands due to the steep topography and geology. Multiple switch backs were excluded from the original road

design (ref images). The road realignment included 1 switchback to the north and 2 additional switch backs to the south and southwest (ref. images 8-10).

- Future Exploration: May expand exploration to unpatented claims SE of the current operations.
- Information Needed from Operator:
 - Am't of ore-bearing material removed from federal minerals since 2013 Notice was filed with BLM
 - o Total surface disturbance of public lands since 2013 Notice was filed with BLM
 - o Sample size taken from core drilling and trenching?

Date inspection shared with CDRMS:

Date inspection shared with Operator:

Images

Image 1:





Comment: SW access road (Mod 3; 11/21/16) leading to the surface excavation on BLM lands

Image 2:





Comment: Fork in the access road leading to the 3 excavated trenches on BLM lands

Images

Image 3:



Comment: Trench 2 (lower trench)

Image 4:





Comment: Trench 1 (middle trench) with sluffing along western face

Image 5:



Comment: Trench 3 (highest trench)

Image 6:



Comment: Drill hole (WP-18-18) located along the access road (Mod 3). 2 drill holes remain to be drilled at this site.

Image 7:



Comment: Trench 3 located along access road




Image 8: Map of Zephyr operational boundary (pink), Mods 1-3 (light blue, orange & blue), road trace from 09/14/18 inspection (purple), road trace of 11/2017 flight (red) and BLM lands (yellow). Road realignment was traced from the 11/2017 flight.




Image 9: Map of Zephyr Notice modifications (1-3) and the 11/2017 flight data of Mod-3 road realignment.




Image 10: Close-up of the Zephyr operations and the 09/14/18 inspection. The trench excavation has been traced from the east-west ends on BLM land. WP-18-18 is 1 of the 2 drill areas that still remains to be drilled under Mod-3.