




**MINERALS PROGRAM INSPECTION REPORT**  
**PHONE: (303) 866-3567**

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

<b>MINE NAME:</b> Burros Mine	<b>MINE/PROSPECTING ID#:</b> M-1977-297	<b>MINERAL:</b> Uranium and vanadium	<b>COUNTY:</b> San Miguel
<b>INSPECTION TYPE:</b> Multi Person Inspection	<b>INSPECTOR(S):</b> Lucas J. West	<b>INSP. DATE:</b> October 16, 2018	<b>INSP. TIME:</b> 11:05
<b>OPERATOR:</b> Gold Eagle Mining, Inc.	<b>OPERATOR REPRESENTATIVE:</b> Kyle Turley, Mary Young	<b>TYPE OF OPERATION:</b> 110d - Designated Limited Impact	
<b>REASON FOR INSPECTION:</b> Normal I&E Program	<b>BOND CALCULATION TYPE:</b> None	<b>BOND AMOUNT:</b> \$100.00	
<b>DATE OF COMPLAINT:</b> NA	<b>POST INSP. CONTACTS:</b> None	<b>JOINT INSP. AGENCY:</b> None	
<b>WEATHER:</b> Clear	<b>INSPECTOR'S SIGNATURE:</b> 	<b>SIGNATURE DATE:</b> November 7, 2018	

**GENERAL INSPECTION TOPICS**

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS----- <u>Y</u>	(FN) FINANCIAL WARRANTY----- <u>N</u>	(RD) ROADS----- <u>N</u>
(HB) HYDROLOGIC BALANCE----- <u>Y</u>	(BG) BACKFILL & GRADING----- <u>N</u>	(EX) EXPLOSIVES----- <u>N</u>
(PW) PROCESSING WASTE/TAILING---- <u>N</u>	(SF) PROCESSING FACILITIES----- <u>N</u>	(TS) TOPSOIL----- <u>N</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>Y</u>	(FW) FISH & WILDLIFE----- <u>N</u>	(RV) REVEGETATION---- <u>N</u>
(SM) SIGNS AND MARKERS----- <u>Y</u>	(SP) STORM WATER MGT PLAN---- <u>N</u>	(RS) RECL PLAN/COMP-- <u>N</u>
(ES) OVERBURDEN/DEV. WASTE----- <u>N</u>	(SC) EROSION/SEDIMENTATION--- <u>N</u>	(ST) STIPULATIONS----- <u>N</u>
(AT) ACID OR TOXIC MATERIALS----- <u>N</u>	(OD) OFF-SITE DAMAGE----- <u>Y</u>	

Y = Inspected and found in compliance / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

## **OBSERVATIONS**

This inspection was conducted as part of the normal monitoring program for all 110 Designated Mining Operations established by the Colorado Division of Reclamation Mining and Safety. The Burros Mine is listed as an active 110d operation that consists of 9.9 permitted acres. The site is located One Mile North of Slick Rock, CO at nearly 5480 Feet in Elevation. The site was not active during the inspection as it lies on a Department of Energy (DOE) Lease Tract. Kyle Turley and Mary Young of Navarro, the contractor for the DOE were present during the inspection. The DOE Lease Tract Projects are currently under a court ordered stay preventing any activities other than site maintenance and emergency repairs. The financial warranty for the site is held by the DOE. Three Photos accompany this report to illustrate the current site conditions.

The proper mine identification signage was posted at the entrance to the site and can be seen in Photo One. The sign is posted on a historical loadout that is within the permitted area. The loadout appears to be stable and in a similar condition to the previous inspection conducted by the Division. The only work that is approved to take place on the site is ongoing weed management and the maintenance of the storm water controls on site. The storm water controls that were observed appear to be stable and functioning as designed. They will however require maintenance soon as there have been recent precipitation events in the area that have impacted the features. Photo Two shows part of the storm water control ditch near the historic loadout. The remaining storm water control features up gradient were in similar condition and require maintenance. The upper sediment pond may require the installation of a rock check dam where flow leaves the sediment pond and enters the storm water control ditch.

The portal has been secured with a safety closure to prevent entry. The closure is a locked steel grate closure that is in good condition and shows no signs of attempted unauthorized entry. Various pipes, lines and historic debris surround the portal and all appear to be stable and in a similar condition from the Division's previous inspection. The closure and the surrounding area can be seen in Photos Three.

The overall footprint of the site is in good condition and is free from excessive trash and debris. All pads and work areas appear to be stable and in good condition. No noxious weeds were observed on site. No problems or possible violations were observed at this time. All responses to this report should be directed to Lucas West at the Division of Reclamation, Mining and Safety at 1313 Sherman Street, Room 215, Denver, CO 80203 or by phone at (970)-243-6368.

### **Inspection Contact Address**

Sen. Don Coram  
Gold Eagle Mining, Inc.  
P.O. Box 3007  
Montrose, CO 81402

EC: Kyle Turley, Navarro

## PHOTOGRAPHS





