

**Annual Report – 2018
Henderson Mine and Mill Reclamation Activities
Permit No. M-1977-342**

1.0 Henderson Mine

1.1 Disturbance

New disturbance at the Mine in 2018 was limited to incremental caving of the glory hole. No changes were made to any of the mine openings (shafts). A site map of the Henderson Mine indicating affected land boundary and disturbance areas is included in Attachment A.

1.2 Interim Reclamation

Interim reclamation was not carried out at the Henderson Mine in 2018.

1.3 Prospecting

1.3.1 Prospecting Contact

The contact person for the Notice of Intent (NOI) and prospecting activities is:

Miguel Hamarat
Environmental Manager
Climax Molybdenum Company
Henderson Operations

P.O. Box 68
1746 County Rd. 202
Empire, CO 80438
(720) 942-3255

1.3.2 Prospecting Activities

Henderson Mine did not conduct prospecting activities in 2018. However, on August 28, 2018, Henderson Mine was released from obligations related to NOI No. P-1978-011.

1.4 Other Activities

1.4.1 – Weed Control

Habitat Management, Inc., a licensed commercial pesticide applicator, performed weed management activities in June and August 2018.

Canada thistle, common mullein, dalmatian toadflax, mayweed chamomile, musk thistle, oxeye daisy, and yellow toadflax were treated throughout the main mine facilities area, the URAD area, Orica Yard and along County Road 202 between URAD and the Henderson Mine. Herbicide applications were spot-applied to targeted weed species.

The herbicides used for treatment include: Telar XP (Chlorosulfuran), Weedestroy AM40 (2,4-D Amine), Weedar 64 (2,4-D Amine), Milestone (Aminopyralid), Ranger Pro (Glyphosphate), and Viewpoint (Imazapic). Induce was utilized as a surfactant and Hi-Light blue marker dye was added to applications to allow greater visibility of treated areas.

Annual Report – 2018
Henderson Mine and Mill Reclamation Activities
Permit No. M-1977-342

Ranger Pro and Viewpoint were applied to the perimeter of the gas stations, natural gas meter building, compressor building, used oil pump building, bulk oil storage building, and the mine's air vents. The smaller electrical substation was also treated whereas other substations were inspected and found to be in good order.

Similar to past years, the mine property was thoroughly inspected for listed noxious weeds species. Through precision tracking via GPS application monitoring, the weed management contractor applied herbicide to approximately 261 acres (combined Mine and URAD).

1.4.2 – Water Quality Data

Water quality data will be provided in the Annual Water Quality Data Report, due to the DRMS by May 31 annually, per the approved Groundwater Management Plan (TR-16).

2.0 Henderson Mill

2.1 Disturbance

The Mill disturbances for 2018 included only the area inundated by the continuous tailing impoundment rise. A site map of the Henderson Mill indicating affected land boundary and disturbance areas is included in Attachment A.

2.2 Interim Reclamation

Interim reclamation was not carried out at the Henderson Mill in 2018.

2.3 Other Activities

2.3.1 – Weed Control

For 2018, Henderson Mill received weed treatments in July and August, when approximately 510 acres were treated. The two treatments covered the following areas: around all shops and mill parking lots, roadsides around the tailing pond, the northern non-industrial areas, the haul roads, the upper canal road, on and below the dam, and the portal.

These areas were treated for the following noxious weeds: Bull thistle, Canada thistle, Common mullein, Dalmatian toadflax, Houndstongue, Mayweed chamomile, Musk thistle, Plumeless thistle, Oxeye daisy and Yellow toadflax

The herbicides used for treatment include: Escort XP (Metsulfuron), Milestone VM (Aminopyralid), Rodeo (Glyphosate), Telar XP (Chlorsulfuron), Transline (Clopyralid), Vastlan (Triclopyr), Weeddestroy (2,4-D Amine), Induce (a nonionic adjuvant) and Blue Hi-Lite indicator dye.

2.3.2 – Water Quality Data

Water quality data will be provided in the Annual Water Quality Report, due to the DRMS by May 31 annually, per the approved Groundwater Management Plan (TR-16).

Annual Report – 2018
Henderson Mine and Mill Reclamation Activities
Permit No. M-1977-342

2.3.3 – Flood Storage Capacity

Analysis of flood storage capacity in the Mill tailings impoundment was carried out by W.W. Wheeler, per DRMS requirements stipulated for Technical Revision (TR) 14. This analysis is included as Attachment B.

2.3.4 – 3-Dam Seepwater Line Leak-Down Test

The annual 3-Dam seepwater line leak-down test for 2018, per DRMS requirements stipulated in TR-09, was completed on June 21, 2018. The seepwater lines held static pressures over a 24-hour period, as designed. See test report in Attachment C.

2.3.5 – Extraction Well Installation

No new extraction wells were installed in 2018. All currently installed extraction wells are operational.

2.3.6 – Gravel Pit Operations

There were no crushing or screening activities at the Henderson Mill during calendar year 2018.

2.3.7- 3-Dam Buttress Project

Work started on the 3-Dam Buttress Project submitted as TR-29 in the summer of 2018 consisting of infrastructure improvements, placement of filter material, and placement of buttress material. Infrastructure improvements included channel relocation, drain extensions, and installation of 3 piezometers. Finally, just over 20,000 cubic yards of filter material was placed before being overlain by nearly 40,000 cubic yards of buttress material.

2.3.8 – Seep Water Collection and Return System Improvements

Work began in the summer of 2018 and included upgrading inlet gate operator electronics and communications, culvert extensions, and installation of a seepage cutoff trench as described in TR-30 submitted in September 2018.

Annual Report – 2018
Henderson Mine and Mill Reclamation Activities
Permit No. M-1977-342

3.0 Anticipated 2019 Activities

3.1 Prospecting

No prospecting activities are currently planned for 2019.

3.2 3-Dam Buttress

Phase 1B of the 3-Dam Buttress project will commence once snowmelt has completed. Any erosion on the buttress sections will be repaired before beginning to place the remaining 2,000 cubic yards of sand filter material. Next, 71,300 cubic yards of sand buttress material will be harvested from 1-Dam and compacted on the step back portion of 3-Dam. This will be followed by the installation of two new piezometers and inclinometers. Phase 1 of the 3-Dam Buttress project will be completed in 2019 and engineering will begin for Phase 2.

3.3 Seep Water Collection and Return System Improvements

Improvements to the Seep Water Collection and Return System will continue in 2019. This summer will see the actual raising of the road embankment. While all related infrastructure work was completed in 2018, the road was not raised due to inclement fall weather. The raising of the road will complete this project.

3.4 Gravel Pit

Henderson is currently evaluating whether any continued operations will persist. For 2019, nothing is planned, at present. Areas near the entrance of the gravel pit will continue to be used to stockpile materials delivered for the 3-Dam Buttress Project.

3.5 Aspen Canyon Well

Henderson Mill completed a rehabilitation of the Aspen Canyon Well during late October-early November 2017. Henderson was limited in its evaluation of the data associated with this well to determine the overall impact and effectiveness of the rehabilitation work due to a change in ownership of the Aspen Canyon Ranch property restricting access. However, as of February 12, 2019 an access agreement with the new owners has been reached allowing future sampling to proceed as scheduled.

3.6 Closure Planning

Henderson continues with closure-based planning and investigation work.

3.7 Reclamation

No reclamation is planned for calendar year 2019.

3.8 Amendment

Henderson intends to submit an Amendment to the permit for inclusion of land occupied by URAD water treatment operations, as well as the area associated with Henderson's mining subsidence.

Annual Report – 2018
Henderson Mine and Mill Reclamation Activities
Permit No. M-1977-342

4.0 Financial Warranty

Henderson Operations currently maintains Financial Warranty Corporate Surety in the amount of \$56,142,434. These are held in the form of two surety bonds valued at \$24,730,784 and \$10,133,000. Additionally, an Irrevocable Letter of Credit in the amount of \$3,130,001 and assets valued at \$18,148,649. Henderson continues working to update the valuation for Henderson and Climax water rights, having contracted a third-party to conduct the valuation.

Attachment A

Figures



MAP FEATURES	
	DISTURBED AREA
	TOPSOIL STOCKPILES
	RECLAMATION AREAS
	LAKE / POND
	BUILDING
	ROAD
	PROPERTY BOUNDARY
	AFFECTED LAND BOUNDARY
	STREAM / DITCH
	DENVER WATER DEPT.
Contour Interval: 50 feet	


REVISION	DATE
Developed in ArcGIS for 2010 Annual Report	3/4/11
Revised for 2011 Annual Report	2/22/12
Revised for 2012 Annual Report	2/27/13
Revised for 2013 Annual Report	2/26/14
Revised for 2014 Annual Report	2/24/2015
Revised for 2015 Annual Report	3/4/2016
Revised for 2016 Annual Report	3/3/2017
Updated dates and imagery	3/4/2019

Climax Molybdenum
A Freeport-McMoRan Company
HENDERSON OPERATIONS
1746 County Road
Empire, Colorado 80438

HENDERSON MINE
MLRB Permit No. M-77-342
Annual Reclamation Report
March 4, 2019

DESIGNED BY:
DRAWN BY: MT (Aquilonix)
DATE DRAWN: 3/4/11

SCALE: 1:4,800



LOCATION MAP

MAP FEATURES

DISTURBED AREA	PROPERTY BOUNDARY
TOPSOIL STOCKPILES	STREAM / DITCH
RECLAMATION AREAS	
LAKE / POND	
BUILDING	
ROAD	


REVISION	DATE	AUTHOR
Developed in ArcGIS for 2011 Annual Report	2/17/12	MT
Revised for 2012 Annual Report	2/28/13	MT
Revised for 2013 Annual Report	2/26/14	MT
Revised for 2014 Annual Report	2/24/15	MT
Updated dates for 2015 Annual Report	2/28/16	MT
Updated dates for 2016 Annual Report	3/3/17	TH
Updated dates and imagery	3/4/19	AP

Climax Molybdenum
A Freeport-McMoRan Company

HENDERSON OPERATIONS
1746 County Road
Empire, Colorado 80438

HENDERSON MINE - URAD
MLRB Permit No. M-77-342
Annual Reclamation Report
March 4, 2019

DESIGNED BY:	SCALE: 1:7,500
DRAWN BY: MT (Aquilonix)	
DATE DRAWN: 2/17/2012	



LOCATION MAP

Sources: Esri, HERE, Garmin, USGS, Intermap, INCREMENT P, NRCan, Esri Japan, METI, Esri China (Hong Kong), Esri

MAP FEATURES

PROPERTY BOUNDARY	PLANNED TOPSOIL STOCKPILES	TRAIL
DISTURBANCE AREA	RECLAMATION AREAS	PERENNIAL STREAM
XCEL ENERGY EASEMENT	BUILDING	INTERMITTENT STREAM
TAILINGS IMPOUNDMENT	UNIMPROVED ROAD	ULTIMATE INTERCEPTOR CANAL
LAKE / POND	IMPROVED ROAD	GRAVEL PIT
EXISTING TOPSOIL STOCKPILES	CONVEYOR	AFFECTED LAND BOUNDARY

Contour Interval: 25 feet

REVISION	DATE	AUTHOR
Developed in ArcGIS for 2010 Annual Report	3/4/11	MT
Revised for 2011 Annual Report	2/22/12	MT
Updated for 2012 Annual Report. Added Ranger Gulch Topsoil Stockpile & Gravel Pit	2/28/13	MT
Revised for 2013 Annual Report	2/27/14	MT
Revised for 2014 Annual Report	2/24/2015	MT
Updated dates for 2015 Annual Report	2/29/2016	MT
Updated dates for 2016 Annual Report	3/3/2017	TH
Updated dates and imagery	3/4/2019	AP

DESIGNED BY:	SCALE: 1:20,000
DRAWN BY: MT(Aquionix)	
DATE DRAWN: 3/4/11	

Climax Molybdenum
A Freeport-McMoRan Company
HENDERSON OPERATIONS
1746 County Road
Empire, Colorado 80438

HENDERSON MILL
MLRB Permit No. M-77-342
Annual Reclamation Report
March 4, 2019

Attachment B

Mill Tailing Impoundment Flood Storage Capacity Analysis

February 8, 2019

Mr. Miguel Hamarat
Climax Molybdenum Company, Henderson Mine
1746 County Road 202
Empire, CO 80438

Re: **#1333.0 - Henderson Mill
TSF Flood Storage**

Dear Miguel:

As requested, we have evaluated the availability of flood storage capacity in the Henderson tailing storage facility (TSF) using information from the pond surveys. The fall survey of the beach and pool area was performed in October and November. Figure 1 is the pond contour map that was generated by Wheeler from the fall survey point data. The survey shows that the average dam crest elevation of 1 Dam at the end of the spigot deposition season is about 8879.5 feet, which is a 1.4-foot increase from last year. The minimum elevation surveyed along the dam crest was 8878.4 feet. This information, as well as other characteristics of the TSF, is summarized in the table in the upper right-hand corner of the TSF map drawing. Table 1 and Figure 2 is the elevation-capacity data for the impoundment that was generated from the fall 2018 contour map. Note that this data is representative of the TSF at the time of the pool survey and changes continuously as additional tailing is deposited.

One of the primary uses of the survey data is to evaluate the flood storage capacity conditions in the water system. As summarized on Figure 1, at the approximate time of the fall survey there was a total system surcharge storage capacity of about **9,779 acre-feet** in the system. This capacity includes both the TSF and East Branch Reservoir and is based on 0.5 feet of residual freeboard below the minimum dam crest elevation of 8,878.4' and a water level of 8,865.5'. The flood storage requirement for the system is **3,582 acre-feet**. This requirement is based on hydrologic modeling of the probable maximum precipitation (PMP) event. The available flood storage capacity in the system at the time of the survey

significantly exceeds the storage requirement. However, this excess capacity will decrease throughout the coming year as additional inflows to the system occur and a portion of the storage space is filled with deposited tailing.

A relatively accurate determination of the flood storage capacity in the impoundment can be made at the time of the pond surveys. An operations model has been developed to track water levels and estimate the flood storage availability in the system between surveys. This model is updated by Henderson personnel or Wheeler on a monthly basis. One of the reports generated by this model is the attached TSF Water Level Report (Figure 3). This graph shows the actual water level in the TSF as compared to the flood pool level in the pond, which is defined as the level corresponding to 3,582 acre-feet of available capacity. Note that the actual water level did not exceed the flood pool level at any time in 2018. This shows that the required flood storage space was maintained in the system throughout the 2018 calendar year.

If you have any questions regarding the enclosed information, or if you require additional information, please call.

Sincerely,

W. W. Wheeler and Associates, Inc.

A handwritten signature in black ink, appearing to read "Steven M. Maly".

Steven M. Maly, P.E.

CC: Dillon Benbow, Henderson Mill (via e-mail)
Geoff Niggeler, Henderson Mill (via e-mail)
Aaron Hilshorst, Henderson Mill (via e-mail)
Katie Kruger, Freeport McMoRan (via e-mail)


TABLE 1
Henderson TSF
Elevation-Area-Capacity

Survey Data:

Bathymetric Oct. 23, 2018
1 Dam Beach Oct. 23, 2018
3 Dam Beach Nov. 15, 2018

Elevation-Area-Capacity Table			
Water Elevation	Surface Area		Storage Capacity
(feet)	(sq. ft.)	(acres)	(ac-ft)
8,837.0	0	0.00	0.0
8,838.0	409,916	9.41	4.7
8,839.0	733,192	16.83	17.8
8,840.0	979,545	22.49	37.5
8,841.0	1,191,491	27.35	62.4
8,842.0	1,385,821	31.81	92.0
8,843.0	1,538,697	35.32	125.6
8,844.0	1,683,094	38.64	162.5
8,845.0	1,829,871	42.01	202.9
8,846.0	2,075,036	47.64	247.7
8,847.0	2,369,767	54.40	298.7
8,848.0	2,636,050	60.52	356.2
8,849.0	2,900,665	66.59	419.7
8,850.0	3,350,477	76.92	491.5
8,851.0	3,866,948	88.77	574.3
8,852.0	4,357,497	100.03	668.7
8,853.0	4,793,104	110.03	773.8
8,854.0	5,243,775	120.38	889.0
8,855.0	5,645,591	129.60	1,014.0
8,856.0	6,047,487	138.83	1,148.2
8,857.0	6,456,845	148.23	1,291.7
8,858.0	6,875,932	157.85	1,444.7
8,859.0	7,379,183	169.40	1,608.4
8,860.0	8,047,548	184.75	1,785.4
8,861.0	8,736,354	200.56	1,978.1
8,862.0	9,454,434	217.04	2,186.9
8,863.0	10,335,089	237.26	2,414.0
8,864.0	11,671,910	267.95	2,666.7
8,865.0	13,665,447	313.72	2,957.5
8,865.5	15,157,555	347.97	3,119.6
8,866.0	16,749,867	384.52	3,306.4
8,867.0	20,165,043	462.93	3,730.1
8,868.0	23,079,339	529.83	4,226.5
8,869.0	25,695,084	589.88	4,786.3
8,870.0	28,581,791	656.15	5,409.4
8,871.0	31,408,774	721.05	6,097.9
8,872.0	33,878,490	777.74	6,847.3
8,873.0	36,552,744	839.14	7,655.8
8,874.0	38,822,708	891.25	8,521.0
8,875.0	40,944,307	939.95	9,436.6
8,876.0	42,947,072	985.93	10,399.5
8,877.0	44,849,575	1,029.60	11,407.3
8,878.0	46,765,699	1,073.59	12,458.9
8,879.0	48,541,698	1,114.36	13,552.9
8,880.0	49,969,780	1,147.15	14,683.6
8,881.0	50,395,440	1,156.92	15,835.6

* All other values are interpolated from this table.



POND DATA SUMMARY	
TAILING POND WATER LEVEL	= 8,865.49 (10/23/18)
TAILING POND WATER STORAGE	= 3,120 AF
WATER POOL SURFACE AREA	= 348 ACRES
AVERAGE NO. 1 DAM CREST ELEV.	= 8,879.5' (12/18)
MIN. NO. 1 DAM CREST ELEV. (New Crest Bench)	= 8,878.4' (12/18)
CREST LINE BENCH ELEV.	= 8,870.0'
PROPOSED DEPOSITION BERM ELEV.	= NA
AVERAGE NO. 3 DAM CREST ELEV.	= 8,880.8 (12/18)
MINIMUM NO. 3 DAM CREST ELEV.	= 8,880.3' (12/18)
NO. 3 DAM CREST LINE BENCH ELEV.	= 8,872.5'
PROPOSED DEPOSITION BERM ELEV.	= NA
MIN. NO. 1 DAM BEACH ELEV. AT 500' LINE	= 8,875.5' (APPROX.)
MIN. NO. 1 DAM BEACH ELEV. AT 800' LINE	= 8,873.6' (APPROX.)
MIN. NO. 1 DAM BEACH ELEV. AT 1,400' LINE	= 8,870.5' (APPROX.)
BARGE - TOP OF PIER ELEV.	= 8,874.72'
BARGE MIN. WSEL (2' CLEARANCE)	= 8,861.8'
ELEV @ 2800 AF CAPACITY (FOR GOLDSIM)	= 8,864.46'

EAST BRANCH RESERVOIR	
EAST BRANCH RES. WATER LEVEL	= 9,028.4' (11/1/18)
EAST BRANCH RES. STORAGE	= 1,525 AF
EAST BRANCH RES. WATER SURFACE AREA	= 52 ACRES
EAST BRANCH RES. FULL CAPACITY (9,038.5)	= 2070 AF
FLOOD STORAGE CALCULATION (11/1/2017)	
TAILING POND STORAGE CAPACITY AT MIN. CREST ELEVATION - 0.5' FB (8877.9)	= 12,354 AF
TAILING POND SURCHARGE CAPACITY	= 9,234 AF (11/1/18)
EAST BRANCH RES. SURCHARGE CAPACITY (MAXIMUM OF 676 AF)	= 545 AF
TOTAL SYSTEM SURCHARGE CAPACITY	= 9,779 AF
SURCHARGE FLOOD STORAGE REQUIRED	= 3,582 AF
EXCESS CAPACITY	= 6,197 AF
TSF LEVEL AT CREST - 0.5' - 3582 AF (8,772 AF)	= 8,874.3'
TSF HIGH-HIGH WATER LEVEL	= 8,873.6'
(MIN. OF BEACH AT 800' AND LEVEL AT 3582 AF STORAGE)	
TSF HIGH WATER LEVEL (1400' LINE ELEV)	= 8,870.5'
GRI SURFACE AREAS (11/1/2018):	
BEACH AREA (CALCULATED)	= 777 ACRES
(BEACH AREA = TOTAL TSF - DAMS - POOL)	
WATER POOL AREA	= 348 ACRES
3 DAM DOWNSTREAM FACE	= 33 ACRES
1 DAM DOWNSTREAM FACE	= 156 ACRES
TOTAL TSF AREA (BEACH, DAMS, POOL)	= 1,314 ACRES

NOTES:
BACKGROUND MAPPING FROM 2015 AERIAL MAPPING.
1 DAM BEACH CONTOURS FROM CLIMAX LIDAR SCAN.
3 DAM BEACH CONTOURS FROM HENDERSON POINT SURVEY.
BATHYMETRIC POINTS FROM HENDERSON BOAT SONAR.

REVISIONS

NO.	DATE	MADE BY	CHKD. BY	REMARKS
1				
2				
3				
4				
5				

"This drawing together with any and all additions, corrections, changes and alterations thereof is the property of Climax Molybdenum Company and is furnished on the express condition that it shall not be reproduced, copied, lent, or disposed of directly or indirectly, nor used for any other purpose than for which it is specifically furnished without the prior written consent of said Climax Molybdenum Company."

REFERENCE DWGS

DRAWING NO.	REFERENCE

Climax Molybdenum
A Freeport-McMoRan Company

W. W. WHEELER & ASSOCIATES, INC.
Water Resources Engineers

3700 S. INCA STREET
ENGLEWOOD, CO 80110-3405
303-761-4130
FAX 303-761-2802

HENDERSON MILL TAILINGS STORAGE FACILITY

BEACH AND POND SURVEY

FALL 2018 SURVEY


DATES: BATH 10/23, BEACH: 10/23 (1 DAM) 11/15 (3 DAM)

Climax Molybdenum Henderson Mill
Parshall, CO


SAA	11/18	SCALE
CHECKED BY SMM	11/18	AS NOTED
ACCEPTED BY ...		DRAWING NO.

FIGURE 1

**Figure 2 - Henderson TSF
Elevation Area Capacity**



**Figure 3 Henderson TSF
Water Pool Level Tracking**



Attachment C

3-Dam Seepwater Line Leak Down Test Results

**FREEPORT-McMORAN****ORDER**

400008646568

Henderson

Sort Field:	111501DA03	Equipment:	100000008159	Equipment Description:	TAILINGS DAM #3
Cost Center:	2402001111	Functional Location:	HE-2-MI-C8-TC-1866	Functional Location Description:	TAILINGS DAMS
Main Work Center:	4600P	Serial No.:		PM Activity Type:	PCM
Order Type:	MN03				
Start Date:	06/04/2018	End Date:	06/06/2018	Priority:	3
Originator:	IP1020180513				
Description: PM LEAK DOWN TEST - #3 DAM SEEP H2O 364D					
Person Responsible:		Person Responsible Description:			

Failure Information	Check	Comments
Maintenance Rework		<i>The main line is still slow to drain</i> COMPLETED
Incident or Accident		
Exceeding Design Parameters		
Poor Operational Practice		
Normal Wear and tear		

FOLLOW ALL SAFETY INSTRUCTIONS RELATED TO EACH OPERATION

Operation Description							
Operation	Sub-Op	Work Center	Operation Description	Act. No. People	Act. Hrs.	Act. Dur.	Comp Date
10		4600P	PM LEAK DOWN TEST - #3 DAM SEEP H2O 364	1	24		6-20-18
Long Text PM LEAK DOWN TEST - #3 DAM SEEP H2O 364 SUPERCEDES: 12/18/2015 SUPERVISER APPROVAL: Scott Marquardt LAST REVEIW DATE: 10/18/2016 MAINT PLAN: 7000000912 ===== PROVIDE COPIES TO TIM HAYNES AND CURTIS BROWN UPON COMPLETEION. ===== 1. <input checked="" type="checkbox"/> Shut the intake valves and make sure that they do not leak by - checking discharge valves for water flow. 2. <input checked="" type="checkbox"/> Shut off lower ball valves east side of road I70 gate. 3. <input checked="" type="checkbox"/> Close discharge valves for drain line and overflow line. 4. <input checked="" type="checkbox"/> Shut power off to pumps in lift station. 5. <input checked="" type="checkbox"/> Close both valves at dosing vault.							

**FREEPORT-McMORAN****ORDER**

400008646568

Henderson

6. ☒ Fill drain line and overflow line and check discharge valves for leaks.

7. ☒ Lock all valves and read pressure gauge at the discharge valves.

Drain Line Pressure 75 PSI Date/Time 9:30-6-20-18

Overflow Line Pressure 11 Date/Time 11

8. Wait over 24 hours and read Pressure gauges:

Drain Line Pressure 75 Date/Time 9:40-6-21-18

Overflow Line Pressure 75 Date/Time 9:40-6-21-18

9. ☒ If there isn't a drop in pressure in the 24 hour period you can remove the locks. Open the intake valves first, then the discharge valves and return the system back to the pond operators.

10. ☐ If there is a drop in pressure note the pressure drop and repair the system, possible leaking pipes or valves.

11. ☒ All machine guards are in good condition, have no open holes and are properly installed.

12. ☒ Pickup area after PM is done. Ensure housekeeping is in good order.

13. ☐ Write WO for any problems found

Completion Comments

Completed by : Print Name

Signature

Date Completed

271076-21-18

Supervisor Reviewer : Print Name

Signature

Date Completed

[Signature]7-24-18**MATERIALS**

Operation	Component	Description:	Qty	UOM	IC	SS	Location

RETURN MATERIALS

Quantity	Stock or Part	Description:	Name