

1313 Sherman Street, Room 215, Denver, CO 80203 P 303.866.3567 F 303.832.8106 http://mining.state.co.us

## **PERMIT INFORMATION**

Permit Number: C-1996-084 Mine Name: Lorencito Canyon Mine Operator: New Elk Coal Company, LLC Operator Address: Mr. Louis Head 12250 Highway 12 Weston, CO 81091	County: Las Animas Operation Type: Surface Permit Status: Permanent Cessation Ownership: Private  Operator Representative Present:
Weston, CO 81091	Nick Mason, Vince Massarotti
Operator Representative Signature: (Field Issuance Only)	
INSPECTION INFORMATION	
Inspection Start Date: May 29, 2019 Inspection Start Time: 07:00 Inspection End Date: May 29, 2019	Inspection Type: Coal Partial Inspection Inspection Reason: Normal I&E Program Weather: Cloudy

Inspection End Date: May 29, 2019
Inspection End Time: 09:00

Joint Inspection Agency:

None

Post Inspection Agency:

None

Inspector(s):

Robert D. Zuber, P.E.

Weather: Cloudy

Weather: Cloudy

Weather: Cloudy

Signature: Cloudy

Weather: Cloudy

Weather: Cloudy

Weather: Cloudy

Inspection Contacts:

Signature: Signature Date:

5/30/2019

## **Inspection Topic Summary**

NOTE: Y=Inspected N=Not Inspected R=Comments Noted V=Violation Issued NA=Not Applicable

NA - Air Resource Protection Y - Roads

 ${f N}$  - Availability of Records  ${f R}$  - Reclamation Success

NA - Backfill & Grading

R - Excess Spoil and Dev. Waste

Y - Revegetation

NA - Subsidence

NA - Explosives Y - Slides and Other Damage Y - Fish & Wildlife NA - Support Facilities On-site

R - Hydrologic Balance N - Signs and Markers

Y - Gen. Compliance With Mine Plan

R - Support Facilities Not On-site

N - Other

N - Special Categories Of Mining

NA - Processing Waste N - Topsoil

## **COMMENTS**

A partial inspection was conducted by Rob Zuber of DRMS on May 29, 2019. The weather was cloudy and cool. The ground was dry.

Vince Massarotti and Nick Mason of NECC were present for the inspection.

#### EXCESS SPOIL and DEVELOPMENT WASTE - Rule 4.09

Placement; Drainage Control; Surface Stabilization:

Fills 7, 8, and 9 were inspected. No large rills or gullies were seen. The vegetation on all three fills looks very good.

#### HYDROLOGIC BALANCE - Rule 4.05

Drainage Control 4.05.1, 4.05.2, 4.05.3; Siltation Structures 4.05.5, 4.05.6; Discharge Structures 4.05.7, 4.05.10; Diversions 4.05.4; Effluent Limits 4.05.2; Ground Water Monitoring 4.05.13; Surface Water Monitoring 4.05.13; Drainage – Acid and Toxic Materials 4.05.8; Impoundments 4.05.6, 4.05.9; Stream Buffer Zones 4.05.18:

All ponds were inspected: 5, 6, 7, 8, 9, and 9a. Pond 6 contained significant water. The others were nearly dry or dry. None of them were discharging. No problems were identified with embankments, spillways, or other features of the ponds.

No problems were found with ditches. Ditch D84 appears to remain stable. Ditch D3 was examined closely, and the channel contained significant vegetation and no erosion.

#### RECLAMATION SUCCESS - Rule 4.15, Rule 3:

No erosion or other problems were seen with BA-3 (it was viewed from across the creek).

The large hill known as "the knob" looked to be generally stable, with no gullies.

Further treatment of rills is recommended on the hillside above Pond 6. The hillside above the pond cleaning dump area is healing well, however the dump area itself has a significant amount of area that is devoid of vegetation.

### OFFSITE SUPPORT FACILIITES - Rule 4.04, 4.28:

New Elk Coal Company manages the Lorencito Canyon Mine as well as the New Elk Mine, and support facilities for both mines are at the New Elk Mine site. No issues were found at the New Elk facilities during a May 28 inspection, as documented in the inspection report for New Elk.

## ENFORCEMENT ACTIONS/COMPLIANCE

No enforcement actions were initiated as a result of this inspection, nor are any pending.

# **PHOTOGRAPHS**



Area where pond cleanings are dumped



Fill 8



Ditch D84 below Fill 8



Pond 6 and watershed above it



Ditch D3, looking downhill



Fill 9