

### **Minerals Plan of Operations Inspection U.S. Department of the Interior Bureau of Land Management Royal Gorge Field Office**



The BLM has conducted an inspection of your operations, which concludes whether the documented operations on file with BLM are compliant or noncompliant. Any non-compliance issues are reported in the Additional Actions Necessary section of this inspection.

**Operation Type:** □ 3809 w/ occupancy

□ 3809 w/	o occupancy
-----------	-------------

<b>Date:</b> Oct 17, 2018	Operation Name: Zimmerman - El Rancho Bondo			
<b>Time:</b> 11:57	Operator: Tom Zimmerman			
Weather: Cloudy	Case Number: COC75265			
	CDRMS Number: M-2018-028			
Attendees	General			
BLM: A. Sanderson	<b>Operation</b> (s) are in compliance with documentation on file			
	$\boxtimes$ Yes $\Box$ No $\Box$ N/A			
<b>Operator(s):</b> Contacted, but not present				
	<b>Operation(s) and disturbance on-site coincide with the</b>			
Other(s): None	operations and access on file			
	$\square$ Yes $\square$ No $\square$ N/A			

**Inspection Purpose**:  $\Box$  Pre-Operations  $\boxtimes$  General  $\Box$  Final  $\Box$  Compliance  $\Box$  Trespass  $\Box$  Complaint

Inspection Items	Compliant	Non- Compliant	N/A	
1. Method of Operations Drill Transh (Surface Execution (Highwall, Underground Execution				
Drill, Trench/Surface Excavation/Highwall, Underground Excavation				
a. Drilling				
Pad Construction				
• Mud Pits				
Borehole Abandonment/Monitoring Well Conversion				
$\Box$ Complete $\Box$ Incomplete				
Pad Reclamation				
b. Trenching/Surface Excavation/Highwall	$\boxtimes$			
Trench/Excavation/Highwall Construction	$\boxtimes$			
• Trench/Excavation/Highwall Stability	$\boxtimes$			
Trench/Excavation/Highwall Reclamation	$\boxtimes$			
c. Underground Excavation			$\boxtimes$	
Portal Construction				
Blasting Operations				
Portal Reclamation/Conversion of Entry				
2. Site Conditions				
a. Material/Waste Rock Management	$\boxtimes$			
b. Erosion & Stormwater Control	$\boxtimes$			
c. Man-made Structures	$\boxtimes$			
d. Weed Management	$\boxtimes$			
e. Safety Conditions	$\boxtimes$			
f. Interim Reclamation	$\boxtimes$			

Inspection Items	Compliant	Non- Compliant	N/A		
3. Housekeeping					
a. Container Management	$\boxtimes$				
b. Spills/Leaks Observed	$\square$				
c. Hazardous Substances/POL Management	$\square$				
d. General Housekeeping	$\boxtimes$				
4. Access					
a. Road Management	$\square$				
b. Berms			$\boxtimes$		
c. Security	$\boxtimes$				
d. Signage	$\square$				
e. Surface Water Controls	$\boxtimes$				
5. Quality Assurance/Quality Control					
a. Routine Site Conditions Monitoring			$\boxtimes$		
b. Air, Water, Noise, Other Monitoring			$\boxtimes$		
c. Monitoring Reporting			$\boxtimes$		
d. Regulatory Submittals			$\boxtimes$		
e. Other Agency/Entity Permits	$\square$				
6. Final Reclamation			$\boxtimes$		
a. Exploration/Sampling Location					
b. Access Roads/Trails					
c. Grading					
d. Revegetation					
e. Removal of Structures					
f. Free of Trash					

#### **Additional Actions Necessary**

Non-Compliance Issues to be addressed by Operator

None

**Final Notes** 

General Comments:

- Operations are inactive until State compliance is met (CDPHE, Dishcarge and/or Stormwater Permits & CDRMS 110(1) permit)
- Dredging operations (Environmental Assessment, EA) are pending until State compliance is met.
- Arkansas River is extremely high due to recent snowmelt, therefore the previous bank stabilization work is under water along with the southern island. No recent bank erosion observed during the inspection.
- Beaver activity has dramatically decreased due to the high water level.
- No evidence of recent mining activity

Date inspection shared with CDRMS: 07/12/2019 Date inspection shared with Operator: 07/12/2019

## Image 1:



Comment: Flagging emplace along western working area to decrease public safety hazards located ~50 to 100 from the river's edge.

# Image 2:



Comment: Northern and Southern views of the active working face

## Image 3:



Comment: Due to high water levels the island located on the southern portion of the claim is under water

## Image 4:



Comment: The recent bank stabilization work has been either washed out or under water due to high water levels and/or river velocities.