

QUARTERLY SEDIMENTATION POND INSPECTION REPORT

CDMR Rule 4.05.9(17)

Mine: New Elk

NPDES ID. No.: Pond #1

Inspection Period: Third Quarter 2019

Inspection Date: 9/19/2019

General Description or Reference to Site Plan:

This pond is located West of the industrial building and serves as a mine water settling and water storage pond.

EMBANKMENT

|   |                      |          |     |                 |
|---|----------------------|----------|-----|-----------------|
| 1. Adequacy of the vegetative cover:                | <div>Excellent</div> | Moderate | Few | Poor            |
| 2. Erosion forming Gullies:                         | <div>Extensive</div> | Some     | Few | <div>None</div> |
| 3. Is wave action causing erosion:                  |                      |          |     |                 |
| On the upstream embankment?                         | Yes                  |          | No  | X               |
| At the principal spillway inlet?                    | Yes                  |          | No  | X               |
| 4. Erosion of the downstream toe of the embankment? | Yes                  |          | No  | X               |
| Cause of erosion can be attributed to:              |                      |          |     |                 |
|   |                      |          |     |                 |
| 5. Is seepage occurring through the dam?            | Yes                  |          | No  | X               |
| Could this seepage cause potential instability?     |                      |          |     |                 |
|   |                      |          |     |                 |

PRINICIPAL SPILLWAY

|  |           |          |               |                 |
|--|-----------|----------|---------------|-----------------|
| 1. Is the principal spillway system in working order?    | Yes       | X        | No            |                 |
| 2. Is the inlet free of debris and restrictive material? | Yes       | X        | No            |                 |
| 3. Is the discharge outlet free of restrictive material? | Yes       | X        | No            |                 |
| 4. Is erosion occurring at the discharge outlet?         | Yes       |          | No            | X               |
| Evaluate the severity:                                   | Extensive | Moderate | Just Starting | <div>None</div> |

EMERGENCY SPILLWAY

1. Does it appear that the emergency spillway has discharged water since the last inspection?  

YES  
NO ☒
2. Is erosion occurring at any section of the emergency spillway?  

YES  
NO ☒

SEDIMENT STORAGE CAPACITY

1. Has the design storage capacity of the reservoir been surpassed?  

YES  
NO ☒

Explain: No sediment in pond

OTHER OBSERVATIONS

Water level continuous to decrease due to evaporation. No water has been pumped in or released.

Pond liner is in good working condition at time of inspection.



MSHA CERTIFIED IMPOUNDMENT INSPECTOR

Date: 9-19-2019

QUARTERLY SEDIMENTATION POND INSPECTION REPORT

CDMR Rule 4.05.9(17)

Mine: New Elk

NPDES ID. No.: Pond #4

Inspection Period: Third Quarter 2019

Inspection Date: 9/19/2019

General Description or Reference to Site Plan:

This sediment control pond lies west of the Development Waste Pile. The majority of run-off from this waste pile flows to this pond. It has never received sufficient inflow to discharge.

EMBANKMENT

|   |                      |          |     |                 |
|---|----------------------|----------|-----|-----------------|
| 1. Adequacy of the vegetative cover:                | <div>Excellent</div> | Moderate | Few | Poor            |
| 2. Erosion forming Gullies:                         | <div>Extensive</div> | Some     | Few | <div>None</div> |
| 3. Is wave action causing erosion:                  |                      |          |     |                 |
| On the upstream embankment?                         | Yes                  |          | No  | <div>X</div>    |
| At the principal spillway inlet?                    | Yes                  |          | No  | <div>X</div>    |
| 4. Erosion of the downstream toe of the embankment? | Yes                  |          | No  | <div>X</div>    |
| Cause of erosion can be attributed to:              |                      |          |     |                 |
|   |                      |          |     |                 |
|   |                      |          |     |                 |
| 5. Is seepage occurring through the dam?            | Yes                  |          | No  | <div>X</div>    |
| Could this seepage cause potential instability?     |                      |          |     |                 |
|   |                      |          |     |                 |
|   |                      |          |     |                 |

PRINCIPAL SPILLWAY

|  |           |              |               |                 |
|--|-----------|--------------|---------------|-----------------|
| 1. Is the principal spillway system in working order?    | Yes       | <div>X</div> | No            |                 |
| 2. Is the inlet free of debris and restrictive material? | Yes       | <div>X</div> | No            |                 |
| 3. Is the discharge outlet free of restrictive material? | Yes       | <div>X</div> | No            |                 |
| 4. Is erosion occurring at the discharge outlet?         | Yes       |              | No            | <div>X</div>    |
| Evaluate the severity:                                   | Extensive | Moderate     | Just Starting | <div>None</div> |

EMERGENCY SPILLWAY

1. Does it appear that the emergency spillway has discharged water since the last inspection?  

YES  
NO X
2. Is erosion occurring at any section of the emergency spillway?  

YES  
NO X

SEDIMENT STORAGE CAPACITY

1. Has the design storage capacity of the reservoir been surpassed?  

YES  
NO X

Explain: Visual observation.

OTHER OBSERVATIONS

Pond is holding water but is not close to discharging.

Vincent Massaratti

MSHA CERTIFIED IMPOUNDMENT INSPECTOR

Date: 9-19-2019

QUARTERLY SEDIMENTATION POND INSPECTION REPORT

CDMR Rule 4.05.9(17)

Mine: New Elk

NPDES ID. No.: Pond #7

Inspection Period: Third Quarter 2019

Inspection Date: 9/19/2019

General Description or Reference to Site Plan:

This sediment control pond lies east of the preparation plant and pond #6. It receives run-off from the majority of the active surface facilities area lying south of State Highway 12.

EMBANKMENT

|   |                      |          |     |                 |
|---|----------------------|----------|-----|-----------------|
| 1. Adequacy of the vegetative cover:                | <div>Excellent</div> | Moderate | Few | Poor            |
| 2. Erosion forming Gullies:                         | <div>Extensive</div> | Some     | Few | <div>None</div> |
| 3. Is wave action causing erosion:                  |                      |          |     |                 |
| On the upstream embankment?                         | Yes                  |          | No  | X               |
| At the principal spillway inlet?                    | Yes                  |          | No  | X               |
| 4. Erosion of the downstream toe of the embankment? | Yes                  |          | No  | X               |
| Cause of erosion can be attributed to:              |                      |          |     |                 |
|   |                      |          |     |                 |
|   |                      |          |     |                 |
| 5. Is seepage occurring through the dam?            | Yes                  |          | No  | X               |
| Could this seepage cause potential instability?     |                      |          |     |                 |
|   |                      |          |     |                 |
|   |                      |          |     |                 |

PRINCIPAL SPILLWAY

|  |           |          |               |                 |
|--|-----------|----------|---------------|-----------------|
| 1. Is the principal spillway system in working order?    | Yes       | X        | No            |                 |
| 2. Is the inlet free of debris and restrictive material? | Yes       | X        | No            |                 |
| 3. Is the discharge outlet free of restrictive material? | Yes       | X        | No            |                 |
| 4. Is erosion occurring at the discharge outlet?         | Yes       |          | No            | X               |
| Evaluate the severity:                                   | Extensive | Moderate | Just Starting | <div>None</div> |

EMERGENCY SPILLWAY

1. Does it appear that the emergency spillway has discharged water since the last inspection?  

YES  
NO X
2. Is erosion occurring at any section of the emergency spillway?  

YES  
NO X

SEDIMENT STORAGE CAPACITY

1. Has the design storage capacity of the reservoir been surpassed?  

YES  
NO X

Explain: Visual observation. Pond cleaned in early 2017.

OTHER OBSERVATIONS

Pond is holding a small amount of water, almost dry.

Vincent Massaro

MSHA CERTIFIED IMPOUNDMENT INSPECTOR

Date: 9-19-2019

QUARTERLY SEDIMENTATION POND INSPECTION REPORT

CDMR Rule 4.05.9(17)

Mine: New Elk

NPDES ID. No.: Pond #8

Inspection Period: Third Quarter 2019

Inspection Date: 9/19/2019

General Description or Reference to Site Plan:

This pond lies north of Highway 12 at the base of the refuse disposal area. The pond receives run-off from the refuse disposal area.

EMBANKMENT

|   |                      |          |     |                 |
|---|----------------------|----------|-----|-----------------|
| 1. Adequacy of the vegetative cover:                  | <div>Excellent</div> | Moderate | Few | Poor            |
| 2. Erosion forming Gullies:                           | <div>Extensive</div> | Some     | Few | <div>None</div> |
| 3. Is wave action causing erosion:                    |                      |          |     |                 |
| On the upstream embankment?                           | Yes                  |          | No  | <div>X</div>    |
| At the principal spillway inlet?                      | Yes                  |          | No  | <div>X</div>    |
| 4. Erosion of the downstream toe of the embankment?   | Yes                  |          | No  | <div>X</div>    |
| Cause of erosion can be attributed to: _____          |                      |          |     |                 |
| _____   |                      |          |     |                 |
| 5. Is seepage occurring through the dam?              | Yes                  |          | No  | <div>X</div>    |
| Could this seepage cause potential instability? _____ |                      |          |     |                 |
| _____   |                      |          |     |                 |

PRINCIPAL SPILLWAY

|  |           |              |               |                 |
|--|-----------|--------------|---------------|-----------------|
| 1. Is the principal spillway system in working order?    | Yes       | <div>X</div> | No            |                 |
| 2. Is the inlet free of debris and restrictive material? | Yes       | <div>X</div> | No            |                 |
| 3. Is the discharge outlet free of restrictive material? | Yes       | <div>X</div> | No            |                 |
| 4. Is erosion occurring at the discharge outlet?         | Yes       |              | No            | <div>X</div>    |
| Evaluate the severity:                                   | Extensive | Moderate     | Just Starting | <div>None</div> |

**EMERGENCY SPILLWAY**

1. Does it appear that the emergency spillway has discharged water since the last inspection?  

YES \_\_\_\_\_ NO X \_\_\_\_\_
2. Is erosion occurring at any section of the emergency spillway?  

YES \_\_\_\_\_ NO X \_\_\_\_\_

**SEDIMENT STORAGE CAPACITY**

1. Has the design storage capacity of the reservoir been surpassed?  

YES \_\_\_\_\_ NO X \_\_\_\_\_

Explain: Visual observation. Sediment cleaned out in May 2018

\_\_\_\_\_

**OTHER OBSERVATIONS**

Pond is holding little water. Sediment currently in pond is leftover sediment from recent cleaning.

No new sediment has been deposited.

\_\_\_\_\_

\_\_\_\_\_



MSHA CERTIFIED IMPOUNDMENT INSPECTOR

Date: 9-19-2019



QUARTERLY SEDIMENTATION POND INSPECTION REPORT

CDMR Rule 4.05.9(17)

Mine: New Elk Pond 6

NPDES ID. No.: None

Inspection Period: Third Quarter 2019

Inspection Date: 9/19/2019

General Description or Reference to Site Plan:

Pond 6 is a non-discharging facility designed to contain plant processing water. The plant has been idle since 1996 and the pond is now used to dewater other ponds prior to clean-out

EMBANKMENT

1. Adequacy of the vegetative cover:

Excellent

Moderate

Few

Poor
2. Erosion forming Gullies:

Extensive

Some

Few

None
3. Is wave action causing erosion:
- On the upstream embankment?

Yes

No

X
- At the principal spillway inlet?

Yes

No

X
4. Erosion of the downstream toe of the embankment?

Yes

No

X
- Cause of erosion can be attributed to:
5. Is seepage occurring through the dam?

Yes

No

X
- Could this seepage cause potential instability?

SEDIMENT STORAGE CAPACITY

1. Has the design storage capacity of the reservoir been surpassed?

YES

NO

X
- Explain:

No design capacity.

OTHER OBSERVATIONS

Water level is low, not close to full.

Vince Massaro

MSHA CERTIFIED IMPOUNDMENT INSPECTOR

Date: 9-19-2019

QUARTERLY SEDIMENTATION POND INSPECTION REPORT

CDMR Rule 4.05.9(17)

Mine: New Elk WP Containment #1  
NPDES ID. No.: None  
Inspection Period: Third Quarter 2019  
Inspection Date: 9/19/2019

General Description or Reference to Site Plan:

This containment basin is a non-discharging facility designed to contain run-off from the West Portal Warehouse area.

EMBANKMENT

1. Adequacy of the vegetative cover:

Excellent

Moderate

Few

Poor
2. Erosion forming Gullies:

Extensive

Some

Few

None
3. Is wave action causing erosion:
- On the upstream embankment?

Yes

No

X
- At the principal spillway inlet?

Yes

No

X
4. Erosion of the downstream toe of the embankment?

Yes

No

X
- Cause of erosion can be attributed to:
5. Is seepage occurring through the dam?

Yes

No

X
- Could this seepage cause potential instability?

SEDIMENT STORAGE CAPACITY

1. Has the design storage capacity of the reservoir been surpassed?

YES

NO

X

Explain: Visual observation.

OTHER OBSERVATIONS

Containment area empty with no sediment at time of inspection.

Vinice Massarzo

MSHA CERTIFIED IMPOUNDMENT INSPECTOR

Date:

9-19-2019

QUARTERLY SEDIMENTATION POND INSPECTION REPORT

CDMR Rule 4.05.9(17)

Mine: New Elk WP Containment #2

NPDES ID. No.: None

Inspection Period: Third Quarter 2019

Inspection Date: 9/19/2019

General Description or Reference to Site Plan:

This containment basin is a non-discharging facility designed to contain run-off from the West Potal airshaft and manway areas.

EMBANKMENT

1. Adequacy of the vegetative cover:

Excellent

Moderate

Few

Poor
2. Erosion forming Gullies:

Extensive

Some

Few

None
3. Is wave action causing erosion:
- On the upstream embankment?

Yes

No

X
- At the principal spillway inlet?

Yes

No

X
4. Erosion of the downstream toe of the embankment?

Yes

No

X
- Cause of erosion can be attributed to:
5. Is seepage occurring through the dam?

Yes

No

X
- Could this seepage cause potential instability?

SEDIMENT STORAGE CAPACITY

1. Has the design storage capacity of the reservoir been surpassed?

YES

NO

X

Explain: Visual observation.

OTHER OBSERVATIONS

Cleaned last year, small amount of water in containment.

Vinny Maeserath

MSHA CERTIFIED IMPOUNDMENT INSPECTOR

Date: 9-19-2019

QUARTERLY SEDIMENTATION POND INSPECTION REPORT

CDMR Rule 4.05.9(17)

Mine: New Elk RDA Containment North  
NPDES ID. No.: None  
Inspection Period: Third Quarter 2019  
Inspection Date: 9/19/2019

General Description or Reference to Site Plan:

This partially incised containment basin is a non-discharging facility designed to contain run-off from the RDA belt conveyor area north of Highway 12.

EMBANKMENT

1. Adequacy of the vegetative cover:

Excellent

Moderate

Few

Poor
2. Erosion forming Gullies:

Extensive

Some

Few

None
3. Is wave action causing erosion:
- On the upstream embankment?

Yes

No

X
- At the principal spillway inlet?

Yes

No

X
4. Erosion of the downstream toe of the embankment?

Yes

No

X
- Cause of erosion can be attributed to:
5. Is seepage occurring through the dam?

Yes

No

X
- Could this seepage cause potential instability?

No embankment, this is an incised containment basin.

SEDIMENT STORAGE CAPACITY

1. Has the design storage capacity of the reservoir been surpassed?

YES

NO

X

Explain: Visual observation.

OTHER OBSERVATIONS

Containment Area is holding water. Sediment will be cleaned from pond within 6 months.

Vino Massaro

MSHA CERTIFIED IMPOUNDMENT INSPECTOR

Date:

9-19-2019

QUARTERLY SEDIMENTATION POND INSPECTION REPORT

CDMR Rule 4.05.9(17)

Mine: New Elk RDA Containment SE  
NPDES ID. No.: None  
Inspection Period: Third Quarter 2019  
Inspection Date: 9/19/2019

General Description or Reference to Site Plan:

This partially incised containment basin is a non-discharging facility designed to contain run-off from the area east of the RDA belt conveyor and south of Highway 12.

EMBANKMENT

1. Adequacy of the vegetative cover:

Excellent

Moderate

Few

Poor
2. Erosion forming Gullies:

Extensive

Some

Few

None
3. Is wave action causing erosion:
- On the upstream embankment?

Yes

No

X
- At the principal spillway inlet?

Yes

No

X
4. Erosion of the downstream toe of the embankment?

Yes

No

X
- Cause of erosion can be attributed to:
5. Is seepage occurring through the dam?

Yes

No

X
- Could this seepage cause potential instability?

SEDIMENT STORAGE CAPACITY

1. Has the design storage capacity of the reservoir been surpassed?

YES

NO

X
- Explain:

Visual observation.

OTHER OBSERVATIONS

Containment Area is dry.

Vincent Massaro  
MSHA CERTIFIED IMPOUNDMENT INSPECTOR

Date: 9-19-2019

QUARTERLY SEDIMENTATION POND INSPECTION REPORT

CDMR Rule 4.05.9(17)

Mine: New Elk RDA Containment SW  
NPDES ID. No.: None  
Inspection Period: Third Quarter 2019  
Inspection Date: 9/19/2019

General Description or Reference to Site Plan:

This partially incised containment basin is a non-discharging facility designed to contain run-off from the area west of the RDA belt conveyor and south of Highway 12.

EMBANKMENT

1. Adequacy of the vegetative cover:

Excellent

Moderate

Few

Poor
2. Erosion forming Gullies:

Extensive

Some

Few

None
3. Is wave action causing erosion:

No

X
- On the upstream embankment?

Yes

No

X
- At the principal spillway inlet?

Yes

No

X
4. Erosion of the downstream toe of the embankment?

Yes

No

X
- Cause of erosion can be attributed to:
5. Is seepage occurring through the dam?

Yes

No

X
- Could this seepage cause potential instability?

No embankment, this is an incised containment basin.

SEDIMENT STORAGE CAPACITY

1. Has the design storage capacity of the reservoir been surpassed?

YES

NO

X

Explain: Visual observation.

OTHER OBSERVATIONS

Containment Area is dry.

Vince Massaro

MSHA CERTIFIED IMPOUNDMENT INSPECTOR

Date: 9-19-2019

QUARTERLY SEDIMENTATION POND INSPECTION REPORT  
New Elk Mine- September 19, 2019



Pond 6



Pond 7





Pond 8



Containment Area #1





Containment Area #2



Containment Area RDA North





Pond RDA Southeast



Containment Area RDA Southwest