

QUARTERLY SEDIMENTATION POND INSPECTION REPORT

CDMR Rule 4.05.9(17)

rd

Mine: Lorencito
NPDES ID. No.: Pond #9 (North)
Inspection Period: First Quarter 2019
Inspection Date: 3/29/2019 12:15 - 64°

General Description or Reference to Site Plan:

This pond is located north-east of the area of mining scheduled for 2001-02. The pond is partially incised into bedrock and the embankment keyed into bedrock. Side slopes are less than 2H:1V. The primary spillway discharges north into a small unnamed drainage.

EMBANKMENT

- 1). Adequacy of the vegetative cover: Excellent Moderate Few Poor
- 2). Erosion forming Gullies: Extensive Some Few None
- 3). Is wave action causing erosion:
- On the Upstream embankment? Yes _____ No ✓
- At the principal spillway inlet? Yes _____ No ✓
- 4). Erosion of the downstream toe of the embankment? Yes _____ No ✓
- Cause of erosion can be attributed to: _____
- _____
- 5). Is seepage occurring through the dam? Yes _____ No ✓
- Could this seepage cause potential instability? _____
- _____
- _____

PRINCIPAL SPILLWAY

- 1). Is the principal spillway system in working order? Yes ✓ No ✗
- 2). Is the inlet free of debris and restrictive material? Yes ✓ No ✗
- 3). Is the discharge outlet free of restrictive material? Yes ✓ No ✗
- 4). Is erosion occurring at the discharge outlet? Yes _____ No ✓
- Evaluate the severity: Extensive Moderate Just starting None

EMERGENCY SPILLWAY

Pond: 9-North

1). Does it appear that the emergency spillway has discharged water since the last inspection?

Yes _____ No ✓

2). Is erosion occurring at any section of the emergency spillway?

Yes _____ No ✓

Describe extent: _____

SEDIMENT STORAGE CAPACITY

1). Has the design storage capacity of the reservoir been surpassed?

Yes _____ No ✓

Explain: _____
Visual observation

OTHER OBSERVATIONS

limited inflow during the winter - water level
diminished by evaporation

Ronald A. Thompson
MSHA Qualified Impoundment Inspector

3/29/2019
Date

QUARTERLY SEDIMENT POND INSPECTION REPORT
Lorencito Canyon Mine – March 29, 2019



Pond 6



Pond 9A (South)



Pond 9B (North)



Pond 8

QUARTERLY SEDIMENTATION POND INSPECTION REPORT

CDMR Rule 4.05.9(17)

Mine: Lorencito
NPDES ID. No.: Pond #5
Inspection Period: First Quarter 2019
Inspection Date: 3/29/19

General Description or Reference to Site Plan:

This pond is located West of the area of mining scheduled for 2001-02. The pond is partially incised into bedrock and the embankment keyed into bedrock. Side slopes are less than 2H:1V. The primary discharges south into Cow Canyon drainage.

EMBANKMENT

1). Adequacy of the vegetative cover:

Excellent

 Moderate Few Poor

2). Erosion forming Gullies: Extensive Some

Few

 None

3). Is wave action causing erosion:

On the Upstream embankment? Yes No ☒

At the principal spillway inlet? Yes No ☒

4). Erosion of the downstream toe of the embankment? Yes No ☒

Cause of erosion can be attributed to:

5). Is seepage occurring through the dam? Yes No ☒

Could this seepage cause potential instability?

PRINCIPAL SPILLWAY

1). Is the principal spillway system in working order? Yes ☒ No

2). Is the inlet free of debris and restrictive material? Yes ☒ No

3). Is the discharge outlet free of restrictive material? Yes ☒ No

4). Is erosion occurring at the discharge outlet? Yes No ☒

Evaluate the severity: Extensive Moderate Just starting None

EMERGENCY SPILLWAY

Pond: 5

1). Does it appear that the emergency spillway has discharged water since the last inspection?
Yes No ✓

2). Is erosion occurring at any section of the emergency spillway?
Yes No ✓

Describe extent:

SEDIMENT STORAGE CAPACITY

1). Has the design storage capacity of the reservoir been surpassed?
Yes No

Explain: Not Verified
Should be surveyed for next quarter

OTHER OBSERVATIONS

By observation a significant inlet sediment delta has formed. The pond should be surveyed as this may impact sediment storage capacity limits.

Ronald L. Thompson
MSHA Qualified Impoundment Inspector

3/29/2019
Date

QUARTERLY SEDIMENTATION POND INSPECTION REPORT

CDMR Rule 4.05.9(17)

Mine: Lorencito
NPDES ID. No.: Pond #6
Inspection Period: First Quarter 2019
Inspection Date: 3/29/19

General Description or Reference to Site Plan:

This pond is located South of the area of mining scheduled for 2001-02. The pond is partially incised into bedrock and the embankment keyed into bedrock. Side slopes are less than 2H:1V. The primary discharges south into Jeff Canyon drainage.

EMBANKMENT

- 1). Adequacy of the vegetative cover: Excellent Moderate Few Poor
- 2). Erosion forming Gullies: Extensive Some Few None
- 3). Is wave action causing erosion:
- On the Upstream embankment? Yes _____ No ✓
- At the principal spillway inlet? Yes _____ No ✓
- 4). Erosion of the downstream toe of the embankment' Yes _____ No ✓
- Cause of erosion can be attributed to: _____
- _____
- 5). Is seepage occurring through the dam? Yes _____ No ✓
- Could this seepage cause potential instability? _____
- _____
- _____

PRINCIPAL SPILLWAY

- 1). Is the principal spillway system in working order? Yes ✓ No _____
- 2). Is the inlet free of debris and restrictive material? Yes ✓ No _____
- 3). Is the discharge outlet free of restrictive material? Yes ✓ No _____
- 4). Is erosion occurring at the discharge outlet? Yes _____ No ✓
- Evaluate the severity: Extensive Moderate Just starting None

EMERGENCY SPILLWAY

Pond: 6

1). Does it appear that the emergency spillway has discharged water since the last inspection?
Yes _____ No X

2). Is erosion occurring at any section of the emergency spillway?
Describe extent: _____
Yes _____ No X

SEDIMENT STORAGE CAPACITY

1). Has the design storage capacity of the reservoir been surpassed?
Explain: _____
Yes _____ No X
Visual Observation

OTHER OBSERVATIONS

Water level is about 18 below base of
Primary Discharge riser.

Ronald H. Thompson
MSHA Qualified Impoundment Inspector

3/29/2019
Date

QUARTERLY SEDIMENTATION POND INSPECTION REPORT

CDMR Rule 4.05.9(17)

Mine: Lorencito
NPDES ID. No.: Pond #7
Inspection Period: First Quarter 2019
Inspection Date: 3/29/19

General Description or Reference to Site Plan:

This pond is located south of the area of mining scheduled for 2001-02. The pond is partially incised into bedrock and the embankment keyed into bedrock. Side slopes are less than 2H:1V. The primary discharges south into Jeff Canyon drainage.

EMBANKMENT

- 1). Adequacy of the vegetative cover: Excellent Moderate Few Poor
- 2). Erosion forming Gullies: Extensive Some Few None
- 3). Is wave action causing erosion:
- On the Upstream embankment? Yes _____ No ✓
- At the principal spillway inlet? Yes _____ No ✓
- 4). Erosion of the downstream toe of the embankment? Yes _____ No ✓
- Cause of erosion can be attributed to: _____
- _____
- 5). Is seepage occurring through the dam? Yes _____ No ✓
- Could this seepage cause potential instability? _____
- _____
- _____

PRINCIPAL SPILLWAY

- 1). Is the principal spillway system in working order? Yes ✓ No _____
- 2). Is the inlet free of debris and restrictive material? Yes ✓ No _____
- 3). Is the discharge outlet free of restrictive material? Yes ✓ No _____
- 4). Is erosion occurring at the discharge outlet? Yes _____ No ✓
- Evaluate the severity: Extensive Moderate Just starting None

Pond: 7

EMERGENCY SPILLWAY

1). Does it appear that the emergency spillway has discharged water since the last inspection?
Yes _____ No ✓

2). Is erosion occurring at any section of the emergency spillway?
Yes _____ No ✓

Describe extent: _____

SEDIMENT STORAGE CAPACITY

1). Has the design storage capacity of the reservoir been surpassed?
Yes _____ No ✓

Explain: _____
Visual observation

OTHER OBSERVATIONS

Appears to be no significant inflow with new
sediment deposition since last inspection.

Ronald H. Thompson
MSHA Qualified Impoundment Inspector

3/29/2019
Date

QUARTERLY SEDIMENTATION POND INSPECTION REPORT

CDMR Rule 4.05.9(17)

Mine: Lorencito
NPDES ID. No.: Pond #8
Inspection Period: First Quarter 2019
Inspection Date: 3/29/19 1:10 pm 64°F

General Description or Reference to Site Plan:

This pond is located north of the area of mining scheduled for 2001-02. The pond is partially incised into bedrock and the embankment keyed into bedrock. Side slopes are less than 2H:1V. The primary discharges north into a small drainage.

EMBANKMENT

1). Adequacy of the vegetative cover: Excellent Moderate Few Poor

2). Erosion forming Gullies: Extensive Some Few None

3). Is wave action causing erosion:

 On the Upstream embankment? Yes _____ No ✓

 At the principal spillway inlet? Yes _____ No ✓

4). Erosion of the downstream toe of the embankment? Yes _____ No ✓

 Cause of erosion can be attributed to: _____

5). Is seepage occurring through the dam? Yes _____ No ✓

 Could this seepage cause potential instability? _____

PRINCIPAL SPILLWAY

1). Is the principal spillway system in working order? Yes ✓ No _____

2). Is the inlet free of debris and restrictive material? Yes ✓ No _____

3). Is the discharge outlet free of restrictive material? Yes ✓ No _____

4). Is erosion occurring at the discharge outlet? Yes _____ No ✓

 Evaluate the severity: Extensive Moderate Just starting None

Pond: 8

EMERGENCY SPILLWAY

1). Does it appear that the emergency spillway has discharged water since the last inspection?
Yes _____ No ✓

2). Is erosion occurring at any section of the emergency spillway?
Yes _____ No ✓

Describe extent: _____

SEDIMENT STORAGE CAPACITY

1). Has the design storage capacity of the reservoir been surpassed?
Yes _____ No ✓

Explain: _____
Visual observation

OTHER OBSERVATIONS

Water level has lowered to about 2 foot below
base of Primary Discharge riser.

Ronald L. Meyer
MSHA Qualified Impoundment Inspector

3/29/2019
Date

QUARTERLY SEDIMENTATION POND INSPECTION REPORT

CDMR Rule 4.05.9(17)

Mine: Lorencito
NPDES ID. No.: Pond #9A (South)
Inspection Period: First Quarter 2019
Inspection Date: 3/29/19 12:40 ~ 6:40

General Description or Reference to Site Plan:

This pond is located south-east of the area of mining scheduled for 2001-02. The pond is partially incised into bedrock and the embankment keyed into bedrock. Side slopes are less than 2H:1V. The primary spillway discharges south into Jeff Canyon.

EMBANKMENT

- 1). Adequacy of the vegetative cover: Excellent Moderate Few Poor
- 2). Erosion forming Gullies: Extensive Some Few None
- 3). Is wave action causing erosion:
- On the Upstream embankment? Yes _____ No ☒
- At the principal spillway inlet? Yes _____ No ☒
- 4). Erosion of the downstream toe of the embankment? Yes _____ No ☒
- Cause of erosion can be attributed to: _____
- 5). Is seepage occurring through the dam? Yes _____ No ☒
- Could this seepage cause potential instability? _____

PRINCIPAL SPILLWAY

- 1). Is the principal spillway system in working order? Yes ☒ No _____
- 2). Is the inlet free of debris and restrictive material? Yes ☒ No _____
- 3). Is the discharge outlet free of restrictive material? Yes ☒ No _____
- 4). Is erosion occurring at the discharge outlet? Yes _____ No ☒
- Evaluate the severity: Extensive Moderate Just starting None

Pond: 9-South

EMERGENCY SPILLWAY

1). Does it appear that the emergency spillway has discharged water since the last inspection?
Yes _____ No ✓

2). Is erosion occurring at any section of the emergency spillway?
Yes _____ No ✓

Describe extent: _____

SEDIMENT STORAGE CAPACITY

1). Has the design storage capacity of the reservoir been surpassed?
Yes _____ No ✓

Explain: _____
Visual observation

OTHER OBSERVATIONS

Pond has minimal water at the base of the pond.


MSHA Qualified Impoundment Inspector

3/29/2019
Date