

QUARTERLY SEDIMENTATION POND INSPECTION REPORT

CDMR Rule 4.05.9(17)

Mine: New Elk
NPDES ID. No.: Pond #1
Inspection Period: Third Quarter 2020
Inspection Date: 7/31/2020

General Description or Reference to Site Plan:

This pond is located West of the industrial building and serves as a mine water settling and water storage pond.

EMBANKMENT

- | | | | | |
|---|------------------|----------|-----|-------------|
| 1. Adequacy of the vegetative cover: | <u>Excellent</u> | Moderate | Few | Poor |
| 2. Erosion forming Gullies: | Extensive | Some | Few | <u>None</u> |
| 3. Is wave action causing erosion: | | | | |
| On the upstream embankment? | Yes | | No | <u>X</u> |
| At the principal spillway inlet? | Yes | | No | <u>X</u> |
| 4. Erosion of the downstream toe of the embankment? | Yes | | No | <u>X</u> |

Cause of erosion can be attributed to: _____

5. Is seepage occurring through the dam? Yes _____ No X

Could this seepage cause potential instability? _____

PRINCIPAL SPILLWAY

- | | | | | |
|--|-----|----------|----|----------|
| 1. Is the principal spillway system in working order? | Yes | <u>X</u> | No | _____ |
| 2. Is the inlet free of debris and restrictive material? | Yes | <u>X</u> | No | _____ |
| 3. Is the discharge outlet free of restrictive material? | Yes | <u>X</u> | No | _____ |
| 4. Is erosion occurring at the discharge outlet? | Yes | _____ | No | <u>X</u> |

Evaluate the severity: Extensive Moderate Just Starting None

EMERGENCY SPILLWAY

1. Does it appear that the emergency spillway has discharged water since the last inspection?

YES _____ NO X _____

2. Is erosion occurring at any section of the emergency spillway?

YES _____ NO X _____

SEDIMENT STORAGE CAPACITY

1. Has the design storage capacity of the reservoir been surpassed?

YES _____ NO X _____

Explain: No sediment in pond

OTHER OBSERVATIONS

Pond liner is in good condition at time of inspection. Pond was holding water at time of inspection.

QUARTERLY SEDIMENTATION POND INSPECTION REPORT

CDMR Rule 4.05.9(17)

Mine: New Elk
NPDES ID. No.: Pond #4
Inspection Period: Third Quarter 2020
Inspection Date: 7/31/2020

General Description or Reference to Site Plan:

This sediment control pond lies west of the Development Waste Pile. The majority of run-off from this waste pile flows to this pond. It has never received sufficient inflow to discharge.

EMBANKMENT

- | | | | | |
|---|------------------|----------|----------|-------------|
| 1. Adequacy of the vegetative cover: | <u>Excellent</u> | Moderate | Few | Poor |
| 2. Erosion forming Gullies: | Extensive | Some | Few | <u>None</u> |
| 3. Is wave action causing erosion: | | | | |
| On the upstream embankment? | Yes _____ | | No _____ | <u>X</u> |
| At the principal spillway inlet? | Yes _____ | | No _____ | <u>X</u> |
| 4. Erosion of the downstream toe of the embankment? | Yes _____ | | No _____ | <u>X</u> |

Cause of erosion can be attributed to: _____

5. Is seepage occurring through the dam? Yes _____ No X

Could this seepage cause potential instability? _____

PRINCIPAL SPILLWAY

- | | | |
|--|--------------|-------------|
| 1. Is the principal spillway system in working order? | Yes <u>X</u> | No _____ |
| 2. Is the inlet free of debris and restrictive material? | Yes <u>X</u> | No _____ |
| 3. Is the discharge outlet free of restrictive material? | Yes <u>X</u> | No _____ |
| 4. Is erosion occurring at the discharge outlet? | Yes _____ | No <u>X</u> |

Evaluate the severity: Extensive Moderate Just Starting None

EMERGENCY SPILLWAY

1. Does it appear that the emergency spillway has discharged water since the last inspection?

YES _____ NO X _____

2. Is erosion occurring at any section of the emergency spillway?

YES _____ NO X _____

SEDIMENT STORAGE CAPACITY

1. Has the design storage capacity of the reservoir been surpassed?

YES _____ NO X _____

Explain: Visual observation.

OTHER OBSERVATIONS

Pond was holding a small amount of water.

QUARTERLY SEDIMENTATION POND INSPECTION REPORT

CDMR Rule 4.05.9(17)

Mine: New Elk Pond 6

NPDES ID. No.: None

Inspection Period: Third Quarter 2020

Inspection Date: 7/31/2020

General Description or Reference to Site Plan:

Pond 6 is a non-discharging facility designed to contain plant processing water. The plant has been idle since 1996 and the pond is now used to dewater other ponds prior to clean-out

EMBANKMENT

- | | | | | |
|---|------------------|----------|----------|-------------|
| 1. Adequacy of the vegetative cover: | <u>Excellent</u> | Moderate | Few | Poor |
| 2. Erosion forming Gullies: | <u>Extensive</u> | Some | Few | <u>None</u> |
| 3. Is wave action causing erosion: | | | | |
| On the upstream embankment? | Yes _____ | | No _____ | <u>X</u> |
| At the principal spillway inlet? | Yes _____ | | No _____ | <u>X</u> |
| 4. Erosion of the downstream toe of the embankment? | Yes _____ | | No _____ | <u>X</u> |
| Cause of erosion can be attributed to: _____ | | | | |
| _____ | | | | |
| 5. Is seepage occurring through the dam? | Yes _____ | | No _____ | <u>X</u> |
| Could this seepage cause potential instability? _____ | | | | |
| _____ | | | | |

SEDMIMENT STORAGE CAPACITY

1. Has the design storage capacity of the reservoir been surpassed?
- YES _____ NO X

Explain: No design capacity.

OTHER OBSERVATIONS

Pond is holding water, not close to full.

QUARTERLY SEDIMENTATION POND INSPECTION REPORT

CDMR Rule 4.05.9(17)

Mine: New Elk

NPDES ID. No.: Pond #7

Inspection Period: Third Quarter 2020

Inspection Date: 7/31/2020

General Description or Reference to Site Plan:

This sediment control pond lies east of the preparation plant and pond #6. It receives run-off from the majority of the active surface facilities area lying south of State Highway 12.

EMBANKMENT

- | | | | | |
|---|-----------|----------|----------|---------|
| 1. Adequacy of the vegetative cover: | Excellent | Moderate | Few | Poor |
| 2. Erosion forming Gullies: | Extensive | Some | Few | None |
| 3. Is wave action causing erosion: | | | | |
| On the upstream embankment? | Yes _____ | | No _____ | X _____ |
| At the principal spillway inlet? | Yes _____ | | No _____ | X _____ |
| 4. Erosion of the downstream toe of the embankment? | Yes _____ | | No _____ | X _____ |

Cause of erosion can be attributed to:

5. Is seepage occurring through the dam? Yes _____ No X

Could this seepage cause potential instability? _____

PRINCIPAL SPILLWAY

- | | | |
|--|-----------------------|-------------------------|
| 1. Is the principal spillway system in working order? | Yes <u> X </u> | No <u> </u> |
| 2. Is the inlet free of debris and restrictive material? | Yes <u> X </u> | No <u> </u> |
| 3. Is the discharge outlet free of restrictive material? | Yes <u> X </u> | No <u> </u> |
| 4. Is erosion occurring at the discharge outlet? | Yes <u> </u> | No <u> X </u> |

Evaluate the severity: Extensive Moderate Just Starting **None**

EMERGENCY SPILLWAY

1. Does it appear that the emergency spillway has discharged water since the last inspection?

YES _____ NO X _____

2. Is erosion occurring at any section of the emergency spillway?

YES _____ NO X _____

SEDIMENT STORAGE CAPACITY

1. Has the design storage capacity of the reservoir been surpassed?

YES _____ NO X _____

Explain: Visual observation. Pond cleaned in early 2017.

OTHER OBSERVATIONS

Pond is holding water, not near the level of the decant.

QUARTERLY SEDIMENTATION POND INSPECTION REPORT

CDMR Rule 4.05.9(17)

Mine: New Elk
NPDES ID. No.: Pond #8
Inspection Period: Third Quarter 2020
Inspection Date: 7/31/2020

General Description or Reference to Site Plan:

This pond lies north of Highway 12 at the base of the refuse disposal area. The pond receives run-off from the refuse disposal area.

EMBANKMENT

- | | | | | |
|---|------------------|----------|----------|-------------|
| 1. Adequacy of the vegetative cover: | <u>Excellent</u> | Moderate | Few | Poor |
| 2. Erosion forming Gullies: | Extensive | Some | Few | <u>None</u> |
| 3. Is wave action causing erosion: | | | | |
| On the upstream embankment? | Yes _____ | | No _____ | <u>X</u> |
| At the principal spillway inlet? | Yes _____ | | No _____ | <u>X</u> |
| 4. Erosion of the downstream toe of the embankment? | Yes _____ | | No _____ | <u>X</u> |

Cause of erosion can be attributed to: _____

5. Is seepage occurring through the dam? Yes _____ No X _____

Could this seepage cause potential instability? _____

PRINCIPAL SPILLWAY

- | | | |
|--|--------------------|-------------------|
| 1. Is the principal spillway system in working order? | Yes <u>X</u> _____ | No _____ |
| 2. Is the inlet free of debris and restrictive material? | Yes <u>X</u> _____ | No _____ |
| 3. Is the discharge outlet free of restrictive material? | Yes <u>X</u> _____ | No _____ |
| 4. Is erosion occurring at the discharge outlet? | Yes _____ | No <u>X</u> _____ |

Evaluate the severity: Extensive Moderate Just Starting None

EMERGENCY SPILLWAY

1. Does it appear that the emergency spillway has discharged water since the last inspection?

YES _____ NO X _____

2. Is erosion occurring at any section of the emergency spillway?

YES _____ NO X _____

SEDIMENT STORAGE CAPACITY

1. Has the design storage capacity of the reservoir been surpassed?

YES _____ NO X _____

Explain: Visual observation. Sediment cleaned out in May 2018

OTHER OBSERVATIONS

Pond was holding water at the time of inspection. No new sediment has been deposited and there is very little sediment in the pond.

QUARTERLY SEDIMENTATION POND INSPECTION REPORT

CDMR Rule 4.05.9(17)

Mine: New Elk WP Containment #1

NPDES ID. No.: None

Inspection Period: Third Quarter 2020

Inspection Date: 7/31/2020

General Description or Reference to Site Plan:

This containment basin is a non-discharging facility designed to contain run-off from the West Portal Warehouse area.

EMBANKMENT

- | | | | | |
|---|------------------|----------|----------|-------------|
| 1. Adequacy of the vegetative cover: | <u>Excellent</u> | Moderate | Few | Poor |
| 2. Erosion forming Gullies: | <u>Extensive</u> | Some | Few | <u>None</u> |
| 3. Is wave action causing erosion: | | | | |
| On the upstream embankment? | Yes _____ | | No _____ | <u>X</u> |
| At the principal spillway inlet? | Yes _____ | | No _____ | <u>X</u> |
| 4. Erosion of the downstream toe of the embankment? | Yes _____ | | No _____ | <u>X</u> |
| Cause of erosion can be attributed to: _____ | | | | |
| _____ | | | | |
| 5. Is seepage occurring through the dam? | Yes _____ | | No _____ | <u>X</u> |
| Could this seepage cause potential instability? _____ | | | | |
| _____ | | | | |

SEDMIMENT STORAGE CAPACITY

1. Has the design storage capacity of the reservoir been surpassed?
YES _____ NO X

Explain: Visual observation.

OTHER OBSERVATIONS

Containment area was empty at time of inspection.

QUARTERLY SEDIMENTATION POND INSPECTION REPORT

CDMR Rule 4.05.9(17)

Mine: New Elk WP Containment #2

NPDES ID. No.: None

Inspection Period: Third Quarter 2020

Inspection Date: 7/31/2020

General Description or Reference to Site Plan:

This containment basin is a non-discharging facility designed to contain run-off from the West Portal airshaft and manway areas.

EMBANKMENT

- | | | | | |
|---|------------------|----------|----------|-------------|
| 1. Adequacy of the vegetative cover: | <u>Excellent</u> | Moderate | Few | Poor |
| 2. Erosion forming Gullies: | <u>Extensive</u> | Some | Few | <u>None</u> |
| 3. Is wave action causing erosion: | | | | |
| On the upstream embankment? | Yes _____ | | No _____ | <u>X</u> |
| At the principal spillway inlet? | Yes _____ | | No _____ | <u>X</u> |
| 4. Erosion of the downstream toe of the embankment? | Yes _____ | | No _____ | <u>X</u> |
| Cause of erosion can be attributed to: _____ | | | | |
| _____ | | | | |
| 5. Is seepage occurring through the dam? | Yes _____ | | No _____ | <u>X</u> |
| Could this seepage cause potential instability? _____ | | | | |
| _____ | | | | |

SEDMIMENT STORAGE CAPACITY

1. Has the design storage capacity of the reservoir been surpassed?
YES _____ NO X

Explain: Visual observation.

OTHER OBSERVATIONS

Containment is empty.

QUARTERLY SEDIMENTATION POND INSPECTION REPORT

CDMR Rule 4.05.9(17)

Mine: New Elk Containment #3

NPDES ID. No.: None

Inspection Period: Third Quarter 2020

Inspection Date: 7/31/2020

General Description or Reference to Site Plan:

This partially incised containment basin is a non-discharging facility designed to contain run-off from the area east of the RDA belt conveyor and south of Highway 12.

EMBANKMENT

- | | | | | | |
|----|--|-----------|---------------------|-----|-----------------|
| 1. | Adequacy of the vegetative cover: | Excellent | <div>Moderate</div> | Few | <div>Poor</div> |
| 2. | Erosion forming Gullies: | Extensive | Some | Few | <div>None</div> |
| 3. | Is wave action causing erosion: | | | | |
| | On the upstream embankment? | Yes | _____ | No | _____X |
| | At the principal spillway inlet? | Yes | _____ | No | _____X |
| 4. | Erosion of the downstream toe of the embankment? | Yes | _____ | No | _____X |
| | Cause of erosion can be attributed to: | _____ | | | |
| | | _____ | | | |
| 5. | Is seepage occurring through the dam? | Yes | _____ | No | _____X |
| | Could this seepage cause potential instability? | _____ | | | |

SEDIMENT STORAGE CAPACITY

1. Has the design storage capacity of the reservoir been surpassed? YES _____ NO X _____

Explain: Visual observation.

OTHER OBSERVATIONS

Containment Area is dry at time of inspection.

QUARTERLY SEDIMENTATION POND INSPECTION REPORT

CDMR Rule 4.05.9(17)

Mine: New Elk Containment #4

NPDES ID. No.: None

Inspection Period: Third Quarter 2020

Inspection Date: 7/31/2020

General Description or Reference to Site Plan:

This partially incised containment basin is a non-discharging facility designed to contain run-off from the area west of the RDA belt conveyor and south of Highway 12.

EMBANKMENT

- | | | | | |
|---|-----------|-----------------|-----|-------------|
| 1. Adequacy of the vegetative cover: | Excellent | <u>Moderate</u> | Few | Poor |
| 2. Erosion forming Gullies: | Extensive | Some | Few | <u>None</u> |
| 3. Is wave action causing erosion: | | | | |
| On the upstream embankment? | Yes | _____ | No | <u>X</u> |
| At the principal spillway inlet? | Yes | _____ | No | <u>X</u> |
| 4. Erosion of the downstream toe of the embankment? | Yes | _____ | No | <u>X</u> |

Cause of erosion can be attributed to: _____

5. Is seepage occurring through the dam? Yes _____ No X

Could this seepage cause potential instability? No embankment, this is an incised containment basin.

SEDMIMENT STORAGE CAPACITY

1. Has the design storage capacity of the reservoir been surpassed?
YES _____ NO X

Explain: Visual observation.

OTHER OBSERVATIONS

Containment Area was dry at time of inspection.

QUARTERLY SEDIMENTATION POND INSPECTION REPORT

CDMR Rule 4.05.9(17)

Mine: New Elk Containment #5
NPDES ID. No.: None
Inspection Period: Third Quarter 2020
Inspection Date: 7/31/2020

General Description or Reference to Site Plan:

This partially incised containment basin is a non-discharging facility designed to contain run-off from the RDA belt conveyor area north of Highway 12.

EMBANKMENT

- | | | | | |
|---|------------------|----------|----------|-------------|
| 1. Adequacy of the vegetative cover: | <u>Excellent</u> | Moderate | Few | Poor |
| 2. Erosion forming Gullies: | <u>Extensive</u> | Some | Few | <u>None</u> |
| 3. Is wave action causing erosion: | | | | |
| On the upstream embankment? | Yes _____ | | No _____ | <u>X</u> |
| At the principal spillway inlet? | Yes _____ | | No _____ | <u>X</u> |
| 4. Erosion of the downstream toe of the embankment? | Yes _____ | | No _____ | <u>X</u> |
| Cause of erosion can be attributed to: _____ | | | | |
| _____ | | | | |
| 5. Is seepage occurring through the dam? | Yes _____ | | No _____ | <u>X</u> |
| Could this seepage cause potential instability? <u>No embankment, this is an incised containment basin.</u> | | | | |

SEDIMENT STORAGE CAPACITY

1. Has the design storage capacity of the reservoir been surpassed?
YES _____ NO X

Explain: Visual observation.

OTHER OBSERVATIONS

Containment Area is empty. Containment Area was cleaned in the first quarter of 2020 and about 70 percent of the sediment in the containment area was removed.

QUARTERLY SEDIMENTATION POND INSPECTION REPORT
New Elk Mine- July 31, 2020



Pond 1



Pond 4



Pond 6



Pond 7



Pond 8



Containment Area #3



Containment Area #4



Containment Area #5

Certification

This inspection was conducted by Vince Massarotti, a qualified professional and MSHA certified impoundment inspector.

This is to certify, to the best of my knowledge and belief, that maintenance, since the previous certification and as determined during this inspection and discussions with mine personnel, is in accordance with designs as approved by the Division of Reclamation, Mining and Safety.

Vince Massarotti
Inspector

8-18-2020
Date

Inspections completed in compliance with Rule 4.09.1(11)(b) must be submitted to the Division within two weeks of completion.