

Zuber - DNR, Rob <rob.zuber@state.co.us>

Inspection report for North Thompson Creek Mine

1 message

Zuber - DNR, Rob <rob.zuber@state.co.us> To: Jim Stover <jestover@bresnan.net>, minrecinc@gmail.com Fri, Nov 20, 2020 at 11:07 AM

Hello -

I inspected the North Thompson site on Wednesday. Please see attached report and contact me with comments and/or questions.

Regards, Rob

Rob Zuber, P.E. **Environmental Protection Specialist II** Active Mines Regulatory Program



P 303.866.3567, extension 8113 | Cell 720.601.2276 1313 Sherman Street, Room 215, Denver, CO 80203 rob.zuber@state.co.us | http://mining.state.co.us

INSP-REPORTC_C1981025_RDZ_11202020103808.pdf 546K



PERMIT INFORMATION

Permit Number: C-1981-025	County: Garfield		
Mine Name: North Thompson Creek Mine	Operation Type: Underground		
Operator: MINREC, Inc.	Permit Status: Inactive		
Operator Address:	Ownership: Private		
Mr. Stan Muhr	-		
627 241/2 Road, Unit H	Operator Representative Present:		
Grand Junction, CO 81505			
,	None		
Operator Representative Signature: (Field Issuance Only)			

INSPECTION INFORMATION

Inspection Start Date: November Inspection Start Time: 10:30 Inspection End Date: November Inspection End Time: 12:45			Inspection Type: Coal Complete Inspection Reason: Normal I&E Weather: Clear	•
Joint Inspection Agency:		Joint Inspection Contacts:		
None				
Post Inspection Agency:		Post	Inspection Contacts:	
None				
Inspector(s):	Inspector	r's Sig	nature: S	ignature Date:
Robert Zuber, P.E.	Plet	D.	24	
				11/20/2020

Inspection Topic Summary

NOTE: Y=Inspected N=Not Inspected R=Comments Noted V=Violation Issued NA=Not Applicable

Y - Air Resource Protection Y - Roads

R - Availability of Records **NA** - Reclamation Success

NA - Backfill & Grading
NA - Revegetation

NA - Excess Spoil and Dev. Waste
 NA - Subsidence
 NA - Explosives
 Y - Slides and Other Damage

R - Fish & Wildlife
 R - Hydrologic Balance
 NA - Support Facilities On-site
 R - Signs and Markers

Y - Gen. Compliance With Mine Plan
N - Support Facilities Not On-site
N - Other
NA - Special Categories Of Mining

NA - Processing Waste NA - Topsoil

COMMENTS

A complete inspection was conducted by Rob Zuber of DRMS on November 18, 2020. The weather was windy and hot for November. The ground was covered with snow in shady areas. No MINREC, Inc. representative was present.

No cattle were seen onsite, but cow feces were seen in many places.

The landowner's pump system at Pond T-2 was not operating at the time of the inspection.

AVAILABILITY OF RECORDS – Rule 5.02.4(1):

A check at the Garfield County building in Glenwood Springs revealed that most records for the North Thompson Creek Mine were available. **However, the current insurance document was not found by the DRMS inspector; this should be updated by the end of 2020.** A list of records is provided in this report.

FISH and WILDLIFE – Rule 4.18:

Two ducks were seen in the Long Pond.

HYDROLOGIC BALANCE - Rule 4.05

Drainage Control 4.05.1, 4.05.2, 4.05.3; Siltation Structures 4.05.5, 4.05.6; Discharge Structures 4.05.7, 4.05.10; Diversions 4.05.4; Effluent Limits 4.05.2; Ground Water Monitoring 4.05.13; Surface Water Monitoring 4.05.13; Drainage – Acid and Toxic Materials 4.05.8; Impoundments 4.05.6, 4.05.9; Stream Buffer Zones 4.05.18:

The pipeline across the creek (attached to a bridge) that carries mine water to the treatment system was intact. The cable supports for the pipe have been fixed to keep the pipe stable.

The structures at the west end of the site (south of the creek) were covered with snow.

All of the on-site ponds were inspected: the Long Pond, Treatment Pond T-1, Treatment Pond T-2, the Polishing Pond (Pond P-9), and the Refuse Pond. All but the Refuse Pond were discharging. The flow through the ponds appeared to be somewhat less than the flow at the upper end (pipe from mine above the Long Pond). This could be due to the fact that water has been detained by freezing (ice was seen on surfaces of all of the ponds). The water discharging from Pond 9 was relatively clear, with no mineral staining or odor. No problems were identified with the ponds.

No problems were identified with ditches between the ponds or the aeration ditch above the Long Pond. At the outlet to Pond P-9, the diversion of discharge to the Refuse Pond is functioning well, and there was no discharge to the creek (Outfall 01). The old ditch out of Pond T-2 (with a pipe spillway) was dry; discharge from Pond T-2 flows directly to Pond P-9.

The ditch into the Refuse Pond (which was breeched in September) was functioning. Along its entire length from Pond P-9, it has been cleared of sediment and vegetation to insure that this ditch continues to function.

SIGNS AND MARKERS – Rule 4.02:

Stream buffer signs were seen between the ponds and North Thompson Creek. Entrance signs were in place.

DOCUMENTS RECEIVED - none

OTHER (SPECIFY) - none

ENFORCEMENT ACTIONS/COMPLIANCE

No enforcement actions were initiated as a result of this inspection, nor are any pending.

PHOTOGRAPHS



Flow into aeration ditch at top of treatment system



Treatment Pond T-1, with Treatment Pond T-2 in the background



Flow out of the Polishing Pond (Pond P-9)



Ditch between Pond P-9 and the Refuse Pond



Refuse Pond

AVAILABILITY OF RECORDS

Permit Application w/Revisions Permit Application w/Revisions yes NPDES Records Through October 2020 Findings Document RN7, 9/17/2018 Stormwater Management Plan NA Insurance Certificate Exp. 9/1/2020 SPCC Plan NA Bond Document \$10,000 MSHA Pond Inspections NA Phased Bond Release SL6 (2009)
Permit Application w/Revisions yes NPDES Records Through October 2020 Findings Document RN7, 9/17/2018 Stormwater Management Plan NA Insurance Certificate Exp. 9/1/2020 SPCC Plan NA NA Bond Document \$10,000 MSHA Pond Inspections NA
Findings Document RN7, 9/17/2018 Stormwater Management Plan NA Insurance Certificate Exp. 9/1/2020 SPCC Plan NA Bond Document \$10,000 MSHA Pond Inspections NA
Insurance CertificateExp. 9/1/2020SPCC PlanNABond Document\$10,000MSHA Pond InspectionsNA
Bond Document \$10,000 MSHA Pond Inspections NA
Phased Bond Release SL6 (2009)
Documents/Findings State Engineer's Pond Inspection NA
Air Emission Permits NA, terminated
1990 Quarterly Pond Inspections 3Q 2020
County Special Use Permits 86-12 Annual Hydrology Reports 2019
UG Mining Landowner Notification NA • Ground Water Monitoring no
Subsidence Monitoring Reports NA • Surface Water Monitoring No discharge
Subsidence Monitoring Data NA • Spring & Seep Monitoring no
Rill & Gully Survey May 2020 • Mine Water Discharge Monitoring NA
Vegetation Monitoring Data NA • Mine Inflow Study NA
Annual Reclamation Reports 2019 Well Permits NA Midterm Review Documents MT7, 12/31/2015
DRMS/OSM Inspection Through
Reports/Enforcement Actions (3 September 2020
Years) BLASTING RECORDS
Transfers/Succession of Operator NA Blasting Publication NA
Temporary Cessation Notification NA Blasting Records (3 years) NA
Reclamation Cost Estimate NA ATFE Explosives Permit NA
CERTIFICATIONS Blasting Variances NA
SEE NA
Pond Certifications COMMENT Pre-Blast Surveys
Annual Certifications for Large
Impoundments NA
Fill Certifications for Excess Spoil ADDITIONAL RECORDS
or Underground Development Waste NA (specify)
• Quarterly Inspections NA
• Compaction Testing NA
• Final Certification NA
Coal Processing Waste Banks NA
Haul Road Certifications NA
Access Road Certifications NA

COMMENTS:

Certified inspection reports from November 2019. Also, construction certifications are available in the records. These were stamped by Professional Engineers in the 1980s and 1990s.