STORMWATER ANNUAL REPORT - METAL MINING (& COAL) COLORADO DEPT. OF PUBLIC HEALTH & ENVIRONMENT

Water Quality Control Division WQCD-P-B2 4300 Cherry Creek Drive South Denver, Colorado 80246-1530

Make enough copies of form for each reporting year. Or go to http://www.cdphe.state.co.us/wq/PermitsUnit/stormwater/industrial.html	Check if this is a
Permittee (Company Name): GCC Energy, LLC	new name, address, etc.
Facility Name: King I and King II Mines	
Mailing Address: 6473 County Road 120, Hesperus, CO 81326	
Facility Phone Number: (970) 385-4528	
Permit Certification No. XXXXXX COG-850001	
Reporting Period: Jan. 1-Dec. 31, 20 2 1 (Form is due by Feb. 15 of the follow	ving year)
Each section must be completed. Please print or type.	
A. A report on the facility's overall compliance with the SWMP. (Include here a sto comply with your Stormwater Management Plan (SWMP), to fully impleme made in any of your Best Management Practices (BMPs), employee training, spencountered, etc. How is your plan working?) King I - All coal mining and processing have ceased, and surface processing equipment have	ent it, changes or improvements pills, other problems
site. Coal mine refuse from the King II mine continues to be placed in the CDRMS approved stormwater BMPs (East and West Sediment Ponds & drainage ditches) will remain in placed mining areas. Comprehensive quarterly inspections are performed by a P.E., with monthly inspections completed by company personnel. Any concerns noted during the inspections is working well, and there were no discharges from the permitted outfalls during the reportions.	ed Refuse Pile. All e until final reclamation of the y and semi-annual s are addressed. The system ing year.
King II - The BMPs in the SWMP are being followed by the facility. Quarterly GCCE and a settling pond are conducted, while company personnel conduct monthly and semi-annual in noted during the inspections are addressed. The system is working well, and there were n sedimentation pond during the reporting year. SWMP and SPCC training was conducted in	inspections. Any concerns no discharges from the
Were changes made to your SWMP? X No Yes - Describe changes	nges on a separate sheet.
First Inspection - Date 02 09/21. Findings, and action taken: inspection performs	year - see page 12 of the permit. nspections made. It is not
King I: Both the East and West sediment ponds were snow covered with a thin layer of snow storage in each pond. Sediment control structures throughout the King I facilities were in go the west SAE have been replaced and adequately anchored into the side of the road. King II: A shallow pool of water was present in the King II pond. There was ample storage capperator has recently cleaned CWD-1C West Clear Water Ditch and the SAE at the King II guard. The silt fence at the gravel storage SAE at King II has been replaced and properly instructures throughout the King II facilities are in good condition. Outlets to culverts C16 and its	apacity in this pond. The mine entrance at the cattle stalled. Sediment control

STORMWATER ANNUAL REPORT - METAL MINING (& COAL)

Permit Cert. No. XXXXX COG-850001

- 4404/04 BUT	Please refer to CDRMS inspection report:
Second Inspection - Date 11/04/21 Findings, and action	Binns, Environmental Protection Specialist III
King I: GCC had begun to clean sediment from the sediment ponds	s at King I until a large storm occurred on site. The East pond
sediment had been cleaned out. This pond looked good and has all cleaned of sediment until the pond became too wet to complete the	mple sediment storage capacity. The West pond was partially a clean out. The West pond does have sediment storage
capacity, but GCC hopes to clean it further. Collection ditches at K	Cing I were in good repair and functional. The SAE's on the
West and East sides of the haul road into King I were in adequate the sediment prior to the winter months.	condition. The West side SAE would benefit from clean out of
King II: he sediment Pond at King II was damp but not holding a po	ool of water. The embankments are well vegetated and not
weedy. Sediment storage capacity is still adequate for Pond 1, but bond. The haul road SAE/Gravel storage area Silt fence is holding	t clean out is part of the operator's regular maintenance of the
was cleaned out and appeared to contain adequate storage capaci	ity prior to the winter months. The roads within King II
facilities area were adequately graded and draining to the sedimen	it control system.
Other Inspections - Date// Findings, and action	taken;
Results and interpretation of any stormwater monitoring results. (Monitoring is not a requirement under the pern the Division. However, the results of any stormwater more reported here.)	nit, unless you were specifically directed to do so by onitoring that you performed on your own should be
Monitoring Results Attached? X No Yes	
Certification	
"I certify under penalty of law that this document and all supervision in accordance with a system designed to assit evaluate the information submitted. Based on my inquir those persons directly responsible for gathering the inforknowledge and belief, true, accurate, and complete. I am submitting false information, including the possibility of	ure that qualified personnel properly gather and by of the person or persons who manage the system, or mation, the information submitted is, to the best of my aware that there are significant penalties for
fort (D)	2-14-22
Signature of Permittee (legally responsible person)	Date Signed
Chris Dorenkamp	Mine Manager
Name (printed)	Title

C.

D.