

PERMIT INFORMATION

Permit Number: C-1981-028 Mine Name: Keenesburg Strip Mine Operator: Coors Energy Company Operator Address: Mr. Ben Moline PO Box 4030 Golden, CO 80402 **County:** Weld **Operation Type:** Surface **Permit Status:** Permanent Cessation **Ownership:** Private

Operator Representative Present:

None

Operator Representative Signature: (Field Issuance Only)

INSPECTION INFORMATION

Inspection Start Date: April 6, 2022 Inspection Start Time: 09:50 Inspection End Date: April 6, 2022 Inspection End Time: 11:00			Inspection Type: Coal Partial Inspection Inspection Reason: Normal I&E Program Weather: Windy		
Joint Inspection Agency:		Joint Inspection Contacts:			
None					
Post Inspection Agency:		Post Inspection Contacts:			
None					
Inspector(s):	Inspecto	r's Sig	nature:	Signature Date:	
Robert Zuber, P.E.			Pher	+ D. 24	
			4/9	/2022	

Inspection Topic Summary

NOT	E: Y =Inspected	N=Not Inspected	R =Comments Noted	V=Violation Issued	NA=Not Applicable

- N Air Resource Protection
 N Availability of Records
 NA Backfill & Grading
 NA Excess Spoil and Dev. Waste
 NA Explosives
 N Fish & Wildlife
 R Hydrologic Balance
 R Gen. Compliance With Mine Plan
 N Other
- NA Processing Waste

NA - Roads
Y - Reclamation Success
Y - Revegetation
NA - Subsidence
Y - Slides and Other Damage
N - Support Facilities On-site
R - Signs and Markers
NA - Support Facilities Not On-site
NA - Special Categories Of Mining
NA - Topsoil

COMMENTS

A partial inspection was conducted by Rob Zuber of DRMS on April 6, 2022. No Coors Energy Company (CEC) representative was present at the inspection. The site is in Permanent Cessation. Reclamation activities were completed in the fall of 2020, however, due to poor success in some areas, Coors Energy is now reclaiming these areas a second time. These areas include (but are not limited to):

- The road west of the Dugout Pond
- Part of Area 42
- Large portions of the Long Term Spoil Area (east, west and south)
- The road south of Area 25.

Equipment was seen by the entrance, and large straw bales (and a dozer to move them) were seen at the west end of the Long Term Spoil Area.

The weather was windy, clear, and cool, and the ground was dry.

HYDROLOGIC BALANCE - Rule 4.05

Drainage Control 4.05.1, 4.05.2, 4.05.3; Siltation Structures 4.05.5, 4.05.6; Discharge Structures 4.05.7, 4.05.10; Diversions 4.05.4; Effluent Limits 4.05.2; Ground Water Monitoring 4.05.13; Surface Water Monitoring 4.05.13; Drainage – Acid and Toxic Materials 4.05.8; Impoundments 4.05.6, 4.05.9; Stream Buffer Zones 4.05.18:

The Dugout Pond contained little to no water (thick vegetation obscures the bottom). It was not discharging during the inspection. There were no signs that it had discharged recently. No problems were observed.

Near the southeast corner of the Dugout Pond, the relatively steep hill (where a topsand pond existed in past years) was stable.

The eastern portion of the northern boundary of the site was observed, and no signs of pollutant loading from the mine site, or any other problems, were seen.

SIGNS AND MARKERS – Rule 4.02:

The entrance sign contained all necessary information.

DOCUMENTS RECEIVED - none

OTHER (SPECIFY) - none

ENFORCEMENT ACTIONS/COMPLIANCE

No enforcement actions were initiated as a result of this inspection, nor are any pending.

PHOTOGRAPHS



Tractor with disking implement and another tractor used for placing straw



Dugout Pond spillway behind trailer



Recently reclaimed road by Dugout Pond



Recent reclamation at Long Term Spoil Area and Area 42



Bales on west side of Long Term Spoil Area



Reclamation southeast of Dugout Pond