



STATE OF
COLORADO

Cazier - DNR, Tim <tim.cazier@state.co.us>

Pikeview monitoring report

1 message

Kos, Paul <paul.kos@stantec.com>

Thu, Apr 28, 2022 at 10:06 AM

To: "Tim Cazier, P.E. (Tim.Cazier@state.co.us)" <tim.cazier@state.co.us>

Cc: "Moore, David (Houston)" <David.Moore@stantec.com>

Tim,

Please find attached the Pikeview monitoring report for March. Let me know if you have any questions.

Paul Kos P.E., P.Eng.

Senior Geological Engineer

Mobile: 303 570-9163
paul.kos@stantec.com

Stantec
2000 South Colorado Boulevard Suite 2-300
Denver CO 80222-7933



The content of this email is the confidential property of Stantec and should not be copied, modified, retransmitted, or used for any purpose except with Stantec's written authorization. If you are not the intended recipient, please delete all copies and notify us immediately.



Pikeview Monitoring Memo March2022-final.pdf
5700K

To: Jerald Schnabel From: Paul Kos
Continental Materials Corp. Denver, CO 80222
File: March 2022 Monitoring Summary Date: April 30, 2022

Reference: March 2022 Geotechnical Monitoring Summary Pikeview Quarry

1.0 INTRODUCTION

Stantec Consulting Services Inc. (Stantec) has prepared this March 2022 Geotechnical Monitoring Summary for the Pikeview Quarry. The Pikeview Quarry is situated along the foothills of the Rocky Mountains, northwest of Colorado Springs, Colorado. Continental Materials Corp. (CMC) operates the quarry, which is currently closed, pending reclamation. A geotechnical monitoring program was established to monitor reclamation activities which will affect the geotechnical performance of the existing and reclaimed slopes during and following reclamation grading. This report presents the geotechnical monitoring results for the slope reclamation activities at the site through the month of March 2022. Continuous monitoring by the robotic survey system began in 2010 and has continued through the month March 2022 uninterrupted. Visual inspections of the slopes were performed by CMC employees and Stantec engineers.

1.1 PURPOSE

The purpose of this report is to summarize the March 2022 geotechnical monitoring results and verify the geotechnical performance of the existing and reclaimed slopes with respect to the historical performance record. The goals of the geotechnical instrumentation monitoring program can be described as:


- Meet corporate risk management requirements,
- Provide ongoing slope monitoring and advance warning of any changed conditions that could pose a hazard to workers or to the public,
- Document the geotechnical performance of the slope, and
- Document monthly site grading activities and construction quality assurance.

1.2 MONITORING SUMMARY

Major components of the instrumentation monitoring program are listed in Table 1 and shown on Figure 1.

Table 1 Monitoring Frequency

| Monitoring Type | Frequency |
|--------------------------|------------------------------------|
| Visual inspection | Daily (CMC) and Monthly (Stantec) |
| Robotic theodolite/prism | Continuous |
| Drone inspection | Monthly |
| Compaction testing | Every 5,000 yd ³ (min.) |




2.0 VISUAL INSPECTIONS

Inspections are completed daily by site personnel and monthly by Stantec personnel to document visual observations of slope conditions, including conditions of instability (i.e., cracking, slumping, over-steepened slopes, seeps, perched boulders, rock falls, erosion, and areas undercut by construction or maintenance activities). Certain areas of the landslide have been designated as safety exclusion zones, and these areas are inspected from adjacent locations.

When present, site operators inspect their work areas for signs of instability on a daily basis before starting work per site safety rules and regulations. The daily inspection starts by reviewing any prism alerts/alarms and inspecting those areas before work begins in that area. The daily inspection also includes visual observations of the quarry walls and floor for any changes. No changes to the quarry conditions were identified during daily inspections in March 2022. The notes from the daily inspections are included in Table A-1 in Appendix A.

Stantec conducted visual inspections of the Pikeview Quarry slopes on March 29, 2022. The engineering inspections were conducted by traversing each area of the mine and observing the uphill slope and the downhill slope for signs of instability, and areas in need of maintenance. Slopes that have been graded and are 2 horizontal (H):1 vertical (V) or shallower are also traversed on foot. The findings are listed below, and photographs of notable observations are included on Figure 2 in Appendix A.

- Reclamation grading began in February 2022 and continued throughout March.
- A buffer zone is being kept between the active work areas and the toe of the slide to safely stop any loose rocks that might come loose and roll down the slope during grading operations. Compacted fill is placed in the buffer zone as the buttress fill is placed, and this area is maintained approximately 5 feet lower than the working bench. (Photo 1)
- The temporary fill stockpile has been removed and placed as compacted fill. The material was spread by dozers and compacted in one-foot lifts in accordance with the project specifications. (Photo 2)
- Three excavators, five dozers and eight haul trucks are operating in a loop on the pit floor to move material from the North Borrow Area to the pit floor for compaction in one-foot lifts. Note that the North Borrow Area is a separate project associated with the City's future plans for the property; this grading was permitted by El Paso County. (Photos 3 and 4)
- Fill material continues to be delivered to the central location on the production floor where it was temporarily placed. Future fill material will not be stockpiled; it will be directly placed, spread, and compacted. (Photo 5)
- A dozer is pushing material down the slope of the south borrow area and into the pit near the reclamation benches on the south-end of the site. The fill is placed in one-foot compacted lifts. (Photo 6)
- Several prisms are being removed and new prisms are coming online as grading progresses, and the line of sight is cut-off between some of the prisms and the station. (Photo 7)
- Riprap has been produced and stockpiled at several locations on site. (Photo 8)
- No cracking was observed on the native granite slopes above the extents of the disturbed area.
- Previously Observed Cracks: Previously observed tension cracks remain on the production floor and at the crest of fill slopes. These cracks appeared the same as in previous inspections.
- Older cracks and recent cracks are being monitored for changes. Currently the cracks are not growing in any of the areas on the slopes of the site. The hummocky field in the area immediately above the



southern extent of the slide shows evidence of cracking but they are not fresh or active. No new or open cracks were found immediately inside or next to the slide area.

- The culvert remains cleared but mostly blocked inside. CMC has partially cleared the debris, but access limitations and supports within the culvert inhibit clearing all the debris. CMC has procured a pump and will begin pumping operations if any water collects behind the culvert. CMC inspects the culvert for ponded water following rain events, and should any water be observed, it will be removed using pumps. To date, no ponding has been observed.
- Visual inspections of the Pikeview Quarry did not reveal any evidence of large-scale instability outside of the landslide areas previously identified. No bulging, rippling, over-steepening, depressions, slumps, or dry slip-offs were observed in areas that have been graded and/or reclaimed.


3.0 PRISM SURVEY

A Leica Robotic station is used to continuously survey the prisms onsite to document slope movements. The station records the location of each prism every hour. There are currently 18 active prisms; 3 prisms are control points located outside the slope movement area, 13 prisms are located on the slopes surrounding the landslide area, and 2 prisms are located at the toe of the landslide. As the slope is backfilled and graded, the existing prisms will be removed, and additional prisms will be installed. In March, 5 prisms were removed because the reclamation grading was going to affect their locations. Two of the prisms were control points, and the control points were replaced with new control prisms. Prism TS1 was added in March. Prism NP1 was removed in anticipation of grading in that area; this grading has been delayed and the prism will be reinstated at its original location. A log of prism removals and installations is included in Appendix B. The prism locations are shown on the current topography in Figure 3, and the proposed prism locations are shown on the reclamation topography in Figure 4. Both figures are included in Appendix B.

The monitoring software, GeoMos, has been programed to provide automatic alarms if there is a movement recorded that is greater than 0.35 feet or if a prism cannot be located. The alarm notes and actions taken are logged, and the alarms are summarized in Table 2. Following each alarm, CMC clears the area of concern until the data can be reviewed and the slope can be inspected. CMC made sure that there were no workers in the area before inspecting the slope. During March 2022, movement alarms were received from prisms NP2, P32, and P33; however, when the prisms were inspected, there were no signs of slope movements. In each case, the subsequent readings returned to normal, and the alarm is assumed to be a data error related to weather conditions. Readings in early March could not be recorded, and this was related to the power outage that disrupted readings in late February. All other alarms were determined to be caused by weather.

Table 2 Alarm Summary


| Date(s) | Alarm | Cause/Actions taken | Issue Resolved |
|-----------------------|---|--|----------------|
| 03/01/2022-03/04/2022 | Compensator out of range/no communication/no readings | Issues related to power outages | 03/04/2022 |
| 03/05/2022 | Several prisms could not be found on multiple scans | Fog and frost blocked prisms | 03/05/2022 |
| 03/06/2022-03/08/2022 | Several prisms could not be found on multiple scans | Fog and snow blocked prisms | 03/08/2022 |
| 03/09/2022-03/10/2022 | Several prisms could not be found on multiple scans | Snow blocked prisms. Operations halted due to snow | 03/10/2022 |
| 03/09/2022 | Regression limit exceeded P32 | No sign of movement after inspection | 03/09/2022 |



| | | | |
|-----------------------|---|--|------------|
| 03/10/2022 | Compensator out of range/points not found | Snow and fog blocked prisms | 03/10/2022 |
| 03/11/2022 | Points not found: CP2, CP3, NP1, TOE2 | Prisms removed due to grading activities | 03/11/2022 |
| 03/11/2022 | Regression limit exceeded P32 | Data error. No sign of movements after inspection. One reading was -0.391' followed by a reading of +0.382'. | 03/11/2022 |
| 03/11/2022 | Regression limit exceeded NP2 | No sign of movements after inspection. | 03/11/2022 |
| 03/14/2022 | Several prisms could not be found on multiple scans | Fog and frost | 03/14/2022 |
| 03/15/2022-03/16/2022 | Regression limit exceeded P33 | Data error. No sign of movements after inspection. One reading was -0.466 followed by a reading of +0.371 | 03/16/2022 |
| 03/16/2022 | Regression limit exceeded P32 | No sign of movements after inspection. | 03/16/2022 |
| 03/17/2022 | Several prisms could not be found on multiple scans | Power outage, snow, no work occurring | 03/17/2022 |
| 03/18/2022 | TOE3 not found | Blocked by fill placement | 03/18/2022 |
| 03/21/2022 | Several points not found | Fog | 03/21/2022 |
| 03/22/2022 | Compensator out of range/points not found | Snow and fog | 03/22/2022 |
| 03/25/2022 | P69 not found | Unknown cause. Single reading after work hours | 03/25/2022 |
| 03/27/2022 | Regression limit exceeded P33 | Data error. No sign of movements after inspection. One reading was +0.371 followed by a reading of -0.372 | 03/27/2022 |
| 03/28/2022 | TOE3 not found | Blocked by fill placement. Prism removed. | 03/28/2022 |
| 03/29/2022-3/30/2022 | Points not found | Snow and fog | 03/30/2022 |

The prism monitoring results for transverse and height displacements, monthly change, and cumulative change are summarized in Table 3 below. The transverse displacement measures the change in the horizontal distance from the robotic station to the prism; positive displacements indicate less distance between the station and prism (movement towards the total station). The height displacement measures the change in the vertical distance from the robotic station to the prism; positive displacements indicate upward movement. The values for the last reading in the month are included in Table 3. The monthly delta is the most recent reading cumulative delta displacement (horizontal, lateral, and vertical) subtracted from the last reading from the previous month. The cumulative delta values are a total displacement and are not associated with a direction. The transverse, height, and cumulative delta displacements are the total displacement over the life of the monitoring, which has been several years for all the prisms except P69. Prism P69 was moved on June 20, 2020, and the displacements included in Table 3 are the displacements since that date. According to Leica documentation, the survey accuracy is $\pm 4 \text{ mm} + 1.5 \text{ ppm}$ for prisms located greater than 500m from the station; these equates to an accuracy of $\pm 0.016 \text{ ft}$.

The data show stable conditions with no movement for 20 of 23 prisms with recorded displacements limited to data scatter and not actual movements. Prisms P63 and TOE3 are located at the toe of the landslide, and these locations showed slope creep movements at slow velocities. Prism NP66 is located above the landslide, and this prism also recorded slope creep movements at slow velocity. This settlement is likely




related to the landslide material consolidating under its own weight. Plots of the transverse and height displacements for each prism are included in Appendix B.

Table 3 Prism Summary

| Prism ID | Cumulative Transverse Displacement (ft) | Cumulative Height Displacement (ft) | Monthly Delta (ft) | Cumulative Delta (ft) | Notes / Recommendations |
|-----------------|--|--|---------------------------|------------------------------|--|
| CP1 | -0.001 | -0.038 | -0.0474 | 0.3503 | |
| CP2 | -0.060 | 0.018 | 0.0220 | 0.4177 | Prism removed 3-11 |
| CP3 | 0.297 | -0.227 | 0.0296 | 0.3773 | Prism removed 3-11 |
| CP4 | 0.673 | -0.923 | 0.0225 | 1.1436 | New Prism |
| CP5 | 0.104 | -0.109 | 0.0440 | 0.2070 | New Prism |
| NP1 | 0.594 | -0.825 | 0.0469 | 1.2423 | Prism removed 3-11 |
| NP2 | 0.342 | -0.063 | -0.0474 | 0.3503 | |
| NP66 | 0.138 | -0.041 | -0.0143 | 0.2228 | Slope creep movements. |
| P1 | -0.013 | 0.025 | 0.0509 | 0.1782 | |
| P2 | -0.068 | -0.091 | 0.0439 | 0.3022 | |
| P25 | -0.100 | -0.061 | 0.0652 | 0.2318 | |
| P32 | 0.021 | -0.191 | 0.0204 | 0.4528 | |
| P33 | 0.366 | -0.144 | -0.0138 | 0.4947 | |
| P35 | 0.395 | -0.163 | -0.0020 | 0.6345 | |
| P4 | 15.839 | -6.490 | 0.0049 | 17.1174 | |
| P5 | 0.004 | -0.067 | 0.0100 | 0.6289 | |
| P63 | 0.338 | -0.340 | -0.0144 | 0.1683 | Slope creep movements. |
| P69 | 0.156 | 0.020 | -0.0144 | 0.1683 | |
| P70 | 0.668 | -0.665 | -0.0094 | 0.9734 | |
| TOE1 | 3.679 | -1.868 | 0.0300 | 4.3315 | |
| TOE2 | 0.006 | -0.028 | -0.0074 | 0.0293 | Prism removed 3-11 |
| TOE3 | 0.025 | -0.064 | 0.0484 | 0.0701 | Slope creep movements. Prism removed 3-11. |
| TS1 | 0.007 | -0.019 | 0.0207 | 0.0271 | New Prism |

4.0 DRONE SURVEY

The site was flown for aerial imagery using an unmanned aircraft system (UAS or 'drone') on, March 28, 2022. The imagery was inspected for signs of instability and used to supplement the onsite visual inspections. Features noted in the aerial imagery review were inspected during Stantec's engineering inspection and are summarized in Section 2 above. The imagery was also used to create site topography.



The February topography was also compared to the March topography to identify changes in the site topography. Comparison of the two surveys showed the placement of the fill material at the toe of the landslide. Fill material is excavated from the South Borrow Area or imported from offsite projects, including the North Borrow Area. No slope movements or other changes in topography were identified. The current imagery and topography are included in Figures 1 and 3, and the comparison surface is included as Figure 5 in Appendix C.

As previously reported in the September 2020 monitoring report, there are limitations with the method of comparing drone surveys from different months. The drone data indicate changes in the slopes along each of the reclamation benches, buildings, and areas with trees or shrubs. These areas are stable, and the changes are the result of survey limitations on or near vertical slopes.

5.0 COMPACTION TESTING

Fill placement started on February 25, 2022 and continued throughout March. The grading commencing by spreading the temporary fill stockpile followed by transporting material from the South Borrow Area and North Borrow Area. Importing fill also continued. Fill was placed in one-foot lifts, moisture conditioned as necessary, and compacted. Compaction testing began March 2022 and will continue at the rate of at least one test per 5,000 yd³ placed. During February and March, approximately 220,000 yd³ had been placed and compacted. This required at least 44 compaction tests, and 64 compaction tests were recorded. All tests met or exceeded the minimum compaction requirement of 90% of the optimal density as measured by a Standard Proctor Test. The compaction testing results are summarized in Appendix D, and the testing locations are shown on Figure 6.

6.0 RECLAMATION PROGRESS

CMC has initiated reclamation grading at the Pikeview Quarry and has contracted with Stantec to provide EPCM services through completion. As an updated feature of our monthly report, we will provide progress of activities, anticipated milestone schedule and a one month look ahead to better communicate project objectives. A phased or 'gated' approach will be used to complete the reclamation process going forward (See milestone schedule below)


Phase 1 - Value Engineering and issue RFP to qualified Contractors

Phase 2 - Commercial negotiations with successful contractor

Phase 3 - Execution planning and Contractor readiness review

Phase 4 - Site Construction execution

Phase 5 - Final revegetation (season 2)



| Task/Milestone | Estimated Dates |
|---|----------------------------|
| Phase 1 – Issue RFP to Bidders | Completed June 2021 |
| Phase 1 – RFP Evaluation & Recommendation | Completed July 2021 |
| Phase 2 – Constructor Contract Award | Completed January 2022 |
| Phase 3 – Project Kick-off with successful Contractor | Completed February 4, 2022 |
| Phase 4 – Contractor Mobilization to Site | Completed February 2022 |
| Phase 4 – Reclamation Grading | February 2022 to present |
| Phase 4 – Contractor Demobilize from Site | Fall 2023 |
| Phase 5 – Final Revegetation season 2 Begins | 2023 until acceptance |

Progress of activities this month:

- Contractor continued earth moving activities
- Quality assurance testing initiated
- Importing fill material continued
- Geotechnical monitoring continued
- Begin removal of existing prisms and replacement with new prisms.

Work planned for next month includes:

- Continue reclamation grading
- Continue importing fill material
- Continue geotechnical monitoring
- Continue quality assurance testing
- Continue removing and replacing prisms on an as-needed basis

7.0 CONCLUSIONS

The data collected in March 2022 demonstrate compliance with the reclamation grading plan. The buttress fill is being placed as intended and specified; this includes one-foot-thick compacted lifts.


None of the data collected in March 2022 indicate evidence of any large-scale movements that increase risk to workers or to the public. The landslide area continues to show slope creep movements with slow velocities. Shallow surface erosion continues to occur requiring ongoing maintenance and cleanup.

- Restricted access to the ungraded landslide slopes should continue.
- All monitoring should continue at current frequencies.
- All alarms shall continue to be taken seriously even if data errors are suspected.



\\us0321-pplss01\workgroup\2274\active\227419041\dlsc\monitoring\2022\2022-03\dwg\pkreview\pkreview_04132022


2022.04.13 8:36:32 PM



Stantec Consulting Services Inc.
2000 South Colorado Boulevard Suite 2-300
Denver CO 80222-7933
Tel: (303) 758-4058
www.stantec.com

LEGEND

- Permit/Affected Lands Boundary
- City Grading Permit Boundary
- Proposed Disturbance Limit
- Landslide Extent
- Buttress Fill Extent
- Existing Prism
- Removed Prism



Client/Project

CONTINENTAL MATERIALS
CORP.
PIKEVIEW QUARRY SLOPE
MONITORING

Project No.
2057288200

Title

SITE MAP

Revision
#

Drawn By
PK

Date
2022.04.30

Figure No.
1

Appendix A

Visual Inspections





Table A-1 Summary of Daily Inspections

| Date | Notes | Inspection By |
|----------------|--|----------------------|
| March 1, 2022 | Power failure at Leica. No movements detected. | Jerald Schnabel |
| March 2, 2022 | Power failure at Leica. No movements detected. | Jerald Schnabel |
| March 3, 2022 | Power failure at Leica. No movements detected. | Jerald Schnabel |
| March 4, 2022 | Power failure at Leica. No movements detected. | Jerald Schnabel |
| March 5, 2022 | No Movement observed. Good to proceed. | Jerald Schnabel |
| March 6, 2022 | Snow and Fog. No movements detected. | Jerald Schnabel |
| March 7, 2022 | Fog Conditions. No movements detected. | Jerald Schnabel |
| March 8, 2022 | Snow. No movements detected. | Jerald Schnabel |
| March 9, 2022 | Snow and Fog. No movements detected. | Jerald Schnabel |
| March 10, 2022 | No Movement observed. Good to proceed. | Jerald Schnabel |
| March 11, 2022 | No Movement observed. Good to proceed. | Jerald Schnabel |
| March 12, 2022 | No Movement observed. Good to proceed. | Jerald Schnabel |
| March 13, 2022 | No Movement observed. Good to proceed. | Jerald Schnabel |
| March 14, 2022 | Snow. No movements detected. | Jerald Schnabel |
| March 15, 2022 | No Movement observed. Good to proceed. | Jerald Schnabel |
| March 16, 2022 | No Movement observed. Good to proceed. | Jerald Schnabel |
| March 17, 2022 | No Movement observed. Good to proceed. | Jerald Schnabel |
| March 18, 2022 | No Movement observed. Good to proceed. | Jerald Schnabel |
| March 19, 2022 | No Movement observed. Good to proceed. | Jerald Schnabel |
| March 20, 2022 | No Movement observed. Good to proceed. | Jerald Schnabel |
| March 21, 2022 | No Movement observed. Good to proceed. | Jerald Schnabel |
| March 22, 2022 | No Movement observed. Good to proceed. | Jerald Schnabel |
| March 23, 2022 | No Movement observed. Good to proceed. | Jerald Schnabel |
| March 24, 2022 | No Movement observed. Good to proceed. | Jerald Schnabel |
| March 25, 2022 | No Movement observed. Good to proceed. | Jerald Schnabel |
| March 26, 2022 | No Movement observed. Good to proceed. | Jerald Schnabel |
| March 27, 2022 | No Movement observed. Good to proceed. | Jerald Schnabel |
| March 28, 2022 | No Movement observed. Good to proceed. | Jerald Schnabel |
| March 29, 2022 | No Movement observed. Good to proceed. | Jerald Schnabel |
| March 30, 2022 | Snow. No movements detected. | Jerald Schnabel |
| March 31, 2022 | Snow and Fog. No movements detected. | Jerald Schnabel |



v:\2274\active\227419041\disc\monitoring\2022\2022-03\dwg\p\review\p\figs_04182022 2022.04.28 9:57:17 AM



6. Dozer pushing material at south borrow area.



5. View to the south: Pit floor and south borrow.

NOTE 1:
NO CRACKS

NOTE 1:
NO CRACKS




4. Excavator, dozer and haul trucks at borrow area



3. View of the north borrow area to the northeast.



7. TOE-3 Prism removed as pit floor rises.



2. Sheep's foot compactor in the pit area.



8. Riprap stockpiled at the south-end near top of ramp.



1. Safety buffer between toe of slope and work area.




Stantec Consulting Services Inc.
2000 South Colorado Boulevard Suite 2-300
Denver CO 80222-7933
Tel: (303) 758-4358
www.stantec.com

LEGEND

- Permit/Affected Lands Boundary
- City Grading Permit Boundary
- Proposed Disturbance Limit
- Landslide Extent
- Butress Fill Extent
- Observed Crack

NOTES

1. NO CRACKS OBSERVED IN THIS AREA.
2. ALL PHOTOS TAKEN MARCH 29, 2021.



Client/Project

CONTINENTAL MATERIALS
CORP.
PIKEVIEW QUARRY SLOPE
MONITORING

Project No.

2057288200

Title

OBSERVATIONS FROM
MARCH INSPECTION

Revision
#

Drawn By
PK

Date


2022.04.30

Figure No.


2

Appendix B

Prism Survey



\\us0321-pptss01\workgroup\2274\active\227419041\disc\monitoring\2022\2022-03\dwg\pikeview prisms_04132022
2022.04.13 8:37:20 PM



Stantec Consulting Services Inc.
2000 South Colorado Boulevard Suite 2-300
Denver CO 80222-7933
Tel: (303) 758-4058
www.stantec.com

LEGEND

- Permit/Affected Lands Boundary
- City Grading Permit Boundary
- Proposed Disturbance Limit
- Landslide Extent
- Buttress Fill Extent
- Existing Prism
- Removed Prism

1. GRADING AND MOVEMENT OF STATION WILL BE EXTENDED AS LONG AS POSSIBLE.
2. PRISMS WILL BE INSTALLED AS EACH BENCH IS FINISHED.
3. ALL PRISMS WILL BE RETAINED AS LONG AS POSSIBLE.
4. TOPOGRAPHY FROM MARCH 28, 2022 DRONE SURVEY.
5. CONTOUR INTERVAL IS 10 FEET

Client/Project

CONTINENTAL MATERIALS
CORP.
PIKEVIEW QUARRY SLOPE
MONITORING

Project No.
2057288200

Title

EXISTING PRISMS WITH
CURRENT SURFACE


Revision
#

Drawn By
PK

Date
2022.04.30

Figure No.
3

\\us0321-pptss01\workgroup\2274\active\227419041\disc\monitoring\2022\2022-03\dwg\pikeview prisms_04132022 2022.04.13 8:37:50 PM



Stantec Consulting Services Inc.
2000 South Colorado Boulevard Suite 2-300
Denver CO 80222-7933
Tel: (303) 758-4058
www.stantec.com

LEGEND

- Permit/Affected Lands Boundary
- City Grading Permit Boundary
- Proposed Disturbance Limit
- Landslide Extent
- Buttress Fill Extent
- Proposed Prism

NOTES

1. GRADING AND MOVEMENT OF STATION WILL BE EXTENDED AS LONG AS POSSIBLE.
2. PRISMS WILL BE INSTALLED AS EACH BENCH IS FINISHED.
3. ALL PRISMS WILL BE RETAINED AS LONG AS POSSIBLE.

Client/Project

CONTINENTAL MATERIALS
CORP.
PIKEVIEW QUARRY SLOPE
MONITORING

Project No.

2057288200

Title

PROPOSED PRISMS WITH
RECLAMATION SURFACE

Revision
#


Drawn By
PK

Date
2022.04.30



Figure No.
4

Prism Log

| Prism | Date | Action | Comment |
|-------|-----------|---------------|---|
| CP2 | 11-Mar-22 | Prism Removed | Reclamation grading to affect prism in near future |
| CP3 | 11-Mar-22 | Prism Removed | Reclamation grading to affect prism in near future |
| NP1 | 11-Mar-22 | Prism Removed | Reclamation grading to affect prism in near future |
| TOE2 | 11-Mar-22 | Prism Removed | Reclamation grading to affect prism in near future |
| CP4 | 11-Mar-22 | Prism Added | Control Point Replacement |
| CP5 | 11-Mar-22 | Prism Added | Control Point Replacement |
| TS1 | 12-Mar-22 | Prism Added | New Prism Added |
| TOE3 | 30-Mar-22 | Prism Removed | Reclamation grading to affect buffer filling activities |



Prism CP1





Notes:

1. Survey accuracy is ± 0.016 feet.
2. Alarm threshold is ± 0.35 feet.
3. Transverse displacement is in the horizontal direction. Positive direction means closer to the robotic station.
4. Height displacement is in the vertical direction. Positive direction means higher in elevation.



Prism CP2





Notes:

1. Survey accuracy is ± 0.016 feet.
2. Alarm threshold is ± 0.35 feet.
3. Transverse displacement is in the horizontal direction. Positive direction means closer to the robotic station.
4. Height displacement is in the vertical direction. Positive direction means higher in elevation.
5. Prism removed March 11, 2022 but reinstalled until March 16 when CP4 and CP5 could replace the control prism. The height displacement recorded is the result of the prism being removed and then replaced.




Prism CP3





Notes:

1. Survey accuracy is +/-0.016 feet.
2. Alarm threshold is +/-0.35 feet.
3. Transverse displacement is in the horizontal direction. Positive direction means closer to the robotic station.
4. Height displacement is in the vertical direction. Positive direction means higher in elevation.
5. Prism removed March 11, 2022.




Prism CP4





Notes:

1. Survey accuracy is ± 0.016 feet.
2. Alarm threshold is ± 0.35 feet.
3. Transverse displacement is in the horizontal direction. Positive direction means closer to the robotic station.
4. Height displacement is in the vertical direction. Positive direction means higher in elevation.
5. Prism installed March 11, 2022.



Prism CP5





Notes:

1. Survey accuracy is +/-0.016 feet.
2. Alarm threshold is +/-0.35 feet.
3. Transverse displacement is in the horizontal direction. Positive direction means closer to the robotic station.
4. Height displacement is in the vertical direction. Positive direction means higher in elevation.
5. Prism installed March 11, 2022.




Prism NP1





Notes:

1. Survey accuracy is ± 0.016 feet.
2. Alarm threshold is ± 0.35 feet.
3. Transverse displacement is in the horizontal direction. Positive direction means closer to the robotic station.
4. Height displacement is in the vertical direction. Positive direction means higher in elevation.
5. Prism removed March 11, 2022.



Prism NP2





Notes:

1. Survey accuracy is ± 0.016 feet.
2. Alarm threshold is ± 0.35 feet.
3. Transverse displacement is in the horizontal direction. Positive direction means closer to the robotic station.
4. Height displacement is in the vertical direction. Positive direction means higher in elevation.
5. A regression limit alarm was received on March 11.




Prism NP66





Notes:

1. Survey accuracy is ± 0.016 feet.
2. Alarm threshold is ± 0.35 feet.
3. Transverse displacement is in the horizontal direction. Positive direction means closer to the robotic station.
4. Height displacement is in the vertical direction. Positive direction means higher in elevation.
5. Prism records slope creep movements with slow velocity.




Prism P1





Notes:

1. Survey accuracy is ± 0.016 feet.
2. Alarm threshold is ± 0.35 feet.
3. Transverse displacement is in the horizontal direction. Positive direction means closer to the robotic station.
4. Height displacement is in the vertical direction. Positive direction means higher in elevation.



Prism P2





Notes:

1. Survey accuracy is ± 0.016 feet.
2. Alarm threshold is ± 0.35 feet.
3. Transverse displacement is in the horizontal direction. Positive direction means closer to the robotic station.
4. Height displacement is in the vertical direction. Positive direction means higher in elevation.




Prism P25





Notes:

1. Survey accuracy is ± 0.016 feet.
2. Alarm threshold is ± 0.35 feet.
3. Transverse displacement is in the horizontal direction. Positive direction means closer to the robotic station.
4. Height displacement is in the vertical direction. Positive direction means higher in elevation.
5. Alarm recorded on February 13, 2022. Attributed to wildlife in the area.




Prism P32





Notes:

1. Survey accuracy is ± 0.016 feet.
2. Alarm threshold is ± 0.35 feet.
3. Transverse displacement is in the horizontal direction. Positive direction means closer to the robotic station.
4. Height displacement is in the vertical direction. Positive direction means higher in elevation.
5. Alarm recorded on February 10, 2022. Assumed to be data error from inclement weather.
6. Regression limit alarms were received on March 9, 11, and 17.




Prism P33





Notes:

1. Survey accuracy is ± 0.016 feet.
2. Alarm threshold is ± 0.35 feet.
3. Transverse displacement is in the horizontal direction. Positive direction means closer to the robotic station.
4. Height displacement is in the vertical direction. Positive direction means higher in elevation.
5. Regression limit alarms were received on March 16 and 27.




Prism P35





Notes:

1. Survey accuracy is ± 0.016 feet.
2. Alarm threshold is ± 0.35 feet.
3. Transverse displacement is in the horizontal direction. Positive direction means closer to the robotic station.
4. Height displacement is in the vertical direction. Positive direction means higher in elevation.
- 5.



Prism P4





Notes:

1. Survey accuracy is ± 0.016 feet.
2. Alarm threshold is ± 0.35 feet.
3. Transverse displacement is in the horizontal direction. Positive direction means closer to the robotic station.
4. Height displacement is in the vertical direction. Positive direction means higher in elevation.




Prism P5





Notes:

1. Survey accuracy is ± 0.016 feet.
2. Alarm threshold is ± 0.35 feet.
3. Transverse displacement is in the horizontal direction. Positive direction means closer to the robotic station.
4. Height displacement is in the vertical direction. Positive direction means higher in elevation.




Prism P63





Notes:

1. Survey accuracy is ± 0.016 feet.
2. Alarm threshold is ± 0.35 feet.
3. Transverse displacement is in the horizontal direction. Positive direction means closer to the robotic station.
4. Height displacement is in the vertical direction. Positive direction means higher in elevation.
5. Prism records slope creep movements with slow velocity.



Prism P69





Notes:

1. Survey accuracy is ± 0.016 feet.
2. Alarm threshold is ± 0.35 feet.
3. Transverse displacement is in the horizontal direction. Positive direction means closer to the robotic station.
4. Height displacement is in the vertical direction. Positive direction means higher in elevation.



Prism P70





Notes:

1. Survey accuracy is ± 0.016 feet.
2. Alarm threshold is ± 0.35 feet.
3. Transverse displacement is in the horizontal direction. Positive direction means closer to the robotic station.
4. Height displacement is in the vertical direction. Positive direction means higher in elevation.




Prism TOE1





Notes:

1. Survey accuracy is ± 0.016 feet.
2. Alarm threshold is ± 0.35 feet.
3. Transverse displacement is in the horizontal direction. Positive direction means closer to the robotic station.
4. Height displacement is in the vertical direction. Positive direction means higher in elevation.



Prism TOE2





Notes:

1. Survey accuracy is ± 0.016 feet.
2. Alarm threshold is ± 0.35 feet.
3. Transverse displacement is in the horizontal direction. Positive direction means closer to the robotic station.
4. Height displacement is in the vertical direction. Positive direction means higher in elevation.
5. Prism removed March 11, 2022.



Prism TOE3





Notes:

1. Survey accuracy is ± 0.016 feet.
2. Alarm threshold is ± 0.35 feet.
3. Transverse displacement is in the horizontal direction. Positive direction means closer to the robotic station.
4. Height displacement is in the vertical direction. Positive direction means higher in elevation.
5. Prism located at toe of slide where ongoing slope creep movements at slow velocity are expected.
6. Prism removed March 30.




Prism TS1




Notes:

1. Survey accuracy is ± 0.016 feet.
2. Alarm threshold is ± 0.35 feet.
3. Transverse displacement is in the horizontal direction. Positive direction means closer to the robotic station.
4. Height displacement is in the vertical direction. Positive direction means higher in elevation.
5. Prism installed March 12, 2022.




Appendix C

Drone Survey



\\us0321-pplss01\workgroup\2274\active\2274\9041\dlsc\monitoring\2022\2022-03\dwg\pkreview\pkreview_04132022

2022.04.13 8:38:23 PM



Stantec Consulting Services Inc.
2000 South Colorado Boulevard Suite 2-300
Denver CO 80222-7933
Tel: (303) 758-4058
www.stantec.com

LEGEND

- Permit/Affected Lands Boundary
- City Grading Permit Boundary
- Proposed Disturbance Limit
- Landslide Extent
- Buttress Fill Extent
- Comparison Contour. Increase in elevation. (CI=2')
- Comparison Contour. Decrease in elevation. (CI=2')

1. COMPARISON OF DRONE FLIGHTS FROM 02/15/2022 and 03/28/2022.

Client/Project

CONTINENTAL MATERIALS
CORP.
PIKEVIEW QUARRY SLOPE
MONITORING

Project No.
2057288200

Title

EXISTING PRISMS WITH
CURRENT SURFACE

Revision
#


Drawn By
PK

Date
2022.04.30

Figure No.
5


Appendix D

Compaction Testing Results




Compaction Testing Log

| BCC Test | CTL Test | Date | Elevation (ft) | Northing (ft) | Easting (ft) | Wet Density (pcf) | Moisture Content (%) | Dry Density (pcf) | Compaction (%) |
|----------|----------|--------|----------------|---------------|--------------|-------------------|----------------------|-------------------|----------------|
| Test A1 | #1 | 1-Mar | - | - | - | 122 | 10.5 | 110.4 | 90 |
| Test A2 | #2 | 1-Mar | - | - | - | 126.5 | 7.1 | 118.1 | 90 |
| Test A3 | #3 | 1-Mar | - | - | - | 122.9 | 7.6 | 114.2 | 93 |
| Test A4 | #4 | 1-Mar | - | - | - | 120.4 | 7.9 | 111.6 | 91 |
| Test A5 | #5 | 1-Mar | - | - | - | 122.8 | 8.7 | 113 | 92 |
| Test A6 | #6 | 1-Mar | - | - | - | 121.4 | 8.4 | 112 | 91 |
| Test A7 | #7 | 1-Mar | - | - | - | 121.5 | 10.3 | 110.2 | 90 |
| Test A8 | #8 | 1-Mar | - | - | - | 130.6 | 7.9 | 121 | 92 |
| Test B1 | #9 | 2-Mar | - | - | - | 106.5 | 11.5 | 95.5 | 99 |
| Test B2 | #10 | 2-Mar | - | - | - | 123.1 | 6.9 | 115.2 | 94 |
| Test B3 | #11 | 2-Mar | - | - | - | 124 | 4.1 | 119.1 | 91 |
| Test B4 | #12 | 2-Mar | - | - | - | 119.3 | 7.4 | 111.1 | 90 |
| Test B5 | #13 | 2-Mar | - | - | - | 102.7 | 7.2 | 112.6 | 92 |
| Test B6 | #14 | 2-Mar | - | - | - | 106.4 | 11.8 | 95.2 | 99 |
| Test B7 | #15 | 2-Mar | - | - | - | 102.8 | 14.7 | 89.6 | 93 |
| Test B8 | #16 | 2-Mar | - | - | - | 119.6 | 8.3 | 110.4 | 90 |
| Test C1 | #17 | 4-Mar | 7192 | 1401242 | 3173593 | 120.5 | 6.9 | 113.7 | 93 |
| Test C2 | #18 | 4-Mar | 7192 | 1401347 | 3173422 | 115.2 | 8.2 | 107 | 100 |
| Test C3 | #19 | 4-Mar | 7190 | 1401585 | 3173529 | 115.7 | 13.8 | 101.8 | 96 |
| Test C4 | #20 | 4-Mar | 7191 | 1401780 | 3173529 | 122.1 | 7.7 | 114.4 | 93 |
| Test C5 | #21 | 4-Mar | 7192 | 1401873 | 3173410 | 119.2 | 7.4 | 111.8 | 91 |
| Test D1 | #22 | 8-Mar | 7190 | 1401501 | 3173679 | 120.8 | 11.2 | 108.6 | 90 |
| Test D2 | #23 | 8-Mar | 7190 | 1401622 | 3173642 | 119.2 | 7.9 | 111.3 | 91 |
| Test D3 | #24 | 8-Mar | 7190 | 1401718 | 3173630 | 119.6 | 11 | 108.6 | 90 |
| Test D4 | #25 | 8-Mar | 7195 | 1402062 | 3173332 | 115.8 | 11.5 | 104.3 | 99 |
| Test D5 | #26 | 8-Mar | 7200 | 1402142 | 3173278 | 119.2 | 11.4 | 107.8 | 90 |
| Test E1 | #27 | 11-Mar | 7194 | 1401297 | 3173501 | 133.5 | 14 | 119.5 | 98 |
| Test E2 | #28 | 11-Mar | 7193 | 1401396 | 3173475 | 133.1 | 12.4 | 120.7 | 99 |
| Test E3 | #29 | 11-Mar | 7193 | 1401497 | 3173439 | 124.3 | 8.9 | 115.4 | 94 |
| Test E4 | #30 | 11-Mar | 7193 | 1401739 | 3173412 | 126.4 | 9.9 | 116.5 | 95 |
| Test E5 | #31 | 11-Mar | 7195 | 1401944 | 3173344 | 117.6 | 7.4 | 109.4 | 90 |
| Test E6 | #32 | 11-Mar | 7199 | 1402110 | 3173290 | 133.33 | 7.6 | 124.1 | 94 |
| Test F1 | #33 | 18-Mar | 7195 | 1401333 | 3173159 | 121.8 | 7.9 | 113.9 | 93 |
| Test F2 | #34 | 18-Mar | 7195 | 1401507 | 3173474 | 122.5 | 9.2 | 112.2 | 93 |
| Test F3 | #35 | 18-Mar | 7194 | 1401688 | 3173470 | 123.8 | 114.1 | 108.5 | 90 |
| Test F4 | #36 | 18-Mar | 7194 | 1401799 | 3173406 | 123.6 | 6.6 | 117 | 96 |
| Test F5 | #37 | 18-Mar | 7202 | 1402147 | 3173263 | 116.8 | 8.9 | 107.9 | 99 |




| BCC Test | CTL Test | Date | Elevation (ft) | Northing (ft) | Easting (ft) | Wet Density (pcf) | Moisture Content (%) | Dry Density (pcf) | Compaction (%) |
|-----------------|-----------------|-------------|-----------------------|----------------------|---------------------|--------------------------|-----------------------------|--------------------------|-----------------------|
| Test F6 | #38 | 18-Mar | 7211 | 1402295 | 3173205 | 119.7 | 5.4 | 114.3 | 93 |
| Test G1 | #39 | 21-Mar | 7193 | 1401416 | 3173681 | 123.4 | 8.2 | 115.2 | 94 |
| Test G2 | #40 | 21-Mar | 7197 | 1401580 | 3173437 | 121.8 | 11.6 | 110.2 | 91 |
| Test H1 | #41 | 22-Mar | 7196 | 1401682 | 3173479 | 118.1 | 11.5 | 106.5 | 93 |
| Test H2 | #42 | 22-Mar | 7198 | 1401820 | 3173365 | 126.5 | 8 | 118.9 | 97 |
| Test H3 | #43 | 22-Mar | 7199 | 1401976 | 3173343 | 118.6 | 8.1 | 110.5 | 90 |
| Test H4 | #44 | 23-Mar | 7205 | 1402175 | 3173256 | 119.3 | 5.5 | 113.8 | 93 |
| Test H5 | #45 | 23-Mar | 7213 | 1402290 | 3173211 | 115.5 | 6.2 | 109.4 | 90 |
| Test H6 | #46 | 23-Mar | 7220 | 1402388 | 3173183 | 120.6 | 2.5 | 118.1 | 97 |
| Test I1 | #47 | 25-Mar | 7203 | 1400919 | 3173558 | 121.1 | 1.9 | 119.3 | 97 |
| Test I2 | #48 | 25-Mar | 7200 | 1401110 | 3173535 | 116.4 | 2.4 | 114 | 93 |
| Test I3 | #49 | 25-Mar | 7200 | 1401334 | 3173455 | 113.4 | 3.2 | 110.2 | 90 |
| Test I4 | #50 | 25-Mar | 7198 | 1401465 | 3173500 | 116.9 | 2.8 | 114.1 | 91 |
| Test I5 | #51 | 25-Mar | 7198 | 1401668 | 3173485 | 115.2 | 2.5 | 112.7 | 92 |
| Test I6 | #52 | 25-Mar | 7197 | 1401818 | 3173436 | 118.1 | 2.5 | 115.5 | 95 |
| Test I7 | #53 | 25-Mar | 7200 | 1402018 | 3173361 | 118.5 | 1.6 | 116.9 | 90 |
| Test I8 | #54 | 25-Mar | 7203 | 1402105 | 3173323 | 115.7 | 5.6 | 110.1 | 95 |
| Test I9 | #55 | 25-Mar | 7173 | 1402367 | 3173434 | 130.1 | 6.2 | 122.3 | 100 |
| Test J1 | #56 | 28-Mar | 7200 | 1401155 | 3173580 | 115.5 | 2.6 | 112.8 | 92 |
| Test J2 | #57 | 28-Mar | 7203 | 1400966 | 3173543 | 122.9 | 11.7 | 111.2 | 91 |
| Test J3 | #58 | 28-Mar | 7202 | 1401256 | 3173484 | 115.3 | 2.6 | 112.6 | 92 |
| Test J4 | #59 | 28-Mar | 7201 | 1401371 | 3173517 | 113.2 | 1.5 | 111.7 | 91 |
| Test J5 | #60 | 31-Mar | 7200 | 1401645 | 3173478 | 126.2 | 15.4 | 110.8 | 91 |
| Test J6 | #61 | 31-Mar | 7201 | 1401815 | 3173367 | 128 | 6.3 | 121.7 | 99 |
| Test J7 | #62 | 31-Mar | 7205 | 1401996 | 3173286 | 124.6 | 3.8 | 120.8 | 97 |
| Test J8 | #63 | 31-Mar | 7201 | 1402083 | 3173400 | 120.5 | 3.3 | 117.6 | 95 |
| Test J9 | #64 | 31-Mar | 7202 | 1402083 | 3173400 | 124 | 4.7 | 119.3 | 96 |



\\us0321-pptss01\workgroup\2274\active\227419041\dmsc\monitoring\2022\2022-03\dwg\pkreview\ptms_04132022

2022.04.13 8:38:50 PM




Stantec Consulting Services Inc.
2000 South Colorado Boulevard Suite 2-300
Denver CO 80222-7933
Tel: (303) 758-4058
www.stantec.com

LEGEND

- Permit/Affected Lands Boundary
- City Grading Permit Boundary
- Proposed Disturbance Limit
- Landslide Extent
- Buttress Fill Extent
- Compaction Test Location

1. TESTS #1 THROUGH #16 WERE NOT SURVEYED
2. TESTS PERFORMED ON 10 SEPARATE LIFTS.



Client/Project

CONTINENTAL MATERIALS
CORP.
PIKEVIEW QUARRY SLOPE
MONITORING

Project No.
2057288200

Title

COMPACTION TEST
LOCATIONS

Revision

Drawn By
PK

Date
2022.04.30
Figure No.
6