

PERMIT INFORMATION

Permit Number: C-1981-028					
Mine Name: Keenesburg Strip Mine	County: Weld				
Operator: Coors Energy Company	Operation Type: Surface				
Operator Address:	Permit Status: Permanent Cessation				
Mr. Ben Moline	Ownership: Private				
PO Box 4030	-				
Golden, CO 80402	Operator Representative Present:				
	None				
Operator Representative Signature: (Field Issuance Only)					

INSPECTION INFORMATION

Inspection Start Date: May 12, 2 Inspection Start Time: 07:45 Inspection End Date: May 12, 20 Inspection End Time: 09:30			Inspection Type: Coal Partial Inspection Reason: Normal I Weather: Clear	*
Joint Inspection Agency:		Joint Inspection Contacts:		
None				
Post Inspection Agency:		Post Inspection Contacts:		
None				
Inspector(s):	Inspector's Signature: Sign		Signature Date:	
Robert Zuber, P.E.	Phot D. The			
				5/12/2022

Inspection Topic Summary

NOTE: Y=Inspected N=Not Inspected R=Comments Noted V=Violation Issued NA=Not Applicable

Y - Air Resource Protection NA - Roads

N - Availability of Records Y - Reclamation Success

NA - Backfill & Grading R - Revegetation

NA - Excess Spoil and Dev. Waste NA - Subsidence

NA - Explosives Y - Slides and Other Damage Y - Fish & Wildlife Y - Support Facilities On-site R - Hydrologic Balance Y - Signs and Markers

R - Gen. Compliance With Mine Plan
N - Other
NA - Support Facilities Not On-site
NA - Special Categories Of Mining

NA - Processing Waste NA - Topsoil

COMMENTS

A partial inspection was conducted by Rob Zuber of DRMS on May 12, 2022. No Coors Energy Company (CEC) representative was present at the inspection.

The site is in Permanent Cessation. Reclamation activities were completed in the fall of 2020. However, due to poor success in some areas, Coors Energy reclaimed these areas a second time in spring 2022.

An area by the entrance from the facilities area has not been reclaimed. This area is approximately 100 feet by 35 feet.

The weather was warm (55 degrees F) and cloudy, and the ground was dry.

HYDROLOGIC BALANCE - Rule 4.05

Drainage Control 4.05.1, 4.05.2, 4.05.3; Siltation Structures 4.05.5, 4.05.6; Discharge Structures 4.05.7, 4.05.10; Diversions 4.05.4; Effluent Limits 4.05.2; Ground Water Monitoring 4.05.13; Surface Water Monitoring 4.05.13; Drainage – Acid and Toxic Materials 4.05.8; Impoundments 4.05.6, 4.05.9; Stream Buffer Zones 4.05.18:

Sediment Pond 2 and the Dugout Pond contained little to no water (thick vegetation obscures the bottoms). They were not discharging during the inspection. There were no signs that either pond had discharged recently. No problems were observed.

The ditch west of Sediment Pond 2 appeared to be functioning well.

Near the southeast corner of the Dugout Pond, the relatively steep hill (where a topsand pile existed in past years) was stable, with no erosion.

Number of <u>Partial</u> Inspection this Fiscal Year: 6 Number of <u>Complete</u> Inspections this Fiscal Year: 3

GENERAL MINE PLAN COMPLIANCE:

The northern boundary of the site was observed, and no signs of pollutant loading from the mine site, or any other problems, were seen. No problems were observed within the undisturbed area north of reclaimed B Pit.

REVEGETATION – Rule 4.15

Vegetative Cover; Timing:

Green grass was seen emerging at several locations, including (but not limited to) Areas 37 and 42 and the Long Term Spoil Area.

DOCUMENTS RECEIVED - none

OTHER (SPECIFY) - none

ENFORCEMENT ACTIONS/COMPLIANCE

No enforcement actions were initiated as a result of this inspection, nor are any pending.

PHOTOGRAPHS



Sediment Pond 2 embankment



Area 42 – new and older reclamation

Number of <u>Partial</u> Inspection this Fiscal Year: 6 Number of <u>Complete</u> Inspections this Fiscal Year: 3



Emerging vegetation in Area 37



Emerging vegetation in reclaimed Long Term Spoil Area

Number of <u>Partial</u> Inspection this Fiscal Year: 6 Number of <u>Complete</u> Inspections this Fiscal Year: 3



Slope southeast of Dugout Pond