

# QUARTERLY POND INSPECTION REPORT

Operator: **Bowie Resources LLC**  
 Mine: **Bowie No. 2 Mine - C-1996-083**

Quarter: **Second 2022**  
 Inspection Date: **22-Jun-22**

Pond Identification	B	C	D - Gob Pile	F - New Gob	J UTL East	K UTL West
Type of Pond	Sediment	Sediment	Sediment	Sediment	Sediment	Sediment

## Status During Inspection:

Approximate Water Level	5942'	5990'	5970'	5944	5848	5819
Sediment (% remaining)	90%	90%	80%	60%	80%	80%
Outflow (cfs)	0	0	0	0	0	0

Features	Problem	Problem	Problem	Problem	Problem	Problem
	Yes/No	Yes/No	Yes/No	Yes/No	Yes/No	Yes/No

## Erosional

Rills & Gulleys	No	No	No	No	No	No
Inadequate Vegetation	No	No	No	No	No	No
Outlet Channel Erosion	No	No	No	No	No	No
Burrows	No	No	No	No	No	No
Other	No	No	No	No	No	No

## Structural

Differential Settling	No	No	No	No	No	No
Cracks or Slides	No	No	No	No	No	No
Seepage	No	No	No	No	No	No
Other	No	No	No	No	No	No

## Appurtenant Structures


Defective Spillways	No	No	No	No	No	No
Dewatering Devices Clogged	No	No	No	No	No	No
Faulty Gates, Etc.	No	No	No	No	No	No
Other	No	No	No	No	No	No

## Additional Comments

Design depth measured from pond bottom to invert of emergency spillway:  
 Pond B=10, C=10, D=10, J=10, K=3, F=10' TD  
 Pond Bottom Elevations B=5942, C=5990, D=5970, J=5846, F=5944, K=5819  
 Pond C was dry.  
 Pond B held about 1' of water.  
 Pond D held a puddle of water.  
 Pond J held between 1-2' of water.  
 Pond K was dry.  
 Pond F held a puddle.

SWMP components were inspected and found to be in good condition. No corrections necessary at this time.

Name of Inspector: **Tamme Bishop**



Date