




MINERALS PROGRAM INSPECTION REPORT

PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME: Robins Pit No. 1	MINE/PROSPECTING ID#: M-2002-014	MINERAL: Gravel	COUNTY: Conejos
INSPECTION TYPE: Monitoring	INSPECTOR(S): Clayton Wein	INSP. DATE: August 9, 2022	INSP. TIME: 11:15
OPERATOR: Robins Construction, LLLP	OPERATOR REPRESENTATIVE: Randy Robins	TYPE OF OPERATION: 112c - Construction Regular Operation	
REASON FOR INSPECTION: Normal I&E Program	BOND CALCULATION TYPE: Complete Bond	BOND AMOUNT: \$41,834.71	
DATE OF COMPLAINT: NA	POST INSP. CONTACTS: None	JOINT INSP. AGENCY: None	
WEATHER: Clear	INSPECTOR'S SIGNATURE: 	SIGNATURE DATE: August 23, 2022	

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS----- <u>N</u>	(FN) FINANCIAL WARRANTY----- <u>Y</u>	(RD) ROADS----- <u>N</u>
(HB) HYDROLOGIC BALANCE----- <u>Y</u>	(BG) BACKFILL & GRADING----- <u>N</u>	(EX) EXPLOSIVES----- <u>N</u>
(PW) PROCESSING WASTE/TAILING---- <u>N</u>	(SF) PROCESSING FACILITIES----- <u>N</u>	(TS) TOPSOIL----- <u>Y</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>Y</u>	(FW) FISH & WILDLIFE----- <u>N</u>	(RV) REVEGETATION---- <u>N</u>
(SM) SIGNS AND MARKERS----- <u>Y</u>	(SP) STORM WATER MGT PLAN---- <u>N</u>	(RS) RECL PLAN/COMP-- <u>N</u>
(ES) OVERBURDEN/DEV. WASTE----- <u>N</u>	(SC) EROSION/SEDIMENTATION--- <u>Y</u>	(ST) STIPULATIONS----- <u>N</u>
(AT) ACID OR TOXIC MATERIALS----- <u>N</u>	(OD) OFF-SITE DAMAGE----- <u>N</u>	

Y = Inspected / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

OBSERVATIONS

This report documents the observations made during a normal monitoring inspection of the Robins Pit #1 conducted on August 9, 2022. The inspection was conducted by Clayton Wein of the Colorado Division of Reclamation, Mining and Safety (the Division). Randy Robins and Scott Johnson represented Robins Construction, LLLP during the inspection. The weather was clear with a temperature near 80 degrees F. The ground conditions were dry. Please see the attached photographs for a visual of the site conditions during the inspection.

The Robins pit #1 is a 112c site consisting of 18.53 acres. The mine site is located approximately 10 miles to the west of Antonito Colorado.

The mine identification sign was displayed to the right side of the entrance to the affected area boundary. The boundary for the site was marked by a fence. The fence was easily identified and one section could be seen from one another.

The site was inactive at the time of the inspection. Material was stockpiled in the pit floor. There were two portions of the site that had highwalls. The northwestern portion was at approximately 1:1 slope and was the highwall being utilized. The highwall located in the southern section was at about a 3:1 slope. The pit was roughly at a maximum depth of 15 feet. The slopes of the highwalls were stable and there were no erosional concerns identified. There was not any fuel or other hydrocarbons stored at the mine site.

Topsoil resources for the site was stockpiled and covered with vegetation. There were no indications of erosion or loss of topsoil resources.

As a result of this inspection, the Division will be conducting an update to the reclamation cost estimate. The new reclamation cost estimate will be sent to the operator under a separate cover.

The Division did not identify any maintenance items or possible violations during the inspection.

Questions or responses to this inspection report should be directed to Clayton Wein at the Division of Reclamation, Mining and Safety Grand Junction Field Office, located at 101 south 3rd Street, Room 301, Grand Junction Colorado 81501. Or by phone at (303)-866-3567 x8185.

PHOTOGRAPHS



Inspection Contact Address

Randy Robins
Robins Construction, LLLP
P.O. Box 212
Antonito, CO 81120

Enclosure

CC: Travis Marshall, Senior Environmental Protection Specialist