

## QUARTERLY POND INSPECTION REPORT

Operator:

Bowie Resources LLC

Quarter:

Third 2022

Mine:

Bowie No. 2 Mine - C-1996-083

Inspection Date:

28-Sep-22

### Pond Identification

Type of Pond

B	C	D - Gob Pile	F - New Gob	J UTL East	K UTL West
Sediment	Sediment	Sediment	Sediment	Sediment	Sediment

### Status During Inspection:

Approximate Water Level

5942'	5990'	5970'	5945'	5846'	5819'
-------	-------	-------	-------	-------	-------

Sediment (% remaining)

90%	90%	80%	90%	85%	80%
-----	-----	-----	-----	-----	-----

Outflow (cfs)

0	0	0	0	0	0
---	---	---	---	---	---

### Features

Problem	Problem	Problem	Problem	Problem	Problem
Yes/No	Yes/No	Yes/No	Yes/No	Yes/No	Yes/No

### Erosional

Rills & Gulleys	No	No	No	No	No	No
Inadequate Vegetation	No	No	No	No	No	No
Outlet Channel Erosion	No	No	No	No	No	No
Burrows	No	No	No	No	No	No
Other	No	No	No	No	No	No

### Structural

Differential Settling	No	No	No	No	No	No
Cracks or Slides	No	No	No	No	No	No
Seepage	No	No	No	No	No	No
Other	No	No	No	No	No	No

### Appurtenant Structures

Defective Spillways	No	No	No	No	No	No
Dewatering Devices Clogged	No	No	No	No	No	No
Faulty Gates, Etc.	No	No	No	No	No	No
Other	No	No	No	No	No	No

### Additional Comments

Design depth measured from pond bottom to invert of emergency spillway:

Pond B=10, C=10, D=10, J=10, K=3, F=10' TD

Pond Bottom Elevations B=5942, C=5990, D=5970, J=5846, F=5944, K=5819

Pond C held just a puddle of water.

Pond B held just a puddle of water

Pond D held just a puddle of water

Pond J held a puddle of water

Pond K was damp

Pond F held approximately 1' of water.

SWMP components were inspected and found to be in good condition. No corrections necessary at this time.

Name of Inspector: Tamme Bishop

