



TRAPPER MINING INC.

September 26, 2022

Ms. Robin Reilley
Environmental Protection Specialist
Colorado Division of Reclamation, Mining, and Safety
1313 Sherman Street, Room 215
Denver, CO 80203

Dear Ms. Robin Reilley:

**RE: Trapper Mining Inc., Permit C-81-010
Third Quarter 2022 Sediment Pond Inspections**

All impoundment inspections were conducted by a qualified impoundment inspector. Inspections took place on August 24th and 30th and September 1st, 8th and 13th.

Maintenance items noted during the inspections were as follows:

- East Pyeatt #1 sediment marker needs to be replace.
- East Pyeatt #2 sediment marker needs to be replace.
- East Pyeatt #3 sediment marker needs to be replace.
- Jeffway #1 identification sign needs to be put back up.

Trapper will address these maintenance items in a timely matter.

The sediment in No Name #2 Pond was removed this quarter.

Data related to pond capacity is attached. The last column on the table provides an estimate of the remaining capacity in each pond where remaining capacity is defined as the volume remaining after considering the estimated amount of sediment noted during the inspections.

Please contact me if you have any questions.

Sincerely,


Tonia Marie Perkins
CO PE 43864

C: EQ file 118.7



Trapper Mining Inc.
Third Quarter 2022
Impoundment Inspection - Pond Capacity Data

Pond ID	Princ. Spillway Stage (ft)	Total Capacity to PS stage (acre-feet)	60% Sediment Capacity (acre-feet)	60% Sediment Capacity Stage (ft)	Remaining Design Capacity (acre-feet)	Inspection Observation (% sediment)	Qtr. 2 Estimated Sediment (acre-feet)	Qtr. 2 Approximate Rem. Capacity (acre-feet)
Far East Buzzard	2.0	0.03	0.02	1.4	0.01	10.00	0.00	0.03
Coyote	30.5	75.1	45.06	26.7	30.04	0.00	0.00	75.10
No Name #2	8.5	8.47	5.08	6.0	3.39	0.00	0.00	8.47
No Name #4	14.5	8.23	4.94	11.7	3.29	10.00	0.82	7.41
No Name #5	6.0	1.03	0.62	4.7	0.41	20.00	0.21	0.82
Johnson #6	9.0	1.80	1.08	7.1	0.72	25.00	0.45	1.35
Johnson #7R	7.0	2.99	1.79	5.2	1.20	35.00	1.05	1.94
Johnson #8	7.0	3.58	2.15	4.6	1.43	35.00	1.25	2.33
Johnson #9	8.5	2.74	1.64	6.6	1.10	20.00	0.55	2.19
Johnson #10	9.0	6.09	3.65	7.0	2.44	25.00	1.52	4.57
West Pyeatt #1	9.0	2.76	1.66	7.0	1.10	45.00	1.24	1.52
West Pyeatt #2	10.0	1.89	1.13	7.3	0.76	45.00	0.85	1.04
Middle Pyeatt #1	10.0	1.40	0.84	8.1	0.56	40.00	0.56	0.84
Middle Pyeatt #2	10.0	1.26	0.76	8.4	0.50	20.00	0.25	1.01
Middle Pyeatt #3	10.0	5.70	3.42	7.9	2.28	40.00	2.28	3.42
East Pyeatt #1	8.0	0.99	0.59	6.5	0.40	10.00	0.10	0.89
East Pyeatt #2	8.0	4.15	2.49	6.1	1.66	10.00	0.42	3.74
East Pyeatt #3	8.0	1.51	0.91	6.8	0.60	25.00	0.38	1.13
Grouse #1	7.5	3.35	2.01	5.7	1.34	40.00	1.34	2.01
Grouse # 2	4.5	0.79	0.47	3.6	0.32	10.00	0.08	0.71
Sage #1	8.0	2.67	1.60	6.4	1.07	10.00	0.27	2.40
Sage #2	7.0	2.07	1.24	5.8	0.83	10.00	0.21	1.86
Oak #1	13.0	1.43	0.86	10.6	0.57	45.00	0.64	0.79
Oak #2	9.5	0.93	0.56	7.7	0.37	5.00	0.05	0.88

Trapper Mining Inc.
Third Quarter 2022
Impoundment Inspection - Pond Capacity Data

Pond ID	Princ. Spillway Stage (ft)	Total Capacity to PS stage (acre-feet)	60% Sediment Capacity (acre-feet)	60% Sediment Capacity Stage (ft)	Remaining Design Capacity (acre-feet)	Inspection Observation (% sediment)	Qtr. 2 Estimated Sediment (acre-feet)	Qtr. 2 Approximate Rem. Capacity (acre-feet)
West Flume	10.0	2.35	1.41	7.8	0.94	0.00	0.00	2.35
Middle Flume #1	11.7	0.80	0.48	9.0	0.32	40.00	0.32	0.48
Middle Flume # 3	14.0	3.36	2.02	10.5	1.34	35.00	1.18	2.18
East Middle Flume	13.0	2.56	1.54	9.2	1.02	15.00	0.38	2.18
East Flume	11.3	1.18	0.71	8.5	0.47	15.00	0.18	1.00
Ute	7.0	1.72	1.03	5.2	0.69	45.00	0.77	0.95
Horse	13.3	6.20	3.72	10.3	2.48	55.00	3.41	2.79
West Horse	13.0	2.00	1.20	9.7	0.80	20.00	0.40	1.60
Deal #1	16.8	2.00	1.20	15.1	0.80	10.00	0.20	1.80
Deal #2	6.0	1.66	0.60	3.1	1.06	0.00	0.00	1.66
Deacon #1	14.5	9.00	3.48	7.5	5.52	0.00	0.00	9.00
Deacon #2	12.0	7.03	3.60	7.7	3.43	0.00	0.00	7.03
Jeffway #1	9.0	2.86	1.20	5.3	1.66	0.00	0.00	2.86
Impoundment H	9.5	4.82	2.89	4.9	1.93	5.00	0.24	4.58

TRAPPER MINING INC.

QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Cassandra BrandtSIGNATURE: 

DRAINAGE: FAR EAST BUZZARD

DATE OF INSPECTION: 9-13-22

POND IDENTIFICATION	Far East Buzzard #1				
Approximate water level:	0%				
Sediment level (% total storage):	10%				
Outflow (cfs):	0 cfs				
Sediment marker (install or replace)	In Place				
Identification sign (install or replace)	In Place				
EROSIONAL:					
Rills and/or gullies on downstream face.	No				
Rills and/or gullies on upstream face.	No				
Inadequate vegetation.	No				
Outlet channel erosion.	No				
Burrows.	No				
Erosion of toe.	No				
Water impounded against downstream toe.	No				
Other.	—				
STRUCTURAL:					
Differential settling.	No				
Cracks, slides, or scarps.	No				
Seepage (specify location, color, value).	No				
Defective spillways.	No				
Other.	—				
APPURTENANT STRUCTURES:					
Defective spillways.	No				
Dewatering device clogged.	No				
Cracking or crushing of pipes.	No				
Other.	—				

COMMENTS:

Dry Conditions. No issues noted.



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Cassandra BrandtSIGNATURE: *Cassandra Brandt*DRAINAGE: **COYOTE**DATE OF INSPECTION: 9-13-22

POND IDENTIFICATION	Coyote #1				
Approximate water level:	0%				
Sediment level (% total storage):	Min.				
Outflow (cfs):	0 cfs				
Sediment marker (install or replace)	N/A				
Identification sign (install or replace)	In Place				
EROSIONAL:					
Rills and/or gullies on downstream face.	No				
Rills and/or gullies on upstream face.	No				
Inadequate vegetation.	No				
Outlet channel erosion.	No				
Burrows.	No				
Erosion of toe.	No				
Water impounded against downstream toe.	No				
Other.	—				
STRUCTURAL:					
Differential settling.	No				
Cracks, slides, or scarps.	No				
Seepage (specify location, color, value).	No				
Defective spillways.	No				
Other.	—				
APPURTENANT STRUCTURES:					
Defective spillways.	No				
Dewatering device clogged.	No				
Cracking or crushing of pipes.	No				
Other.	—				

COMMENTS:

Sediment level is measured by a fixed surveyed elevation of 6298.11 ft. (9/29/10).

No water in Pond. Hot and dry conditions noted.



TRAPPER MINING INC.

QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia Perkins

SIGNATURE: Tonia Perkins

DRAINAGE: NO NAME

DATE OF INSPECTION: 8/24/2022


POND IDENTIFICATION	No Name #2	No Name #4	No Name #5		
Approximate water level:	<i>Minimal</i>	<i>100%</i>	<i>100%</i>		
Sediment level (% total storage):	<i>*</i>	<i>10%</i>	<i>20%</i>		
Outflow (cfs):	<i>*</i>	<i>LCFS</i>	<i>LCFS</i>		
Sediment marker (install or replace)	<i>*</i>	<i>In Place</i>	<i>In Place</i>		
Identification sign (install or replace)	<i>In Place</i>	<i>In Place</i>	<i>In Place</i>		
EROSIONAL:					
Rills and/or gullies on downstream face.	<i>*</i>	<i>no</i>	<i>no</i>		
Rills and/or gullies on upstream face.	<i>*</i>	<i>no</i>	<i>no</i>		
Inadequate vegetation.	<i>*</i>	<i>no</i>	<i>no</i>		
Outlet channel erosion.	<i>*</i>	<i>no</i>	<i>no</i>		
Burrows.	<i>*</i>	<i>no</i>	<i>no</i>		
Erosion of toe.	<i>*</i>	<i>no</i>	<i>no</i>		
Water impounded against downstream toe.	<i>*</i>	<i>no</i>	<i>no</i>		
Other.	<i>*</i>	<i>-</i>	<i>-</i>		
STRUCTURAL:					
Differential settling.	<i>*</i>	<i>no</i>	<i>no</i>		
Cracks, slides, or scarps.	<i>*</i>	<i>no</i>	<i>no</i>		
Seepage (specify location, color, value).	<i>*</i>	<i>no</i>	<i>no</i>		
Defective spillways.	<i>*</i>	<i>no</i>	<i>no</i>		
Other.	<i>*</i>	<i>-</i>	<i>-</i>		
APPURTENANT STRUCTURES:					
Defective spillways.	<i>*</i>	<i>no</i>	<i>no</i>		
Dewatering device clogged.	<i>*</i>	<i>no</i>	<i>no</i>		
Cracking or crushing of pipes.	<i>*</i>	<i>no</i>	<i>no</i>		
Other.	<i>*</i>	<i>-</i>	<i>-</i>		

COMMENTS:

#2: use riser/siphon tube as sediment marker; siphon top = 66%, bottom = 50%.

#4: use riser/siphon tube as sediment marker; siphon top = 75%, bottom = 60%.

#5: 60% level = top of post 1.5'.

No name #2 is currently being cleaned.There is some vegetation in the outlet of #4 + #5, the water flow is not obstructed.*

TRAPPER MINING INC.

QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia Perkins

SIGNATURE: *Tonia Perkins*

DRAINAGE: JOHNSON GULCH

DATE OF INSPECTION: *8/24/2022*

POND IDENTIFICATION	Johnson #6	Johnson #7R	Johnson #8R	Johnson #9R	Johnson #10R
Approximate water level:	<i>100%</i>	<i>100%</i>	<i>100%</i>	<i>100%</i>	<i>90%</i>
Sediment level (% total storage):	<i>25%</i>	<i>35%</i>	<i>35%</i>	<i>20%</i>	<i>25%</i>
Outflow (cfs):	<i>41 CFS</i>	<i>41 CFS</i>	<i>41 CFS</i>	<i>41 CFS</i>	<i>0</i>
Sediment marker (install or replace)	<i>In Place</i>	<i>Underwater</i>	<i>Underwater</i>	<i>Underwater</i>	<i>Underwater</i>
Identification sign (install or replace)	<i>In Place</i>	<i>In Place</i>	<i>In Place</i>	<i>In Place</i>	<i>In Place</i>
EROSIONAL:					
Rills and/or gullies on downstream face.	<i>no</i>	<i>no</i>	<i>no</i>	<i>no</i>	<i>no</i>
Rills and/or gullies on upstream face.	<i>no</i>	<i>no</i>	<i>no</i>	<i>no</i>	<i>no</i>
Inadequate vegetation.	<i>no</i>	<i>no</i>	<i>no</i>	<i>no</i>	<i>no</i>
Outlet channel erosion.	<i>no</i>	<i>no</i>	<i>no</i>	<i>no</i>	<i>no</i>
Burrows.	<i>no</i>	<i>no</i>	<i>no</i>	<i>no</i>	<i>no</i>
Erosion of toe.	<i>no</i>	<i>no</i>	<i>no</i>	<i>no</i>	<i>no</i>
Water impounded against downstream toe.	<i>no</i>	<i>no</i>	<i>no</i>	<i>no</i>	<i>no</i>
Other.	<i>-</i>	<i>-</i>	<i>-</i>	<i>-</i>	<i>-</i>
STRUCTURAL:					
Differential settling.	<i>no</i>	<i>no</i>	<i>no</i>	<i>no</i>	<i>no</i>
Cracks, slides, or scarps.	<i>no</i>	<i>no</i>	<i>no</i>	<i>no</i>	<i>no</i>
Seepage (specify location, color, value).	<i>no</i>	<i>no</i>	<i>no</i>	<i>no</i>	<i>no</i>
Defective spillways.	<i>no</i>	<i>no</i>	<i>no</i>	<i>no</i>	<i>no</i>
Other.	<i>-</i>	<i>-</i>	<i>-</i>	<i>-</i>	<i>-</i>
APPURTENANT STRUCTURES:					
Defective spillways.	<i>no</i>	<i>no</i>	<i>no</i>	<i>no</i>	<i>no</i>
Dewatering device clogged.	<i>no</i>	<i>no</i>	<i>no</i>	<i>no</i>	<i>no</i>
Cracking or crushing of pipes.	<i>no</i>	<i>no</i>	<i>no</i>	<i>no</i>	<i>no</i>
Other.	<i>-</i>	<i>-</i>	<i>-</i>	<i>-</i>	<i>-</i>

COMMENTS:

#6: use riser/siphon tube as sediment marker; siphon top = 90%, top - 1.5' = 60%.



TRAPPER MINING INC.

QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tim Cummins

SIGNATURE: Tim Cummins

DRAINAGE: WEST PYEATT

DATE OF INSPECTION: 8/30/22

POND IDENTIFICATION	West Pyeatt #1	West Pyeatt #2			
Approximate water level:	0% damp	0% dry			
Sediment level (% total storage):	45%	45%			
Outflow (cfs):	0	0			
Sediment marker (install or replace)	in place	in place			
Identification sign (install or replace)	in place	in place			
EROSIONAL:					
Rills and/or gullies on downstream face.	No	No			
Rills and/or gullies on upstream face.	No	No			
Inadequate vegetation.	No	No			
Outlet channel erosion.	No	No			
Burrows.	* 3	No			
Erosion of toe.	No	No			
Water impounded against downstream toe.	No	No			
Other.	None	None			
STRUCTURAL:					
Differential settling.	No	No			
Cracks, slides, or scarps.	No	No			
Seepage (specify location, color, value).	No	No			
Defective spillways.	No	No			
Other.	None	None			
APPURTENANT STRUCTURES:					
Defective spillways.	No	No			
Dewatering device clogged.	No	No			
Cracking or crushing of pipes.	No	No			
Other.	None	None			

COMMENTS: * Burrows - non invasive



TRAPPER MINING INC.

QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tim Cummins

SIGNATURE: Tim Cummins

DRAINAGE: MIDDLE PYEATT

DATE OF INSPECTION: 8/30/22

POND IDENTIFICATION	Middle Pyeatt #1	Middle Pyeatt #2	Middle Pyeatt #3		
Approximate water level:	40 %	0% dry	0% dry		
Sediment level (% total storage):	40 %	20 %	40 %		
Outflow (cfs):	0	0	0		
Sediment marker (install or replace)	in place	in place	in place		
Identification sign (install or replace)	in place	in place	in place		
EROSIONAL:					
Rills and/or gullies on downstream face.	No	No	No		
Rills and/or gullies on upstream face.	No	No	No		
Inadequate vegetation.	No	No	No		
Outlet channel erosion.	No	No	No		
Burrows.	No	No	No		
Erosion of toe.	No	No	No		
Water impounded against downstream toe.	No	No	No		
Other.	None	None	None		
STRUCTURAL:					
Differential settling.	No	No	No		
Cracks, slides, or scarps.	No	No	No		
Seepage (specify location, color, value).	No	No	No		
Defective spillways.	No	No	No		
Other.	None	None	None		
APPURTENANT STRUCTURES:					
Defective spillways.	No	No	No		
Dewatering device clogged.	No	No	No		
Cracking or crushing of pipes.	No	No	No		
Other.	None	None	None		
COMMENTS:					




TRAPPER MINING INC.

QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tim CumminsSIGNATURE: Jim CumminsDRAINAGE: **EAST PYEATT**DATE OF INSPECTION: 9/1/22

POND IDENTIFICATION	East Pyeatt #1	East Pyeatt #2	East Pyeatt #3
Approximate water level:	100 %	80 %	70 %
Sediment level (% total storage):	10 %	10 %	25 %
Outflow (cfs):	21 cfs	0	0
Sediment marker (install or replace)	replace	replace	replace
Identification sign (install or replace)	in place	in place	in place
EROSIONAL:			
Rills and/or gullies on downstream face.	No	No	No
Rills and/or gullies on upstream face.	No	No	No
Inadequate vegetation.	No	No	No
Outlet channel erosion.	No	No	No
Burrows.	No	No	No
Erosion of toe.	No	No	No
Water impounded against downstream toe.	No	No	No
Other.	None	None	None
STRUCTURAL:			
Differential settling.	No	No	No
Cracks, slides, or scarps.	No	No	No
Seepage (specify location, color, value).	No	No	No
Defective spillways.	No	No	No
Other.	None	None	None
APPURTENANT STRUCTURES:			
Defective spillways.	No	No	No
Dewatering device clogged.	No	No	No
Cracking or crushing of pipes.	No	No	No
Other.	None	None	None

COMMENTS:



TRAPPER MINING INC. QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Monte McCoy

SIGNATURE: Monte McCoy

DRAINAGE: GROUSE GULCH

DATE OF INSPECTION: 9-8-2022

POND IDENTIFICATION	Grouse #1	Grouse #2			
Approximate water level:	Dry	Dry			
Sediment level (% total storage):	40%	100%			
Outflow (cfs):	0	0			
Sediment marker (install or replace)	in place	in place			
Identification sign (install or replace)	in place	in place			
EROSIONAL:					
Rills and/or gullies on downstream face.	no	no			
Rills and/or gullies on upstream face.	no	no			
Inadequate vegetation.	no	no			
Outlet channel erosion.	no	no			
Burrows.	no	no			
Erosion of toe.	no	no			
Water impounded against downstream toe.	no	no			
Other.	—	—			
STRUCTURAL:					
Differential settling.	no	no			
Cracks, slides, or scarps.	no	no			
Seepage (specify location, color, value).	no	no			
Defective spillways.	no	no			
Other.	—	—			
APPURTENANT STRUCTURES:					
Defective spillways.	no	no			
Dewatering device clogged.	no	no			
Cracking or crushing of pipes.	no	no			
Other.	—	—			
COMMENTS:					



TRAPPER MINING INC. QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Monte McCoy

SIGNATURE: 

DRAINAGE: SAGE GULCH

DATE OF INSPECTION: 9-8-2022

POND IDENTIFICATION	Sage #1	Sage #2			
Approximate water level:	Dry	Dry			
Sediment level (% total storage):	10%	10%			
Outflow (cfs):	0	0			
Sediment marker (install or replace)	in place	in place			
Identification sign (install or replace)	in place	in place			
EROSIONAL:					
Rills and/or gullies on downstream face.	no	no			
Rills and/or gullies on upstream face.	no	no			
Inadequate vegetation.	no	no			
Outlet channel erosion.	no	no			
Burrows.	no	no			
Erosion of toe.	no	no			
Water impounded against downstream toe.	no	no			
Other.	N/A	N/A			
STRUCTURAL:					
Differential settling.	no	no			
Cracks, slides, or scarps.	no	no			
Seepage (specify location, color, value).	no	no			
Defective spillways.	no	no			
Other.	N/A	N/A			
APPURTENANT STRUCTURES:					
Defective spillways.	no	no			
Dewatering device clogged.	no	no			
Cracking or crushing of pipes.	no	no			
Other.	N/A	N/A			

COMMENTS:



TRAPPER MINING INC. QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia Perkins

SIGNATURE: Tonia Perkins

DRAINAGE: OAK GULCH

DATE OF INSPECTION: 8/24/2022

POND IDENTIFICATION	Oak #1	Oak #2			
Approximate water level:	40%	Dry			
Sediment level (% total storage):	45%	5%			
Outflow (cfs):	0	0			
Sediment marker (install or replace)	In Place	In Place			
Identification sign (install or replace)	In Place	In Place			
EROSIONAL:					
Rills and/or gullies on downstream face.	no	no			
Rills and/or gullies on upstream face.	no	no			
Inadequate vegetation.	no	no			
Outlet channel erosion.	no	no			
Burrows.	no	no			
Erosion of toe.	no	no			
Water impounded against downstream toe.	no	no			
Other.	-	-			
STRUCTURAL:					
Differential settling.	no	no			
Cracks, slides, or scarps.	no	no			
Seepage (specify location, color, value).	no	no			
Defective spillways.	no	no			
Other.	-	-			
APPURTENANT STRUCTURES:					
Defective spillways.	no	no			
Dewatering device clogged.	no	no			
Cracking or crushing of pipes.	no	no			
Other.	-	-			

COMMENTS:

Some vegetation in the outlet of both #1 & #2,
but its not obstructing the water flow.



TRAPPER MINING INC.

QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia Perkins

SIGNATURE: Tonia Perkins

DRAINAGE: WEST FLUME

DATE OF INSPECTION: 8/24/2022

POND IDENTIFICATION	West Flume #1				
Approximate water level:	Dry				
Sediment level (% total storage):	0%				
Outflow (cfs):	0-1				
Sediment marker (install or replace)	In Place				
Identification sign (install or replace)	In Place				
EROSIONAL:					
Rills and/or gullies on downstream face.	no				
Rills and/or gullies on upstream face.	no				
Inadequate vegetation.	no				
Outlet channel erosion.	no				
Burrows.	no				
Erosion of toe.	no				
Water impounded against downstream toe.	no				
Other.	-				
STRUCTURAL:					
Differential settling.	no				
Cracks, slides, or scarps.	no				
Seepage (specify location, color, value).	no				
Defective spillways.	no				
Other.	-				
APPURTENANT STRUCTURES:					
Defective spillways.	no				
Dewatering device clogged.	no				
Cracking or crushing of pipes.	no				
Other.	-				
COMMENTS:					



TRAPPER MINING INC.

QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia PerkinsSIGNATURE: Tonia PerkinsDRAINAGE: **MIDDLE FLUME**DATE OF INSPECTION: 8/24/2022

POND IDENTIFICATION	Middle Flume #1	Middle Flume #3			
Approximate water level:	10 %	60 %			
Sediment level (% total storage):	40 %	35 %			
Outflow (cfs):	0	0			
Sediment marker (install or replace)	In Place	In Place			
Identification sign (install or replace)	In Place	In Place			
EROSIONAL:					
Rills and/or gullies on downstream face.	no	no			
Rills and/or gullies on upstream face.	no	no			
Inadequate vegetation.	no	no			
Outlet channel erosion.	no	no			
Burrows.	no	no			
Erosion of toe.	no	no			
Water impounded against downstream toe.	no	no			
Other.	-	-			
STRUCTURAL:					
Differential settling.	no	no			
Cracks, slides, or scarps.	no	no			
Seepage (specify location, color, value).	no	no			
Defective spillways.	no	no			
Other.	-	-			
APPURTENANT STRUCTURES:					
Defective spillways.	no	no			
Dewatering device clogged.	no	no			
Cracking or crushing of pipes.	no	no			
Other.	-	-			
COMMENTS:					



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia Perkins

SIGNATURE: Tonia Perkins

DRAINAGE: EAST MIDDLE FLUME

DATE OF INSPECTION: 8/24/2022

POND IDENTIFICATION	East Middle Flume #1				
Approximate water level:	90%				
Sediment level (% total storage):	15%				
Outflow (cfs):	0%				
Sediment marker (install or replace)	Underwater				
Identification sign (install or replace)	In Place				
EROSIONAL:					
Rills and/or gullies on downstream face.	no				
Rills and/or gullies on upstream face.	no				
Inadequate vegetation.	no				
Outlet channel erosion.	no				
Burrows.	no				
Erosion of toe.	no				
Water impounded against downstream toe.	no				
Other.	-				
STRUCTURAL:					
Differential settling.	no				
Cracks, slides, or scarps.	no				
Seepage (specify location, color, value).	no				
Defective spillways.	no				
Other.	-				
APPURTENANT STRUCTURES:					
Defective spillways.	no				
Dewatering device clogged.	no				
Cracking or crushing of pipes.	no				
Other.	-				

COMMENTS:



TRAPPER MINING INC.

QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia Perkins

SIGNATURE: *Tonia Perkins*

DRAINAGE: EAST FLUME

DATE OF INSPECTION: *8/24/2022*

POND IDENTIFICATION	East Flume #1				
Approximate water level:	<i>30%</i>				
Sediment level (% total storage):	<i>15%</i>				
Outflow (cfs):	<i>0</i>				
Sediment marker (install or replace)	<i>In Place</i>				
Identification sign (install or replace)	<i>In Place</i>				
EROSIONAL:					
Rills and/or gullies on downstream face.	<i>no</i>				
Rills and/or gullies on upstream face.	<i>no</i>				
Inadequate vegetation.	<i>no</i>				
Outlet channel erosion.	<i>no</i>				
Burrows.	<i>no</i>				
Erosion of toe.	<i>no</i>				
Water impounded against downstream toe.	<i>no</i>				
Other.	<i>-</i>				
STRUCTURAL:					
Differential settling.	<i>no</i>				
Cracks, slides, or scarps.	<i>no</i>				
Seepage (specify location, color, value).	<i>no</i>				
Defective spillways.	<i>no</i>				
Other.	<i>-</i>				
APPURTENANT STRUCTURES:					
Defective spillways.	<i>no</i>				
Dewatering device clogged.	<i>no</i>				
Cracking or crushing of pipes.	<i>no</i>				
Other.	<i>-</i>				
COMMENTS:					



TRAPPER MINING INC.

QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia Perkins

SIGNATURE: *Tonia Perkins*

DRAINAGE: UTE GULCH

DATE OF INSPECTION: *8/24/2022*

POND IDENTIFICATION	Ute #1				
Approximate water level:	<i>5%</i>				
Sediment level (% total storage):	<i>45%</i>				
Outflow (cfs):	<i>0%</i>				
Sediment marker (install or replace)	<i>In Place</i>				
Identification sign (install or replace)	<i>In Place</i>				
EROSIONAL:					
Rills and/or gullies on downstream face.	<i>no</i>				
Rills and/or gullies on upstream face.	<i>no</i>				
Inadequate vegetation.	<i>no</i>				
Outlet channel erosion.	<i>no</i>				
Burrows.	<i>no</i>				
Erosion of toe.	<i>no</i>				
Water impounded against downstream toe.	<i>no</i>				
Other.	<i>-</i>				
STRUCTURAL:					
Differential settling.	<i>no</i>				
Cracks, slides, or scarps.	<i>no</i>				
Seepage (specify location, color, value).	<i>no</i>				
Defective spillways.	<i>no</i>				
Other.	<i>-</i>				
APPURTENANT STRUCTURES:					
Defective spillways.	<i>no</i>				
Dewatering device clogged.	<i>no</i>				
Cracking or crushing of pipes.	<i>no</i>				
Other.	<i>-</i>				
COMMENTS:					



TRAPPER MINING INC.

QUARTERLY SEDIMENT POND INSPECTION REPORT


INSPECTOR: Tonia Perkins

SIGNATURE: 

DRAINAGE: HORSE GULCH

DATE OF INSPECTION: 8/24/2022

POND IDENTIFICATION	Horse #1				
Approximate water level:	30%				
Sediment level (% total storage):	55%				
Outflow (cfs):	0				
Sediment marker (install or replace)	In Place				
Identification sign (install or replace)	In Place				
EROSIONAL:					
Rills and/or gullies on downstream face.	no				
Rills and/or gullies on upstream face.	no				
Inadequate vegetation.	no				
Outlet channel erosion.	no				
Burrows.	no				
Erosion of toe.	no				
Water impounded against downstream toe.	no				
Other.	-				
STRUCTURAL:					
Differential settling.	no				
Cracks, slides, or scarps.	no				
Seepage (specify location, color, value).	no				
Defective spillways.	no				
Other.	-				
APPURTENANT STRUCTURES:					
Defective spillways.	no				
Dewatering device clogged.	no				
Cracking or crushing of pipes.	no				
Other.	-				
COMMENTS:					



TRAPPER MINING INC.

QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia PerkinsSIGNATURE: Tonia PerkinsDRAINAGE: **WEST HORSE GULCH**DATE OF INSPECTION: 8/24/2022

POND IDENTIFICATION	West Horse #1				
Approximate water level:	Dry				
Sediment level (% total storage):	20%				
Outflow (cfs):	0				
Sediment marker (install or replace)	In Place				
Identification sign (install or replace)	In Place				
EROSIONAL:					
Rills and/or gullies on downstream face.	no				
Rills and/or gullies on upstream face.	no				
Inadequate vegetation.	no				
Outlet channel erosion.	no				
Burrows.	no				
Erosion of toe.	no				
Water impounded against downstream toe.	no				
Other.	-				
STRUCTURAL:					
Differential settling.	no				
Cracks, slides, or scarps.	no				
Seepage (specify location, color, value).	no				
Defective spillways.	no				
Other.	-				
APPURTENANT STRUCTURES:					
Defective spillways.	no				
Dewatering device clogged.	no				
Cracking or crushing of pipes.	no				
Other.	-				
COMMENTS:					



TRAPPER MINING INC.

QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia Perkins

SIGNATURE: Tonia Perkins

DRAINAGE: DEAL GULCH

DATE OF INSPECTION: 8/24/2022

POND IDENTIFICATION	Deal #1	Deal #2			
Approximate water level:	40%	Dry			
Sediment level (% total storage):	10%	0%			
Outflow (cfs):	0%	0%			
Sediment marker (install or replace)	In Place	In Place			
Identification sign (install or replace)	In Place	In Place			
EROSIONAL:					
Rills and/or gullies on downstream face.	no	no			
Rills and/or gullies on upstream face.	no	no			
Inadequate vegetation.	no	no			
Outlet channel erosion.	no	no			
Burrows.	no	no			
Erosion of toe.	no	no			
Water impounded against downstream toe.	no	no			
Other.	-	-			
STRUCTURAL:					
Differential settling.	no	no			
Cracks, slides, or scarps.	no	no			
Seepage (specify location, color, value).	no	no			
Defective spillways.	no	no			
Other.	-	-			
APPURTENANT STRUCTURES:					
Defective spillways.	no	no			
Dewatering device clogged.	no	no			
Cracking or crushing of pipes.	no	no			
Other.	-	-			
COMMENTS:					



TRAPPER MINING INC.

QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia Perkins

DRAINAGE: DEACON

SIGNATURE: 

DATE OF INSPECTION: 8/24/2022

POND IDENTIFICATION	Deacon #1	Deacon #2			
Approximate water level:	0%	0%			
Sediment level (% total storage):	0%	0%			
Outflow (cfs):	0%	0%			
Sediment marker (install or replace)	In Place	In Place			
Identification sign (install or replace)	In Place	In Place			
EROSIONAL:					
Rills and/or gullies on downstream face.	no	no			
Rills and/or gullies on upstream face.	no	no			
Inadequate vegetation.	no	no			
Outlet channel erosion.	no	no			
Burrows.	no	no			
Erosion of toe.	no	no			
Water impounded against downstream toe.	no	no			
Other.	-	-			
STRUCTURAL:					
Differential settling.	no	no			
Cracks, slides, or scarps.	no	no			
Seepage (specify location, color, value).	no	no			
Defective spillways.	no	no			
Other.	-	-			
APPURTENANT STRUCTURES:					
Defective spillways.	no	no			
Dewatering device clogged.	no	no			
Cracking or crushing of pipes.	no	no			
Other.	-	-			
COMMENTS:					



TRAPPER MINING INC.

QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia Perkins

DRAINAGE: JEFFWAY

SIGNATURE

DATE OF INSPECTION:

Tonia Perkins
8/24/2022

POND IDENTIFICATION	Jeffway #1				
Approximate water level:	<i>Dry</i>				
Sediment level (% total storage):	<i>0%</i>				
Outflow (cfs):	<i>0 cfs</i>				
Sediment marker (install or replace)	<i>In Place</i>				
Identification sign (install or replace)	<i>Install *</i>				
EROSIONAL:					
Rills and/or gullies on downstream face.	<i>no</i>				
Rills and/or gullies on upstream face.	<i>no</i>				
Inadequate vegetation.	<i>no</i>				
Outlet channel erosion.	<i>no</i>				
Burrows.	<i>no</i>				
Erosion of toe.	<i>no</i>				
Water impounded against downstream toe.	<i>no</i>				
Other	<i>-</i>				
STRUCTURAL:					
Differential settling.	<i>no</i>				
Cracks, slides, or scarps.	<i>no</i>				
Seepage (specify location, color, value).	<i>no</i>				
Defective spillways.	<i>no</i>				
Other.	<i>-</i>				
APPURTENANT STRUCTURES:					
Defective spillways.	<i>no</i>				
Dewatering device clogged.	<i>no</i>				
Cracking or crushing of pipes.	<i>no</i>				
Other.	<i>-</i>				

COMMENTS:

** Cows have knocked ID sign out of the ground.
 Needs to be pounded back into the ground.*



TRAPPER MINING INC.

QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia Perkins

SIGNATURE: Tonia Perkins

DRAINAGE: IMPOUNDMENT H

DATE OF INSPECTION: 8/24/2022

POND IDENTIFICATION	Impoundment H				
Approximate water level:	Dry				
Sediment level (% total storage):	5%				
Outflow (cfs):	0%				
Sediment marker (install or replace)	In Place				
Identification sign (install or replace)	In Place				
EROSIONAL:					
Rills and/or gullies on downstream face.	no				
Rills and/or gullies on upstream face.	no				
Inadequate vegetation.	no				
Outlet channel erosion.	no				
Burrows.	no				
Erosion of toe.	no				
Water impounded against downstream toe.	no				
Other.	-				
STRUCTURAL:					
Differential settling.	no				
Cracks, slides, or scarps.	no				
Seepage (specify location, color, value).	no				
Defective spillways.	no				
Other.	-				
APPURTENANT STRUCTURES:					
Defective spillways.	no				
Dewatering device clogged.	no				
Cracking or crushing of pipes.	no				
Other.	-				
COMMENTS:					



TRAPPER MINING INC.

QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia Perkins

SIGNATURE: 

DRAINAGE: INDUSTRIAL WASTE POND

DATE OF INSPECTION: 8/24/2022

POND IDENTIFICATION	Industrial Waste Pond #1				
Approximate water level:	60%				
Sediment level (% total storage):	5%				
Outflow (cfs):	0%				
Sediment marker (install or replace)	N/A				
Identification sign (install or replace)	In Place				
EROSIONAL:					
Rills and/or gullies on downstream face.	no				
Rills and/or gullies on upstream face.	no				
Inadequate vegetation.	no				
Outlet channel erosion.	no				
Burrows.	no				
Erosion of toe.	no				
Water impounded against downstream toe.	no				
Other.	-				
STRUCTURAL:					
Differential settling.	no				
Cracks, slides, or scarps.	no				
Seepage (specify location, color, value).	no				
Defective spillways.	no				
Other.	-				
APPURTENANT STRUCTURES:					
Defective spillways.	N/A				
Dewatering device clogged.	N/A				
Cracking or crushing of pipes.	N/A				
Other.	-				
COMMENTS:					

