




PERMIT INFORMATION

Permit Number: C1981033 Mine Name: Bear Mine Operator: N/A Operator Address: N/A	County: Gunnison Operation Type: Underground Permit Status: Revoked Ownership: Private
	Operator Representative Present: N/A
Operator Representative Signature: (Field Issuance Only) 	

INSPECTION INFORMATION

Inspection Start Date: November 29, 2022 Inspection Start Time: 14:00 Inspection End Date: November 29, 2022 Inspection End Time: 15:00		Inspection Type: Coal Complete Inspection Inspection Reason: Normal I&E Program Weather: Clear	
Joint Inspection Agency: None		Joint Inspection Contacts: 	
Post Inspection Agency: None		Post Inspection Contacts: 	
Inspector(s): Leigh Simmons	Inspector's Signature: 		Signature Date: December 14,

Inspection Topic Summary

NOTE: Y=Inspected N=Not Inspected R=Comments Noted V=Violation Issued NA=Not Applicable

N - Air Resource Protection
 N - Availability of Records
 N - Backfill & Grading
 N - Excess Spoil and Dev. Waste
 N - Explosives
 N - Fish & Wildlife
 N - Hydrologic Balance
 N - Gen. Compliance With Mine Plan
 N - Other
 N - Processing Waste

R - Roads
 N - Reclamation Success
 N - Revegetation
 N - Subsidence
 R - Slides and Other Damage
 N - Support Facilities On-site
 N - Signs and Markers
 N - Support Facilities Not On-site
 N - Special Categories Of Mining
 N - Topsoil

COMMENTS

The Bear mine permit is revoked, the site has been reclaimed, and the required inspection frequency has been reduced to quarterly. The weather was cold and clear and the ground was frozen hard. Contractors with Tetra Tech, and their subcontractors (Bower Brothers Construction of Craig, CO, and Authentic Drilling of Kiowa, CO), were on site, attempting to characterise the underground coal fire.

ROADS – Rule 4.03

Construction 4.03.1(3)/4.03.2(3), Drainage 4.03.1(4)/4.03.2(4), Surfacing and Maintenance 4.03.1(5) and (6)/4.03.2(5) and (6), Reclamation 4.03.1(7)/4.03.2(7):

Bower Brothers had been contracted to maintain road access to the bench. Another road had been constructed from the first hairpin to give access immediately below the escarpment - the goal was to provide access for the drill rig to get to the B seam without encountering voids.

SLIDES and DAMAGE - Rule 4.12:

Jeff DeTienne of Tetra Tech described the drilling program. Three holes of a planned 20 had been drilled. The drillers expected to be on site until Christmas. The drilling method was air/rotary. The drill rig advanced a 6 5/8" surface casing into competent rock, then a 3" hole was drilled until either a large void or the target (C or B seam) was encountered. Depending on the conditions encountered the hole could be immediately grouted or could be capped with a thermocouple in place.

DOCUMENTS RECEIVED

N/A

OTHER (SPECIFY)

N/A

ENFORCEMENT ACTIONS/COMPLIANCE

N/A

Number of Partial Inspection this Fiscal Year: 1Number of Complete Inspections this Fiscal Year: 2

PHOTOGRAPHS



Figure 1: Air/rotary drill rig



Figure 2: Access to drilling site

Number of Partial Inspection this Fiscal Year: 1

Number of Complete Inspections this Fiscal Year: 2



Figure 3: Equipment on site



Figure 4: Road access from first hairpin below escarpment

Number of Partial Inspection this Fiscal Year: 1

Number of Complete Inspections this Fiscal Year: 2