

Reilley - DNR, Robin <robin.reilley@state.co.us>

Inspections: Seneca IIW and Williams Fork June 2023

1 message

Reilley - DNR, Robin <robin.reilley@state.co.us> Fri, Jun 23, 2023 at 10:22 AM To: "Kawcak, Miranda" <MKawcak@peabodyenergy.com>, Robin Reilley - DNR <robin.reilley@state.co.us>

Good Morning Miranda,

Please find the above referenced inspection reports. Please let me know of any questions that come up.

Robin Reilley, M.S. GISP Environmental Protection Specialist II



P 303.866.3567 ext 8105 | F 303.832.8106 Physical Address: 1313 Sherman Street St., Suite 215, Denver, CO 80203 Mailing Address: DRMS Room 215, 1001 E 62nd Ave, Denver, CO 80216 robin.reilley@state.co.us | http://mining.state.co.us

2 attachments



WF_Inspection__2023June.pdf



PERMIT INFORMATION

Permit Number: C-1981-044 **Mine Name:** Williams Fork Mines **Operator:** Moffat County Mining, LLC

Operator Address: MS Miranda Kawcak 29515 Routt County Road #27 Oak Creek, CO 80467 County: Moffat Operation Type: Underground Permit Status: Active Ownership: Private

Operator Representative Present:

Miranda Kawcak

Operator Representative Signature: (Field Issuance Only)

This report was issued electronically from the Divisions' Denver Office.

INSPECTION INFORMATION

Inspection Start Date: June 22, 2 Inspection Start Time: 8:30 a.m. Inspection End Date: June 22, 20 Inspection End Time: 4:00 p.m.			Inspection Type: Coal Cor Inspection Reason: OSM (Weather: Cloudy	1 I
Joint Inspection Agency:		Joint Inspection Contacts:		
None				
Post Inspection Agency:		Post Inspection Contacts:		
None				
Inspector(s):	Inspecto	r's Sig	nature:	Signature Date:
Robin Reilley, GISP Amber Michels DRMS Brook Zeller OSM	Boli	n s	Keillen	June 22 2023

NOTE: Y=Inspected	N=Not Inspected R=Comments Noted V=Violation Issued
NA=Not Applicable	
R - Air Resource Protection	R - Roads
N - Availability of Records	R - Reclamation Success
R - Backfill & Grading	R - Revegetation
NA - Excess Spoil and Dev. Was	Y - Subsidence
NA - Explosives	Y - Slides and Other Damage
R - Fish & Wildlife	Y - Support Facilities On-site
R - Hydrologic Balance	R - Signs and Markers
R - Gen. Compliance With Mine	an NA - Support Facilities Not On-site
N - Other	NA - Special Categories Of Mining
NA - Processing Waste	R - Topsoil

COMMENTS

This was a complete inspection of the Williams Fork Mine; permit C1981044, operated by Moffat County Mining LLC. The inspection was conducted and the report and photos prepared by me, Robin Reilley of the DRMS. Miranda Kawcak, mine representative, was present throughout the inspection. Amber Michels of the DRMS participated in the inspection. As this also comprised an oversight inspection, Brook Zeller of the Office of Surface Mining (OSM) was also present throughout the inspection. The temperature hovered around 75 degrees F. There was a light breeze and conditions were cloudy. Wildlife, particularly deer and elk frequent the site. Numerous carcasses littered the landscape due to the severe winter.

Records were checked seperately after the OSM oversight inspection.

PERMITTING ACTIONS in PROGRESS: RN8

MAINTENANCE ITEMS Rills and gullies at the slope below the No 5 Portal to the 5A-P1 Pond

MAINTENANCE ITEMS ADDRESSED

INSPECTION

GENERAL MINE PLAN COMPLIANCE:

Reclamation is progressing as permitted. Facilities have been removed throughout the site and reclamation has been completed. Topsoil below the 5A Portal was placed and will be seeded this spring.

SIGNS and MARKERS – Rule 4.02

o Ponds were staked and topsoil piles were marked.

ROADS - Rule 4.03

Construction 4.03.1(3) I 4.03.2(3); Drainage 4.03.1(4) I 4.03.2(4); Surfacing and Maintenance 4.03.1(5) and (6) I 4.03.2(5) and (6); Reclamation 4.03.1(7) I 4.03.2(7)

• The Haul Road at the entrance off State Highway 13 was passable and the site completely was accessible.

HYDROLOGIC BALANCE – Rule 4.05

Drainage Control 4.05.1, 4.05.2, 4.05.3; Siltation Structures 4.05.5, 4.05.6; Discharge Structures 4.05.7, 4.05.10; Diversions 4.05.4; Effluent Limits 4.05.2; Ground Water Monitoring 4.05.13; Drainage-Acid and Toxic Materials 4.05.8; Impoundments 4.05.6, 4.05.9; Stream Buffer Zones 4.05.18

Ponds were holding small amounts of snowmelt.

- Pond 9-P6 was dry at the time of inspection. Several large badger holes exist on pond banks.
- Pond 5A-P1 at 5A at portal was dry at the time of inspection. Sloped area to the pond had been topsoiled but not seeded. The slope has rills and gullies the length of the slope to the pond, approximately 8 to 12 inches wide and varying depths between 3 to 10 inces. The operator agreed to grade these gullies and armor a constructed drainage channel to direct water to the pond.
- Ponds SH- P1 and SH-P2 above the portal appeared dry at the time of inspection.

TOPSOIL – RULE 4.06

Removal 4.06.2; Substitute Materials 4.06.4(4); Storage and Protection 4.06.3; Redistribution 4.06.4

- No instability was noted at the time of inspection and piles were marked with sakes.
- Topsoil pile along road near the SH-P2 pond had been spread at the slope to the 5A-P1 Pond.

SLIDES and OTHER DAMAGE- Rule 4.12

No recent slumping was observed.

BACKFILL and GRADING - RULE 4.14

- Backfilling and grading has been completed.
- Rills and gullies in the recently spread topsoil below the 5A Portal will be graded and repaired.
- A small crack in the slope of the 5A Portal was observed. This will be monitored over the course of the field season for any additional movement.

REVEGETATION - Rule 4.15

General Requirements 4.15.1; Use of Species 4.15.2, Grazing 4.15.5

- Reclamation, (topsoil and seeding) has been completed with the exception seeding at the 5A Portal, scheduled for this spring.
- The weeds identified throughout the inspection included, hounds tongue, thistle, yellow clover, kosha' pig weed and cheat grass. Weeds were not a topic of concern as the operator has a robust weed mitigation program and there was no infestation.
- Hydroseeding of the 5A Portal is scheduled to take place as soon as the hydroseeding products become available.
- Refuse pile exhibited good mix of native grasses, bromes, orchard grass, and some wheat grass. Some small bare spots and weeds were present.
- Cropland areas along the Williams Fork River exhibited established perennial grasses and good ground cover.

FISH and WILDLIFE-RULE 4.18

Wildlife is often observed throughout the Seneca IIW mine site. Wildlife observed comprised a variety of raptors Deer and elk were also observed to have been present at the site.

INSPECTION, ENFORCEMENT and CIVIL PENALTIES – RULE 5 Inspections 5.02; Availability of Records

Permit documents were inspected.

DOCUMENTS RECEIVED

None

OTHER (SPECIFY)

ENFORCEMENT ACTIONS/COMPLIANCE

No enforcement actions were initiated as a result of this inspection, nor are any pending.

PHOTOGRAPHS



Photo 1: Erosion on slope to Pond 5A-P1 at 5A portal.



Photo 2: Erosional features with Pond 5A-P1 at the top of the photo.



Photo 3: Vegetation in the south cropland bottomlands.



Photo 4: Pond 9-P6.



Photo 5: Perennial grasses at the refuse pile looking west.



AVAILABILITY OF RECORDS

PERMIT RECORDS		HYDROLOGIC RECORDS	
DRMS Permit	Yes Exp 2023. RN 6 2015	NPDES Permit	Yes
Permit Application w/Revisions		NPDES Records	2022 Q1 Computer
Findings Document	SL in Miranda's office	Stormwater Management Plan	Yes
Insurance Certificate	Aug 2023	SPCC Plan	Yes
Bond Document	Yes 2016	MSHA Pond Inspections	NA
Phased Bond Release	SL 4 and 5		
Documents/Findings	Miranda Office	State Engineer's Pond Inspection	
Air Emission Permits	yes	Quarterly Pond Inspections	2022 Q2
County Special Use Permits	yes	Annual Hydrology Reports	2020
UG Mining Landowner Notification	yes	Ground Water Monitoring	AHR
Subsidence Monitoring Reports	yes	Surface Water Monitoring	AHR
Subsidence Monitoring Data		Spring & Seep Monitoring	AHR
Rill & Gully Survey	2018	Mine Water Discharge Monitoring	AHR
Vegetation Monitoring Data	Miranda's Office	Mine Inflow Study	
Specific Variance Approvals	NA	Water Consumption Records	
Annual Reclamation Reports	2021	Well Permits	yes
Midterm Review Documents	MT7 2013		
DRMS/OSM Inspection Reports/Enforcement Actions (3 Years)	Through January 2022	BLASTING RECORDS	
Transfers/Succession of Operator	2006	Blasting Publication	NA
Temporary Cessation Notification	2016 Deactivated	Blasting Records (3 years)	NA
Reclamation Cost Estimate	SL5 /MT. Electronically	ATFE Explosives Permit	NA
CERTIFICATIONS		Blasting Variances	NA
Pond Certifications	Permit	Pre-Blast Surveys	NA
Annual Certifications for Impoundments	2021 Q3		
Fill Certifications for Excess Spoil or Underground Development Waste		ADDITIONAL RECORDS (specify)	
Quarterly Inspections			
 Compaction Testing 			
• Final Certification			
Coal Processing Waste Banks	Q1 2022 (reclaimed 2020)		
Haul Road Certifications	permit		
Access Road Certifications	permit		

COMMENTS: Items highlighted in yellow require addressing refuse pile report is included with pond reports