## QUARTERLY POND INSPECTION REPORT

Operator:	Bowie Resources LLC Bowie No. 2 Mine - C-1996-083				Quarter:	Second 2023
Mine:					Inspection Date:	29-Jun-23
Pond Identification	В	l c	D - Gob Pile	F - New Gob	J UTL East	K UTL West
Type of Pond	Sediment	Sediment	Sediment	Sediment	Sediment	Sediment
Status During Inspection:						
Approximate Water Level	5942'	5991'	5970'	5944'	5846'	5819
Sediment (% remaining)	90%	90%	80%	60%	80%	80%
Outflow (cfs)	0	0	0	0	0	0
- -eatures	Problem	Problem	Problem	Problem	Problem	Problem
· Catal CO	Yes/No	Yes/No	Yes/No	Yes/No	Yes/No	Yes/No
Erosional	/	1		L		
Rills & Gulleys	No	No	No	No	No	No
Inadequate Vegetation	No	No	No	No	No	No
Outlet Channel Erosion	No	No	No	No	No	No
Burrows	No	No	No	No	No	No
Other	No	No	No	No	No	No
Structural						
Differential Settling	No	No	No	No	No	No
Cracks or Slides	No	No	No	No	No	No
Seepage	No	No	No	No	No	No
Other	No	No	No	No	No	No
Appurtenant Structures Defective Spillways	No	No	No	No	I / No I	No
Devatering Devices Clogged	No	No	No	No	No	No
Faulty Gates, Etc.	No	No	No	No	No	No
Other	No	No	No	No	No	No

## Additional Comments

Design depth measured from pond bottom to invert of emergency spillway:

Pond B=10, C=10, D=10, J=10, K=3, F=10' TD

Pond Bottom Elevations B=5942, C=5990, D=5970, J=5846, F=5944, K=5819

Pond C was a puddle, at most held 1 foot of water.

Pond B was dry.

Pond D was dry.

Pond J was dry.

Pond K was dry.

Pond F was dry.

SWMP components were inspected and found to be in good condition. No corrections necessary at this time.

Name of Inspector: Tamme Bishop

