



TRAPPER MINING INC.

October 18, 2023

Ms. Robin Reilley
Environmental Protection Specialist
Colorado Division of Reclamation, Mining, and Safety
1313 Sherman Street, Room 215
Denver, CO 80203

Dear Ms. Robin Reilley:

**RE: Trapper Mining Inc., Permit C-81-010
Fourth Quarter 2023 Sediment Pond Inspections**

All impoundment inspections were conducted by a qualified impoundment inspector. Inspections took place on October 10th and October 17th.

The following maintenance items were noted:

- Far East Buzzard sediment marker needs to be repaired.
- East Pyeatt #1 sediment marker need to be replaced.
- Jeffway #1 identification sign needs to be repaired.

Trapper will address these maintenance items in a timely matter.


Data related to pond capacity is attached. The last column on the table provides an estimate of the remaining capacity in each pond where remaining capacity is defined as the volume remaining after considering the estimated amount of sediment noted during the inspections.

Please contact me if you have any questions.

Sincerely,

Tonia Marie Perkins
CO PE 43864

C: EQ file 118.7



Trapper Mining Inc.
Fourth Quarter 2023
Impoundment Inspection - Pond Capacity Data

Pond ID	Princ. Spillway Stage (ft)	Total Capacity to PS stage (acre-feet)	60% Sediment Capacity (acre-feet)	60% Sediment Capacity Stage (ft)	Remaining Design Capacity (acre-feet)	Inspection Observation (% sediment)	Qtr. 4 Estimated Sediment (acre-feet)	Qtr. 4 Approximate Rem. Capacity (acre-feet)
Far East Buzzard	2.0	0.03	0.02	1.4	0.01	10.00	0.00	0.03
Coyote	30.5	75.1	45.06	26.7	30.04	0.00	0.00	75.10
No Name #2	8.5	8.47	5.08	6.0	3.39	10.00	0.85	7.62
No Name #4	14.5	8.23	4.94	11.7	3.29	15.00	1.23	7.00
No Name #5	6.0	1.03	0.62	4.7	0.41	25.00	0.26	0.77
Johnson #6	9.0	1.80	1.08	7.1	0.72	25.00	0.45	1.35
Johnson #7R	7.0	2.99	1.79	5.2	1.20	35.00	1.05	1.94
Johnson #8	7.0	3.58	2.15	4.6	1.43	35.00	1.25	2.33
Johnson #9	8.5	2.74	1.64	6.6	1.10	20.00	0.55	2.19
Johnson #10	9.0	6.09	3.65	7.0	2.44	25.00	1.52	4.57
West Pyeatt #1	9.0	2.76	1.66	7.0	1.10	45.00	1.24	1.52
West Pyeatt #2	10.0	1.89	1.13	7.3	0.76	45.00	0.85	1.04
Middle Pyeatt #1	10.0	1.40	0.84	8.1	0.56	10.00	0.14	1.26
Middle Pyeatt #2	10.0	1.26	0.76	8.4	0.50	25.00	0.32	0.95
Middle Pyeatt #3	10.0	5.70	3.42	7.9	2.28	40.00	2.28	3.42
East Pyeatt #1	8.0	0.99	0.59	6.5	0.40	0.00	0.00	0.99
East Pyeatt #2	8.0	4.15	2.49	6.1	1.66	20.00	0.83	3.32
East Pyeatt #3	8.0	1.51	0.91	6.8	0.60	30.00	0.45	1.06
Grouse #1	7.5	3.35	2.01	5.7	1.34	40.00	1.34	2.01
Grouse #2	4.5	0.79	0.47	3.6	0.32	15.00	0.12	0.67
Sage #1	8.0	2.67	1.60	6.4	1.07	10.00	0.27	2.40
Sage #2	7.0	2.07	1.24	5.8	0.83	10.00	0.21	1.86
Oak #1	13.0	1.43	0.86	10.6	0.57	45.00	0.64	0.79
Oak #2	9.5	0.93	0.56	7.7	0.37	10.00	0.09	0.84

Trapper Mining Inc.
Fourth Quarter 2023
Impoundment Inspection - Pond Capacity Data

Pond ID	Princ. Spillway Stage (ft)	Total Capacity to PS stage (acre-feet)	60% Sediment Capacity (acre-feet)	60% Sediment Capacity Stage (ft)	Remaining Design Capacity (acre-feet)	Inspection Observation (% sediment)	Qtr. 4 Estimated Sediment (acre-feet)	Qtr. 4 Approximate Rem. Capacity (acre-feet)
West Flume	10.0	2.35	1.41	7.8	0.94	10.00	0.24	2.12
Middle Flume #1	11.7	0.80	0.48	9.0	0.32	40.00	0.32	0.48
Middle Flume # 3	14.0	3.36	2.02	10.5	1.34	40.00	1.34	2.02
East Middle Flume	13.0	2.56	1.54	9.2	1.02	20.00	0.51	2.05
East Flume	11.3	1.18	0.71	8.5	0.47	15.00	0.18	1.00
Ute	7.0	1.72	1.03	5.2	0.69	45.00	0.77	0.95
Horse	13.3	6.20	3.72	10.3	2.48	55.00	3.41	2.79
West Horse	13.0	2.00	1.20	9.7	0.80	20.00	0.40	1.60
Deal #1	16.8	2.00	1.20	15.1	0.80	15.00	0.30	1.70
Deal #2	6.0	1.66	0.60	3.1	1.06	0.00	0.00	1.66
Deacon #1	14.5	9.00	3.48	7.5	5.52	0.00	0.00	9.00
Deacon #2	12.0	7.03	3.60	7.7	3.43	0.00	0.00	7.03
Jeffway #1	9.0	2.86	1.20	5.3	1.66	0.00	0.00	2.86
Impoundment H	9.5	4.82	2.89	4.9	1.93	5.00	0.24	4.58

TRAPPER MINING INC.**QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia Perkins

SIGNATURE:

**DRAINAGE: FAR EAST BUZZARD**

DATE OF INSPECTION:

10/17/2023

POND IDENTIFICATION	Far East Buzzard #1				
Approximate water level:	OK				
Sediment level (% total storage):	10%				
Outflow (cfs):	0				
Sediment marker (install or replace)	Repair				
Identification sign (install or replace)	In place				
EROSIONAL:					
Rills and/or gullies on downstream face.	NO				
Rills and/or gullies on upstream face.	NO				
Inadequate vegetation.	NO				
Outlet channel erosion.	NO				
Burrows.	NO				
Erosion of toe.	NO				
Water impounded against downstream toe.	NO				
Other.					
STRUCTURAL:					
Differential settling.	NO				
Cracks, slides, or scarps.	NO				
Seepage (specify location, color, value).	NO				
Defective spillways.	NO				
Other.					
APPURTENANT STRUCTURES:					
Defective spillways.	NO				
Dewatering device clogged.	NO				
Cracking or crushing of pipes.	NO				
Other.					
COMMENTS:					

Sediment marker is tilted, needs to be straightened & checked.



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia Perkins

DRAINAGE: COYOTE

SIGNATURE:



DATE OF INSPECTION:

10/17/2023

POND IDENTIFICATION	Coyote #1				
Approximate water level:	30'.				
Sediment level (% total storage):	minimal				
Outflow (cfs):	0				
Sediment marker (install or replace)	N/A				
Identification sign (install or replace)	In Place				
EROSIONAL:					
Rills and/or gullies on downstream face.	no				
Rills and/or gullies on upstream face.	no				
Inadequate vegetation.	no				
Outlet channel erosion.	no				
Burrows.	no				
Erosion of toe.	no				
Water impounded against downstream toe.	no				
Other.	-				
STRUCTURAL:					
Differential settling.	no				
Cracks, slides, or scarps.	no				
Seepage (specify location, color, value).	no				
Defective spillways.	no				
Other.	-				
APPURTENANT STRUCTURES:					
Defective spillways.	no				
Dewatering device clogged.	no				
Cracking or crushing of pipes.	no				
Other.	-				
COMMENTS:					

Sediment level is measured by a fixed surveyed elevation of 6298.11 ft. (9/29/10).



TRAPPER MINING INC.

TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia PerkinsDRAINAGE: **NO NAME**SIGNATURE: *Dennis Marie Perkins*DATE OF INSPECTION: 10/10/2023

POND IDENTIFICATION	No Name #2	No Name #4	No Name #5		
Approximate water level:	100%	100%	100%		
Sediment level (% total storage):	10%	15%	25%		
Outflow (cfs):	< 1 CFS	< 1 CFS	< 1 CFS		
Sediment marker (install or replace)	In Place	In Place	In Place		
Identification sign (install or replace)	In Place	In Place	In Place		
EROSIONAL:					
Rills and/or gullies on downstream face.	NO	NO	NO		
Rills and/or gullies on upstream face.	NO	NO	NO		
Inadequate vegetation.	NO	NO	NO		
Outlet channel erosion.	NO	NO	NO		
Burrows.	NO	NO	NO		
Erosion of toe.	NO	NO	NO		
Water impounded against downstream toe.	NO	NO	NO		
Other.	-	-	-		
STRUCTURAL:					
Differential settling.	NO	NO	NO		
Cracks, slides, or scarps.	NO	NO	NO		
Seepage (specify location, color, value).	NO	NO	NO		
Defective spillways.	NO	NO	NO		
Other.	-	-	-		
APPURTENANT STRUCTURES:					
Defective spillways.	NO	NO	NO		
Dewatering device clogged.	NO	NO	NO		
Cracking or crushing of pipes.	NO	NO	NO		
Other.	-	-	-		
COMMENTS:					

#4: use riser/siphon tube as sediment marker; siphon top = 75%, bottom = 60%.
 #5: 60% level = top of post - 4.5'.

There is some vegetation in outflows of #4 + #5, not hindering the water flow.



TRAPPER MINING INC.**QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia Perkins

SIGNATURE: 

DRAINAGE: JOHNSON GULCH

DATE OF INSPECTION: 10/16/2023

POND IDENTIFICATION	Johnson #6	Johnson #7R	Johnson #8R	Johnson #9R	Johnson #10R
Approximate water level:	100%	100%	100%	100%	100%
Sediment level (% total storage):	25%	35%	35%	20%	25%
Outflow (cfs):	21 CFS	21 CFS	21 CFS	21 CFS	21 CFS
Sediment marker (install or replace)	In Place	Underwater	Underwater	Underwater	Underwater
Identification sign (install or replace)	In Place	In Place	In Place	In Place	In Place
EROSIONAL:					
Rills and/or gullies on downstream face.	no	no	no	no	no
Rills and/or gullies on upstream face.	no	no	no	no	no
Inadequate vegetation.	no	no	no	no	no
Outlet channel erosion.	no	no	no	no	no
Burrows.	no	no	no	no	no
Erosion of toe.	no	no	no	no	no
Water impounded against downstream toe.	no	no	no	no	no
Other.	-	-	-	-	-
STRUCTURAL:					
Differential settling.	no	no	no	no	no
Cracks, slides, or scarps.	no	no	no	no	no
Seepage (specify location, color, value).	no	no	no	no	no
Defective spillways.	no	no	no	no	no
Other.	-	-	-	-	-
APPURTENANT STRUCTURES:					
Defective spillways.	no	no	no	no	no
Dewatering device clogged.	no	no	no	no	no
Cracking or crushing of pipes.	no	no	no	no	no
Other.	-	-	-	-	-
COMMENTS:					

#6: use riser/siphon tube as sediment marker; siphon top = 90%, top - 1.5' = 60%.


There is vegetation in the outflows of #7, #8 & #9, the water flow is not hindered.



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECT Tonia PerkinsDRAINAGE: **WEST PYEATT**

SIGNATURE: _____



DATE OF INSPECTION: _____



POND IDENTIFICATION	West Pyeatt #1	West Pyeatt #2		
Approximate water level:	DRY	DRY		
Sediment level (% total storage):	45%	45%		
Outflow (cfs):	0	0		
Sediment marker (install or replace)	In place	In place		
Identification sign (install or replace)	In place	In place		
EROSIONAL:				
Rills and/or gullies on downstream face.	no	no		
Rills and/or gullies on upstream face.	no	no		
Inadequate vegetation.	no	no		
Outlet channel erosion.	no	no		
Burrows.	no	no		
Erosion of toe.	no	no		
Water impounded against downstream toe.	no	no		
Other.	-	-		
STRUCTURAL:				
Differential settling.	no	no		
Cracks, slides, or scarps.	no	no		
Seepage (specify location, color, value).	no	no		
Defective spillways.	no	no		
Other.	-			
APPURTENANT STRUCTURES:				
Defective spillways.	no	no		
Dewatering device clogged.	no	no		
Cracking or crushing of pipes.	no	no		
Other.	-	-		
COMMENTS:				



TRAPPER MINING INC.

TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia Perkins

SIGNATURE:



DRAINAGE: MIDDLE PYEATT

DATE OF INSPECTION:

10/10/2023

POND IDENTIFICATION	Middle Pyeatt #1	Middle Pyeatt #2	Middle Pyeatt #3		
Approximate water level:	Normal-Muddy	Dry	Dry		
Sediment level (% total storage):	10%	25%	40%		
Outflow (cfs):	0	0	0		
Sediment marker (install or replace)	In Place	In Place	In Place		
Identification sign (install or replace)	In Place	In Place	In Place		
EROSIONAL:					
Rills and/or gullies on downstream face.	no	no	no		
Rills and/or gullies on upstream face.	no	no	no		
Inadequate vegetation.	no	no	no		
Outlet channel erosion.	no	no	no		
Burrows.	no	no	no		
Erosion of toe.	no	no	no		
Water impounded against downstream toe.	no	no	no		
Other.	-	-	-		
STRUCTURAL:					
Differential settling.	no	no	no		
Cracks, slides, or scarps.	no	no	no		
Seepage (specify location, color, value).	no	no	no		
Defective spillways.	no	no	no		
Other.	-	-	-		
APPURTENANT STRUCTURES:					
Defective spillways.	no	no	no		
Dewatering device clogged.	no	no	no		
Cracking or crushing of pipes.	no	no	no		
Other.	-	-	-		
COMMENTS:					



TRAPPER MINING INC.

TRAPPER MINING INC.**QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia Perkins

SIGNATURE:

**DRAINAGE: EAST PYEATT**

DATE OF INSPECTION:

10/10/2023

POND IDENTIFICATION	East Pyeatt #1	East Pyeatt #2	East Pyeatt #3		
Approximate water level:	Minimal - Muddy	100% 20%	100% 30%		
Sediment level (% total storage):	0	21 CFS	21 CFS		
Outflow (cfs):	21 CFS	21 CFS	21 CFS		
Sediment marker (install or replace)	Needs to be replaced	underwater	underwater		
Identification sign (install or replace)	In Place	In Place	In Place		
EROSIONAL:					
Rills and/or gullies on downstream face.	NO	NO	NO		
Rills and/or gullies on upstream face.	NO	NO	NO		
Inadequate vegetation.	NO	NO	NO		
Outlet channel erosion.	NO	NO	NO		
Burrows.	NO	NO	NO		
Erosion of toe.	NO	NO	NO		
Water impounded against downstream toe.	NO	NO	NO		
Other.	-	-	-		
STRUCTURAL:					
Differential settling.	NO	NO	NO		
Cracks, slides, or scarps.	NO	NO	NO		
Seepage (specify location, color, value).	NO	NO	NO		
Defective spillways.	NO	NO	NO		
Other.	-	-	-		
APPURTENANT STRUCTURES:					
Defective spillways.	NO	NO	NO		
Dewatering device clogged.	NO	NO	NO		
Cracking or crushing of pipes.	NO	NO	NO		
Other.	-	-	-		
COMMENTS:					

**TRAPPER MINING INC.**

TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tim Cummins

SIGNATURE:



DRAINAGE: GROUSE GULCH

DATE OF INSPECTION: 10/10/23

POND IDENTIFICATION	Grouse #1	Grouse #2			
Approximate water level:	30%	1%			
Sediment level (% total storage):	40%	15%			
Outflow (cfs):	0	0			
Sediment marker (install or replace)	in place	in place			
Identification sign (install or replace)	in place	in place			
EROSIONAL:					
Rills and/or gullies on downstream face.	No	No			
Rills and/or gullies on upstream face.	No	No			
Inadequate vegetation.	No	No			
Outlet channel erosion.	No	No			
Burrows.	No	No			
Erosion of toe.	No	No			
Water impounded against downstream toe.	No	No			
Other.	—	—			
STRUCTURAL:					
Differential settling.	No	No			
Cracks, slides, or scarps.	No	No			
Seepage (specify location, color, value).	No	No			
Defective spillways.	No	No			
Other.	—	—			
APPURTENANT STRUCTURES:					
Defective spillways.	No	No			
Dewatering device clogged.	No	No			
Cracking or crushing of pipes.	No	No			
Other.	—	—			
COMMENTS:	Grouse #2 almost dry.				



TRAPPER MINING INC.

TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tim Cummins

SIGNATURE: *Tim Cummins*

DRAINAGE: SAGE GULCH

DATE OF INSPECTION: 10/10/23

POND IDENTIFICATION	Sage #1	Sage #2			
Approximate water level:	0 %	0 %			
Sediment level (% total storage):	10 %	10 %			
Outflow (cfs):	0	0			
Sediment marker (install or replace)	in place	in place			
Identification sign (install or replace)	in place	in place			
EROSIONAL:					
Rills and/or gullies on downstream face.	No	No			
Rills and/or gullies on upstream face.	No	No			
Inadequate vegetation.	No	No			
Outlet channel erosion.	No	No			
Burrows.	No	No			
Erosion of toe.	No	No			
Water impounded against downstream toe.	No	No			
Other.	—	—			
STRUCTURAL:					
Differential settling.	No	No			
Cracks, slides, or scarps.	No	No			
Seepage (specify location, color, value).	No	No			
Defective spillways.	No	No			
Other.	—	—			
APPURTENANT STRUCTURES:					
Defective spillways.	No	No			
Dewatering device clogged.	No	No			
Cracking or crushing of pipes.	No	No			
Other.	—	—			
COMMENTS:	Both ponds were dry				



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia PerkinsSIGNATURE: *Tonia Perkins*DRAINAGE: **OAK GULCH**DATE OF INSPECTION: 10/10/2023

POND IDENTIFICATION	Oak #1	Oak #2			
Approximate water level:	58%	DRY			
Sediment level (% total storage):	45%	10%			
Outflow (cfs):	0	0			
Sediment marker (install or replace)	In Place	In Place			
Identification sign (install or replace)	In Place	In Place			
EROSIONAL:					
Rills and/or gullies on downstream face.	NO	NO			
Rills and/or gullies on upstream face.	NO	NO			
Inadequate vegetation.	NO	NO			
Outlet channel erosion.	NO	NO			
Burrows.	NO	NO			
Erosion of toe.	NO	NO			
Water impounded against downstream toe.	NO	NO			
Other.	-				
STRUCTURAL:					
Differential settling.	NO	NO			
Cracks, slides, or scarps.	NO	NO			
Seepage (specify location, color, value).	NO	NO			
Defective spillways.	NO	NO			
Other.					
APPURTENANT STRUCTURES:					
Defective spillways.	NO	NO			
Dewatering device clogged.	NO	NO			
Cracking or crushing of pipes.	NO	NO			
Other.	-				
COMMENTS:					

Some vegetation in the outflows of #1 & #2, not hindering water flow.



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia Perkins

DRAINAGE: WEST FLUME

SIGNATURE:



DATE OF INSPECTION:

10/10/2023

POND IDENTIFICATION	West Flume #1				
Approximate water level:	PRY				
Sediment level (% total storage):	10%				
Outflow (cfs):	0				
Sediment marker (install or replace)	In Place				
Identification sign (install or replace)	In Place				
EROSIONAL:					
Rills and/or gullies on downstream face.	NO				
Rills and/or gullies on upstream face.	NO				
Inadequate vegetation.	NO				
Outlet channel erosion.	NO				
Burrows.	NO				
Erosion of toe.	NO				
Water impounded against downstream toe.	NO				
Other.	-				
STRUCTURAL:					
Differential settling.	NO				
Cracks, slides, or scarps.	NO				
Seepage (specify location, color, value).	NO				
Defective spillways.	NO				
Other.	-				
APPURTENANT STRUCTURES:					
Defective spillways.	NO				
Dewatering device clogged.	NO				
Cracking or crushing of pipes.	NO				
Other.					
COMMENTS:					



TRAPPER MINING INC.**QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia Perkins

SIGNATURE:

**DRAINAGE: MIDDLE FLUME**

DATE OF INSPECTION:

10/10/2023

POND IDENTIFICATION	Middle Flume #1	Middle Flume #3			
Approximate water level:	40%.	75%.			
Sediment level (% total storage):	40%.	40%.			
Outflow (cfs):	0	0			
Sediment marker (install or replace)	In Place	Underwater			
Identification sign (install or replace)	In Place	In Place			
EROSIONAL:					
Rills and/or gullies on downstream face.	no	no			
Rills and/or gullies on upstream face.	no	no			
Inadequate vegetation.	no	no			
Outlet channel erosion.	no	no			
Burrows.	no	no			
Erosion of toe.	no	no			
Water impounded against downstream toe.	no	no			
Other.	-				
STRUCTURAL:					
Differential settling.	no	no			
Cracks, slides, or scarps.	no	no			
Seepage (specify location, color, value).	no	no			
Defective spillways.	no	no			
Other.					
APPURTENANT STRUCTURES:					
Defective spillways.	no	no			
Dewatering device clogged.	no	no			
Cracking or crushing of pipes.	no	no			
Other.	-	-			
COMMENTS:					



TRAPPER MINING INC.

TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia Perkins

SIGNATURE:



DRAINAGE: EAST MIDDLE FLUME

DATE OF INSPECTION:



POND IDENTIFICATION	East Middle Flume #1				
Approximate water level:	100%				
Sediment level (% total storage):	20%				
Outflow (cfs):	21 CFS				
Sediment marker (install or replace)	Underwater				
Identification sign (install or replace)	In Place				
EROSIONAL:					
Rills and/or gullies on downstream face.	NO				
Rills and/or gullies on upstream face.	NO				
Inadequate vegetation.	NO				
Outlet channel erosion.	NO				
Burrows.	NO				
Erosion of toe.	NO				
Water impounded against downstream toe.	NO				
Other.					
STRUCTURAL:					
Differential settling.	NO				
Cracks, slides, or scarps.	NO				
Seepage (specify location, color, value).	NO				
Defective spillways.	NO				
Other.					
APPURTENANT STRUCTURES:					
Defective spillways.	NO				
Dewatering device clogged.	NO				
Cracking or crushing of pipes.	NO				
Other.	NO				
COMMENTS:					



TRAPPER MINING INC.

TRAPPER MINING INC.**QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia Perkins

SIGNATURE:

**DRAINAGE: EAST FLUME**

DATE OF INSPECTION:

10/10/2023

POND IDENTIFICATION	East Flume #1				
Approximate water level:	DRY				
Sediment level (% total storage):	15%				
Outflow (cfs):	0				
Sediment marker (install or replace)	In Place				
Identification sign (install or replace)	In Place				
EROSIONAL:					
Rills and/or gullies on downstream face.	no				
Rills and/or gullies on upstream face.	no				
Inadequate vegetation.	no				
Outlet channel erosion.	no				
Burrows.	no				
Erosion of toe.	no				
Water impounded against downstream toe.	no				
Other.	-				
STRUCTURAL:					
Differential settling.	no				
Cracks, slides, or scarps.	no				
Seepage (specify location, color, value).	no				
Defective spillways.	no				
Other.	-				
APPURTENANT STRUCTURES:					
Defective spillways.	no				
Dewatering device clogged.	no				
Cracking or crushing of pipes.	no				
Other.	-				
COMMENTS:					



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia Perkins

DRAINAGE: UTE GULCH

SIGNATURE:



DATE OF INSPECTION:

10/17/2023

POND IDENTIFICATION	Ute #1				
Approximate water level:	55 ft				
Sediment level (% total storage):	45%				
Outflow (cfs):	0				
Sediment marker (install or replace)	In place				
Identification sign (install or replace)	In place				
EROSIONAL:					
Rills and/or gullies on downstream face.	no				
Rills and/or gullies on upstream face.	no				
Inadequate vegetation.	no				
Outlet channel erosion.	no				
Burrows.	no				
Erosion of toe.	no				
Water impounded against downstream toe.	no				
Other.	-				
STRUCTURAL:					
Differential settling.	no				
Cracks, slides, or scarps.	no				
Seepage (specify location, color, value).	no				
Defective spillways.	no				
Other.	-				
APPURTENANT STRUCTURES:					
Defective spillways.	no				
Dewatering device clogged.	no				
Cracking or crushing of pipes.	no				
Other.	-				
COMMENTS:					



TRAPPER MINING INC.

TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia Perkins

DRAINAGE: HORSE GULCH

SIGNATURE:



DATE OF INSPECTION:

10/10/2023

POND IDENTIFICATION	Horse #1				
Approximate water level:	60%.				
Sediment level (% total storage):	55%.				
Outflow (cfs):	0				
Sediment marker (install or replace)	In Place				
Identification sign (install or replace)	In place				
EROSIONAL:					
Rills and/or gullies on downstream face.	NO				
Rills and/or gullies on upstream face.	NO				
Inadequate vegetation.	NO				
Outlet channel erosion.	NO				
Burrows.	NO				
Erosion of toe.	NO				
Water impounded against downstream toe.	NO				
Other.	-				
STRUCTURAL:					
Differential settling.	NO				
Cracks, slides, or scarps.	NO				
Seepage (specify location, color, value).	NO				
Defective spillways.	NO				
Other.	-				
APPURTENANT STRUCTURES:					
Defective spillways.	NO				
Dewatering device clogged.	NO				
Cracking or crushing of pipes.	NO				
Other.	-				
COMMENTS:					




TRAPPER MINING INC.

TRAPPER MINING INC.**QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia Perkins

SIGNATURE:



DRAINAGE: WEST HORSE GULCH

DATE OF INSPECTION:

10/10/2023

POND IDENTIFICATION	West Horse #1				
Approximate water level:	DRY				
Sediment level (% total storage):	20%				
Outflow (cfs):	0				
Sediment marker (install or replace)	In place				
Identification sign (install or replace)	In place				
EROSIONAL:					
Rills and/or gullies on downstream face.	no				
Rills and/or gullies on upstream face.	no				
Inadequate vegetation.	no				
Outlet channel erosion.	no				
Burrows.	no				
Erosion of toe.	no				
Water impounded against downstream toe.	no				
Other.					
STRUCTURAL:					
Differential settling.	no				
Cracks, slides, or scarps.	no				
Seepage (Specify location, color, value).	no				
Defective spillways.	no				
Other.					
APPURTENANT STRUCTURES:					
Defective spillways.	no				
Dewatering device clogged.	no				
Cracking or crushing of pipes.	no				
Other.					
COMMENTS:					



TRAPPER MINING INC.**QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia Perkins

DRAINAGE: DEAL GULCH

SIGNATURE:



DATE OF INSPECTION:

10/10/2023

POND IDENTIFICATION	Deal #1	Deal #2			
Approximate water level:	90%	DRY			
Sediment level (% total storage):	15%	Minimal			
Outflow (cfs):	0	0			
Sediment marker (install or replace)	underwater	In Place			
Identification sign (install or replace)	In Place	In Place			
EROSIONAL:					
Rills and/or gullies on downstream face.	no	no			
Rills and/or gullies on upstream face.	no	no			
Inadequate vegetation.	no	no			
Outlet channel erosion.	no	no			
Burrows.	no	no			
Erosion of toe.	no	no			
Water impounded against downstream toe.	no	no			
Other.	-	-			
STRUCTURAL:					
Differential settling.	no	no			
Cracks, slides, or scarps.	no	no			
Seepage (specify location, color, value).	no	no			
Defective spillways.	no	no			
Other.	-	-			
APPURTENANT STRUCTURES:					
Defective spillways.	no	no			
Dewatering device clogged.	no	no			
Cracking or crushing of pipes.	no	no			
Other.	-	-			
COMMENTS:					



TRAPPER MINING INC.

TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia Perkins

DRAINAGE: DEACON

SIGNATURE:



DATE OF INSPECTION:

10/10/2023

POND IDENTIFICATION	Deacon #1	Deacon #2			
Approximate water level:	DRY	DRY			
Sediment level (% total storage):	0	0			
Outflow (cfs):	0	0			
Sediment marker (install or replace)	In Place	In Place			
Identification sign (install or replace)	In Place	In Place			
EROSIONAL:					
Rills and/or gullies on downstream face:	NO	NO			
Rills and/or gullies on upstream face:	NO	NO			
Inadequate vegetation:	NO	NO			
Outlet channel erosion:	NO	NO			
Burrows:	NO	NO			
Erosion of toe:	NO	NO			
Water impounded against downstream toe:	NO	NO			
Other:	-	-			
STRUCTURAL:					
Differential settling:	NO	NO			
Cracks, slides, or scarps:	NO	NO			
Seepage (specify location, color, value):	NO	NO			
Defective spillways:	NO	NO			
Other:	-	-			
APPURTENANT STRUCTURES:					
Defective spillways:	NO	NO			
Dewatering device clogged:	NO	NO			
Cracking or crushing of pipes:	NO	NO			
Other:	-	-			
COMMENTS:					



TRAPPER MINING INC.

TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia Perkins

DRAINAGE: JEFFWAY

SIGNATURE:

Tonia Perkins

DATE OF INSPECTION:

10/17/2023

POND IDENTIFICATION	Jeffway #1				
Approximate water level:	5'1.				
Sediment level (% total storage):	0				
Outflow (cfs):					
Sediment marker (install or replace)	In Place				
Identification sign (install or replace)	Repair *				
EROSIONAL:					
Rills and/or gullies on downstream face.	no				
Rills and/or gullies on upstream face.	no				
Inadequate vegetation.	no				
Outlet channel erosion.	no				
Burrows.	no				
Erosion of toe.	no				
Water impounded against downstream toe.	no				
Other.	-				
STRUCTURAL:					
Differential settling.	no				
Cracks, slides, or scarps.	no				
Seepage (specify location, color, value).	no				
Defective spillways.	no				
Other.	-				
APPURTENANT STRUCTURES:					
Defective spillways.	no				
Dewatering device clogged.	no				
Cracking or crushing of pipes.	no				
Other.	-				
COMMENTS:					

Tied sign up to post, needs to be secured better.



TRAPPER MINING INC.**QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia Perkins

DRAINAGE: IMPOUNDMENT H

SIGNATURE:



DATE OF INSPECTION:

12/19/2023

POND IDENTIFICATION	Impoundment H					
Approximate water level:	DRY					
Sediment level (% total storage):	5%					
Outflow (cfs):	0					
Sediment marker (install or replace)	In place					
Identification sign (install or replace)	In place					
EROSIONAL:						
Rills and/or gullies on downstream face.	no					
Rills and/or gullies on upstream face.	no					
Inadequate vegetation.	no					
Outlet channel erosion.	no					
Burrows.	no					
Erosion of toe.	no					
Water impounded against downstream toe.	no					
Other.						
STRUCTURAL:						
Differential settling.	no					
Cracks, slides, or scarps.	no					
Seepage (specify location, color, value).	no					
Defective spillways.	no					
Other.						
APPURTENANT STRUCTURES:						
Defective spillways.	no					
Dewatering device clogged.	no					
Cracking or crushing of pipes.	no					
Other.						
COMMENTS:						



TRAPPER MINING INC.

TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia Perkins

SIGNATURE:



DRAINAGE: INDUSTRIAL WASTE POND

DATE OF INSPECTION:

10/10/2023

POND IDENTIFICATION	Industrial Waste Pond #1				
Approximate water level:	85%				
Sediment level (% total storage):	5%				
Outflow (cfs):	0				
Sediment marker (install or replace)	N/A				
Identification sign (install or replace)	In place				
EROSIONAL:					
Rills and/or gullies on downstream face.	no				
Rills and/or gullies on upstream face.	no				
Inadequate vegetation.	no				
Outlet channel erosion.	no				
Burrows.	no				
Erosion of toe.	no				
Water impounded against downstream toe.	no				
Other.					
STRUCTURAL:					
Differential settling.	no				
Cracks, slides, or scarps.	no				
Seepage (specify location, color, value).	no				
Defective spillways.	no				
Other.					
APPURTENANT STRUCTURES:					
Defective spillways.	N/A				
Dewatering device clogged.	N/A				
Cracking or crushing of pipes.	N/A				
Other.					
COMMENTS:					

