

Reilley - DNR, Robin <robin.reilley@state.co.us>

Review_2023 Q3, Q4 Sed Pond and Q4 HG Fill Reports Trapper

1 message

Reilley - DNR, Robin <robin.reilley@state.co.us>

Thu, Oct 19, 2023 at 1:20 PM

To: Tonia Perkins <tonia.perkins@trappermine.com>, Robin Reilley - DNR <robin.reilley@state.co.us>

Dear Ms. Perkins,

Thank you for the timely submission of the above referenced reports. DRMS has no question or concerns at this time.

Sincerely

Robin Reilley, M.S. GISP Environmental Protection Specialist II




P 303.866.3567 ext 8105 |

F 303.832.8106


Physical Address: 1313 Sherman Street St., Suite 215, Denver, CO 80203 Mailing Address: DRMS Room 215, 1001 E 62nd Ave, Denver, CO 80216

robin.reilley@state.co.us | http://mining.state.co.us

3 attachments









19 October 2023

Tonia Perkins Trapper Mine, Inc. P.O. Box 187 Craig, Colorado 81626

RE: Trapper Mining Inc., Permit; C1981010 Review: Sediment Pond Report 2023 Q4

Dear Ms. Perkins

The Colorado Division of Reclamation, Mining and Safety (The Division), has reviewed the above referenced report received by the Division on 18 October 2023. The report complies with applicable sections of Rule 4.05.9 (*Impoundments*). The inspection took place on 10 and 17 October.

Maintenance issues noted during the inspection comprised sediment markers requiring replacement or repair at Far East Buzzard, East Pyeatt #1 and Jeffway #1.

The following ponds were discharging at a rate of less than one cubic foot/second:

- o No Name ponds were 100% full.
- O Johnson #s 6, 7R, 8R, 9R and 10R ponds were 100% full.
- o East Pyeatt s#2 and #3, were 100%, full.
- o East Middle Flume #1

The following ponds held water and where not discharging at the time of inspection:

Oak #1No Name #2Industrial Waste PondDeal #1Ute #1Middle Flume #1 and 3

Grouse Jeffway #1 Horse #1 Coyote

Trappers's Permit indicates that other than Coyote Pond, all sediment ponds with 60% or more of sediment storage used following spring runoff will have the sediment removed in the same year. Sediment levels in the all ponds were recorded.



Thank you for the timely submission of the Q4 2023 Sediment Pond Report. DRMS has no questions or concerns at this time.

Best Regards

Robin Reilley, M.S. GISP Environmental Protection Specialist II

Robin.reilley@state.co.us



4 October 2023

Tonia Perkins Trapper Mine, Inc. P.O. Box 187 Craig, Colorado 81626

RE: Trapper Mining Inc., Permit; C1981010 Review: Sediment Pond Report 2023 Q3

Dear Ms. Perkins

The Colorado Division of Reclamation, Mining and Safety (The Division), has reviewed the above referenced report received by the Division on 4 October 2023. The report complies with applicable sections of Rule 4.05.9 (*Impoundments*). The inspection took place over the course of 29 August and September 11, 12, 13, 16 and 28.

Maintenance issues noted during the inspection comprised sediment markers requiring replacement at East Pyeatt system. Middle Pyeatt Pond #1 and East Pyeatt Pond #1 were being dredged at the time of inspection.

The following ponds were discharging at a rate of less than one cubic foot/second:

- 1. No Name ponds were 100% full.
- 2. Johnson #s 6, 7R, 8R, 9R and 10R ponds were 100% full.
- 3. East Pyeatt s#2 and #3, were 100%, full.
- 4. East Middle Flume #1

The following ponds held water and where not discharging at the time of inspection:

Oak #1 West Horse#1 Sage

Deal #1 No Name #2 Industrial Waste Pond
Grouse Ute #1 Impoundment H

Horse #1 Jeffway #1 Middle Flume #1 and 3

Trappers's Permit indicates that other than Coyote Pond, all sediment ponds with 60% or more of sediment storage used following spring runoff will have the sediment removed in the same year. Sediment levels in the all ponds were recorded.



Thank you for the timely submission of the Q3 2023 Sediment Pond Report. DRMS has no questions or concerns at this time.

Best Regards

Robin Reilley, M.S. GISP Environmental Protection Specialist II

Robin.reilley@state.co.us