



## TRAPPER MINING INC.

April 1, 2024

Ms. Robin Reilley  
Environmental Protection Specialist  
Colorado Division of Reclamation, Mining, and Safety  
1313 Sherman Street, Room 215  
Denver, CO 80203

Dear Ms. Robin Reilley:

**RE: Trapper Mining Inc., Permit C-81-010  
First Quarter 2024 Sediment Pond Inspections**

All impoundment inspections were conducted by a qualified impoundment inspector. Inspections took place on March 5<sup>th</sup>, 12<sup>th</sup>, 14<sup>th</sup>, 21<sup>st</sup> and 27<sup>th</sup>.

The following maintenance items were noted:


- Far East Buzzard sediment marker needs to be repaired.
- Jeffway #1 identification sign needs to be repaired.

Trapper will address these maintenance items in a timely matter.

Data related to pond capacity is attached. The last column on the table provides an estimate of the remaining capacity in each pond where remaining capacity is defined as the volume remaining after considering the estimated amount of sediment noted during the inspections.

Please contact me if you have any questions.

Sincerely,

  
Tonia Marie Perkins  
CO PE 43864

C: EQ file 118.7



**Trapper Mining Inc.**  
**First Quarter 2024**  
**Impoundment Inspection - Pond Capacity Data**

Pond ID	Princ. Spillway Stage (ft)	Total Capacity to PS stage (acre-feet)	60% Sediment Capacity (acre-feet)	60% Sediment Capacity Stage (ft)	Remaining Design Capacity (acre-feet)	Inspection Observation (% sediment)	Qtr. 1 Estimated Sediment (acre-feet)	Qtr. 1 Approximate Rem. Capacity (acre-feet)
Far East Buzzard	2.0	0.03	0.02	1.4	0.01	10.00	0.00	0.03
Coyote	30.5	75.1	45.06	26.7	30.04	0.00	0.00	75.10
No Name #2	8.5	8.47	5.08	6.0	3.39	10.00	0.85	7.62
No Name #4	14.5	8.23	4.94	11.7	3.29	15.00	1.23	7.00
No Name #5	6.0	1.03	0.62	4.7	0.41	25.00	0.26	0.77
Johnson #6	9.0	1.80	1.08	7.1	0.72	25.00	0.45	1.35
Johnson #7R	7.0	2.99	1.79	5.2	1.20	35.00	1.05	1.94
Johnson #8	7.0	3.58	2.15	4.6	1.43	35.00	1.25	2.33
Johnson #9	8.5	2.74	1.64	6.6	1.10	20.00	0.55	2.19
Johnson #10	9.0	6.09	3.65	7.0	2.44	25.00	1.52	4.57
West Pyeatt #1	9.0	2.76	1.66	7.0	1.10	45.00	1.24	1.52
West Pyeatt #2	10.0	1.89	1.13	7.3	0.76	45.00	0.85	1.04
Middle Pyeatt #1	10.0	1.40	0.84	8.1	0.56	10.00	0.14	1.26
Middle Pyeatt #2	10.0	1.26	0.76	8.4	0.50	25.00	0.32	0.95
Middle Pyeatt #3	10.0	5.70	3.42	7.9	2.28	40.00	2.28	3.42
East Pyeatt #1	8.0	0.99	0.59	6.5	0.40	0.00	0.00	0.99
East Pyeatt #2	8.0	4.15	2.49	6.1	1.66	20.00	0.83	3.32
East Pyeatt #3	8.0	1.51	0.91	6.8	0.60	30.00	0.45	1.06
Grouse #1	7.5	3.35	2.01	5.7	1.34	50.00	1.68	1.68
Grouse #2	4.5	0.79	0.47	3.6	0.32	15.00	0.12	0.67
Sage #1	8.0	2.67	1.60	6.4	1.07	10.00	0.27	2.40
Sage #2	7.0	2.07	1.24	5.8	0.83	10.00	0.21	1.86
Oak #1	13.0	1.43	0.86	10.6	0.57	45.00	0.64	0.79
Oak #2	9.5	0.93	0.56	7.7	0.37	10.00	0.09	0.84

**Trapper Mining Inc.**  
**First Quarter 2024**  
**Impoundment Inspection - Pond Capacity Data**

Pond ID	Princ. Spillway Stage (ft)	Total Capacity to PS stage (acre-feet)	60% Sediment Capacity (acre-feet)	60% Sediment Capacity Stage (ft)	Remaining Design Capacity (acre-feet)	Inspection Observation (% sediment)	Qtr. 1 Estimated Sediment (acre-feet)	Qtr. 1 Approximate Rem. Capacity (acre-feet)
West Flume	10.0	2.35	1.41	7.8	0.94	10.00	0.24	2.12
Middle Flume #1	11.7	0.80	0.48	9.0	0.32	40.00	0.32	0.48
Middle Flume # 3	14.0	3.36	2.02	10.5	1.34	40.00	1.34	2.02
East Middle Flume	13.0	2.56	1.54	9.2	1.02	20.00	0.51	2.05
East Flume	11.3	1.18	0.71	8.5	0.47	15.00	0.18	1.00
Ute	7.0	1.72	1.03	5.2	0.69	45.00	0.77	0.95
Horse	13.3	6.20	3.72	10.3	2.48	55.00	3.41	2.79
West Horse	13.0	2.00	1.20	9.7	0.80	20.00	0.40	1.60
Deal #1	16.8	2.00	1.20	15.1	0.80	15.00	0.30	1.70
Deal #2	6.0	1.66	0.60	3.1	1.06	0.00	0.00	1.66
Deacon #1	14.5	9.00	3.48	7.5	5.52	0.00	0.00	9.00
Deacon #2	12.0	7.03	3.60	7.7	3.43	0.00	0.00	7.03
Jeffway #1	9.0	2.86	1.20	5.3	1.66	0.00	0.00	2.86
Impoundment H	9.5	4.82	2.89	4.9	1.93	5.00	0.24	4.58

# **TRAPPER MINING INC.** **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR:

*Tonia Perkins*

DRAINAGE: FAR EAST BUZZARD

SIGNATURE:

*Stacy Perkins*

DATE OF INSPECTION:

*3/12/2024*

POND IDENTIFICATION	Far East Buzzard #1					
Approximate water level:	<i>10'.</i>					
Sediment level (% total storage):	<i>10'.</i>					
Outflow (cfs):	<i>0</i>					
Sediment marker (install or replace)	<i>Replace</i>					
Identification sign (install or replace)	<i>In place</i>					
<b>EROSIONAL:</b>						
Rills and/or gullies on downstream face.	<i>no</i>					
Rills and/or gullies on upstream face.	<i>no</i>					
Inadequate vegetation.	<i>no</i>					
Outlet channel erosion.	<i>no</i>					
Burrows.	<i>no</i>					
Erosion of toe.	<i>no</i>					
Water impounded against downstream toe.	<i>no</i>					
Other.	<i>-</i>					
<b>STRUCTURAL:</b>						
Differential settling.	<i>no</i>					
Cracks, slides, or scarps.	<i>no</i>					
Seepage (specify location, color, value).	<i>no</i>					
Defective spillways.	<i>no</i>					
Other.	<i>-</i>					
<b>APPURTENANT STRUCTURES:</b>						
Defective spillways.	<i>no</i>					
Dewatering device clogged.	<i>no</i>					
Cracking or crushing of pipes.	<i>no</i>					
Other.	<i>-</i>					
COMMENTS:						

*Sediment marker needs to be re-installed - its crooked  
 Pond is frozen & snow covered*



TRAPPER MINING INC.



**TRAPPER MINING INC.****QUARTERLY SEDIMENT POND INSPECTION REPORT**INSPECTOR: Randell Dick

DRAINAGE: COYOTE

SIGNATURE: [Signature]DATE OF INSPECTION: 3/5/2024

POND IDENTIFICATION	Coyote #1				
Approximate water level:	3095				
Sediment level (% total storage):	Minimal				
Outflow (cfs):	2				
Sediment marker (install or replace)	N/A				
Identification sign (install or replace)	IN Place				
<b>EROSIONAL:</b>					
Rills and/or gullies on downstream face.					
Rills and/or gullies on upstream face.	NO				
Inadequate vegetation.	NO				
Outlet channel erosion.	NO				
Burrows.	NO				
Erosion of toe.	NO				
Water impounded against downstream toe.	NO				
Other.					
<b>STRUCTURAL:</b>					
Differential settling.					
Cracks, slides, or scarps.	NO				
Seepage (specify location, color, value).	NO				
Defective spillways.	NO				
Other.					
<b>APPURTENANT STRUCTURES:</b>					
Defective spillways.	NO				
Dewatering device clogged.	NO				
Cracking or crushing of pipes.	NO				
Other.					
COMMENTS:					

Sediment level is measured by a fixed surveyed elevation of 6298.11 ft. (9/29/10).



TRAPPER MINING INC.

**TRAPPER MINING INC.**  
**QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Graham Roberts

SIGNATURE: Al Ole

DRAINAGE: NO NAME

DATE OF INSPECTION: 3-5-24

POND IDENTIFICATION	No Name #2	No Name #4	No Name #5		
Approximate water level:	100%	100%	100%		
Sediment level (% total storage):	10%	15%	25%		
Outflow (cfs):	< 1 cfs	< 1 cfs	< 1 cfs		
Sediment marker (install or replace)	In Place	In Place	In Place		
Identification sign (install or replace)	In Place	In Place	In Place		
<b>EROSIONAL:</b>					
Rills and/or gullies on downstream face.	No	No	No		
Rills and/or gullies on upstream face.	No	No	No		
Inadequate vegetation.	No	No	No		
Outlet channel erosion.	No	No	No		
Burrows.	No	No	No		
Erosion of toe.	No	No	No		
Water impounded against downstream toe.	No	No	No		
Other.	—	—	—		
<b>STRUCTURAL:</b>					
Differential settling.	No	No	No		
Cracks, slides, or scarps.	No	No	No		
Seepage (specify location, color, value).	No	No	No		
Defective spillways.	No	No	No		
Other.	—	—	—		
<b>APPURTENANT STRUCTURES:</b>					
Defective spillways.	No	No	No		
Dewatering device clogged.	NA	NA	NA		
Cracking or crushing of pipes.	NA	NA	NA		
Other.	—	—	—		
<b>COMMENTS:</b>					

#4: use riser/siphon tube as sediment marker; siphon top = 75%, bottom = 60%.  
#5: 60% level = top of post - 4.5'.

*Ponds frozen, dams snow covered, no issues observed.*





# **TRAPPER MINING INC.** **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Sasha KibbutSIGNATURE: [Signature]DRAINAGE: **JOHNSON GULCH**DATE OF INSPECTION: 3/14/24

POND IDENTIFICATION	Johnson #6	Johnson #7R	Johnson #8R	Johnson #9R	Johnson #10R
Approximate water level:	100%	100%	100%	100%	100%
Sediment level (% total storage):	Sig. covered 21 CFS	Sig. covered 21 CFS	Sig. covered 21 CFS	Sig. covered 21 CFS	25% 21 CFS
Outflow (cfs):	Sig. covered 1.2 place	Sig. covered 1.2 place	Sig. covered 1.2 place	Sig. covered 1.2 place	Underwater/ice In place
Sediment marker (install or replace)					
Identification sign (install or replace)					
<b>EROSIONAL:</b>					
Rills and/or gullies on downstream face.	No	No	No	No	No
Rills and/or gullies on upstream face.					
Inadequate vegetation.					
Outlet channel erosion.					
Burrows.					
Erosion of toe.					
Water impounded against downstream toe.					
Other.					
<b>STRUCTURAL:</b>					
Differential settling.	No	No	No	No	No
Cracks, slides, or scarps.					
Seepage (specify location, color, value).					
Defective spillways.					
Other.					
<b>APPURTENANT STRUCTURES:</b>					
Defective spillways.	No	No	No	No	No
Dewatering device clogged.					
Cracking or crushing of pipes.					
Other.					
<b>COMMENTS:</b>					

#6: use riser/siphon tube as sediment marker; siphon top = 90%, top - 1.5' = 60%.

#10 Inspected 3-5-24, ELR



TRAPPER MINING INC.

**TRAPPER MINING INC.****QUARTERLY SEDIMENT POND INSPECTION REPORT**INSPECTOR: Graham RobertsSIGNATURE: GRDRAINAGE: WEST PYEATTDATE OF INSPECTION: 3-5-24

POND IDENTIFICATION	West Pyeatt #1	West Pyeatt #2		
Approximate water level:	80%	0%		
Sediment level (% total storage):	45%	45%		
Outflow (cfs):	0	0		
Sediment marker (install or replace)	In place	In place		
Identification sign (install or replace)	In place	In place		
<b>EROSIONAL:</b>				
Rills and/or gullies on downstream face.	No	No		
Rills and/or gullies on upstream face.	No	No		
Inadequate vegetation.	No	No		
Outlet channel erosion.	No	No		
Burrows.	No	No		
Erosion of toe.	No	No		
Water impounded against downstream toe.	No	No		
Other.				
<b>STRUCTURAL:</b>				
Differential settling.	No	No		
Cracks, slides, or scarps.	No	No		
Seepage (specify location, color, value).	No	No		
Defective spillways.	No	No		
Other.				
<b>APPURTENANT STRUCTURES:</b>				
Defective spillways.	No	No		
Dewatering device clogged.	NA	NA		
Cracking or crushing of pipes.	NA	NA		
Other.				
COMMENTS:				

#1 Beginning to fill, dam - snow covered  
 #2 Snow covered





**TRAPPER MINING INC.****QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR:

*Graham Roberts*

SIGNATURE:

*GR*

DRAINAGE: MIDDLE PYEATT

DATE OF INSPECTION:

*3-5-24*

POND IDENTIFICATION	Middle Pyeatt #1	Middle Pyeatt #2	Middle Pyeatt #3
Approximate water level:	80%	0%	0%
Sediment level (% total storage):	10%	25%	40%
Outflow (cfs):	0	0	0
Sediment marker (install or replace)	In place	In place	In place
Identification sign (install or replace)	In place	In place	In place
<b>EROSIONAL:</b>			
Rills and/or gullies on downstream face.	No	No	No
Rills and/or gullies on upstream face.	No	No	No
Inadequate vegetation.	No	No	No
Outlet channel erosion.	No	No	No
Burrows.	No	No	No
Erosion of toe.	No	No	No
Water impounded against downstream toe.	No	No	No
Other.	—	—	—
<b>STRUCTURAL:</b>			
Differential settling.	No	No	No
Cracks, slides, or scarps.	No	No	No
Seepage (specify location, color, value).	No	No	No
Defective spillways.	No	No	No
Other.	—	—	—
<b>APPURTENANT STRUCTURES:</b>			
Defective spillways.	No	No	No
Dewatering device clogged.	NA	NA	NA
Cracking or crushing of pipes.	NA	NA	NA
Other.	—	—	—
COMMENTS:	<i>Ponds ice and snow covered</i>		



TRAPPER MINING INC.

# **TRAPPER MINING INC.** **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Graham RobertsSIGNATURE: GRDRAINAGE: EAST PYEATTDATE OF INSPECTION: 3-5-24

POND IDENTIFICATION	East Pyeatt #1	East Pyeatt #2	East Pyeatt #3		
Approximate water level:	100%	100%	100%		
Sediment level (% total storage):	N/A	20%	30%		
Outflow (cfs):	21 cfs	< 1 cfs	< 1 cfs		
Sediment marker (install or replace)	Underwater?	Underwater	Underwater		
Identification sign (install or replace)	In place	In place	In place		
<b>EROSIONAL:</b>					
Rills and/or gullies on downstream face.	No	No	No		
Rills and/or gullies on upstream face.	No	No	No		
Inadequate vegetation.	No	No	No		
Outlet channel erosion.	No	No	No		
Burrows.	No	No	No		
Erosion of toe.	No	No	No		
Water impounded against downstream toe.	No	No	No		
Other.					
<b>STRUCTURAL:</b>					
Differential settling.	No	No	No		
Cracks, slides, or scarps.	No	No	No		
Seepage (specify location, color, value).	No	No	No		
Defective spillways.	No	No	No		
Other.					
<b>APPURTENANT STRUCTURES:</b>					
Defective spillways.	No	No	No		
Dewatering device clogged.	N/A	N/A	N/A		
Cracking or crushing of pipes.	N/A	N/A	N/A		
Other.					
COMMENTS:					

All ponds ice and snow covered



TRAPPER MINING INC.



# **TRAPPER MINING INC.** **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: David WhiteSIGNATURE: [Signature]

DRAINAGE: GROUSE GULCH

DATE OF INSPECTION: 5/21/2024

POND IDENTIFICATION	Grouse #1	Grouse #2		
Approximate water level:	90%	30%		
Sediment level (% total storage):	50%	75%		
Outflow (cfs):	0.8	0.8		
Sediment marker (install or replace)	1/2 place	1/2 place		
Identification sign (install or replace)	1/2 place	1/2 place		
<b>EROSIONAL:</b>				
Rills and/or gullies on downstream face.	NO	NO		
Rills and/or gullies on upstream face.				
Inadequate vegetation.				
Outlet channel erosion.				
Burrows.				
Erosion of toe.				
Water impounded against downstream toe.				
Other.				
<b>STRUCTURAL:</b>				
Differential settling.	NO	NO		
Cracks, slides, or scarps.				
Seepage (specify location, color, value).				
Defective spillways.				
Other.				
<b>APPURTENANT STRUCTURES:</b>				
Defective spillways.	NO	NO		
Dewatering device clogged.				
Cracking or crushing of pipes.				
Other.				
COMMENTS:				





**TRAPPER MINING INC.****QUARTERLY SEDIMENT POND INSPECTION REPORT**INSPECTOR: Scott KeckSIGNATURE: DRAINAGE: **SAGE GULCH**DATE OF INSPECTION: 3/21/2024

POND IDENTIFICATION	Sage #1	Sage #2			
Approximate water level:	8 1/2'	0%			
Sediment level (% total storage):	10%	10%			
Outflow (cfs):	6	0			
Sediment marker (install or replace)	10 place	10 place			
Identification sign (install or replace)	10 place	10 place			
<b>EROSIONAL:</b>					
Rills and/or gullies on downstream face.	NO	1/2			
Rills and/or gullies on upstream face.					
Inadequate vegetation.					
Outlet channel erosion.					
Burrows.					
Erosion of toe.					
Water impounded against downstream toe.					
Other.					
<b>STRUCTURAL:</b>					
Differential settling.	NO	1/2			
Cracks, slides, or scarps.					
Seepage (specify location, color, value).					
Defective spillways.					
Other.					
<b>APPURTENANT STRUCTURES:</b>					
Defective spillways.	NO	NO			
Dewatering device clogged.					
Cracking or crushing of pipes.					
Other.					
COMMENTS:					



**TRAPPER MINING INC.****QUARTERLY SEDIMENT POND INSPECTION REPORT**INSPECTOR: David W. WhiteSIGNATURE: [Signature]DRAINAGE: **OAK GULCH**DATE OF INSPECTION: 3/7/2024

POND IDENTIFICATION	Oak #1	Oak #2			
Approximate water level:	100%	65%			
Sediment level (% total storage):	45%	15%			
Outflow (cfs):	41 CFS	OK			
Sediment marker (install or replace)	6 pin	12 pin			
Identification sign (install or replace)	12 pin	12 pin			
<b>EROSIONAL:</b>					
Rills and/or gullies on downstream face.	NO	NO			
Rills and/or gullies on upstream face.					
Inadequate vegetation.					
Outlet channel erosion.					
Burrows.					
Erosion of toe.	↓	↓			
Water impounded against downstream toe.					
Other.					
<b>STRUCTURAL:</b>					
Differential settling.					
Cracks, slides, or scarps.	NO	NO			
Seepage (specify location, color, value).	↓	↓			
Defective spillways.					
Other.					
<b>APPURTENANT STRUCTURES:</b>					
Defective spillways.	NO	NO			
Dewatering device clogged.	↓	↓			
Cracking or crushing of pipes.					
Other.					
COMMENTS:					





**TRAPPER MINING INC.**  
**QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Joselle KelseySIGNATURE: DRAINAGE: **WEST FLUME**DATE OF INSPECTION: 3/27/2024

POND IDENTIFICATION	West Flume #1				
Approximate water level:	104%				
Sediment level (% total storage):	104%				
Outflow (cfs):	0%				
Sediment marker (install or replace)	In place				
Identification sign (install or replace)	In place				
<b>EROSIONAL:</b>					
Rills and/or gullies on downstream face.	1/10				
Rills and/or gullies on upstream face.					
Inadequate vegetation.					
Outlet channel erosion.					
Burrows.					
Erosion of toe.					
Water impounded against downstream toe.					
Other.					
<b>STRUCTURAL:</b>					
Differential settling.	1/10				
Cracks, slides, or scarps.					
Seepage (specify location, color, value).					
Defective spillways.					
Other.					
<b>APPURTENANT STRUCTURES:</b>					
Defective spillways.	1/10				
Dewatering device clogged.					
Cracking or crushing of pipes.					
Other.					
COMMENTS:					





# **TRAPPER MINING INC.** **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Graham RobertsSIGNATURE: GRDRAINAGE: **MIDDLE FLUME**DATE OF INSPECTION: 3-5-24

POND IDENTIFICATION	Middle Flume #1	Middle Flume #3			
Approximate water level:	40%	100%			
Sediment level (% total storage):	40%	40%			
Outflow (cfs):	0	< 1 cfs			
Sediment marker (install or replace)	In place	Underwater			
Identification sign (install or replace)	In place	In place			
<b>EROSIONAL:</b>					
Rills and/or gullies on downstream face.	No	No			
Rills and/or gullies on upstream face.	No	No			
Inadequate vegetation.	No	No			
Outlet channel erosion.	No	No			
Burrows.	No	No			
Erosion of toe.	No	No			
Water impounded against downstream toe.	No	No			
Other.	—	—			
<b>STRUCTURAL:</b>					
Differential settling.	No	No			
Cracks, slides, or scarps.	No	No			
Seepage (specify location, color, value).	No	No			
Defective spillways.	No	No			
Other.	—	—			
<b>APPURTENANT STRUCTURES:</b>					
Defective spillways.	No	No			
Dewatering device clogged.	NA	NA			
Cracking or crushing of pipes.	NA	NA			
Other.	—	—			
COMMENTS:					

Ponds ice and snow covered.



**TRAPPER MINING INC.****QUARTERLY SEDIMENT POND INSPECTION REPORT**INSPECTOR: Graham RobertsSIGNATURE: MR RobertsDRAINAGE: **EAST MIDDLE FLUME**DATE OF INSPECTION: 3-5-24

POND IDENTIFICATION	East Middle Flume #1				
Approximate water level:	100%				
Sediment level (% total storage):	20%				
Outflow (cfs):	< 1 cfs				
Sediment marker (install or replace)	Underwater?				
Identification sign (install or replace)	In place				
<b>EROSIONAL:</b>					
Rills and/or gullies on downstream face.	No				
Rills and/or gullies on upstream face.	No				
Inadequate vegetation.	No				
Outlet channel erosion.	No				
Burrows.	No				
Erosion of toe.	No				
Water impounded against downstream toe.	No				
Other.					
<b>STRUCTURAL:</b>					
Differential settling.	No				
Cracks, slides, or scarps.	No				
Seepage (specify location, color, value).	No				
Defective spillways.	No				
Other.					
<b>APPURTENANT STRUCTURES:</b>					
Defective spillways.	No				
Dewatering device clogged.	NA				
Cracking or crushing of pipes.	NA				
Other.					
COMMENTS:					

Ice and snow covered



TRAPPER MINING INC.



# **TRAPPER MINING INC.** **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR:

*Graham Roberts*

SIGNATURE:

*GR*DRAINAGE: **EAST FLUME**

DATE OF INSPECTION:

*3-5-24*

POND IDENTIFICATION	East Flume #1				
Approximate water level:	<i>0%</i>				
Sediment level (% total storage):	<i>15%</i>				
Outflow (cfs):	<i>0</i>				
Sediment marker (install or replace)	<i>In place</i>				
Identification sign (install or replace)	<i>In place</i>				
<b>EROSIONAL:</b>					
Rills and/or gullies on downstream face.	<i>No</i>				
Rills and/or gullies on upstream face.	<i>No</i>				
Inadequate vegetation.	<i>No</i>				
Outlet channel erosion.	<i>No</i>				
Burrows.	<i>No</i>				
Erosion of toe.	<i>No</i>				
Water impounded against downstream toe.	<i>No</i>				
Other.	<i>No</i>				
<b>STRUCTURAL:</b>					
Differential settling.	<i>No</i>				
Cracks, slides, or scarps.	<i>No</i>				
Seepage (specify location, color, value).	<i>No</i>				
Defective spillways.	<i>No</i>				
Other.	<i>No</i>				
<b>APPURTENANT STRUCTURES:</b>					
Defective spillways.	<i>No</i>				
Dewatering device clogged.	<i>NA</i>				
Cracking or crushing of pipes.	<i>NA</i>				
Other.	<i>NA</i>				
COMMENTS:					

*Pond snow covered*



# **TRAPPER MINING INC.** QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: David K. H. H.DRAINAGE: UTE GULCHSIGNATURE: [Signature]DATE OF INSPECTION: 3/14/24

POND IDENTIFICATION	Ute #1					
Approximate water level:	3m above road 50%					
Sediment level (% total storage):	3m above road 45%					
Outflow (cfs):	0					
Sediment marker (install or replace)	in place					
Identification sign (install or replace)	in place					
<b>EROSIONAL:</b>						
Rills and/or gullies on downstream face.	NO					
Rills and/or gullies on upstream face.						
Inadequate vegetation.						
Outlet channel erosion.						
Burrows.						
Erosion of toe.						
Water impounded against downstream toe.						
Other.						
<b>STRUCTURAL:</b>						
Differential settling.	NO					
Cracks, slides, or scarps.						
Seepage (specify location, color, value).						
Defective spillways.						
Other.						
<b>APPURTENANT STRUCTURES:</b>						
Defective spillways.	NO					
Dewatering device clogged.						
Cracking or crushing of pipes.						
Other.						
COMMENTS:						



TRAPPER MINING INC.

**TRAPPER MINING INC.****QUARTERLY SEDIMENT POND INSPECTION REPORT**INSPECTOR: David HallSIGNATURE: [Signature]DRAINAGE: **HORSE GULCH**DATE OF INSPECTION: 3/14/24

POND IDENTIFICATION	Horse #1					
Approximate water level:	<u>Snow covered 70%</u>					
Sediment level (% total storage):	<u>Snow covered 55%</u>					
Outflow (cfs):	<u>0</u>					
Sediment marker (install or replace)	<u>Snow covered</u>					
Identification sign (install or replace)	<u>1st Place</u>					
<b>EROSIONAL:</b>						
Rills and/or gullies on downstream face.	<u>NO</u>					
Rills and/or gullies on upstream face.						
Inadequate vegetation.						
Outlet channel erosion.						
Barrows.						
Erosion of toe.						
Water impounded against downstream toe.	<u>NO</u>					
Other.						
<b>STRUCTURAL:</b>						
Differential settling.	<u>NO</u>					
Cracks, slides, or scarps.						
Seepage (specify location, color, value).						
Defective spillways.	<u>NO</u>					
Other.						
<b>APPURTENANT STRUCTURES:</b>						
Defective spillways.	<u>NO</u>					
Dewatering device clogged.						
Cracking or crushing of pipes.	<u>NO</u>					
Other.						
COMMENTS:						

**TRAPPER MINING INC.**



# **TRAPPER MINING INC.** **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: David KellerSIGNATURE: [Signature]DRAINAGE: **WEST HORSE GULCH**DATE OF INSPECTION: 3/14/24

POND IDENTIFICATION	West Horse #1				
Approximate water level:	Small covered box				
Sediment level (% total storage):	Small covered box				
Outflow (cfs):	0				
Sediment marker (install or replace)	Small covered box				
Identification sign (install or replace)	1st place				
<b>EROSIONAL:</b>					
Rills and/or gullies on downstream face.	190				
Rills and/or gullies on upstream face.					
Inadequate vegetation.					
Outlet channel erosion.					
Burrows.					
Erosion of toe.					
Water impounded against downstream toe.					
Other.					
<b>STRUCTURAL:</b>					
Differential settling.	NO				
Cracks, slides, or scarps.					
Seepage (specify location, color, value).					
Defective spillways.					
Other.					
<b>APPURTENANT STRUCTURES:</b>					
Defective spillways.	NO				
Dewatering device clogged.					
Cracking or crushing of pipes.					
Other.					
COMMENTS:					





# **TRAPPER MINING INC.** **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Sarah KettellSIGNATURE: DRAINAGE: **DEAL GULCH**DATE OF INSPECTION: 3/14/24

POND IDENTIFICATION	Deal #1	Deal #2		
Approximate water level:	7000 ft	5000 ft		
Sediment level (% total storage):	15%	10%		
Outflow (cfs):	0	0		
Sediment marker (install or replace)	1 in blue	1 in blue		
Identification sign (install or replace)	1 in blue	1 in blue		
<b>EROSIONAL:</b>				
Rills and/or gullies on downstream face.	NO	NO		
Rills and/or gullies on upstream face.				
Inadequate vegetation.				
Outlet channel erosion.				
Burrows.				
Erosion of toe.				
Water impounded against downstream toe.				
Other.				
<b>STRUCTURAL:</b>				
Differential settling.	NO	NO		
Cracks, slides, or scarps.				
Seepage (specify location, color, value).				
Defective spillways.				
Other.				
<b>APPURTENANT STRUCTURES:</b>				
Defective spillways.	NO	NO		
Dewatering device clogged.				
Cracking or crushing of pipes.				
Other.				
COMMENTS:				



**TRAPPER MINING INC.****QUARTERLY SEDIMENT POND INSPECTION REPORT**INSPECTOR: Tonia PerkinsDRAINAGE: **DEACON**SIGNATURE: Tonia PerkinsDATE OF INSPECTION: 3/12/2023

POND IDENTIFICATION	Deacon #1	Deacon #2			
Approximate water level:	SNOW COVER	SNOW COVER			
Sediment level (% total storage):	0	0			
Outflow (cfs):	0	0			
Sediment marker (install or replace)	In Place	In Place			
Identification sign (install or replace)	In Place	In Place			
<b>EROSIONAL:</b>					
Rills and/or gullies on downstream face.	NO	NO			
Rills and/or gullies on upstream face.	NO	NO			
Inadequate vegetation.	NO	NO			
Outlet channel erosion.	NO	NO			
Burrows.	NO	NO			
Erosion of toe.	NO	NO			
Water impounded against downstream toe.	NO	NO			
Other.	-	-			
<b>STRUCTURAL:</b>					
Differential settling.	NO	NO			
Cracks, slides, or scarps.	NO	NO			
Seepage (specify location, color, value).	NO	NO			
Defective spillways.	NO	NO			
Other.	-	-			
<b>APPURTENANT STRUCTURES:</b>					
Defective spillways.	NO	NO			
Dewatering device clogged.	NO	NO			
Cracking or crushing of pipes.	NO	NO			
Other.	-	-			
COMMENTS:					

1.5' SNOW COVER



TRAPPER MINING INC.



**TRAPPER MINING INC.****QUARTERLY SEDIMENT POND INSPECTION REPORT**INSPECTOR: Tonia PerkinsSIGNATURE: Tonia PerkinsDRAINAGE: JEFFWAYDATE OF INSPECTION: 3/16/2024

POND IDENTIFICATION		Jeffway #1					
Approximate water level:		10'.					
Sediment level (% total storage):		0					
Outflow (cfs):		0					
Sediment marker (install or replace)		In Place					
Identification sign (install or replace)		Repair					
<b>EROSIONAL:</b>							
Rills and/or gullies on downstream face.		no					
Rills and/or gullies on upstream face.		no					
Inadequate vegetation.		no					
Outlet channel erosion.		no					
Burrows.		no					
Erosion of toe.		no					
Water impounded against downstream toe.		no					
Other.							
<b>STRUCTURAL:</b>							
Differential settling.		no					
Cracks, slides, or scarps.		no					
Seepage (specify location, color, value).		no					
Defective spillways.		no					
Other.							
<b>APPURTENANT STRUCTURES:</b>							
Defective spillways.		no					
Dewatering device clogged.		no					
Cracking or crushing of pipes.		no					
Other.							

COMMENTS:

ID sign needs new bolts.  
2.5' snow cover, Pond is frozen



**TRAPPER MINING INC.**  
**QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia Perkins

SIGNATURE: Tonia Perkins

DRAINAGE: **IMPOUNDMENT H**

DATE OF INSPECTION: 3/13/2024  
12

POND IDENTIFICATION	Impoundment H				
Approximate water level:	20%.				
Sediment level (% total storage):	5%.				
Outflow (cfs):	0				
Sediment marker (install or replace)	In Place				
Identification sign (install or replace)	In Place				
<b>EROSIONAL:</b>					
Rills and/or gullies on downstream face.	no				
Rills and/or gullies on upstream face.	no				
Inadequate vegetation.	no				
Outlet channel erosion.	no				
Burrows.	no				
Erosion of toe.	no				
Water impounded against downstream toe.	no				
Other.	-				
<b>STRUCTURAL:</b>					
Differential settling.	no				
Cracks, slides, or scarps.	no				
Seepage (specify location, color, value).	no				
Defective spillways.	no				
Other.	-				
<b>APPURTENANT STRUCTURES:</b>					
Defective spillways.	no				
Dewatering device clogged.	no				
Cracking or crushing of pipes.	no				
Other.	-				
COMMENTS:					

Pond is frozen & covered with snow.





# **TRAPPER MINING INC.** **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia PerkinsSIGNATURE: Tonia Perkins

DRAINAGE: INDUSTRIAL WASTE POND

DATE OF INSPECTION: 3/12/2024

POND IDENTIFICATION	Industrial Waste Pond #1				
Approximate water level:	85%				
Sediment level (% total storage):	5%				
Outflow (cfs):	0				
Sediment marker (install or replace)	N/A				
Identification sign (install or replace)	In Place				
<b>EROSIONAL:</b>					
Rills and/or gullies on downstream face.	no				
Rills and/or gullies on upstream face.	no				
Inadequate vegetation.	no				
Outlet channel erosion.	no				
Burrows.	no				
Erosion of toe.	no				
Water impounded against downstream toe.	no				
Other.	-				
<b>STRUCTURAL:</b>					
Differential settling.					
Cracks, slides, or scarps.	no				
Seepage (specify location, color, value).	no				
Defective spillways.	no				
Other.	-				
<b>APPURTENANT STRUCTURES:</b>					
Defective spillways.	N/A				
Dewatering device clogged.	N/A				
Cracking or crushing of pipes.	N/A				
Other.	-				
COMMENTS:					



TRAPPER MINING INC.