

PERMIT INFORMATION

Permit Number: C-1981-038 Mine Name: Bowie No. 1 Mine Operator: Bowie Resources, LLC Operator Address: Mr. Basil Bear P.O. Box 1488 Paonia, CO 81428	County: Delta Operation Type: Underground Permit Status: Active Ownership: Private Operator Representative Present: None
Operator Representative Signature: (Field Issua	nce Only)

INSPECTION INFORMATION

Inspection Start Date: May 22, 2 Inspection Start Time: 13:00 Inspection End Date: May 22, 20 Inspection End Time: 16:00			Inspection Type: Coal Compl Inspection Reason: Normal Id Weather: Cloudy	•	
Joint Inspection Agency:		Joint	Joint Inspection Contacts:		
None					
Post Inspection Agency:		Post Inspection Contacts:			
None					
Inspector(s):	Inspecto	r's Sig	gnature:	Signature Date:	
Robert Zuber, P.E.	Phot D. Th				
				5/23/2024	

Inspection Topic Summary

NOTE: Y=Inspected N=Not Inspected R=Comments Noted V=Violation Issued NA=Not Applicable

Y - Air Resource Protection R - Roads

R - Availability of Records **R** - Reclamation Success

N - Backfill & Grading
NA - Excess Spoil and Dev. Waste
Y - Subsidence

NA - Explosives

Y - Slides and Other Damage

NA - Explosives

NA - Support Facilities On significant for the support for the

Y - Fish & Wildlife

R - Hydrologic Balance

NA - Support Facilities On-site

R - Signs and Markers

Y - Gen. Compliance With Mine Plan

R - Signs and Markers

R - Signs and Markers

R - Signs and Markers

N - Other Y - Special Categories Of Mining

NA - Processing Waste Y - Topsoil

COMMENTS

A complete inspection was conducted by Rob Zuber of DRMS on May 22, 2024. No Bowie Resources Limited (BRL) representative was at the inspection.

No mining or reclamation activities were being conducted at this site. BRL is focusing on Bowie No. 2 in 2024.

The weather was warm and partly cloudy. The ground was muddy.

AVAILABILITY OF RECORDS – Rule 5.02.4(1):

The records were found to be well organized and complete. Please see the list of records included in this report.

HYDROLOGIC BALANCE - Rule 4.05

Drainage Control 4.05.1, 4.05.2, 4.05.3; Siltation Structures 4.05.5, 4.05.6; Discharge Structures 4.05.7, 4.05.10; Diversions 4.05.4; Effluent Limits 4.05.2; Ground Water Monitoring 4.05.13; Surface Water Monitoring 4.05.13; Drainage – Acid and Toxic Materials 4.05.8; Impoundments 4.05.6, 4.05.9; Stream Buffer Zones 4.05.18:

The ponds at the loadout, the Coal Storage Area (near Black Bridge Road), and the West Mine contained little to no water, and no problems were identified with these ponds.

The irrigation ditch that flows under the loadout (the Farmers Ditch) was flowing full. No problems were identified with the large culvert that contains this ditch.

ROADS - Rule 4.03

Construction 4.03.1(3)/4.03.2(3), Drainage 4.03.1(4)/4.03.2(4), Surfacing and Maintenance 4.03.1(5) and (6)/4.03.2(5) and (6), Reclamation 4.03.1(7)/4.03.2(7):

No problems were seen with the road to the reclaimed ROM area.

RECLAMATION SUCCESS - Rule 4.15, Rule 3:

No erosion was seen at the reclaimed ponds at the East Mine (Ponds 1-4) or the West Mine, including the reclaimed road and the West Mine Fan.

REVEGETATION - Rule 4.15

Vegetative Cover; Timing:

The vegetation at the West Mine was good, except for small amounts of thistle. No yellow starthistle was seen.

SIGNS AND MARKERS - Rule 4.02:

No issues with signs or markers were identified during the inspection.

OFFSITE SUPPORT FACILIITES - Rule 4.04, 4.28:

No erosion or other problems were seen with the Coal Storage Area beside the intersection of Highway 133 and Black Bridge Road.

No erosion was seen at the loadout, including the steep slope between the loadout and the orchard below. The trestle across the river appears stable.

DOCUMENTS RECEIVED - none

OTHER (SPECIFY) - none

ENFORCEMENT ACTIONS/COMPLIANCE

No enforcement actions were initiated as a result of this inspection, nor are any pending.

PHOTOGRAPHS



Coal storage area by highway and Black Bridge Road



Drainage at East Mine, looking up at Ponds 1 and 2



Drainage at East Mine, looking down at Ponds 3 and 4



West Mine Fan



Reclaimed road at West Mine

AVAILABILITY OF RECORDS

PERMIT RECORDS	F : 4/00/0000	HYDROLOGIC RECORDS	00 00 100 15
DRMS Permit	Expires 4/20/2028	NPDES Permit	CO-0049045 Exp. 2025
Permit Application w/Revisions	On shelf	NPDES Records (DMRs)	Thru
			April 2024
Findings Document	RN8 findings 7/27/2023	Stormwater Management Plan	Aug. 2018
Insurance Certificate	Exp.5/1/2025	SPCC Plan	No longer valid
Bond Document	SEE COMMENT 1	MSHA Pond Inspections	NA
Phased Bond Release	SL9 findings		NA
Documents/Findings	12/7/2023	State Engineer's Pond Inspection	
Air Emission Permits	NA	Quarterly Pond Inspections	Thru 1Q 2024
County Special Use Permits	NA	Annual Hydrology Reports	2022
UG Mining Landowner Notification	1993 and 1994	Ground Water Monitoring	2022 AHR
Subsidence Monitoring Reports	NA	Surface Water Monitoring	2022 AHR
Subsidence Monitoring Data	NA	Spring & Seep Monitoring	2022 AHR
Rill & Gully Survey	May 2023	Mine Water Discharge Monitoring	NA
Vegetation Monitoring Data		Mine Inflow Study	NA
Specific Variance Approvals	2.06.1(3) Steep	Water Consumption Records	NA
	Slope	·	
Annual Reclamation Reports	2023	Well Permits	NA
Midterm Review Documents	MT8 10/13/2020		
DRMS/OSM Inspection	Thru		
Reports/Enforcement Actions (3 Years)	April 2024	BLASTING RECORDS	NA
Transfers/Succession of Operator	7/29/2009		
Temporary Cessation Notification	NA NA		
Reclamation Cost Estimate	SEE COMMENT 2		
CERTIFICATIONS	\\\ 1 and \\\ 2 (2002\	ADDITIONAL RECORDS	
Pond Certifications	W-1 and W-2 (2002)		D'I #2000FF
Annual Certifications for Large Impoundments	NA	CDOT Access Permit	Permit #399055 (June 1999)
Fill Certifications for Excess Spoil or Underground Development Waste	Yes 2/4/1987	Annual Subsidence Report	2021 ARR
 Quarterly Inspections 	NA		
Compaction Testing	NA		
Final Certification	NA		
Coal Processing Waste Banks	NA		
Haul Road Certifications	Yes, several years		
Access Road Certifications	Yes, PAP Vol. 8A		
COMMENTS.			

COMMENTS:

1. Two instruments with Lexon Insurance Co.: \$2,500,000 + \$268,916 = \$2,768,916.

2. The cost estimate of \$1,639,674 (from MT8) does not match liability. This is explained in SL-06 findings.