



STATE OF
COLORADO

Reilley - DNR, Robin <robin.reilley@state.co.us>

Review Trapper Q2 Fill and Sediment Pond and 2024 May DMR

1 message

Reilley - DNR, Robin <robin.reilley@state.co.us>

Mon, Jul 15, 2024 at 4:16 PM

To: Graham Roberts <graham.roberts@trappermine.com>, Tonia Perkins <tonia.perkins@trappermine.com>, Robin Reilley - DNR <robin.reilley@state.co.us>

Good Afternoon,

Please find DRMS's review of the above referenced compliance monitoring reports.

Thank you for your timely submission of the reports. I'm available to answer any questions.

Thank you,

Robin Reilley, M.S. GISP
Environmental Protection Specialist II



COLORADO
Division of Reclamation,
Mining and Safety
Department of Natural Resources

P 303.866.3567 |

F 303.832.8106

Physical Address: 1313 Sherman Street St., Suite 215, Denver, CO 80203

Mailing Address: DRMS Room 215, 1001 E 62nd Ave, Denver, CO 80216

robin.reilley@state.co.us | <http://mining.state.co.us>

3 attachments



SedPondReview_2024_Q2_Trapper.pdf

240K



Review_DMR_2024_05May_Trapper.pdf

266K



Review_HGFill_2024_Q2_Trapper.pdf

239K



COLORADO
Division of Reclamation,
Mining and Safety
Department of Natural Resources

15 July 2024

Tonia Perkins
Trapper Mine, Inc.
P.O. Box 187
Craig, Colorado 81626

RE: Trapper Mining Inc., Permit; C1981010
Review: Horse Gulch Fill Monitoring 2024 Q2

Dear Ms. Perkins:

The Colorado Division of Reclamation, Mining, and Safety (CDRMS) has reviewed and found the above referenced report to be in general compliance with the following CDRMS regulations:

4.09.1(11)(a) Inspected at least quarterly by a registered engineer, or other qualified professional specialist in construction of earth and rockfill embankments under the direction of a qualified engineer throughout the construction.

The certified report covers the second quarter monitoring period from April 2024 through June 2024, and the inspection was conducted by yourself, a certified engineer on 17 June 2024.

4.09.1(11)(b) Provide to the Division a certified report within 2 weeks after each inspection that the fill has been constructed as specified in the design approved by the Division. The report shall include a description of any appearances of instability, structural weakness, and other hazardous conditions.

The Division received the report via electronic transmission on 17 June 2024. Portions of the fill inspected comprised the southeast and northeast sides of the fill, as these areas are not fully bond released. No instability, structural weakness, or other hazardous conditions were noted during this inspection of the fill. The area where cracks were detected on the top south portion of the fill during the first quarter of 2013 was inspected and no additional cracking was observed.

No organic material removal was conducted during this quarter. All fill has been placed and compacted.

DRMS has no questions at this time. Thank you for the timely submission of the 2024 Q2 fill report.

Sincerely,



Robin Reilley M.S. GISP
Environmental Protection Specialist II
Robin.reilley@state.co.us