



STATE OF
COLORADO

Reilley - DNR, Robin <robin.reilley@state.co.us>

Review Compliance Reports 2024 Q3

1 message

Reilley - DNR, Robin <robin.reilley@state.co.us>

Fri, Sep 27, 2024 at 8:52 AM

To: Graham Roberts <graham.roberts@trappermine.com>, Tonia Perkins <tonia.perkins@trappermine.com>, Robin Reilley - DNR <robin.reilley@state.co.us>

Colleagues,

Please find DRMS's review of Trappers 2024 Q3 DMRs, Sediment Pond and Horse Gulch Fill reports. DRMS has no concerns at this time.

Thank you for your timely submission of the reports.

Robin Reilley, M.S. GISP
Environmental Protection Specialist II



COLORADO
Division of Reclamation,
Mining and Safety
Department of Natural Resources

P [303.866.3567](tel:303.866.3567) |

F [303.832.8106](tel:303.832.8106)

Physical Address: 1313 Sherman Street St., Suite 215, Denver, CO 80203

Mailing Address: DRMS Room 215, 1001 E 62nd Ave, Denver, CO 80216
robin.reilley@state.co.us | <http://mining.state.co.us>

3 attachments



Review_HGFill_2024_Q3_Trapper.pdf
240K



Review_DMR_2024_08August_Trapper.pdf
269K



SedPondReview_2024_Q3_Trapper.pdf
242K



27 September 2024

Tonia Perkins
Trapper Mine, Inc.
P.O. Box 187
Craig, Colorado 81626

RE: Trapper Mining Inc., Permit; C1981010
Review: Sediment Pond 2024 Q3

Dear Ms. Perkins

The Colorado Division of Reclamation, Mining and Safety (The Division), has reviewed the above referenced report received by the Division on 17 September 2024. The report complies with applicable sections of Rule 4.05.9 (*Impoundments*). The inspection took place over several days in July and September 2024 by Tonia Perkins and Tim Cummins.

Maintenance issues noted during the inspection comprised a sediment marker requiring replacement at one pond. The following ponds were discharging at a rate of less than 1 cubic foot/second:

1. No Name #2, #4 and #5 ponds were at 100% capacity.
2. Johnson #s 6, 7R, 8R, 9R and 10R ponds were 100% full.
3. East Pyeatt #s 1, 2, 3 were 100% full.
4. East Middle Flume #1 was 100% full.

The following ponds held water and were not discharging at the time of inspection:

| | | |
|-------------------------|-----------------------|-------------------------------|
| <i>Coyote</i> | <i>West Pyeatt #1</i> | <i>Middle Pyeatt #1</i> |
| <i>Grouse #1 and #2</i> | <i>Ute #1</i> | <i>Middle Flume #1 and #3</i> |
| <i>Horse Gulch #1</i> | <i>Oak #1</i> | <i>Industrial Waste Pond</i> |
| <i>Deal #1</i> | <i>Jeffway</i> | <i>Impoundment H</i> |

Trappers' Permit indicates that other than Coyote Pond, all sediment ponds with 60% or more of sediment storage used following spring runoff will have the sediment removed in the same year. Sediment levels in the all ponds were recorded. DRMS notes that only Horse Pond is approaching the upper limit of its sediment storage capacity (55%).

DRMS notes that the recently built Buzzard Ponds are not on the Pond Capacity Table. The table should be updated and these ponds should be added to the quarterly inspection events.



Thank you for the timely submission of the Q3 2024 Sediment Pond Report. DRMS has no questions or concerns at this time.

Sincerely,

A handwritten signature in blue ink that reads "Robin Reilley". The signature is fluid and cursive, with the first name "Robin" and last name "Reilley" clearly distinguishable.

Robin Reilley M.S. GISP
Environmental Protection Specialist II
Robin.reilley@state.co.us