

**STATE OF
COLORADO**

Reilley - DNR, Robin <robin.reilley@state.co.us>

2024 September and Q3 Compliance Monitoring Reports: Fill, Sed Ponds, DMRs

1 message

Reilley - DNR, Robin <robin.reilley@state.co.us>

Tue, Oct 29, 2024 at 11:22 AM

To: Graham Roberts <graham.roberts@trappermine.com>, Tonia Perkins <tonia.perkins@trappermine.com>, Robin Reilley - DNR <robin.reilley@state.co.us>

Good Morning Colleagues,

Please find DRMS's review of the 2024 September and Q3 compliance monitoring reports referenced above for Trapper Mine. Thank you for the timely submission of these reports. The Division has no concerns.

Thank you

Robin Reilley, M.S. GISP
Environmental Protection Specialist II



COLORADO
Division of Reclamation,
Mining and Safety
Department of Natural Resources

P 303.866.3567|

F 303.832.8106

Physical Address: 1313 Sherman Street St., Suite 215, Denver, CO 80203

Mailing Address: DRMS Room 215, 1001 E 62nd Ave, Denver, CO 80216

robin.reilley@state.co.us | <http://mining.state.co.us>

3 attachments

**Review_HGFill_2024_Q4_Trapper.pdf**

285K

**SedPondReview_2024_Q4_Trapper.pdf**

287K

**Review_DMR_2024_09Sept_Q3_Trapper.pdf**

292K



COLORADO
Division of Reclamation,
Mining and Safety
Department of Natural Resources

29 October 2024

Tonia Perkins
Trapper Mine, Inc.
P.O. Box 187
Craig, Colorado 81626

RE: Trapper Mining Inc., Permit; C1981010
Review: Horse Gulch Fill Monitoring 2024 Q4

Dear Ms. Perkins:

The Colorado Division of Reclamation, Mining, and Safety (CDRMS) has reviewed and found the above referenced report to be in general compliance with the following CDRMS regulations:

4.09.1(11)(a) Inspected at least quarterly by a registered engineer, or other qualified professional specialist in construction of earth and rockfill embankments under the direction of a qualified engineer throughout the construction.

The certified report covers the fourth quarter monitoring period from 1 October through 30 December 2024, and the inspection was conducted by yourself, a certified engineer on 15 October 2024.

4.09.1(11)(b) Provide to the Division a certified report within 2 weeks after each inspection that the fill has been constructed as specified in the design approved by the Division. The report shall include a description of any appearances of instability, structural weakness, and other hazardous conditions.

The Division received the report via electronic transmission on 28 October 2024. Portions of the fill inspected comprised the southeast and northeast sides of the fill, as these areas are not fully bond released. No instability, structural weakness, or other hazardous conditions were noted during this inspection of the fill. The area where cracks were detected on the top south portion of the fill during the first quarter of 2013 was inspected and no additional cracking was observed.

No organic material removal was conducted during this quarter. All fill has been placed and compacted.

DRMS has no questions at this time. Thank you for the timely submission of the fill report.

Sincerely,



Robin Reilley M.S. GISP
Environmental Protection Specialist II
Robin.reilley@state.co.us