




MINERALS PROGRAM INSPECTION REPORT
PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME: Siloam Mine	MINE/PROSPECTING ID#: M-1977-326	MINERAL: Clay (general) and ag	COUNTY: Pueblo
INSPECTION TYPE: Monitoring	WEATHER: Clear	INSP. DATE: December 5, 2024	INSP. TIME: 12:45
OPERATOR: General Shale Brick, Inc.	OPERATOR REPRESENTATIVE: Mr. Jason McGraw	TYPE OF OPERATION: 110c - Construction Limited Impact	
REASON FOR INSPECTION: Normal I&E Program	BOND CALCULATION TYPE: Complete Bond	BOND AMOUNT: \$28,000.00	
DATE OF COMPLAINT: NA	POST INSP. CONTACTS: None	JOINT INSP. AGENCY: None	
INSPECTOR(S): Jocelyn Carter Ursula Armstrong	INSPECTOR'S SIGNATURE: 	SIGNATURE DATE: January 6, 2025	

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS----- <u>Y</u>	(FN) FINANCIAL WARRANTY----- <u>Y</u>	(RD) ROADS----- <u>Y</u>
(HB) HYDROLOGIC BALANCE----- <u>Y</u>	(BG) BACKFILL & GRADING----- <u>N</u>	(EX) EXPLOSIVES----- <u>Y</u>
(PW) PROCESSING WASTE/TAILING---- <u>N</u>	(SF) PROCESSING FACILITIES----- <u>NA</u>	(TS) TOPSOIL----- <u>N</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>N</u>	(FW) FISH & WILDLIFE----- <u>N</u>	(RV) REVEGETATION---- <u>N</u>
(SM) SIGNS AND MARKERS----- <u>Y</u>	(SP) STORM WATER MGT PLAN---- <u>NA</u>	(RS) RECL PLAN/COMP-- <u>N</u>
(ES) OVERBURDEN/DEV. WASTE----- <u>N</u>	(SC) EROSION/SEDIMENTATION-- <u>N</u>	(ST) STIPULATIONS----- <u>NA</u>
(AT) ACID OR TOXIC MATERIALS----- <u>NA</u>	(OD) OFF-SITE DAMAGE----- <u>N</u>	

Y = Inspected / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

OBSERVATIONS

The inspection of the Siloam Mine, Permit No. M-1977-326, was conducted by Jocelyn Carter and Ursula Armstrong on behalf of the Division of Reclamation, Mining, and Safety (Division/DRMS). Siloam Mine is operated by General Shale Brick, Inc. and Jason McGraw was present for the inspection. The inspection took place during the afternoon and the weather was clear with cool temperatures and some snow on the ground.

Siloam Mine is 110c permit that extracts clay for manufacturing bricks and the post mine land use is rangeland. The site is located about 8.5 miles southeast of Wetmore in Pueblo County. To access the site from the intersection of Colorado 67 (CO-67) and Colorado 96 (CO-96) in Wetmore, travel east on CO-96 for 6.8 miles, turn south on Siloam Rd and continue on Siloam Rd for 8 miles, the entrance to the site is on the east side of the road. Siloam Mine is non-contiguous permit consisting of three parcels: an eastern parcel and a north and southwestern portion. Much of the permitted area is located in the eastern parcel. located within the permit boundary of the Bedrock Mine, Permit No. M-1997-086, and immediately east of Pinion Mine, permit No. M-1997-094, both operated by Siloam Stone, Inc. The two operators have a working relationship.

The target layer for the Siloam Mine is a gray clay layer situated below approximately ~16 feet of sandstone layers. Siloam Stone, Inc. removes the sandstone layers as part of their mining process, exposing a capstone sandstone layer just above the gray clay. The capstone layer is kept as overburden material to be used for reclamation by General Shale Brick, Inc. The clay is removed and stockpiled.

Mining activities were not taking place during the time of the inspection. There is a stockpile clay material located around the northwest parcel. According to Mr. McGraw, approximately 700 tons of the material has been removed annually. Once the stockpile has been exhausted, clay material will be extracted from the current highwall located on the east parcel. The highwall was measured using satellite imagery, the current length is about 530 feet, and the average depth is 12.5 feet. According to the last inspection by DRMS, performed in July of 2020, the stockpile had enough material to last for years. According to historic and current imagery, the stockpile has been reduced to half of its size in October 2024 from its size in September of 2020.

The financial warranty held by the Division for this permit is \$28,000. Using information for the inspection and satellite imagery, the reclamation cost estimate was recalculated as part of this inspection. The financial warranty is no longer adequate to cover reclamation costs, according to the Division's calculation, the reclamation costs for this site based on the current disturbances is \$37, 969.

A copy of the Division's reclamation cost estimate calculations is attached to this report. Photos taken during the inspection are also included in this report. Questions regarding this inspection report can be directed to me, Jocelyn Carter, at Jocelyn.carter@state.co.us or (720) 666-1065.

Records

There are no open violations or enforcement issues with this permit. The annual map, report, and fees were submitted on October 30, 2024. The last inspection of the site occurred on July 14, 2020, by Patrick Lennberg.

Hydrological Balance

During the July 14, 2020, inspection, an area was noted where it had potential to hold water for an extended period of time. It was recommended that the Operator fill in the area to prevent any disruption to the hydrologic balance. The area has been filled in and did not appear to be disrupting the hydrologic balance.

Signs and Markers

There is a sign at the entrance of the mine site that meets the requirements of Rule 3.1.12(1), see Photo #1.

Financial Warranty

The Davison has re-calculated the reclamation cost estimate for the disturbances observed on site. The current bond held for the permit by the Division is \$28,000 which is \$9,969 short of the estimated cost of \$37,969. The Division will issue a Surety Increase to the Operator.

Roads

Roads on the permit site are stable and in good condition.

Explosives

The permit does have a blasting plan in place, approved through technical revision TR-1 in February of 1999. Mr. McGraw stated that the last time explosives were used at the site had been years but was unable to say for sure when.

Topsoil

The topsoil stockpile for the site is not kept within the permit boundary for Siloam M-1977-326. The topsoil stockpile is located on the Bedrock Mine #1 M-1997-086 permit site and appears to be adequate in volume, stable, and well vegetated.

PHOTOGRAPHS



Photo #1: Mine sign in accordance with Rule 3.1.12(1).



Photo #2: Product stockpile, the grey clay, viewed from the west looking east.



Photo #3: Highwall seen on the left side of the photo, photo taken from the pit floor looking southwest.



Photo #4: Highwall seen on the right side of the photo, photo taken from the pit floor looking northeast.




Photo #5: View above the working highwall for this permit, standing on the capstone layer. Looking to the southwest, the highwall seen in this photo is attributed to disturbance from the Bedrock Mine #1 operation.



Photo #6: Equipment located on the northeast section of the permitted area; looking to the southeast.



Photo #7: From the northern section of the permit area looking to the south-southwest. The bedrock Mine #1 highwall, the capstone layer above the gray clay, the Siloam Mine highwall, and the pit floor can be seen on the left side of the photo. On the right side of the photo, the area above the pit floor is used for storage of product material for the other two mines operated by Siloam Stone, Inc.



2024 annual map submitted for the Siloam Mine permit.

Inspection Contact Address

Mr. Jason McGraw
General Shale Brick, Inc.
1845 W. Dartmouth Ave.
Denver, CO 80110

Enclosure: Division Reclamation Cost Estimate 2024

CC: Amy Eschberger, DRMS

COST SUMMARY WORK

Task description: Cost Summary

Site: Siloam Mine

Permit Action: 2024 Inspection

Permit/Job#: M1977326

PROJECT IDENTIFICATION

Task #: 000

State: Colorado

Abbreviation: None

Date: 12/19/2024

County: Pueblo

Filename: M326-000

User: JLC

Agency or organization name: DRMS

TASK LIST (DIRECT COSTS)

Task	Description	Form Used	Fleet Size	Task Hours	Cost
001	Grade Highwall to 3H:1V	DOZER	1	1.24	\$273
002	Spread 6 inches of topsoil over 9.9 acres	DOZER	1	35.49	\$7,782
003	Revegetation	REVEGE	1	20.00	\$17,800
004	Mobilization/demobilization	MOBILIZE	1	3.54	\$2,769
<u>SUBTOTALS:</u>				60.27	\$28,624

INDIRECT COSTS

OVERHEAD AND PROFIT:

Liability insurance: 2.02
Performance bond: 1.05
Job superintendent: 30.14
Profit: 10.00

Total = \$578

Total = \$301

Total = \$2,389

Total = \$2,862

TOTAL O & P = \$6,130

CONTRACT AMOUNT (direct + O & P) = \$34,754

LEGAL - ENGINEERING - PROJECT MANAGEMENT:

Financial warranty processing (legal/related costs): \$0

Total = \$0

Engineering work and/or contract/bid preparation: 4.25

Total = \$1,477

Reclamation management and/or administration: 5.00

\$1,738

CONTINGENCY: 0.00

Total = \$0

TOTAL INDIRECT COST = \$9,345

TOTAL BOND AMOUNT (direct + indirect) = \$37,969

BULLDOZER WORKTask description: **Grade Highwall to 3H:1V**Site: **Siloam Mine**Permit Action: **2024 Inspection**Permit/Job#: **M1977326****PROJECT IDENTIFICATION**Task #: **001**State: **Colorado**Abbreviation: **None**Date: **12/19/2024**County: **Pueblo**Filename: **001**User: **JLC**Agency or organization name: **DRMS****HOURLY EQUIPMENT COST**Basic Machine: **Cat D7R DS XR Series II**Horsepower: **240**Blade Type: **Semi-Universal**Attachment: **3-shank ripper**Shift Basis: **1 per day**Data Source: **(CRG)****Cost Breakdown:**

		<u>Utilization %</u>
Ownership Cost/Hour:	\$90.24	NA
Operating Cost/Hour:	\$78.95	100
Ripper own. Cost/Hour:	\$9.25	NA
Ripper op. Cost/Hour:	\$1.56	30
Operator Cost/Hour:	\$40.04	NA
Total unit Cost/Hour:	\$220.04	
Total Fleet Cost/Hour:	\$220.04	

MATERIAL QUANTITIESInitial Volume: **930**Swell factor: **1.220**Loose volume: **1,135 LCY**Source of estimated volume: **Length 530 ft height 13 ft**Source of estimated swell
factor: **Cat Handbook****HOURLY PRODUCTION**Average push distance: **50 feet**Unadjusted hourly
production: **1,022.9 LCY/hr**Materials consistency description: **Partly consolidated stockpile 1.1**Average push
gradient: **-10 %**Average site altitude: **5,850 feet**Material weight: **2,800 lbs/LCY**Weight description: **Clay - Natural bed**Job Condition Correction FactorSource

Operator Skill:	0.900	(AB.AVG.)
Material consistency:	1.100	(CAT HB)
Dozing method:	1.200	(SLOT)
Visibility:	1.000	(AVG.)
Job efficiency:	0.830	(1 SHIFT/DAY)
Spoil pile:	0.900	(SSD-FC)
Push gradient:	1.225	(CAT HB)
Altitude:	1.000	(CAT HB)
Material Weight:	0.821	(CAT HB)
Blade type:	1.000	(PAT)

Net correction: 0.8925

Adjusted unit
production: 912.94 LCY/hr
Adjusted fleet
production: **912.94** LCY/hr

JOB TIME AND COST

Fleet size: 1 Dozer(s)
Unit cost: \$0.241/LCY

Total job time: **1.24** Hours
Total job cost: **\$273**

BULLDOZER WORKTask description: Spread 6 inches of topsoil over 9.9 acresSite: Siloam MinePermit Action: 2024 InspectionPermit/Job#: M1977326**PROJECT IDENTIFICATION**Task #: 002State: ColoradoAbbreviation: NoneDate: 12/19/2024County: PuebloFilename: 002User: JLCAgency or organization name: DRMS**HOURLY EQUIPMENT COST**Basic Machine: Cat D7R DS XR Series IIHorsepower: 240Blade Type: Semi-UniversalAttachment: 3-shank ripperShift Basis: 1 per dayData Source: (CRG)**Cost Breakdown:**

		<u>Utilization %</u>
Ownership Cost/Hour:	<u>\$90.24</u>	<u>NA</u>
Operating Cost/Hour:	<u>\$78.95</u>	<u>100</u>
Ripper own.		
Cost/Hour:	<u>\$9.25</u>	<u>NA</u>
Ripper op. Cost/Hour:	<u>\$0.78</u>	<u>15</u>
Operator Cost/Hour:	<u>\$40.04</u>	<u>NA</u>

Total unit Cost/Hour: \$219.26Total Fleet Cost/Hour: \$219.26**MATERIAL QUANTITIES**Initial Volume: 8,000Swell factor: 1.230Loose volume: 9,840 LCYSource of estimated volume: Division of Reclamation, Mining & Safety

Source of estimated swell

factor: Cat Handbook**HOURLY PRODUCTION**Average push distance: 295 feetUnadjusted hourly
production: 314.4 LCY/hrMaterials consistency description: Consolidated stockpile 1.0

Average push

gradient: -10 %Average site altitude: 5,850 feetMaterial weight: 2,100 lbs/LCYWeight description: Earth - LoamJob Condition Correction FactorSource

Operator Skill:	0.900	(AB.AVG.)
Material consistency:	1.000	(CAT HB)
Dozing method:	1.100	(50% SL)
Visibility:	1.000	(AVG.)
Job efficiency:	0.830	(1 SHIFT/DAY)
Spoil pile:	0.800	(FND-RF)
Push gradient:	1.225	(CAT HB)
Altitude:	1.000	(CAT HB)
Material Weight:	1.095	(CAT HB)
Blade type:	1.000	(PAT)

Net correction: 0.8818

Adjusted unit
production: 277.24 LCY/hr
Adjusted fleet
production: **277.24** LCY/hr

JOB TIME AND COST

Fleet size: 1 Dozer(s)
Unit cost: \$0.791/LCY

Total job time: **35.49** Hours
Total job cost: **\$7,782**

REVEGETATION WORKTask description: **Revegetation**Site: **Siloam Mine**Permit Action: **2024 Inspection**Permit/Job#: **M1977326****PROJECT IDENTIFICATION**Task #: **003**State: **Colorado**Abbreviation: **None**Date: **12/19/2024**County: **Pueblo**Filename: **003**User: **JLC**Agency or organization name: **DRMS****SEEDING**

Seed Mix	Rate – PLS LBS / Acre	Seeds per SQ. FT	Cost /Acre
Blue Grama - Hachita	1.50	24.48	\$42.97
Indian Ricegrass - Native	1.00	3.24	\$17.29
Sideoats Grama - Vaughn	2.00	6.57	\$49.18
Sheep Fescue - Bighorn	0.50	7.81	\$2.48
Thickspike Wheatgrass - Critana	2.00	7.07	\$16.30
Western Wheatgrass - Barton	4.00	10.10	\$37.58
Needlegrass, Green - Lodorm	1.00	4.16	\$8.65
Totals Seed Mix	12.00	63.42	\$174.45

Application

Description	Cost /Acre
Drill Seeding (DRMS Survey Cost)	\$236.64
Total Seed Application Cost/Acre	\$236.64

MULCHING and MISCELLANEOUS**Materials**

Description	Units / Acre	Unit	Cost / Unit	Cost /Acre
Hay, delivered {MEANS 31 25 14.16 1200}	2.00	TON	\$492.78	\$985.56
Total Mulch Materials Cost/Acre				\$985.56

Application

Description	Cost /Acre
Crimping, with tractor {DMG survey data}	\$85.37
Power mulcher (MEANS 32 91 13.16 0350)	\$157.25
Total Mulch Application Cost/Acre	\$242.63

JOB TIME AND COST

No. of Acres:	<u>9.9</u>	Cost /Acre:	<u>\$1,756.89</u>
Estimated Failure Rate:	<u>10%</u>	Cost /Acre*:	<u>\$411.09</u>
*Selected Replanting Work Items:	<u>SEEDING</u>		
Initial Job Cost:	<u>\$17,393.21</u>		
Reseeding Job Cost:	<u>\$406.98</u>		
Total Job Cost:	<u>\$17,800</u>		
Job Hours:	<u>20.00</u>		

EQUIPMENT MOBILIZATION/DEMOBILIZATIONTask description: Mobilization/demobilizationSite: Siloam MinePermit Action: 2024 InspectionPermit/Job#: M1977326**PROJECT IDENTIFICATION**Task #: 004State: ColoradoAbbreviation: NoneDate: 12/19/2024County: PuebloFilename: 004User: JLCAgency or organization name: DRMS**EQUIPMENT TRANSPORT RIG COST**Shift basis: 1 per dayCost Data Source: CRG DataTruck Tractor Description: GENERIC ON-HIGHWAY TRUCK TRACTOR, 6X4, DIESEL POWERED,
400 HP (2ND HALF, 2006)Truck Trailer Description: GENERIC FOLDING GOOSENECK, DROP DECK EQUIPMENT
TRAILER (25T, 50T, AND 100T)**Cost Breakdown:**

Available Rig Capacities	0-25 Tons	26-50 Tons	51+ Tons
Ownership Cost/Hour:	\$10.44	\$22.18	\$23.94
Operating Cost/Hour:	\$26.48	\$54.55	\$55.65
Operator Cost/Hour:	\$22.52	\$22.52	\$22.52
Helper Cost/Hour:	\$0.00	\$23.53	\$23.53
Total Unit Cost/Hour:	\$59.44	\$122.78	\$125.64

NON ROADABLE EQUIPMENT:

Machine Description	Weight/ Unit (TONS)	Owner ship Cost/hr/ unit	Haul Rig Cost/hr/unit	Fleet Size	Haul Trip Cost/hr/ fleet	Return Trip Cost/hr/ fleet	DOT Permit Cost/ fleet
Cat D7R DS XR Series II	35.93	\$99.49	\$122.78	1	\$222.27	\$122.78	\$250.00
Power Mulcher (Bowie LD-90)	6.00	\$27.21	\$59.44	1	\$86.65	\$59.44	\$250.00
Drill/Broadcast Seeder with Tractor	25.00	\$41.02	\$59.44	1	\$100.46	\$59.44	\$250.00

Subtotals: **\$409.38** **\$241.66** **\$750.00****ROADABLE EQUIPMENT:**

Machine Description	Total Cost/hr/ unit	Fleet Size	Haul Trip Cost/hr/ fleet	Return Trip Cost/hr/ fleet
Light Duty Pickup, 4x4, 1 T. Crew	\$24.60	1	\$24.60	\$24.60

Subtotals: **\$24.60** **\$24.60**

EQUIPMENT HAUL DISTANCE and Time

Nearest Major City or Town within project area region:	<u>PUEBLO</u>	
Total one-way travel distance:	<u>35.00</u>	miles
Average Travel Speed:	<u>55.00</u>	mph

Total Non-Roadable Mob/Demob Cost *	<u>\$2,737.98</u>
** two round trips with haul rig:	
Total Roadable Mob/Demob Cost **	<u>\$31.31</u>
** one round trip, no haul rig:	

Transportation Cycle Time:

	Non-Roadable Equipment	Roadable Equipment
Haul Time (Hours):	<u>0.64</u>	<u>0.64</u>
Return Time (Hours):	<u>0.64</u>	<u>0.64</u>
Loading Time (Hours):	<u>0.25</u>	<u>NA</u>
Unloading Time (Hours):	<u>0.25</u>	<u>NA</u>
Subtotals:	<u>1.77</u>	<u>1.27</u>

JOB TIME AND COST

Total job time:	<u>3.55</u>	Hours
-----------------	-------------	-------

Total job cost:	<u>\$2,769</u>
-----------------	----------------