

Minerals Exploration/Sampling/Testing Inspection

U.S. Department of the Interior Bureau of Land Management Royal Gorge Field Office



The BLM has conducted an inspection of your operations, which concludes whether the documented operations on file with BLM are compliant or non-compliant. Any non-compliance issues are reported in the Additional Actions Necessary section of this inspection.

Operation Type: □ 3600 □ 3809 w/ occupancy ⊠ 3809 w/o occupancy											
Date: 2/5/2025 Time: 2 PM Weather: Clear, 50s		Operation Name: Passiflora Operator: Viscount Case Number: COCO105863224 CDRMS #:									
	<u>Attendees</u>		G	<u>eneral</u>							
BLM: Daniel Pike, John Brotherton Operator(s): Drilling Company Other(s):		Operation(s) are in-compliance with documentation on file Yes No No Operation(s) and disturbance onsite coincide with the operations and access on file									
									⊠ Yes	□No	□ N/A
						Inspection	Purpose : □ Pre-Operations □ 0	General	☐ Final	☐ Trespass	
Inspection Items			Compliant	Non- Compliant	N/A						
	d of Operations Trenching/Surface Excavation & Underground Ex	cavation									
a. D	rilling		\boxtimes								
i.	Pad Construction										
	ii. Drill/Drilling Equipment										
iii.	Mud Pits Parabala Abandanmant/Manitoring Wall C	lanvaraian									
iv.	Borehole Abandonment/Monitoring Well C	onversion	Ш								
**	☐ Complete ☐ Incomplete Pad Reclamation										
V.											
b. Trenching/Surface Excavation											
i. ii.	Trench/Excavation Construction Trench/Excavation Stability										
iii.	Excavation/Reclamation Equipment										
iv.	Trench/Excavation Reclamation										
	nderground Excavation										
i.	Portal Construction										
ii.	Portal Stability										
iii.	-	External									
iv.	Excavation/Reclamation Equipment										
v.	Portal Reclamation/Conversion of Entry										

Inspection Items	Compliant	Non- Compliant	N/A				
2. Site Conditions							
a. Material/Waste Rock Management			\boxtimes				
b. Erosion & Stormwater Controls			\boxtimes				
c. Man-made Structures			\boxtimes				
d. Weed Management	\boxtimes						
e. Safety Conditions	\boxtimes						
f. Interim Reclamation			\boxtimes				
3. Housekeeping							
a. Container Management		\boxtimes					
b. Spills/Leaks Observed							
c. Hazardous Substances/POL Management							
d. General Housekeeping	\boxtimes						
4. Access							
a. Road Management	\boxtimes						
b. Berms			\boxtimes				
c. Security			\boxtimes				
d. Signage							
e. Surface Water Controls	\boxtimes						
5. Quality Assurance/Quality Control							
a. Routine Site Conditions Monitoring							
b. Air, Water, Noise, Other Monitoring			\boxtimes				
c. Monitoring Reporting			\boxtimes				
d. Regulatory Submittals			\boxtimes				
e. Other Agency/Entity Permits			\boxtimes				
6. Final Reclamation							
a. Exploration/Sampling Location			☒				
b. Access Roads/Trails			×				
c. Grading			×				
d. Revegetation			\boxtimes				
e. Removal of Structures							
f. Free of Trash							
g. RGFO Solid Minerals Reclamation Standards met			\boxtimes				
7. Occupancy & Use – under the Mining Law (3715 regs)							
a. Occupancy Concurrence on File			\boxtimes				
b. Occupancy Remains Reasonably Incident			×				
c. Substantially Regular Work							
d. Exploration Equipment is Mobile			\boxtimes				
e. Other Equipment/Materials Used for the							
Maintenance, Repair or Fabrication of Parts	_	_					
f. Occupancy Related Structures & Signage			\boxtimes				

Additional Actions Necessary

Non-Compliance Issues to be addressed by Operator

After action report to be submitted to BLM to reflect additional disturbance after drilling is completed POLs to be placed in secondary containment

Hydrocarbon spill to be cleaned up

Final Notes

General Comments: The location was inspected by Daniel Pike on 2/5/2025. The operator had recently started drilling the exploratory hole. Several complaints were received from members of the public regarding the initiation of the program. There was a diesel spill in the road, and some equipment had been staged in the county road at the start of the program. An oil and gas geologist from Royal Gorge went onsite to take photos during the week of 1/20.

Overall, operations onsite were similar to the scope of what was proposed in the notice of exploration submitted to the BLM. The drill pad was bigger than proposed in the notice, the overland travel is essentially a road, and a small staging area away from the drill pad was in use. Total disturbance on site was approximately 0.42 acres- 0.32 acre drill pad, 0.08 acre access road, and 0.02 acre staging area. The sumps were larger than proposed in the notice, with total surface area of approximately 360 ft². The sumps have an unknown depth, as they were full of fluid at the time of inspection. There is orange fencing around the sumps, and the sumps are plastic lined.

POLs were observed outside secondary containment on the drill pad and secondary containment area. A small hydrocarbon spill was observed on the secondary staging area. The POLs were discussed with drillers on site, and they stated most of them had been delivered the day of the inspection, and they did not have a chance to place them in containment yet.

Equipment on site includes a drill rig, pickup truck, forklift, backhoe, water truck, and two utility trailers. Materials and equipment are stacked around one utility trailer which is being used as a workshop. POLs were staged here outside secondary containment. Drill pipe was stacked on blocks around the drill site.

Issues, including uncontained POLs and secondary staging area, were discussed with the drill operators onsite. Harald Hoegberg was called to discuss issues onsite. Harald was notified of POLs outside containment, secondary staging area, hydrocarbon spill, and size of disturbance associated with this project. Harald will submit an "after action report" to reflect additional disturbance over the sizes listed in the notice submitted to BLM. The bond posted with DRMS is adequate to cover additional disturbance, and the project is overall within the "scope" of what was submitted to BLM. A follow up inspection will be completed to determine if the operator is still using the secondary staging area, and if POLs are still outside secondary containment. The hydrocarbon spill should be cleaned up per applicable standards.

D-4-	·	-1 1	:41-	CDDMC	i.
Date	inspection	snarea	with	CDKM3	٠:


Date inspection shared with Operator:

Image(s):



Comment: Overview of the site looking to the west


Image(s):



Comment: Overview of site looking to the northwest. Core in middle of photo in cardboard boxes


Images

Image(s):



Comment: Utility trailer with materials/tools. Uncontained POLs along the left side of the trailer

Image(s):



Comment: Overview of one of the lined sumps, looking to the northeast

Image(s):



Comment: Uncontained POLs near utility trailer, other materials/tools

Image(s):



Comment: Overview of sumps looking to the west. Total length of sumps approximately 45 feet

Image(s):




Comment: Overview of site looking the west

Image(s):



Comment: Secondary staging area separated from drill pad. Secondary area not included in notice

Image(s):



Comment: Secondary staging area looking to the north

Image(s):



Comment: Hydrocarbon spill at secondary staging area.