QUARTERLY POND INSPECTION REPORT

Operator:	Bowie Resources LLC Bowie No. 2 Mine - C-1996-083				Quarter:	First 2025
Mine:					Inspection Date:	31-Mar-25
Pond Identification	В	С	D - Gob Pile	F - New Gob	J UTL East	K UTL Wes
Type of Pond	Sediment	Sediment	Sediment	Sediment	Sediment	Sediment
Status During Inspection:						
Approximate Water Level	5942'	5990	5970'	5948'	5846'	5819
Sediment (% remaining)	90%	90%	80%	80%	100%	80%
Outflow (cfs)	0	0	0	0	0	0
Features	Problem	Problem	Problem	Problem	Problem	Problem
reatures	Yes/No	Yes/No	Yes/No	Yes/No	Yes/No	Yes/No
Erosional	1 03/140	103/110	103/110	103/110	103/140	103/110
Rills & Gulleys	No	No	No	No	No	No
Inadequate Vegetation	No	No	No	No	No	No
Outlet Channel Erosion	No	No	No	No	No	No
Burrows	No	No	No	No	No	No
Other	No	No	No	No	No	No
Structural						
Differential Settling	No	No	No	No	No	No
Cracks or Slides	No	No	No	No	No	No
Seepage	No	No	No	No	No	No
Other	No	No	No	No	No	No
Appurtenant Structures						
Defective Spillways	No	No	No	No	No	No
Dewatering Devices Clogged	No	No	No	No	No	No
Faulty Gates, Etc.	No	No	No	No	No	No
Other	No	No	No	No	No	No

Additional Comments

Design depth measured from pond bottom to invert of emergency spillway:

Pond B=10', C=10', D=10', J=10', K=3', F=10' TD

Pond Bottom Elevations B=5942, C=5990, D=5970, F=5944, J=5846, K=5819

Pond B water 1 foot deep

Pond C water less than six inches c Pond C water less than six inches deep

Pond D dry

Pond F water is two feet deep, sediment delta and needs to be cleaned this summer

Pond J sediment removed late Q4 2024, water less than six inches deep

Pond K dry

SWMP components were inspected and found to be in good condition. No corrections necessary at this time.

Name of Inspector: Art Etter

Arthur Etter

Colorado P. E. 42377 Date