



MINERALS PROGRAM INSPECTION REPORT
PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME: Little Tommy Mine	MINE/PROSPECTING ID#: P-2007-007	MINERAL: Gold, silver, lead and	COUNTY: Summit
INSPECTION TYPE: Monitoring	WEATHER: Clear	INSP. DATE: August 13, 2025	INSP. TIME: 11:00
OPERATOR: Iowa Milling Corp	OPERATOR REPRESENTATIVE: Randy Stone	TYPE OF OPERATION: MP - Mineral Prospecting	
REASON FOR INSPECTION: Normal I&E Program		BOND CALCULATION TYPE: BOND AMOUNT: \$5,000.00	
DATE OF COMPLAINT: NA		POST INSP. CONTACTS: None	
INSPECTOR(S): Brock Bowles		JOINT INSP. AGENCY: None	
INSPECTOR'S SIGNATURE: 		SIGNATURE DATE: August 29, 2025	

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS----- <u>N</u>	(FN) FINANCIAL WARRANTY----- <u>Y</u>	(RD) ROADS----- <u>Y</u>
(HB) HYDROLOGIC BALANCE----- <u>Y</u>	(BG) BACKFILL & GRADING----- <u>N</u>	(EX) EXPLOSIVES----- <u>N</u>
(PW) PROCESSING WASTE/TAILING---- <u>N</u>	(SF) PROCESSING FACILITIES----- <u>N</u>	(TS) TOPSOIL----- <u>N</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>Y</u>	(FW) FISH & WILDLIFE----- <u>N</u>	(RV) REVEGETATION---- <u>N</u>
(SM) SIGNS AND MARKERS----- <u>N</u>	(SP) STORM WATER MGT PLAN---- <u>N</u>	(RS) RECL PLAN/COMP-- <u>N</u>
(ES) OVERBURDEN/DEV. WASTE----- <u>N</u>	(SC) EROSION/SEDIMENTATION-- <u>N</u>	(ST) STIPULATIONS----- <u>N</u>
(AT) ACID OR TOXIC MATERIALS----- <u>N</u>	(OD) OFF-SITE DAMAGE----- <u>N</u>	

Y = Inspected / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

OBSERVATIONS

This inspection was conducted by Brock Bowles of the Division of Reclamation, Mining and Safety (Division). John Lee and Amy Titterington of the USFS and Randy Stone of the Iowa Mill (operator) were present for the inspection. The weather during the inspection was clear and warm. The ground was dry. The disturbed area is approximately 0.5 acre. Up to 1.0 acre is approved for disturbance.

The Tommy Mine is operated by the same operator and in conjunction with the Iowa Mill (P-1995-013) which is located 1/4 downhill from the Tommy Mine.

Financial Warranty:

The Division holds a \$5,000 reclamation bond for the site. It has been determined the amount held is adequate to cover the reclamation cost which include contouring the pad area, reclaiming the road and seeding both areas.

Hydrologic Balance:

There were no signs of water draining from the portal. The hillside around the portal appeared to be stable (photo 1). The pad area around the portal appeared to be stable as there were no signs of erosion.

Gen. Compliance With Mine Plan:

The mine pad area contained a Conex box, a cribbing structure that holds back waste rock, wooden storage shed and a secured steel portal (photo 2). The site was well maintained, and the portal was locked upon arrival.

Mining was not taking place during this inspection. The waste pile that is being held up by the cribbing appears to contain more material than in previous inspections. The cribbing structure appeared to be stable. A couple of historic tram towers with a cable suspended between them cross the site (photo 3).

Roads:

The entrance gate to the mine site was locked upon arrival.

PHOTOGRAPHS



Photo 1- Portal entrance is well secured with no signs of water discharge.



Photo 2- Cribbing structure below mine portal and Conex box.



Photo 3- Historic tram tower with cable on south side of waste pile.

Inspection Contact Address

Randy Stone
Iowa Milling Corp
4278 Garland St
Wheatridge, CO 80033