Schwartzwalder Daily Summary Report



			Lead C	Lead Operator:		Chris P	
Report Date:	8/29/2025		Assistant (Assistant Operator(s):		Patrick D	
			Assistant				
Effluent Discharged:		1.075 Mgal	MW-18 Level:		236.2 ft	118.9 ft	
Average Flowrate:		193.0 gpm	Transducer Level:		172.7 ft	123.3 ft	
Effluent to Date:		17.963 Mgal	(Fiel	(Field Reading Value below 150')		50')	
	рН		Flowrate				
			250				
9.5							
8.5			200				
8			150				
7.5			100				
7			100				
6.5			50				
5.5			0				
0:00	0:00 0:0	0:00 0:00	0:00	0:00 0:00	0:00	0:00	
	0	- 11		Finished Water Quality			
Compliance Level		Parameters	Temp	рН	Cond		
vel (f			Values	20°C	7.39	196 μS/cm	
9 50							
Stev				Chemical Inventory			
05 100			Chemicals	Antiscalant	NaOH	BaCl	
Depth below 150' Steve Level (ff) 20' Steve Level (ff) 13-Abr			Vol. Used	33 Gal	99 Gal	32 Gal	
150			Vol. Remaining		237 Gal	49 Gal	
td 13-Apr	2-Jun	22-Jul 10-Sep	Vol. Staged	230 Gal	599 Gal	380 Gal	
-	─ Transducer Level	── MW-18	Days Available	63 Days	34 Days	54 Days	

Safety Issues/Concerns:

- N/A

Notes:

- Sampled TSS for outfall 001A
- Shutdown plant at 8:54 on 8/29 to install the analog input board on the RO PLC. Replacing the board did not fix the issue seen on the PLC. Further problem solving efforts included replacing the 2032 batteries in both PLCs and replacing the power supply to the PLC to the RO PLC. All were unsuccessful at resolving the issue.
- Routed an extension cord to RO2 so that RO2 is not powered through the RO PLC.
- Plant started up at 11:24 with 2 ROs in operation. Antiscalant and BaCl pumps still operating in manual
- Peter Hays onsite inspection. New depth to water meter brought onsite for transducer work

NOTE: The level graph has been adjusted to show field readings relative to the water level below the compliance elevation (150' below the Steve Adit - 6459' ASL). Data from 5/1/2025 to 6/5/2025 was recorded using an atmospheric transducer with a 500-ft cable, installed at the end of the 2024 season and remained in place over the winter. On 6/6/2025, it was replaced with an absolute transducer with a 600-ft cable at a lower depth. A 77.1-ft difference in readings was observed. While some of offset may be a result from the deeper installation and transducer type, the old data's accuracy is questionable due to damage to the atmospheric vent, which may have allowed moisture intrusion.