



MINERALS PROGRAM INSPECTION REPORT
PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME: Nestor Pit	MINE/PROSPECTING ID#: M-2021-033	MINERAL: Borrow material for	COUNTY: Lincoln
INSPECTION TYPE: Monitoring	WEATHER: Clear	INSP. DATE: October 22, 2025	INSP. TIME: 11:00
OPERATOR: Castle Rock Construction Company of Colorado	OPERATOR REPRESENTATIVE: Travis Bell	TYPE OF OPERATION: 111 - Construction by Government Agency	
REASON FOR INSPECTION: Normal I&E Program	BOND CALCULATION TYPE: Complete Bond	BOND AMOUNT: \$22,500.00	
DATE OF COMPLAINT: NA	POST INSP. CONTACTS: None	JOINT INSP. AGENCY: None	
INSPECTOR(S): Ben Hammar	INSPECTOR'S SIGNATURE: 	SIGNATURE DATE: October 30, 2025	

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS----- <u>Y</u>	(FN) FINANCIAL WARRANTY----- <u>Y</u>	(RD) ROADS----- <u>Y</u>
(HB) HYDROLOGIC BALANCE----- <u>Y</u>	(BG) BACKFILL & GRADING----- <u>Y</u>	(EX) EXPLOSIVES----- <u>NA</u>
(PW) PROCESSING WASTE/TAILING----- <u>NA</u>	(SF) PROCESSING FACILITIES----- <u>NA</u>	(TS) TOPSOIL----- <u>Y</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>Y</u>	(FW) FISH & WILDLIFE----- <u>NA</u>	(RV) REVEGETATION---- <u>Y</u>
(SM) SIGNS AND MARKERS----- <u>Y</u>	(SP) STORM WATER MGT PLAN---- <u>NA</u>	(RS) RECL PLAN/COMP-- <u>Y</u>
(ES) OVERBURDEN/DEV. WASTE----- <u>NA</u>	(SC) EROSION/SEDIMENTATION--- <u>Y</u>	(ST) STIPULATIONS----- <u>NA</u>
(AT) ACID OR TOXIC MATERIALS----- <u>NA</u>	(OD) OFF-SITE DAMAGE----- <u>NA</u>	

Y = Inspected / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

OBSERVATIONS

This was a standard monitoring inspection performed by Ben Hammar of the Division, who was accompanied by Travis Bell, a representative of the operator. The Nestor Pit is an 8.84 acre 111 construction materials operation located 8.6 miles south of Hugo, CO. At the time of inspection the site was in reclamation and the ground was clear.

Little evidence of mining remains at this site. The mine sign and boundary markers are present, but otherwise the site is functionally indistinguishable from the surrounding grazing land. Some roadways are still present at the request of the landowner, but otherwise no significant signs of disturbance remain. Vegetation cover appears fairly complete, and this site would generally be releasable if a request was submitted during the spring.

No impact to the hydrologic balance was observed, and no erosion or offsite disturbance were observed.

The bond currently held for this site is \$22,500. Given that reclamation is nearing completion, no bond update will be pursued at this time. No other issues were found.

Inspection Contact Address

Travis Bell
Castle Rock Construction Company of Colorado, LLC
6374 S Racine Circle
Centennial, CO 80111

Enclosure

CC:

PHOTOGRAPHS



Photo 1: Posted mine sign.



Photo 2: Boundary marker located near ID sign and site entrance.



Photo 3: Northern site boundary marker.



Photo 4: Reclaimed site. Flotsam shown was placed by landowner.

