

# COLORADO DIVISION OF RECLAMATION, MINING AND SAFETY COAL PROGRAM INSPECTION REPORT



## **PERMIT INFORMATION**

Permit Number: C-2009-087 Mine Name: Peabody Sage Creek Mine Operator: Peabody Sage Creek Mining, LLC Operator Address: Mr B. Scott Cowman P.O. Box 250 36600 Routt County Road 27 Hayden, CO 81639	County: Routt Operation Type: Underground Permit Status: Active Ownership: Federal  Operator Representative Present: Scott Cowman
Operator Representative Signature: (Field Issuan	nce Only)

## **INSPECTION INFORMATION**

Inspection Start Date: May 7, 2013 Inspection Start Time: 10:00 Inspection End Date: May 7, 2013 Inspection End Time: 15:00		Inspection Type: Coal Complete Inspection Inspection Reason: Normal I&E Program Weather: Raining		
Joint Inspection Agency:		Joint Inspection Contacts:		
None				
Post Inspection Agency:		Post Inspection Contacts:		
None				
Inspector(s):	Inspector	r's Sig	nature: Signature Date:	
Jason D. Musick	have	of.	5/14/2013	

Inspection Topic Summary NOTE: Y=Inspected N=Not Inspected R=Comments Noted	V=Violation Issued NA=Not Applicable
Y - Air Resource Protection	R - Roads
<b>R</b> - Availability of Records	<b>R</b> - Reclamation Success
NA - Backfill & Grading	Y - Revegetation
NA - Excess Spoil and Dev. Waste	NA - Subsidence
<b>R</b> - Explosives	NA - Slides and Other Damage
Y - Fish & Wildlife	R - Support Facilities On-site
<b>R</b> - Hydrologic Balance	R - Signs and Markers
Y - Gen. Compliance With Mine Plan	NA - Support Facilities Not On-site
NA - Other	NA - Special Categories Of Mining
NA - Processing Waste	R - Topsoil
-	-

### **COMMENTS**

This was a complete coal inspection conducted by Jason Musick of CDRMS. The weather was cloudy and raining and the site was wet during the inspection. No mining activities are occurring as the site remains idle.

#### AVAILABILITY OF RECORDS – Rule 5.02.4(1):

All records were checked at the Peabody Sage Creek Mine offices. All required records were on site and up to date at the time of the inspection.

#### EXPLOSIVES - Rule 4.08

Distance Prohibitions 4.08.4; Warnings 4.08.4; Control of Adverse Effects 4.08.4:

The explosives storage area was stable. The area consists of gravel pad, two explosive storage containers and an 8 foot chain link fence. No problems were noted.

#### HYDROLOGIC BALANCE - Rule 4.05

Drainage Control 4.05.1, 4.05.2, 4.05.3; Siltation Structures 4.05.5, 4.05.6; Discharge Structures 4.05.7, 4.05.10; Diversions 4.05.4; Effluent Limits 4.05.2; Ground Water Monitoring 4.05.13; Surface Water Monitoring 4.05.13; Drainage – Acid and Toxic Materials 4.05.8; Impoundments 4.05.6, 4.05.9; Stream Buffer Zones 4.05.18: The Pecoco Pond, Upper Sump, Lower Sump, and Pond 002 were observed during the inspection. Pond 002, which receives discharge from Pecoco Pond and the upper and lower sumps, was discharging at the time of the inspection. Pond 004 was inaccessible due to wet conditions.





Pecoco Pond

Lower Sump Riser Pipe



Lower Sump Outlet

The primary spillway of the Lower Sump was damaged due to ice over the winter. The repair work to the riser pipe has been completed and the lower sump was holding water and discharging at the time of the inspection. Seeding will be required in the areas of disturbance due to the repair work.

Ditches and culverts observed throughout the main facilities area are stable and functioning as designed with the exception of the following:

- The area near the electrical substation around ditches FA-D1 and FA-D1A remains an issue due to the wet conditions. This area will need to be addressed when conditions improve to provide adequate runoff to the ditches.
- During the April inspection, it was noted that the west side of the substation pad containment ditch had breached the upper portion of the ditch and created a small gully to the compressor building pad. This area remains should be addressed to avoid the collection of water and provide adequate run-off of the pad.

Number of <u>Partial</u> Inspection this Fiscal Year: 8 Number of Complete Inspections this Fiscal Year: 4 ROADS – Rule 4.03 Construction 4.03.1(3)/4.03.2(3) Drainage 4.03.1(4)/4.03.2(4) Surfacing and Maintenance4.03.1(5) and (6)/4.03.2(5) and (6) Reclamation 4.03.1(7)/4.03.2(7):

All roads from the North facilities Area to the topsoil pile at the South Facilities Area were accessible and stable at the inspection.

#### RECLAMATION SUCCESS - Rule 4.15, Rule 3:

The majority of the mine site was previously approved under the Seneca II Mine (C-1980-005). These areas, with the exception of the currently approved disturbance boundary have been Phase II released and the remaining areas are currently a part of SL-1 which is a Phase II bond release application currently being reviewed by the Division. The reclaimed areas are stable with good vegetation growth and no problems noted.

#### SUPPORT FACILITIES - Rule 4.04:

The construction of the compressor building pad is near completion. The main facilities area is stable with no problems noted with the exception of the following:

- The areas of the compressor building pad and the substation pad was littered with non-coal waste. This area should be cleared of non-coal waste to ensure waste does not leave the site.

#### SIGNS AND MARKERS - Rule 4.02:

Signs and markers were in place as permitted with no problems noted, with the exception of the following:

- Topsoil markers were not observed to delineate the permitted topsoil piles.
- The Mine ID sign displayed the name "Sage Creek Mine" rather than the permitted and approved "Peabody Sage Creek Mine".

TOPSOIL – Rule 4.06 Removal 4.06.2; Substitute Materials 4.06.4(4); Storage and Protection 4.06.3; Redistribution 4.06.4:

The topsoil pile was stable and wet at the time of the inspection. Vegetation is growing throughout the pile and no signs of erosion were observed during the inspection.

## ENFORCEMENT ACTIONS/COMPLIANCE

No enforcement actions are pending and none were taken as a result of this inspection.

# **AVAILABILITY OF RECORDS**

PERMIT RECORDS		HYDROLOGIC RECORDS				
DRMS Permit	Exp 8/20/2015	NPDES Permit	COG0048275			
Permit Application w/Revisions	OK MR18	NPDES Records	1Q2013			
Findings Document	5/17/2010	Stormwater Management Plan	2012			
Insurance Certificate	Exp 11/1/2013	SPCC Plan	2012			
Bond Document	SB-007	MSHA Pond Inspections	NA			
	\$6,160,431.65					
Phased Bond Release	See Note 1		NA			
Documents/Findings		State Engineer's Pond Inspection				
Air Emission Permits	10RO1175F mod1	Quarterly Pond Inspections	4Q2012			
County Special Use Permits	PP2010-17	Annual Hydrology Reports	2012			
<b>UG Mining Landowner Notification</b>	3/29/2011	<ul> <li>Ground Water Monitoring</li> </ul>	AHR			
Subsidence Monitoring Reports	NA	<ul> <li>Surface Water Monitoring</li> </ul>	AHR			
Subsidence Monitoring Data	OK	<ul> <li>Spring &amp; Seep Monitoring</li> </ul>	AHR			
Rill & Gully Survey	2012	<ul> <li>Mine Water Discharge Monitoring</li> </ul>	NA			
Vegetation Monitoring Data	2012	Mine Inflow Study	NA			
Specific Variance Approvals	NA	Water Consumption Records	NA			
Annual Reclamation Reports	2012	Well Permits	PAP			
Midterm Review Documents	2013					
DRMS/OSM Inspection	Thru 4/2013					
Reports/Enforcement Actions (3						
Years)		BLASTING RECORDS				
Transfers/Succession of Operator	SO1	Blasting Publication	8/6/2011			
Temporary Cessation Notification	NA	Blasting Records (3 years)	Thru 10/19/2011			
Reclamation Cost Estimate	MT1	ATFE Explosives Permit	Exp 3/1/2014			
CERTIFICATIONS		Blasting Variances	NA			
Pond Certifications	PAP See Note 2	Pre-Blast Surveys	NA			
Annual Certifications for	2012					
Impoundments						
Fill Certifications for Excess Spoil	NA	ADDITIONAL RECORDS				
or Underground Development Waste		(specify)				
<ul> <li>Quarterly Inspections</li> </ul>	NA					
<ul> <li>Compaction Testing</li> </ul>	NA					
<ul> <li>Final Certification</li> </ul>	NA					
Coal Processing Waste Banks	NA					
Haul Road Certifications	PAP					
Access Road Certifications	PAP					
COMMENTS: 1 SI 1 currently and	or ravious by the Division	n 2 As built cortifications for approx	vod sump			
COMMENTS: 1 – SL1 currently under review by the Division 2 – As-built certifications for approved sump  Construction have yet to be completed, ongoing construction						
Construction have yet to be completed	, ongoing construction					

Number of <u>Partial</u> Inspection this Fiscal Year: 8 Number of <u>Complete</u> Inspections this Fiscal Year: 4