STATE OF COLORADO

DIVISION OF RECLAMATION, MINING AND SAFETY Department of Natural Resources

1313 Sherman St., Room 215 Denver, Colorado 80203 Phone: (303) 866-3567 FAX: (303) 832-8106

Memo

To: File M-1978-208, Shaffers Crossing Quarry, Elk Creek Sand & Gravel, LLC

From: Tom Kaldenbach, Senior Environmental Protection Specialist

Tom Kldubal

Date: July 25, 2013

Re: Review of monitoring data from October 2, 2012 blast

My inspection report from the October 16, 2012 inspection of the Shaffers Crossing Quarry indicated a need for a follow-up inspection for the purpose of evaluating off-site impacts of blasting. Based on the evaluation of seismic monitoring data provided by the operator (page 1 of the blast monitoring report, dated October 2, 2012, prepared by Matheson Mining Consultants, Inc.), such a follow-up inspection is not needed.

The Matheson report indicates peak particle velocities were less than 0.5 inches/second on adjoining properties (see attached copy of page 1 of the report).



John W. Hickenlooper Governor

Mike King Executive Director

Loretta E. Pineda Director



303-816-7147 p.1 303-816-7147 p.1 2801 Youngfield Street, Suite 171 Golden, CO 80401-2266 303-456-5638 Toll Free 888-456-5638 Fax 303-456-5639 www.mathesonmining.com

TAK

October 2, 2012

Mr. Jim Knoll Yenter Companies 20300 Highway 72 Arvada, CO 80007

Re: Elk Creek Sand & Gravel Quarry, Jefferson County, CO; October 2, 2012

Dear Mr. Knoll,

On October 2, 2012, Matheson Mining Consultants Inc. (MMC) monitored one production blast at the Elk Creek Sand & Gravel Quarry located @ CO HWY 285/South Elk Creek Rd. (near "Shaffer's Crossing") in Jefferson County, Colorado. Portable seismographs were deployed at four separate locations; one adjacent to the equipment maintenance building/well, on the Elk Creek Sand & Gravel Quarry property (Loc. 1), one at the Elk Creek Sand & Gravel office trailer/truck scale (Loc. 2), one at the residence of Rodger & Juliet Moores (Loc. 3), & one at Cliff Eden's shop building, directly across the street from the quarry (Loc. 4). Below is a table listing the location # / instrument serial number, distance & direction from the blast, peak particle velocity, and peak air overpressure measurements.

Ground Vibration Summary

. Location (#) / Inst. Serial Number	Distance (yards) & Direction	Peak Particle Velocity (inches/sec)	Peak Air Overpressure dB(L)
(1) / BA10328	~105 - NW	1.03	127.6
(2) / BA10185	~140 - NNW	0.64	126.2
(3) / BA5738	~280 - SE	0.26	117.5
(4) / BA6752	~255 - West	0.23	127.8

The highest reading measured was at the closest distance; adjacent to the Elk Creek Sand & Gravel equipment maintenance building (where the well is located).

All four instruments recorded vibrations that are significantly less than the United States Bureau of Mines Report of Investigations 8507 and the Office of Surface Mining Reclamation and Enforcement non-damage standards for drywall in framed houses.

RECEIVED

1 2013

Division of Reclamation, Mining & Safety