

COLORADO DIVISION OF RECLAMATION, MINING AND SAFETY COAL PROGRAM INSPECTION REPORT



PERMIT INFORMATION

Permit Number: C-1981-012 Mine Name: New Elk Mine Operator: New Elk Coal Company, LLC Operator Address: Mr Ron Thompson 12250 Highway 12 Weston, CO 81091 **County:** Las Animas **Operation Type:** Underground **Permit Status:** Temporary Cessation **Ownership:** Private

Operator Representative Present:

Operator Representative Signature: (Field Issuance Only)

INSPECTION INFORMATION

| Inspection Start Date: December 18, 2013 Inspection Start Time: 11:00 Inspection End Date: December 18, 2013 Inspection End Time: 11:30 | | | Inspection Type: Aerial Inspection Inspection Reason: Normal I&E Program Weather: Cloudy | |
|--|-----------|----------------------------|--|-------------------|
| Joint Inspection Agency: | | Joint Inspection Contacts: | | |
| None | | | | |
| Post Inspection Agency: | | Post Inspection Contacts: | | |
| None | | | | |
| Inspector(s): | Inspector | r's Sig | nature: | Signature Date: |
| Leigh D. Simmons Harry B. Ranney | 1A | }- | \checkmark | December 24, 2013 |

Inspection Topic Summary

NOTE: Y=Inspected N=Not Inspected R=Comments Noted V=Violation Issued NA=Not Applicable

- **N** Air Resource Protection
- ${\bf N}\,$ Availability of Records
- $N\,$ Backfill & Grading
- **R** Excess Spoil and Dev. Waste
- N Explosives
- $N\,$ Fish & Wildlife
- **R** Hydrologic Balance
- **R** Gen. Compliance With Mine Plan
- N Other
- **R** Processing Waste

- N Roads
- N Reclamation Success
- N Revegetation
- N Subsidence
- ${\bf N}\,$ Slides and Other Damage
- **N** Support Facilities On-site
- N Signs and Markers
- N Support Facilities Not On-site
- ${\bf N}\,$ Special Categories Of Mining
- N Topsoil

COMMENTS

This was an aerial inspection. Pictures were taken by Harry Ranney of Colorado Division of Reclamation, Mining and Safety (the Division) during a flight on December 18, 2013. Conditions were overcast, but the air was clear. A little snow was on the ground on shaded northerly aspects.

Several permitting actions are in progress, these are detailed under the heading GENERAL MINE PLAN COMPLIANCE.

Two recent enforcement actions have been abated and terminated; a third has since been issued. Details are given under the heading ENFORCEMENT ACTIONS.

The New Elk Mine continues in Temporary Cessation whilst NECC searches for investors and coal customers.

On November 26, 2013, Cline Mining announced that they had received the 90-day notice of resignation of Mark Haywood as President, CEO and director. Doug Blackburn has been hired by Cline Mining to act as General Manager of New Elk Coal Company (NECC). Mr Blackburn is employed as a contractor, rather than a permanent employee of either company.

EXCESS SPOIL and DEVELOPMENT WASTE - Rule 4.09

Placement; Drainage Control; Surface Stabilization:

The Development Waste Pile (DWDA 1) appears well vegetated when viewed from above. There were no signs of erosion or instability.

The Development Waste Disposal Area (DWDA 2) was stable however, it was clear that the east end of the pile had not yet been re-shaped following the repairs to the adjacent ditch. **The pile should be restored to match the design specifications**.

Additional development waste has been stored in the soil storage area. It appeared that the piles had been partially re-shaped. An orange fence was used to segregate different types of material.

HYDROLOGIC BALANCE - Rule 4.05

Drainage Control 4.05.1, 4.05.2, 4.05.3; Siltation Structures 4.05.5, 4.05.6; Discharge Structures 4.05.7, 4.05.10;

Diversions 4.05.4; Effluent Limits 4.05.2; Ground Water Monitoring 4.05.13; Surface Water Monitoring 4.05.13; Drainage – Acid and Toxic Materials 4.05.8; Impoundments 4.05.6, 4.05.9; Stream Buffer Zones 4.05.18:

There was no indication that any work had taken place to restore the upland diversion ditch above the RDA. This ditch is the subject of NOV CV 2013-009.

GENERAL MINE PLAN COMPLIANCE:

TR68 was reviewed for adequacy by the Division in a letter dated November 27, 2013. The Division awaits NECC's response. The proposed decision due date is December 31, 2013.

TR64 and PR4 were withdrawn.

It was previously stated, incorrectly, that TR67 had been withdrawn. In fact that is not the case, although the Division suggests that NECC consider withdrawing the revision since it is unlikely that the proposed work would be completed in the near future.

The proposed decision due date for MR120 was extended to December 31, 2013. Currently the Division is waiting on a response to the last adequacy letter.

An application for permit renewal (RN6) was received in good time and found complete. It is not feasible to approve the application until such time as the response to the last mid-term review is completed (MT6 and TR68).

PROCESSING WASTE/COAL MINE WASTE PILES - Rule 4.10 and 4.11

Drainage Control; Surface Stabilization; Placement:

Pictures of the RDA showed no signs of instability or erosion. There was no indication that any waste had been deposited recently.

DOCUMENTS RECEIVED N/A

OTHER (SPECIFY)

N/A

ENFORCEMENT ACTIONS/COMPLIANCE

Infraction Number: CV2013007

Inspection Date: July 23, 2013 Date Issued: August 22, 2013 Primary Topic: Hydrologic Balance Description: Failure to treat surface drainage from a disturbed area before leaving the permit area, in violation of Rule 4.05.2(1)

The violation has been terminated. Payment of the fixed penalty was received on December 16, 2013.

Infraction Number: CV2013008

Inspection Date: July 23, 2013 Date Issued: August 22, 2013 Primary Topic: Hydrologic Balance Description: Failure to maintain ditches, culverts and berms in compliance with the approved design, in violation of Rule 2.07.7(7).

The violation has been terminated. Payment of the fixed penalty was received on November 26, 2013.

Infraction Number: CV2013009

Inspection Date: Date Issued: November 25, 2013 Primary Topic: Hydrologic Balance Secondary Topic: Processing Waste Description: Abatement #: 1 Abatement #: 1 Abatement Due Date: 1/24/2014 Abatement Description: Construct the RDA upland diversion ditch so that is in compliance with the approved design

PHOTOGRAPHS









