

# COLORADO DIVISION OF RECLAMATION, MINING AND SAFETY MINERALS PROGRAM INSPECTION REPORT

PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME:	MINE/PROSPECTING ID#:	MINERAL:	COUNTY:
LaSalle Pit	M-2009-042	Gravel and sand	Montrose
INSPECTION TYPE:	INSPECTOR(S):	INSP. DATE:	INSP. TIME:
Monitoring	Dustin M. Czapla	April 17, 2014	13:00
OPERATOR:	OPERATOR REPRESENTATIVE:	TYPE OF OPERATION:	
Montrose County	Norm David	112c - Construction Regular Operation	

REASON FOR INSPECTION:	BOND CALCULATION TYPE:	BOND AMOUNT:
Normal I&E Program	Complete Bond	\$0.00
DATE OF COMPLAINT:	POST INSP. CONTACTS:	JOINT INSP. AGENCY:
NA	None	None
WEATHER:	INSPECTOR'S SIGNATURE:	SIGNATURE DATE:
Clear		April 18, 2014

### GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS <u>Y</u>	(FN) FINANCIAL WARRANTY NA	(RD) ROADS <u>Y</u>
(HB) HYDROLOGIC BALANCE <u>Y</u>	(BG) BACKFILL & GRADING <u>N</u>	(EX) EXPLOSIVES <u>NA</u>
(PW) PROCESSING WASTE/TAILING <u>NA</u>	(SF) PROCESSING FACILITIES <u>Y</u>	(TS) TOPSOIL <u>Y</u>
(MP) GENL MINE PLAN COMPLIANCE- Y	(FW) FISH & WILDLIFE <u>Y</u>	(RV) REVEGETATION N
(SM) SIGNS AND MARKERS <u>Y</u>	(SP) STORM WATER MGT PLAN NA	(SB) COMPLETE INSP Y
(ES) OVERBURDEN/DEV. WASTE NA	(SC) EROSION/SEDIMENTATION Y	(RS) RECL PLAN/COMP N
(AT) ACID OR TOXIC MATERIALS Y	(OD) OFF-SITE DAMAGE <u>NA</u>	(ST) STIPULATIONS <u>NA</u>

Y = Inspected and found in compliance / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

PERMIT #: M-2009-042 INSPECTOR'S INITIALS: DMC INSPECTION DATE: April 17, 2014

#### **OBSERVATIONS**

This inspection was conducted as part of the Division of Reclamation, Mining and Safety's (Division) normal monitoring program. Norm David and Curtis Hamilton, representing the Operator, were present during this inspection. Photographs are included with this report in order to illustrate some of the conditions observed.

The LaSalle Pit is located approximately three miles northwest of Montrose and accessed from 6175 Road. The site is a 112c operation that includes a total of 27.76 permitted acres.

Adequate mine identification signage was noted at the entrance to the site.

The affected area was marked by fencing that was clearly visible and adequate to delineate the affected area boundary.

The Phase 1 area has been stripped of topsoil and overburden. Soil has been placed around the perimeter of the pit to create a visual berm. Mining has commenced in the north part of the Phase 1 area, to a depth of approximately 15 feet, and is progressing south. Materials stockpiles are stored throughout the Phase 2 area.

No problems or violations were noted during this inspection.

Responses to this inspection report should be directed to Dustin Czapla at the Division of Reclamation, Mining and Safety, Grand Junction Field Office, 101 South 3<sup>rd</sup> Street, Room 301, Grand Junction, Colorado 81501, phone number (970) 243-6299.

## **PHOTOGRAPHS**



Figure 1: Phase 1 mining area



Figure 2: Phase 1 mining area



Figure 3: Southern Phase 1 area to be mined



Figure 4: Southern Phase 1 area to be mined



Figure 5: Phase 2 area to be mined



Figure 6: Phase 2 area to be mined

## **Inspection Contact Address**

Norm David Montrose County 161 South Townsend Avenue Montrose, CO 81401