



**COLORADO DIVISION OF RECLAMATION, MINING AND SAFETY**  
**MINERALS PROGRAM INSPECTION REPORT**  
**PHONE: (303) 866-3567**

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

<b>MINE NAME:</b> Sunday Mine	<b>MINE/PROSPECTING ID#:</b> M-1977-285	<b>MINERAL:</b> Uranium & vanadium	<b>COUNTY:</b> San Miguel
<b>INSPECTION TYPE:</b> Monitoring	<b>INSPECTOR(S):</b> Bob Oswald	<b>INSP. DATE:</b> July 16, 2014	<b>INSP. TIME:</b> 12:30
<b>OPERATOR:</b> Energy Fuels Resources (USA) Inc.	<b>OPERATOR REPRESENTATIVE:</b> David Turk	<b>TYPE OF OPERATION:</b> 112d-2 - Designated Mining Operation	
<b>REASON FOR INSPECTION:</b> Normal I&E Program	<b>BOND CALCULATION TYPE:</b> None	<b>BOND AMOUNT:</b> \$304,184.00	
<b>DATE OF COMPLAINT:</b> NA	<b>POST INSP. CONTACTS:</b> U.S. BLM	<b>JOINT INSP. AGENCY:</b> U.S. BLM	
<b>WEATHER:</b> Cloudy	<b>INSPECTOR'S SIGNATURE:</b> <i>Bob Oswald</i>	<b>SIGNATURE DATE:</b> August 5, 2014	

**GENERAL INSPECTION TOPICS**

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS----- <u>NA</u>	(FN) FINANCIAL WARRANTY----- <u>Y</u>	(RD) ROADS----- <u>Y</u>
(HB) HYDROLOGIC BALANCE----- <u>Y</u>	(BG) BACKFILL & GRADING----- <u>N</u>	(EX) EXPLOSIVES----- <u>NA</u>
(PW) PROCESSING WASTE/TAILING---- <u>NA</u>	(SF) PROCESSING FACILITIES----- <u>NA</u>	(TS) TOPSOIL----- <u>N</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>NA</u>	(FW) FISH & WILDLIFE----- <u>NA</u>	(RV) REVEGETATION---- <u>Y</u>
(SM) SIGNS AND MARKERS----- <u>Y</u>	(SP) STORM WATER MGT PLAN---- <u>NA</u>	(SB) COMPLETE INSP---- <u>NA</u>
(ES) OVERBURDEN/DEV. WASTE----- <u>Y</u>	(SC) EROSION/SEDIMENTATION--- <u>Y</u>	(RS) RECL PLAN/COMP-- <u>NA</u>
(AT) ACID OR TOXIC MATERIALS----- <u>Y</u>	(OD) OFF-SITE DAMAGE----- <u>NA</u>	(ST) STIPULATIONS----- <u>NA</u>

Y = Inspected and found in compliance / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

## OBSERVATIONS

This was a routine inspection conducted by the Division as part of its monitoring of 112 DMO permits. The operator's representative named on page one was present throughout the inspection. The site was not active on the day of the inspection. The required permit ID sign was observed posted at the entrance gate to the permitted area. Permit boundary markers were observed at several boundary corners. All mining disturbances were within the permit boundary.

An intense precipitation event occurred the night before the inspection, which resulted in the partial or complete failure of nearly every stormwater control structure on the site. The structures were designed by the operator's engineers during the formulation of the Environmental Protection Plan (EPP) several years ago, to provide sufficient capacity for the design storm. They were installed and maintained regularly as required. However, the intensity and/or total amount of precipitation in this event was beyond the design capacity of most of the structures. Only a few of the structures were intact (and full) at the time of the inspection.

The range of stormwater controls observed during this inspection includes upland diversion ditches, safety berms along the crests of the waste rock dumps, catchments at the upper edges of the dumps, cells and control dikes on the pad surfaces, sediment ponds below the toe of the dumps, culverts, waterbars and ditches along the roads. This report will not list all of the individual items observed, because they were so numerous and similarly affected. What was apparent about the damage was that all the structures appeared to have functioned properly up to a point of maximum capacity and strength, evident by a visible high-water mark of organic debris (indicating impoundment) and one or several locations of vertical down-cutting through each impoundment. In some cases, failure of one impoundment caused a slug of water and sediment to overwhelm one or more lower structures, resulting in a series of breaches.

The approved stormwater control structures have been inspected previously and found to be installed according to the approved criteria, and in a maintained condition. The damaged condition of the structures and resultant release of sediment, as observed during this inspection, are not being noted as a problem, since size and intensity of this storm event is considered to be beyond the design specifications in the EPP. The operator is, however, urged to perform the following measures as soon as possible:

1. repair all damaged stormwater control structures, at least to the specifications in the approved EPP; upgrade the strength (cross-sectional thickness) of the dikes wherever possible, but do not raise only the height of the dikes;
2. consider designing and installing armored outlets (spillways) for at least the critical impoundments;
3. remove the sediment and debris from the impoundments, to re-establish the design capacity;
4. consider using the salvaged sediments as growth media, and either stockpile them for later use or spread them on graded surfaces and seed them;
5. reseed disturbed areas so that they become better protected against erosion; and
6. monitor for new areas of weeds since seeds may have been deposited with the sediments.

For all changes that are being considered at the site, please contact this office to see if a revision is needed.

The bond was recently calculated and is considered sufficient. There were no contaminants or inadequately contained hydrocarbons observed. The operator is controlling noxious weeds, although Halogeton remains

prevalent on the site. No problems are noted in this report.

For questions related to this report, please contact this inspector at the Division's Durango Field Office: telephone 970-247-5193, or 303-866-3567 ext 8175.

All written correspondence should be sent directly to the Division's Denver Office:  
Division of Reclamation, Mining & Safety  
1313 Sherman Street, Room 215  
Denver, CO 80203

**Inspection Contact Address**

Andrea Reither  
Energy Fuels Resources (USA) Inc.  
225 Union Blvd., Ste. 600  
Lakewood, CO 80228

EC: James Blair, BLM, Tres Rios Field Office, Dolores

Photographs from the inspection are on the following page.



**PHOTOGRAPHS**

