

Page 2 of 3

## 110c Annual Report

Total acres backfilled:	0	Total acres seeded w/ approved mix:	0	Total acres w/topsoil replaced:	0	Total acres mulched w/ approved mulch:	0
Total acres graded:	0	Total acres fertilized w/ apvd fertilizer:	0	Topsoil replacement depth (in.):	0	Mulch application rate (tons):	0
Seed application method:	N/A	Fertilizer application method:	N/A	Mulch application method:	N/A		

13. Is weed control being conducted in accordance with an approved Weed Control Plan? YES NO N/A  
If "YES", indicate the weed species, control area, control type, application rate and treatment date on the report map.
14. Is adequate topsoil reserved for reclamation, based on your approved permit? YES NO N/A  
If "NO", please explain:
15. Is the reserved topsoil vegetated/stabilized in accordance with Rule 3.1.9(1)? YES NO N/A  
If "NO" please explain:
16. If mining has exposed groundwater, is the site in compliance with the approved mining plan and Office of the State Engineer (Well Permit, S.W.S.P., and/or Permanent Augmentation Plan)? YES NO N/A
17. Are all hazardous materials stored within approved spill containment structures? YES NO N/A
18. Is your financial warranty value sufficient to cover the cost to complete reclamation? YES NO N/A
19. Is your basis for legal right to enter still valid? YES NO
20. Does your permit require you to submit monitoring information annually? YES NO N/A  
If "Yes", please attach the required monitoring results to this Annual Report.
21. As required by Colorado Mined Land Reclamation Act and/or Colorado Land Reclamation Act for the Extraction of Construction Materials (C.R.S. 34-32-116 or 34-32.5-116), attach a map to this report that accurately depicts the permit boundary, current affected area boundary and location of the acreages specified in items 7- 12 and 14.  
UPDATED MAP ATTACHED:

Division records indicate the following permittee contact information. If this information is not current, please type or print **current** contact information:

Permittee Contact:	John DeWitt	
Permittee Company:	Lincoln County	
Address:	P.O. Box 39 Hugo, CO 80821	
Phone Number:	(719) 743-2337	
Fax Number:		
Email Address:	CF.PR.email	

I, the undersigned, hereby state that the information provided in this report is true and accurate, and that site operations are being conducted in accordance with the Division approved mining and reclamation plans.

  
Signature of Permittee, Corporate Officer, Owner, or Documented Designee

11-4-14  
Date

RECEIVED

NOV 13 2014

DIVISION OF RECLAMATION  
MINING AND SAFETY

OWNER'S ACCESS ROAD

HAUL ROAD

100

600'

4+00

2+00

0+00

WORK AREA

MINING AREA

ARIKAREE

RIVER

(Intermittent)

BASELINE



SCALE

0 100 200 FEET

LINCOLN COUNTY

IVAN ENDERSON PIT  
(M-1979-111)

SW1/4 SW1/4, SECTION 6  
TOWNSHIP 7 SOUTH,  
RANGE 52 WEST  
TOTAL AFFECTED ACREAGE = 6.3

ALL LAND ADJACENT LAND TO THE  
AREA IS OWNED BY IVAN ENDERSON

MAP IS CURRENT AS OF:

11/4/14

**Division of Reclamation, Mining, and Safety**

**Fee Receipt for M1979111**

Lincoln County

000000000

**Receipt #:** 18530

**Date:** 11/13/2014

**Permit:** M1979111

Payment Method	Revenue Code	Fee Description/Notes	Amount
27105 msr	4300-MAF0	Minerals Annual Fees M1979-111	\$323.00

<b>Receipt Total:</b>	<b>\$323.00</b>
-----------------------	-----------------