


Appendix J.7 Secondary Geomembrane Acceptance Notifications




CLIENT:	Cripple Creek & Victor Mining Co.	Page / of 2
PROJECT:	Squaw Gulch VLF PSSA	Weather_ Sunny
PROJECT NUMBER:	74201125N0	Date6-16 - 14
Work Activity:	100-mil LLDPE Geomembrane Liner	
ii)		
Area/Location:	See attached sketch PAPELS 2	TARU 10 FROM 9450 70
PSSA POPD	FLOOR TOP	
Items	Visual inspection of installed panels	
Inspected:	Visual inspection of wedge welds	
	Visual inspection of extrusion welding	
	Survey completed V	
Tests	Air testing on seams	
Completed:	Vacuum box testing on extrusion welds	*
	Repairs and patches tested as required	
	3rd party conformance tests	
Deficient	ROCKS AND MEMOR DIFFRCTS	WIERZ MARKED WITH ORMUN
Items:	PARNT AND REQUERE A BE	
		,
	,	
Remedial	ROCKS AND MENOR DEPLOTS	with REPATIBD. WATHERS
Action:	WELL BR ADDRASSAD DURENG	LOW VOLUMA PLACEMENT
Accepted:	Yes 🗶	No
Explain:		
·		
Signatures		
AMEC		
AMEC		ECA
Ames	ello 1/2	Other
CC&V	the death	Other






	Cripple Creek & Victor Mining Co. Page / of 2
PROJECT:	Squaw Gulch VLF PSSA Weather Survey
PROJECT NUMBER:	74201125N0 Date 6/17/14
Work Activity:	100-mil LLDPE Geomembrane Liner
Area/Location:	See attached sketch - ADR PLATFORM, CLOSURIE DRAZO WEST, SOWTH
AND GAST SE	prs. PAIRLY S-11 PHRU S-130
	Visual inspection of installed panels
Inspected:	Visual inspection of wedge welds
	Visual inspection of extrusion welding
	Survey completed
	Air testing on seams
Completed:	Vacuum box testing on extrusion welds
	Repairs and patches tested as required
	3rd party conformance tests
Deficient	MINOR DIFFRET WERR FORMS) AND MARIERD WETH ORANGE OR PENE
Items:	
,	
Remedial	REPATRI MADE DUNIN, LOW VOLUME PLACEMENT
Remedial Action:	REPAIRS MADE DURING LOW VOLUME PLACEMENT
Remedial Action:	REPAIRS MADE DURING LOW VOLUME PLACEMENT
Remedial Action:	
Action:	Yes
Action: Accepted: Explain:	Yes
Action: Accepted: Explain:	Yes
Action: Accepted: Explain:	Yes No






CLIENT:	Cripple Creek & Victor Mining Co. Page / of 2
PROJECT:	Squaw Gulch VLF PSSA Weather Swry
PROJECT NUMBER:	74201125N0 Date 6/28/14
Work Activity:	100-mil LLDPE Geomembrane Liner
Area/Location:	See attached sketch - PSSA CLOSURA DRAIN PAPING S-151THRUS
5-143	▼ 1.1 (1.1 (1.1 (1.1 (1.1 (1.1 (1.1 (1.1
Items	Visual inspection of installed panels
Inspected:	
	Visual inspection of extrusion welding
	Survey completed
Tests	Air testing on seams
Completed:	Vacuum box testing on extrusion welds
	Repairs and patches tested as required
	3rd party conformance tests
Deficient	DRAED PIDE MUST 1319 RAMMED AT A FUTURE DATE.
Items:	OVERLAP WRONG DERRETTON
Remedial	EXTRUSTED WALD OUTSTLAP
Action:	area of Argin pipe to be removed will not have
	Low volcime placed.
Accepted:	Yes No
Explain:	
- 20	
Signatures	
AMEC	ECA
Ames	Other
CC&V	Hone Other






CLIENT:	Cripple Creek & Victor Mining Co. Page / of 2	
PROJECT:	Squaw Gulch VLF PSSA Weather Survey	
PROJECT NUMBER	: 74201125N0 Date 7/2/14	
Work Activity:	: 100-mil LLDPE Geomembrane Liner	
Area/Location:	: See attached sketch PSSA POND PANTY 5-13 THAN 5-1	145
Aron 5	-164 THRU SITY 9450 BRILL TO TOK OF SLOPE E.	
	Visual inspection of installed panels	
Inspected:	Visual inspection of wedge welds	
	Visual inspection of extrusion welding	
	Survey completed -	
	Air testing on seams	
Completed:	Vacuum box testing on extrusion welds	
	Repairs and patches tested as required	
	3rd party conformance tests	
Deficient	ROCKS FOURD AND MARKED WITH ORANGE PAINT.	
Items:	JACUM TRSTEPG OF ALL PATCHURS.	
Remedial	Vacuum testing of all patches completed and	d
Action:	Vacuum testing of all patches completed and	
	,	8
Accepted:	Yes No	
Explain:		
1-		
Signatures		
AMEC	ECA	
	9 744	
Ames_	C. Marsh Other	
CC&V	Other Other	
-		






CLIENT:	Cripple Creek & Victor Mining Co. Page
PROJECT:	Squaw Gulch VLF PSSA Weather รู่บาวการ
PROJECT NUMBER:	Squaw Gulch VLF PSSA Weather
Work Activity:	100-mil LLDPE Geomembrane Liner
Area/Location:	See attached sketch - PANELS 5-1 THROUGH 5-10, 5-131 THROUGH
5-134 FROM T	TOE OF SUPE TO EAST END OF SEAM.
	Visual inspection of installed panels
Inspected:	
	Visual inspection of extrusion welding
	Survey completed
Tests	Air testing on seams
Completed:	
	Repairs and patches tested as required
	3rd party conformance tests
Deficient	
Items:	
Remedial	A)On 1/2
Action:	
Accepted:	Y Y
Explain:	
Signatures	
Signatures	
AMEG	ECA
Ames	Other
CC&V	How Other






CLIENT:	Cripple Creek & Victor Mining Co. Page 2 of
PROJECT:	Squaw Gulch VLF PSSA Weather 5 wmg
PROJECT NUMBER:	
Work Activity:	100-mil LLDPE Geomembrane Liner
Area/Location:	See attached sketch PSSA 20,51) FEDORL SOUTH VEIST SEUTZON.
PAPRLS S-	175 - \$Hey 5-185, 5-194 + 5-195
	Visual inspection of installed panels
Inspected:	Visual inspection of wedge welds
	Visual inspection of extrusion welding
	Survey completed /
Tests	Air testing on seams /
Completed:	Vacuum box testing on extrusion welds
	Repairs and patches tested as required
	3rd party conformance tests
Deficient	SOIL LIPRE IZELL SOFT FROM TOR OF SLOPA
Items:	
Remedial	ARGA WAS I GET TO DRY WITHOUT ANY ATTONS
Remedial Action:	ARRA WAS LEFT TO DRY WITHOUT ANY ACTION.
Action:	ANGA WAS REINSPRCTRI) AND APPROUND.
Action: Accepted:	Yes X No
Action:	Yes X No
Action: Accepted:	Yes X No
Action: Accepted: Explain:	Yes X No
Action: Accepted: Explain:	Yes X No No
Action: Accepted: Explain:	Yes X No No
Action: Accepted: Explain:	Yes X No ECA
Action: Accepted: Explain: Signatures AMEC	Yes X No ECA Other






CLIENT:	Cripple Creek & Victor Mining Co.	Pageof
PROJECT:	Squaw Gulch VLF PSSA	Weather_Swwy
PROJECT NUMBER:	74201125N0	Date 7/3/14
Work Activity:	100-mil LLDPE Geomembrane Liner	
Area/Location:	See attached sketch PANELS 5-146	70 S-150
Items	Visual inspection of installed panels V	
Inspected:	Visual inspection of wedge welds \(\)	
	Visual inspection of extrusion welding	
	Survey completed /	
	Air testing on seams 🗸	
Completed:	Vacuum box testing on extrusion welds 🗸	
	Repairs and patches tested as required /	
Eller Control	3rd party conformance tests	
Deficient	POPE	
Items:		
Remedial	PONE	
Action:		
Accepted:	Yes	No
Explain:		
Signatures		
ABACO	10.	
AMEC	9	CA
Ames	2- Marolf Oth	ner
CC&V	the 24 Oth	ner






CLIENT:	Cripple Creek & Victor Mining Co.	Page/_of2
PROJECT:	Squaw Gulch VLF PSSA	Weather
PROJECT NUMBER:	74201125N0	Date 7/11/2014
Work Activity:	100-mil LLDPE Geomembrane Liner	
	Panels 200,201, 202, and 1	83
Area/Location:	See attached sketch	

Items	Visual inspection of installed panels - אפט	
Increated:		
	Visual inspection of extrusion welding - Yes	
	Survey completed - Yes	, , , , , , , , , , , , , , , , , , , ,
Tests	Air testing on seams - clane	
Completed:	Vacuum box testing on extrusion welds - dien	ρ
	Repairs and patches tested as required - Ye	
	3rd party conformance tests N/A	
Deficient	Rocks under the liner	
Items:		
Remedial	Removed and the lines	Mr. Daired Maniform
Action:	Removed and the liner and inspected by Dyla	n Budreau
		., ., .,
Accepted:	Yes X No	
-	Drawing attached. Se	e at the hack
	J. W. G. C.	
Signatures		
	And	
AMEC	Fin M. ECA_	Web states and the state of the
Ames	Other_	
CC&V	A Other	






CLIENT:	Cripple Creek & Victor Mining Co.	Page/of
PROJECT:	Squaw Gulch VLF PSSA	Weather CLeui) y
PROJECT NUMBER:	74201125N0	Weather <u>CLeui) y</u> Date <u>7/11/14</u>
Work Activity:	100-mil LLDPE Geomembrane Liner	
Area/Location:	See attached sketch - PANGLS 5	- 184 5-202 8 8-204
,	Odd attached chotch 7777 (3)	10./3.203 3 20
Items	Visual inspection of installed panels	
Inspected:		
	Visual inspection of extrusion welding	
	Survey completed	
Tanta	A	
l ests Completed:	Air testing on seams	
	Vacuum box testing on extrusion welds	
	Repairs and patches tested as required	
	3rd party conformance tests	
Deficient		
Items:		
Remedial		
Action:		
Accomtod	X X	
Accepted:		No
Explain:		
Signatures		
AMEC		ECA
Ames		Other
CC&V	XX O	Other






CLIENT:	Cripple Creek & Victor Mining Co.	Pageof
PROJECT:	Squaw Gulch VLF PSSA	Weather (Loui) Y
PROJECT NUMBER:	74201125N0	Date_7/11/14
Work Activity:	100-mil LLDPE Geomembrane Liner	
Area/Location:	See attached sketch PANELS 5-13	6 THROUGH 5-138 \$ 5-140
THROUGH 5-14	1	OM TOB OF SLOPE TO EAST END OF SEAM.
	Visual inspection of installed panels	
Inspected:	Visual inspection of wedge welds	
	Visual inspection of extrusion welding	
	Survey completed	
Tests	Air testing on seams	
Completed:	Vacuum box testing on extrusion welds	3
	Repairs and patches tested as required	
	3rd party conformance tests	
Deficient	7 01 11	
Items:		
Remedial		
Action:		
Accepted:	YesX	No
Explain:		
Signatures		52
A1450		ECA
AMEC	5	ECA
Ames	5	Other
CC&V	ALO_	Other






CLIENT:	Cripple Creek & Victor Mining Co. Page / of /
PROJECT:	Squaw Gulch VLF PSSA Weather SUNY
PROJECT NUMBER:	74201125N0 Date 7/24)14
Work Activity:	100-mil LLDPE Geomembrane Liner
Area/Location:	See attached sketch - PANELS S-220 TMRU S-224
	Visual inspection of installed panels
Inspected:	Visual inspection of wedge welds
	Visual inspection of extrusion welding
	Survey completed
	Air testing on seams
Completed:	Vacuum box testing on extrusion welds
	Repairs and patches tested as required
	3rd party conformance tests
Deficient	GROMEMBRANE NOT APPROVIED FOR THE EAST
Items:	5' OF PANSES 5-195 S-220
Remedial	
Action:	
Accepted:	Yes No
Explain:	
Signatures	
AMEC	ECA
	Santa
Ames	Top For Ames Other
CC&V	And Other






CLIENT: PROJECT: PROJECT NUMBER: Work Activity:	Cripple Creek & Victor Mining Co. Squaw Gulch VLF PSSA Weather CLOUP 74201125N0 Date 7/25/14
Area/Location:	See attached sketch PANRLS 5-224 THROUGH S-233, S191,5192
	Visual inspection of installed panels
Tests Completed:	Repairs and patches tested as required
Deficient Items:	3rd party conformance tests
Remedial Action:	
Accepted: Explain:	
Signatures AMEC	ECA
Ames	Bell Van Other
CC&V	Other_






CLIENT:	Cripple Creek & Victor Mining Co. Page / of
PROJECT:	Squaw Gulch VLF PSSA Weather Swift
PROJECT NUMBER:	Squaw Gulch VLF PSSA Weather 5wry 74201125N0 Date 7/26/14
Work Activity:	100-mil LLDPE Geomembrane Liner
Area/Location:	See attached sketch PANELS S-186 THROUGH S-190
	Visual inspection of installed panels
Inspected:	Visual inspection of wedge welds
*	Visual inspection of extrusion welding
	Survey completed
	Air testing on seams
Completed:	Vacuum box testing on extrusion welds
	Repairs and patches tested as required
	3rd party conformance tests
Deficient	- V 1/2
Items:	
Remedial	
Action:	
Accepted:	Yes No
Explain:	
Signatures	
AMEÇ	
AIVIE	ECA
Ames	Other
CC&V	Hol Other






CLIENT:	Cripple Creek & Victor Mining Co. Page / of /		
PROJECT:	Squaw Gulch VLF PSSA Weather PARTLY CLOUDY		
PROJECT NUMBER:			
Work Activity:	100-mil LLDPE Geomembrane Liner		
Area/Location:	See attached sketch ADR HAUL ROAD RAMP AND EAST SLOPE		
PANELS S-	276 THROUGH S-301, S-244 THROUGH S-247		
	Visual inspection of installed panels		
Inspected:	Visual inspection of wedge welds		
	Visual inspection of extrusion welding		
	Survey completed		
	Air testing on seams		
Completed:	Vacuum box testing on extrusion welds		
	Repairs and patches tested as required		
	3rd party conformance tests		
Deficient			
Items:			
у.			
Remedial			
Action:			
Accepted:	YesNo		
Explain:			
Signatures			
AMEC	ECA		
AlVI ma V	EGA_		
Ames	Channing Brown Other		
CC&V-	Hall Date Other		






CLIENT:	Cripple Creek & Victor Mining Co. Page / of /
PROJECT:	Squaw Gulch VLF PSSA Weather รูบคหุ
PROJECT NUMBER:	21. 1.1
Work Activity:	100-mil LLDPE Geomembrane Liner
,	
Area/Location:	See attached sketch PSSA FLOOR PANELS 5-302 THROUGH
5-314, AND PR	NELS S-232, 5-233, S-208 THROUGH S-217 FROM ADR HAUL
DOAD TO DISA	Visual inspection of installed panels
Inspected:	Visual inspection of wedge welds
	Visual inspection of extrusion welding
	Survey completed
	eurey completed
Tosts	Air testing on seams
Completed:	
	Vacuum box testing on extrusion welds
	Repairs and patches tested as required
	3rd party conformance tests
Deficient Items:	NONE
items.	
Remedial	NONE NEEDED
Action:	
Accepted:	Yes No
Explain:	
Signatures	
Oignatures	
AMEÇ	ECA
Ames	Other
CC&V	95 () of Other






CLIENT:	Cripple Creek & Victor Mining Co.	Page <u>/</u> of_<
PROJECT:	Squaw Gulch VLF PSSA	Weather Sawy
PROJECT NUMBER:	74201125N0	Date 8/24/14
Work Activity:	100-mil LLDPE Geomembrane Liner	
Area/Location:	See attached sketch PANELS 5-3	315 THROUGH 5-328 & 5-218,
THROUND 5-169	FROM TOE OF SUPE TO EED OF Visual inspection of installed panels	ADR HAUL ROAD. PAHELS S-167 SEAM.
Inspected:	Visual inspection of wedge welds	
*	Visual inspection of extrusion welding	
	Survey completed	
	Survey completed	
Tooto	Air tasting an assema	
Completed:	Air testing on seams	
	Vacuum box testing on extrusion welds	
	Repairs and patches tested as required	
	3rd party conformance tests	
Deficient		
Items:		
Remedial	NONE NEEDED	
Action:		
Accepted:	Yes	No
12944		NO
Explain:		
Signatures		
AMEC	THURE 3 HOW DOWN	ECA
Ames	Channing Brown	Other
CC&V	The Color	Other






CLIENT:	Cripple Creek & Victor Mining Co.	Pageof2_
PROJECT:	Squaw Gulch VLF PSSA	WeatherSunny
PROJECT NUMBER:	74201125N0	Date8/25/14
Work Activity:	100-mil LLDPE Geomembrane Liner	
Area/Location:	See attached sketch PANELS S- A OF SEAM, 3-329 THROUGH S-345	170 THROUGH S-174 TOE OF
SLOPE TO E-CITO	of 254mil 2-274 Historian 2-24	Treat only of PSSA.
	Visual inspection of installed panels	
Inspected:	Visual inspection of wedge welds	
*	Visual inspection of extrusion welding	
	Survey completed	
		No. 1 Company
	Air testing on seams	
Completed:	Vacuum box testing on extrusion welds	
	Repairs and patches tested as required	
	3rd party conformance tests	
Deficient	3140(1	
Items:		
Remedial	NONE	
Action:		
Accepted:	Yes	No
Explain:		
		The second second
Signatures		
AMEC		ECA
	0 = 01 0	
Ames	Channis Brown 0	ther
CC&V	The Rotto o	ther






CLIENT:	Cripple Creek & Victor Mining Co.	Pageof
PROJECT:	Squaw Gulch VLF PSSA	Weather Coupy
PROJECT NUMBER:	74201125N0	Date 8/27/14
Work Activity:	100-mil LLDPE Geomembrane Liner	
Area/Location:	See attached sketch PANELS 5-27	8 THROUGH S-290 AND 5-329
THROUGH 5-34	7 FROM ADR HAUL ROAD TO	PSSA FLOOR.
Items	Visual inspection of installed panels	
Inspected:	Visual inspection of wedge welds	
	Visual inspection of extrusion welding	9
	Survey completed	
Tests	Air testing on seams	
Completed		8
	Repairs and patches tested as required	d
	3rd party conformance tests	
Deficient	Novie	
Items		
Remedia	Hone	
Action		
Accepted:	Yes	Mo
	NO PROPERTY OF THE CONTROL OF THE CO	No
Explain:		
Claust		
Signatures		
AMEC		ECA
Ames	MORM	Other
CC&V	Les Des	Other






CLIENT:	Cripple Creek & Victor Mining Co.	Pageof
PROJECT:	Squaw Gulch VLF PSSA	Weather CLOUDY
PROJECT NUMBER:	74201125N0	Date 8/27/14
Work Activity:	100-mil LLDPE Geomembrane Liner	
Area/Location:	See attached sketch PANELS 5-196	THROUGH S-199 AND 5-234
THROUGH 5-257		
	Visual inspection of installed panels	
Inspected:	Visual inspection of wedge welds	
* 1 1 1 1 1 1 1 1 1	Visual inspection of extrusion welding	
	Survey completed	
	Air testing on seams	
Completed:	Vacuum box testing on extrusion welds	
	Repairs and patches tested as required	
	3rd party conformance tests	
Deficient		
Items:		
Remedial	NONE	
Action:		
Accepted:	Yes	No
Explain:		
M. La La		
Signatures		
AMEÇ		ECA
AIVIE	100011	ECA
Ames	NUM	Other
CC&V	Holl day	Other





CLIENT: PROJECT: PROJECT NUMBER:	Cripple Creek & Victor Mining Co. Page / of 2 Squaw Gulch VLF PSSA Weather	
Work Activity:	100-mil LLDPE Geomembrane Liner	
Area/Location:	See attached sketch - PANIELS 5-290 THROUGH 5-294 FROM ADR FLOOR, 5-288 THROUGH 5-275 AND 5-348 THROUGH 5-360.	
Items	Visual inspection of installed panels	
Inspected:		
	Visual inspection of extrusion welding	
	Survey completed	
Tests Completed:	Air testing on seams	
Completed.	Vacuum box testing on extrusion welds	
	Repairs and patches tested as required	
	3rd party conformance tests	
Deficient Items:	NONE	
Dame diel		
Remedial Action:	NONE	
Accented:	Yes X	
	APPROVED FOR LOW VOLUME PLACEMENT	
	APPROVED FULL LUW WILLIME TURCEINEN	
Signatures		
AMEC	ECA_	
Ames	Chang Brown Other	
CC&V		





CLIENT:	Cripple Creek & Victor Mining Co.	Page
PROJECT:	Squaw Gulch VLF PSSA	Weather_CLONDY
PROJECT NUMBER:	74201125N0	Date 9/6/14
Work Activity:	100-mil LLDPE Geomembrane Liner	
Area/Location:	See attached sketch - PANELS 5- 295	THRENGH S-306, S-361
THROUGH 5-3		
	Visual inspection of installed panels	
Inspected:	Visual inspection of wedge welds	
	Visual inspection of extrusion welding	•
	Survey completed	
	Air testing on seams	
Completed:	Vacuum box testing on extrusion welds	
	Repairs and patches tested as required	
	3rd party conformance tests	
	NONE	
Items:		
Remedial	NONE	
Action:		
Accepted:	Yes X	0
Explain:		
Signatures		
AME@:		
AIVIES	ECA	1
Ames	Chaning Brown Other	r
CC&V	The Other	r

