




COLORADO DIVISION OF RECLAMATION, MINING AND SAFETY
MINERALS PROGRAM INSPECTION REPORT
PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME: Camp Bird Mine	MINE/PROSPECTING ID#: M-1982-090	MINERAL: Gold, silver, lead, zinc	COUNTY: Ouray
INSPECTION TYPE: Monitoring	INSPECTOR(S): Travis H. Marshall	INSP. DATE: August 19, 2015	INSP. TIME: 13:00
OPERATOR: Camp Bird Colorado, Inc.	OPERATOR REPRESENTATIVE: None	TYPE OF OPERATION: 112 - Hard Rock Regular Operation	
REASON FOR INSPECTION: Normal I&E Program	BOND CALCULATION TYPE: None	BOND AMOUNT: \$90,000.00	
DATE OF COMPLAINT: NA	POST INSP. CONTACTS: None	JOINT INSP. AGENCY: None	
WEATHER: Clear	INSPECTOR'S SIGNATURE: 	SIGNATURE DATE: September 15, 2015	

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS----- <u>Y</u>	(FN) FINANCIAL WARRANTY----- <u>Y</u>	(RD) ROADS----- <u>Y</u>
(HB) HYDROLOGIC BALANCE----- <u>Y</u>	(BG) BACKFILL & GRADING----- <u>Y</u>	(EX) EXPLOSIVES----- <u>NA</u>
(PW) PROCESSING WASTE/TAILING---- <u>NA</u>	(SF) PROCESSING FACILITIES----- <u>Y</u>	(TS) TOPSOIL----- <u>Y</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>Y</u>	(FW) FISH & WILDLIFE----- <u>Y</u>	(RV) REVEGETATION---- <u>NA</u>
(SM) SIGNS AND MARKERS----- <u>Y</u>	(SW) STORM WATER MGT PLAN---- <u>Y</u>	(CI) COMPLETE INSP---- <u>Y</u>
(ES) OVERBURDEN/DEV. WASTE----- <u>NA</u>	(SC) EROSION/SEDIMENTATION--- <u>Y</u>	(RS) RECL PLAN/COMP-- <u>NA</u>
(AT) ACID OR TOXIC MATERIALS----- <u>NA</u>	(OD) OFF-SITE DAMAGE----- <u>Y</u>	(ST) STIPULATIONS----- <u>NA</u>

Y = Inspected and found in compliance / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

OBSERVATIONS

This inspection was conducted as part of the normal monitoring program established by the Colorado Division of Reclamation Mining and Safety. The Camp Bird Mine is a 112 active underground mine. The commodities to be mined are copper, zinc, lead, silver and gold. The mine currently consists of 35 permitted acres and a maximum allowed disturbance of 35 acres. The Camp Bird Mine is located approximately 3.5 miles southwest of Ouray Colorado off of Ouray County Road 26. No operator representative was present during the inspection.

The mine identification sign was observed at the entrance to the mine site but no permit area boundary markers were observed. The lack of permit boundary markers is considered a problem and the operator has until November 16, 2015 to install makers that meet the requirements of Rule 3.1.12. **The operator must provide DRMS staff photo-documentation that demonstrates the makers have been correctly placed no later than November 16, 2015.**

Camp Bird Colorado, Inc. is currently going through a bankruptcy process and the mine was inactive during the inspection. The purpose of the inspection was to observe the current conditions of the site and determine if any issues needed to be addressed.

The mine drainage conveyance feature appeared to be in good properly functioning condition. The mine discharge outfall that drains to the settling pond appeared to be properly functioning.

No erosion or sedimentation issues were noted. There are no major or minor drainages within the permit area that warrant addressing.

Responses to this inspection report should be directed to Travis Marshall at the Division of Reclamation Mining and Safety Grand Junction Field Office, 101 South 3rd Street, Suite 301, Grand Junction, Colorado 81501 phone no. (970) 241-2042.

PHOTOGRAPHS





Inspection Contact Address

Scott Butters
Camp Bird Colorado, Inc.
P.O. Box 806
Salt Lake City, UT 84110

cc: Russ Means, DRMS