

COLORADO DIVISION OF RECLAMATION, MINING AND SAFETY MINERALS PROGRAM INSPECTION REPORT

PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME:	MINE/PROSPECTING ID#:	MINERAL:	COUNTY:
Thank You Lord Claim	M-2013-041	Gemstones	Chaffee
INSPECTION TYPE:	INSPECTOR(S):	INSP. DATE:	INSP. TIME:
Monitoring	Dustin Czapla, Michael Cunningham	September 11, 2015	15:30
OPERATOR:	OPERATOR REPRESENTATIVE:	TYPE OF OPERATION:	
Brian Busse		110(2) - Hard Rock Limited Impact	

REASON FOR INSPECTION:	BOND CALCULATION TYPE:	BOND AMOUNT:
Normal I&E Program	None	\$5,700.00
DATE OF COMPLAINT:	POST INSP. CONTACTS:	JOINT INSP. AGENCY:
NA	None	None
WEATHER:	INSPECTOR'S SIGNATURE:	SIGNATURE DATE:
Cloudy	16	September 11, 2015

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.


(AR) RECORDS <u>Y</u>	(FN) FINANCIAL WARRANTY <u>Y</u>	(RD) ROADS <u>NA</u>
(HB) HYDROLOGIC BALANCE <u>Y</u>	(BG) BACKFILL & GRADING <u>N</u>	(EX) EXPLOSIVES NA
(PW) PROCESSING WASTE/TAILING NA	(SF) PROCESSING FACILITIES <u>NA</u>	(TS) TOPSOIL <u>NA</u>
(MP) GENL MINE PLAN COMPLIANCE- Y	(FW) FISH & WILDLIFE <u>N</u>	(RV) REVEGETATION NA
(SM) SIGNS AND MARKERS <u>N</u>	(SW) STORM WATER MGT PLAN NA	(CI) COMPLETE INSP Y
(ES) OVERBURDEN/DEV. WASTE NA	(SC) EROSION/SEDIMENTATION Y	(RS) RECL PLAN/COMP N
(AT) ACID OR TOXIC MATERIALS NA	(OD) OFF-SITE DAMAGE <u>NA</u>	(ST) STIPULATIONS NA

Y = Inspected and found in compliance / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

OBSERVATIONS

This was a routine monitoring inspection. A representative for the operator was not present. The site was observed from the footpath leading to the site from FR277. The site is located at 38.661536°, -106.263451°, approximately 11.5 miles west of Nathrop at an elevation of 12,300 feet. The site is accessed by foot from FR277. Mining at the site consists of excavating into the talus slope with hand tools. Little to no topsoil or vegetation exists at the site. Less than 0.5 acres appeared to be disturbed. No problems or violations were noted.

Responses to this inspection report should be directed to Dustin Czapla at the Division of Reclamation, Mining and Safety, Grand Junction Field Office, 101 South 3rd Street, Room 301, Grand Junction, Colorado 81501, phone number (970) 243-6299.



Inspection Contact Address

Brian Busse 1437 G Sreet Salida, CO 81201