

# COLORADO DIVISION OF RECLAMATION, MINING AND SAFETY MINERALS PROGRAM INSPECTION REPORT

PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME:	MINE/PROSPECTING ID#:	MINERAL:	COUNTY:
Whirlwind Mine	M-2007-044	Uranium and vanadio	Mesa
INSPECTION TYPE:	INSPECTOR(S):	INSP. DATE:	INSP. TIME:
Monitoring	Stephanie J. Mitchell	August 11, 2015	09:00
OPERATOR:	OPERATOR REPRESENTATIVE:	TYPE OF OPERATION:	
Energy Fuels Resources (USA) Inc.	Race Fisher and Todd Eldridge	112d-1 - Designated Mining Operation	

REASON FOR INSPECTION: Normal I&E Program	BOND CALCULATION TYPE: Complete Bond	BOND AMOUNT: \$375.078.00
DATE OF COMPLAINT:	POST INSP. CONTACTS:	JOINT INSP. AGENCY:
NA WEATHER:	None INSPECTOR'S SIGNATURE:	None SIGNATURE DATE:
Cloudy	3Xmitelle	October 6, 2015

#### **GENERAL INSPECTION TOPICS**

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS <u>Y</u>	(FN) FINANCIAL WARRANTY Y	(RD) ROADS <u>Y</u>
(HB) HYDROLOGIC BALANCE <u>Y</u>	(BG) BACKFILL & GRADING <u>Y</u>	(EX) EXPLOSIVES N
(PW) PROCESSING WASTE/TAILING Y	(SF) PROCESSING FACILITIES Y	(TS) TOPSOIL <u>Y</u>
(MP) GENL MINE PLAN COMPLIANCE- Y	(FW) FISH & WILDLIFE <u>Y</u>	(RV) REVEGETATION <u>Y</u>
(SM) SIGNS AND MARKERS <u>Y</u>	(SW) STORM WATER MGT PLAN N	(CI) COMPLETE INSP Y
(ES) OVERBURDEN/DEV. WASTE N	(SC) EROSION/SEDIMENTATION $\underline{Y}$	(RS) RECL PLAN/COMP Y
(AT) ACID OR TOXIC MATERIALS Y	(OD) OFF-SITE DAMAGE <u>N</u>	(ST) STIPULATIONS Y

Y = Inspected and found in compliance / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

PERMIT #: M-2007-044 INSPECTOR'S INITIALS: SJM INSPECTION DATE: August 11, 2015

#### **OBSERVATIONS**

This was a normal monitoring inspection of the Whirlwind Mine; permit number M-2007-044. This site is located about seven miles southeast of Gateway, Colorado in Mesa County. I, Stephanie Mitchell of the Colorado Division of Reclamation, Mining and Safety conducted the inspection. Mr. Race Fisher and Mr. Todd Eldridge of Western Fuels accompanied me on the inspection.

The permit area for this site is designated as 31.91 acres with 22.60 of maximum allowed disturbance. The Whirlwind Mine is a 112d underground mine. The post mine land used designated for this site is Rangeland. The proper mine identification sign was in place, and the entire permit boundary was walked, and all the corners of the permit area were marked with posts and delineated with a fence.

The site is currently inactive and in Temporary Cessation status. No fuel is being stored on site and all buildings, including the portal are secured. Energy Fuels is waiting for the price of Uranium to increase before starting up mining operations again.

No problems were observed at this site.


Photographs are included at the end of this report in order to illustrate some of the conditions observed during this inspection.


Responses to this inspection report should be directed to Stephanie Mitchell at the Division of Reclamation, Mining and Safety, Grand Junction Field Office, 101 South 3rd Street, Room 301, Grand Junction, Colorado 81501, phone number (970) 242-5025.

## **PHOTOGRAPHS**



Mine Identification Sign






Tool Trailer



Bench where portal is located




Waste Rock Pile beyond Fence



Packrat Portal

PERMIT #: M-2007-044 INSPECTOR'S INITIALS: SJM INSPECTION DATE: August 11, 2015











PERMIT #: M-2007-044 INSPECTOR'S INITIALS: SJM INSPECTION DATE: August 11, 2015

### **Inspection Contact Address**

Harold Roberts
Energy Fuels Resources (USA) Inc.
225 Union Blvd., Suite 600
Lakewood, CO 80228

CC: Scott Gerwe BLM- Grand Junction Field Office 2815 H Road Grand Junction, CO 81506