




COLORADO DIVISION OF RECLAMATION, MINING AND SAFETY
MINERALS PROGRAM INSPECTION REPORT
PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME: Kittimac Tailings Repository	MINE/PROSPECTING ID#: P-2011-015	MINERAL: Unknown commodity	COUNTY: San Juan
INSPECTION TYPE: Monitoring	INSPECTOR(S): Lucas J. West	INSP. DATE: September 10, 2015	INSP. TIME: 10:45
OPERATOR: Colorado Goldfields Inc.	OPERATOR REPRESENTATIVE: None	TYPE OF OPERATION: MP - Mineral Prospecting	

REASON FOR INSPECTION: Normal I&E Program	BOND CALCULATION TYPE: None	BOND AMOUNT: \$298.00
DATE OF COMPLAINT: NA	POST INSP. CONTACTS: None	JOINT INSP. AGENCY: None
WEATHER: Clear	INSPECTOR'S SIGNATURE: 	SIGNATURE DATE: October 13, 2015

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS----- <u>N</u>	(FN) FINANCIAL WARRANTY----- <u>N</u>	(RD) ROADS----- <u>N</u>
(HB) HYDROLOGIC BALANCE----- <u>Y</u>	(BG) BACKFILL & GRADING----- <u>Y</u>	(EX) EXPLOSIVES----- <u>N</u>
(PW) PROCESSING WASTE/TAILING---- <u>N</u>	(SF) PROCESSING FACILITIES----- <u>N</u>	(TS) TOPSOIL----- <u>N</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>N</u>	(FW) FISH & WILDLIFE----- <u>N</u>	(RV) REVEGETATION---- <u>N</u>
(SM) SIGNS AND MARKERS----- <u>N</u>	(SW) STORM WATER MGT PLAN---- <u>N</u>	(CI) COMPLETE INSP---- <u>Y</u>
(ES) OVERBURDEN/DEV. WASTE----- <u>N</u>	(SC) EROSION/SEDIMENTATION--- <u>N</u>	(RS) RECL PLAN/COMP-- <u>Y</u>
(AT) ACID OR TOXIC MATERIALS----- <u>N</u>	(OD) OFF-SITE DAMAGE----- <u>Y</u>	(ST) STIPULATIONS----- <u>N</u>

Y = Inspected and found in compliance / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

OBSERVATIONS

This inspection was conducted as part of the routine monitoring program for Hard Rock and Metals prospecting NOIs. The site was not active during the time of the inspection. No Operator representative was present during the inspection. The site is located six miles Northeast of Silverton adjacent to County Road 2. The Division currently holds a \$298.00 financial warranty for the site. Two Photos accompany this report to illustrate current site conditions.

The site was not active at the time of the inspection. This operation consisted of drilling several auger holes into a pre law tailings dump. The site has been fully reclaimed, at the time of the inspection only three drill holes were located. The drill holes observed were backfilled with gravel and plugged with concrete upon completion as seen in Photo One. According to records held by the Division each drill hole was reclaimed prior to the commencement of drilling at the next sequential hole. No casings or drill cuttings were observed on site. All disturbances are fully reclaimed at this time.


The sites showed little vegetation as seen in Photo Two. Due to the site being located in a pre-law tailings dump, revegetation was never a part of the approved reclamation plan. Some native bunch grasses and willow brush is located on site but was not disturbed by the operation. No noxious weeds were observed on site and the overall footprint of the site was in good condition and free from trash and debris.

All disturbance appears to be fully reclaimed and is eligible for final release. No problems or possible violations were observed at this time. If the Operator wishes to apply for final release a request must be submitted in writing and in compliance with Hard Rock and Metals Rule 4.16. If a release request is received within 60 days of the date of this report, this inspection will satisfy the inspection requirements of the request.

The operator is reminded that in order for the Division to consider approving a release request, ALL annual report and fee requirements must be up-to-date.

Responses to this inspection report should be directed to Lucas West at the Division of Reclamation, Mining and Safety, 1313 Sherman Street, Room 215 Denver, CO 80203.

PHOTOGRAPHS



Inspection Contact Address

Stephen Guyer
Colorado Goldfields Inc.
7986 S. Datura Circle West
Littleton, CO 80120

Enclosure

CC: